



# Home Report

27 Mathers Avenue

Whitburn

Bathgate

West Lothian

EH47 ONA

Offices throughout Scotland alliedsurveyorsscotland.com

## survey report on:

Property address	27 Mathers Avenue, Whitburn, BATHGATE, West Lothian, EH47 0NA
Customer	Power of Attorney of Mrs J McGill
	,
Customer address	C/O Sneddon Morrison, 34-46 North Bridge Street, Bathgate, West Lothian, EH48 1TL
Prepared by	Allied Surveyors Scotland Ltd



10th July 2024

**Date of inspection** 

#### **PART 1 - GENERAL**

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
  or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.<sup>2</sup>

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 - DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	This is a two storey semi-detached house.
Accommodation	GROUND FLOOR - Hallway, living room, kitchen/breakfast room. FIRST FLOOR - Landing, two bedrooms, bathroom (with WC).
Gross internal floor area (m²)	This is estimated at 73m2.
Neighbourhood and location	The property is situated within an established residential area of mixed public sector, tenanted and privately owner occupied housing to the west of Whitburn town centre.  All the usual facilities and amenities are available locally and there is a regular public transport service to neighbouring communities and to the nearby cities of Edinburgh and Glasgow.
Age	This is estimated at 74 years.
Weather	At the time of inspection, it was dull and overcast with occasional showers.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.  The chimney stack is of brick construction with concrete coping and a metal cowl.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.  Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.  Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.

Roofing including roof space	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof is pitched with a tile covering over timber sarking and rafters.
	Access to the roof void is by means of a hatch located within the first floor landing ceiling. Fibre wool insulative material is present within the roof void as are redundant cold water storage cisterns.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	These are of cast iron construction with guttering connected to downpipes.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	These are of cavity brick with a render finish applied externally.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows are of a PVC framed pivot, casement or tilt and turn character with double glazed sealed units installed.
	The external doors are PVC framed and double glazed.
External decorations	Visually inspected.
	Decorative finishes are in paint or stain.
Conservatories / porches	There are no conservatories and there are no porches with this property.
Communal areas	There are no communal areas.
Garages and permanent outbuildings	There is no garage with this property and there are no significant permanent outbuildings.
	Off-street parking is provided and there is a small frame, metal clad shed.
L .	

Outside areas and boundaries	Visually inspected.
	Garden areas exist to the front, side and rear of the property.
	Boundaries, where present, are formed in timber fences and brick walls.
Ceilings	Visually inspected from floor level.
	These are of a plasterboard nature.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	These are of a plaster or plasterboard character.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	These are of a solid concrete or suspended timber nature.
	Floor coverings were fitted and no sub-floor inspection has been made.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Internal doors are timber framed or timber framed and glazed.
	Timber facings and skirting boards are present within the property and the staircase to first floor level is also of timber construction.
	There are fitted floor and wall units in the kitchen area.
Chimney breasts and fireplaces	Visually inspected.
	No testing of the flues or fittings was carried out.
	The chimney breast is of brick construction with a slab based fireplace. The fireplace has been removed and the redundant flue blocked.

Internal decorations	Vigually inapported
internal decorations	Visually inspected.  Decerative finishes are in point, paper or both. Some tiling and
	Decorative finishes are in paint, paper or both. Some tiling and boarding have also been used.
Cellars	There are no cellars with this property.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and
	meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	There is a mains supply of electricity connected to the property.
	The distribution board, housing a circuit breaker unit, is located within an under-stair cupboard.
	Visible wiring was PVC coated.
Gas	Accessible parts of the system were visually inspected
	without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	There is a mains gas supply connected to the property.
	The gas metre is located within an external storage box.
	The gas supply serves the central heating boiler and other appliances within this house.
Water plumbing bothroom fittings	
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	There is a mains waster supply connected to the property.
	Visible plumbing fitments were of a copper or PVC nature.
	The bathroom fittings, although not tested, appeared serviceable.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	There is a gas fired central heating system serving panel radiators.

The boiler for this is a Baxi 830 Combi Unit located on the kitchen

wall and vented externally by means of a balanced flue.

The central heating boiler also provides domestic hot water.

# Drainage covers etc were not lifted. Neither drains nor drainage systems were tested. This is understood to be connected to the main public sewer.

#### Fire, smoke and burglar alarms

Visually inspected.

No tests whatsoever were carried out to the system or appliances.

Smoke alarms were noted on ceilings within the property.

No comment is offered in respect of security systems.

The new Fire and Smoke Alarm Standard came into force in February 2022. This new standard requires a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also needs to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon-fuelled appliance such as a boiler, open fire, or wood burner a carbon monoxide detector is also required.


#### Any additional limits to inspection

The property was vacant, but partly furnished and had fitted floor coverings.

No sub-floor inspection has been made and the roof void has been inspected on a head and shoulders basis only.

We do not carry out an inspection for Japanese Knotweed, which is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. We have assumed that there is no Japanese Knotweed within the boundaries of the property or in neighbouring properties. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists, removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.

### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2 Coping stone
- 3) Chimney head
- 4 Flashing
- 5 Ridge ventilation
- 6 Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- 17) Parapet gutter
- (18) Eaves guttering
- (19) Rainwater downpipe
- 20) Verge boards/skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- 25) Window pointing
- 6) Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40 Hot water tank

#### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	There are no indications of significant structural movement with this or neighbouring properties.

Dampness, rot and infestation	
Repair category	1
Notes	Moisture meter readings were obtained within the property, but at a level attributable to condensation or to the inherent moisture content of materials employed within the construction.

Chimney stacks	
Repair category	2
Notes	Some weathered pointing was noted to the chimney stack and the concrete coping has also weathered slightly.
	A full examination of water gaits at the rear of the stack has not been possible. This is an area where defect can occur and not be readily detected.

Roofing including roof space	
Repair category	1
Notes	Roof coverings appear to be original. There were, however, no indications of significant defect at the time of this inspection. Ongoing maintenance should be anticipated.  Roofs are prone to water penetration during adverse weather, but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms.

Rainwater fittings	
Repair category	1
Notes	There were no indications of defect requiring immediate action or repair.
	Some organic material was noted to be present within guttering sections.

Main walls	
Repair category	1
Notes	The render finish has been renewed in the recent past.
	Care should be taken to ensure that adequate pointing is maintained at door and window openings to prevent any possibility of water penetration.
	The render finish has been taken directly to ground level. This may have formed an effective bridge to any existing damp proofing provision.
	Ventilation bricks have been partly obstructed in the re-rendering process.

Windows, external doors and joinery	
Repair category	1
Notes	There were no indications of defect requiring immediate action or repair. It should be noted that double glazed sealed units are ageing and it would not be uncommon for units of this age to fail at anytime.

External decorations	
Repair category	1
Notes	Some weathering was noted to decorative finishes externally.

Conservatories/porches	
Repair category	-
Notes	There are no conservatories and there are no porches with this property.

Communal areas	
Repair category	-
Notes	There are no communal areas.

Garages and permanent outbuildings	
Repair category	1
Notes	There is no garage and there are no significant permanent outbuildings.
	The metal frame, metal clad shed appears to be in an acceptable condition.

Outside areas and boundaries	
Repair category	2
Notes	The render finish to the partition wall in the rear garden is cracked, broken and missing in sections.
	Some unevenness was noted within paved areas.

Ceilings	
Repair category	1
Notes	Some shrinkage cracking was noted in cupboard areas.  Textured finishes have been applied to some ceilings. Early forms of textured finish may contain asbestos material.

Internal walls	
Repair category	1
Notes	Unevenness was noted within plaster finishes.

Floors including sub-floors	
Repair category	1
Notes	There were no indications of significant distortion or deflection found within flooring sections.
	Unevenness was noted but is consistent with service access.
	Unevenness was also present within the bathroom flooring which may be attributable to works undertaken when fittings were renewed.
	It should be noted, however, that flooring has not been subject to inspection and that no examination of flooring beneath bath has taken place.

Internal joinery and kitchen fittings	
Repair category	2
Notes	Some adjustment to individual cupboard hinges is anticipated.
	Marking was noted to worktops.
	Laminate finishes are peeling slightly.

Chimney breasts and fireplaces	
Repair category	1
Notes	There were no indications of defect requiring immediate action or repair.  If it is a potential purchasers intention to utilise the existing flue, then it may be necessary to install a suitable flue liner.

Internal decorations	
Repair category	1
Notes	Limited marking was noted to decorative finishes. Regular decorative maintenance should be anticipated.

Cellars	
Repair category	-
Notes	There are no cellars with this property.

Electricity	
Repair category	1
Notes	There were no visible indications of defect at the time of this inspection.
	Confirmation the system complies with current regulation and is in a serviceable condition can only be given by a qualified electrician.
	The trade bodies governing electrical installations currently advise that these should be tested prior to a change of occupancy and, thereafter, at least once every five years, by a competent Electrician.

Gas	
Repair category	1
Notes	There were no visible indications of defect within those sections of the gas supply
Hotes	There were no visible indications of defect within those sections of the gas supply

Gas	
Repair category	1
Notes	system available for visual inspection.  Confirmation the system complies with current regulation and is in a serviceable condition can only be given by a Gas Safe registered engineer.

F Water, plumbing and bathroom fittings	
Repair category	1
Notes	Care should be taken to ensure that adequate sealant is maintained around the bath to prevent any possibility of water spillage. This is particularly important given the provision of a shower fitment above the bath.

Heating and hot wat	er
Repair category	1
Notes	There were no visible indications of defect at the time of this inspection.  It has been assumed that the heating installation has been regularly serviced and that recent service history records will be made available.

Drainage	
Repair category	1
Notes	There were no indications of significant blockage or backup found at the time of inspection.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	2
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	1
Outside areas and boundaries	2
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	2
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

#### Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground floor & first floor
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes No X
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

The property has been altered in the past in the provision of replacement windows and doors. This work may have been undertaken than some time ago.

Internal partitions appear to have been taken down in the past. These works would appear to have been carried out more than 20 years ago.

The property is located in an area where mineral extraction has taken place. It would, therefore, be prudent to obtain a satisfactory Coal Authority Report.

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a Category 1 rating is used this means that the building must continue to be maintained in the normal way. It is recommended that where repairs, defects or maintenance items have been identified within this report that interested parties make appropriate enquiries in order to satisfy themselves of potential costs or the extent of works required prior to submitting a legal offer to purchase.

#### Estimated reinstatement cost for insurance purposes

The estimated reinstatement cost for insurance purposes is £190,000 (One Hundred & Ninety Thousand Pounds Sterling).

This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction, on a reinstatement basis, assuming reconstruction of the property in its existing design and materials.

#### Valuation and market comments

The market value of the described property in the report is £130,000 (One Hundred & Thirty Thousand Pounds Sterling). This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights.

Signed	Security Print Code [565510 = 7405 ] Electronically signed
Report author	R A Smith
Company name	Allied Surveyors Scotland Ltd
Address	66 South Bridge Street, Bathgate, EH48 1TL

Date of report	17th July 2024
----------------	----------------



Property Address			
Address 27 Mathers Avenue, Whitburn, BATHGATE, West Lothian, EH47 0NA Seller's Name Power of Attorney of Mrs J McGill Date of Inspection 10th July 2024			
Property Details			
Property Type  X House Bungalow Chalet Purpose built maisonette Coach Studio Converted flat Flat over non-residential use Other (specify in General Remark	·ks)		
Property Style  Detached  X Semi detached  Mid terrace  End terrace  Detached  High rise block  Low rise block  Other (specify in General Remark)	ks)		
Does the surveyor believe that the property was built for the public sector, e.g. local authority, military, police?			
Flats/Maisonettes only Floor(s) on which located No. of floors in block Lift provided? Yes No. of units in block			
Approximate Year of Construction 1950			
Tenure			
X Absolute Ownership Leasehold Ground rent £ Unexpired years			
Accommodation			
Number of Rooms  1 Living room(s) 2 Bedroom(s) 1 Kitchen(s) 0 Other (Specify in General remarks)	_		
Gross Floor Area (excluding garages and outbuildings) 73 m² (Internal) 81 m² (External)			
Residential Element (greater than 40%) X Yes No			
Garage / Parking / Outbuildings			
Single garage       □ Double garage       □ No garage / garage space / parking space         Available on site?       □ No	е		
Permanent outbuildings:			
There is a small metal frame, metal clad storage shed in the rear garden area.			

Construction								
Walls	X Brick	Stone	Cor	ncrete	Timber frame			
	Solid	Cavity		el frame	Concrete block	Othe	er (specify in Ger	neral Remarks)
Roof	X Tile	Slate		ohalt [	Felt		, ,	,
	Lead	Zinc	Arti	ificial slate	Flat glass fibre	Othe	er (specify in Ger	neral Remarks)
Special Risks								
Has the property s	suffered structi	ural moveme	ent?				Yes	X No
If Yes, is this recei	nt or progress	ive?					Yes	No
Is there evidence, immediate vicinity	history, or rea?	son to antici	pate subsi	dence, he	ave, landslip o	or flood in th	e Yes	X No
If Yes to any of the	e above, provi	de details in	General R	emarks.				
Service Connec	tion							
Based on visual in of the supply in Ge			es appear	to be nor	-mains, pleas	e comment	on the type a	nd location
Drainage	X Mains	Private	None		Water	X Mains	Private	None
Electricity	X Mains	Private	None		Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None					
Brief description o	f Central Heat	ing:						
There is a gas fir	red central hea	ating system	serving pa	anel radiat	ors.			
Site								
Apparent legal iss	ues to be verif	ied by the co	nvevance	r. Please i	provide a brief	description	in General R	emarks.
Rights of way	Shared drive	-			nities on separate		ared service con	
Agricultural land ind				d boundaries		_	ner (specify in Ge	
Location	· ·	•						,
			Г					
Residential suburb	_	dential within to	wn / city	_	sidential / comme		inly commercial	
Commuter village	Rem	ote village	Ĺ	Isolated i	ural property	U Oth	ner (specify in Ge	neral Remarks)
Planning Issues	;							
Has the property b	een extended	I / converted	/ altered?	X Yes	No			
If Yes provide deta	ails in General	Remarks.						
Roads								
X Made up road	Unmade road	Partly	completed ne	ew road	Pedestrian a	access only	Adopted	Unadopted

General Remarks
The property is situated within an established residential area of mixed public sector, tenanted and privately owner occupied housing to the west of Whitburn town centre. All the usual facilities and amenities are available locally and there is a regular public transport service to neighbouring communities and to the nearby cities of Edinburgh and Glasgow.
The property was found to be in a condition consistent with age and construction. Some upgrading of fittings, fixtures and services has taken place in the past but with further works anticipated. Ongoing maintenance should be envisaged in respect of all elements of the building fabric.
The property has been altered in the past in the provision of replacement windows and doors and in the partial taking down of some partitions. These works would appear to have been undertaken more than 20 years ago.
The property is located in an area where mineral extraction has taken place.
Essential Repairs
None.
Estimated cost of essential repairs £ Retention recommended? Yes X No Amount £

Comment on Mortgageability				
	for which, in normal marketing conditions, there is a steady demand.  d to form adequate loan security, subject to individual lenders criteria.			
Valuations				
Buy To Let Cases  What is the reasonable rangementh Short Assured Tenangement	n of essential repairs lue rebuilding, site clearance, professional fees, ancillary charges plus VAT) r?  ge of monthly rental income for the property assuming a letting on a 6	£ 130,000 £		
Signed Surveyor's name Professional qualifications Company name Address Telephone Fax Report date	Security Print Code [565510 = 7405] Electronically signed by:- R A Smith BSc MRICS Allied Surveyors Scotland Ltd 66 South Bridge Street, Bathgate, EH48 1TL 01506 631 717 01506 633 591 17th July 2024			

## **Energy Performance Certificate (EPC)**

**Dwellings** 

# **Scotland**

#### 27 MATHERS AVENUE, WHITBURN, BATHGATE, EH47 ONA

**Dwelling type:** Semi-detached house

Date of assessment: 10 July 2024
Date of certificate: 10 July 2024
Total floor area: 73 m<sup>2</sup>

Primary Energy Indicator: 326 kWh/m²/year

**Reference number:** 0160-2650-9130-2194-8655 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

#### You can use this document to:

- . Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

Estimated energy costs for your home for 3 years*	£4,833	See your recommendations
Over 3 years you could save*	£1,452	report for more information

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (65)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



#### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide ( $CO_2$ ) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (60)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Cavity wall insulation	£500 - £1,500	£756.00
2 Floor insulation (suspended floor)	£800 - £1,200	£366.00
3 Heating controls (room thermostat)	£350 - £450	£162.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, as built, no insulation (assumed)	***	***
Roof	Pitched, 250 mm loft insulation	****	<b>★★★★</b> ☆
Floor	Suspended, no insulation (assumed)	_	_
Windows	Fully double glazed	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Main heating	Boiler and radiators, mains gas	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Main heating controls	Programmer, TRVs and bypass	<b>★★★☆☆</b>	<b>★★★☆☆</b>
Secondary heating	None	_	_
Hot water	From main system	<b>★★★★</b> ☆	<b>★★★★</b> ☆
Lighting	Low energy lighting in 82% of fixed outlets	****	****

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 57 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 4.2 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 2.2 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

#### Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£3,978 over 3 years	£2,691 over 3 years	
Hot water	£525 over 3 years	£360 over 3 years	You could
Lighting	£330 over 3 years	£330 over 3 years	save £1,452
Totals	£4,833	£3,381	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indicative cost	Typical saving	Rating after improvement	
		Indicative cost	per year	Energy	Environment
1 Ca	vity wall insulation	£500 - £1,500	£252	C 70	D 67
2 Flo	oor insulation (suspended floor)	£800 - £1,200	£122	C 72	C 70
3 Up	grade heating controls	£350 - £450	£54	C 73	C 72
4 Sol	lar water heating	£4,000 - £6,000	£56	C 74	C 74
5 Sol	lar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£462	B 86	B 84

#### **Alternative measures**

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

External insulation with cavity wall insulation

## Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



#### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Cavity wall insulation

Cavity wall insulation, to fill the gap between the inner and outer layers of external walls with an insulating material, reduces heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the outer walls, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work and handle any building standards issues. Further information about cavity wall insulation and details of local installers can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

#### 2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

#### 3 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

#### 4 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

#### 5 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	13,363	N/A	(2,907)	N/A
Water heating (kWh per year)	2,042			

#### **Addendum**

#### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Robert Smith Assessor membership number: EES/008344

Company name/trading name: Allied Surveyors Scotland Ltd Address: Allied Surveyors Scotland Ltd 66 South Bridge Street

Bathgate

EH4§ 1TL Phone number: 01506631717

Email address: bathqate@alliedsurveyorsscotland.com

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



# Property Questionnaire

PROPERTY ADDRESS:	27 MATHERS AUE WHITBURN WEST LOTHIAN CH47 ONA

SELLER(S):	J. MCGILL

COMPLETION DATE OF PROPERTY QUESTIONNAIRE:	17/7/2024

#### PROPERTY QUESTIONNAIRE

#### **NOTE FOR SELLERS**

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the Date of Entry for the sale of your house, tell your solicitor or estate agent immediately.

# PROPERTY QUESTIONNAIRE Information to be given to prospective buyer(s)

1. Length of ownership	
How long have you owned the	property? 720 YEARS
2. Council Tax	
Which Council Tax band is yo	ur property in? DON'T KNOW  E F G H
3. Parking	
What are the arrangements fo	r parking at your property?
(Please indicate all that apply)	
<ul><li>Garage</li><li>Allocated parking space</li></ul>	
• Driveway	
<ul><li>Shared parking</li><li>On street</li></ul>	
<ul><li>Resident permit</li></ul>	
<ul><li>Metered parking</li><li>Other (please specify):</li></ul>	

4.	Conservation Area	
	Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)?	Yes(No) Don't know
5.	Listed Buildings	
	Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)?	Yes/No
6.	Alterations / additions / extensions	
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes/No
	If you have answered yes, please describe the changes which you have made:	
	· · · · · · · · · · · · · · · · · · ·	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes/No

3	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent can arrange to obtain them.	
		erica Surv Più di
	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes/No
	If you have answered yes, please answer the three questions below:	i (NA) Israel
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes/No
	(ii) Did this work involve any changes to the window or door openings?	Yes/No
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):	
	New doors + windows	
	The property of the language of the property o	
	Please give any guarantees which you received for this work to your solicitor or estate agent.	

7.	Central heating	
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom).	Yes/No/ Partial
	If you have answered yes/partial – what kind of central heating is there?	
	(Examples: gas-fired, solid fuel, electric storage heating, gas warm air.)	
	If you have answered yes, please answer the 3 questions below:	
b.	When was your central heating system or partial central heating system installed? Not Sure - Syea	rs ago
c.	Do you have a maintenance contract for the central heating system?	Yes/No
	If you have answered yes, please give details of the company with which you have a maintenance agreement:	
N		
d.	When was your maintenance agreement last renewed? (Please provide the month and year).	

ŧ

8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Ye\$/No
9.	Issues that may have affected your property	
а.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes/No
a de maria de la composição de la composiç	If you have answered yes, is the damage the subject of any outstanding insurance claim?	Yes/No
b.	Are you aware of the existence of asbestos in your property?  If you have answered yes, please give details:	Yes/No
ne de la companya de	nga makana kana ana ana ana ana ana ana ana a	
10.	Services	

a. Please tick which services are connected to your property and give details of the supplier:

Services	Connected	Supplier
Gas / liquid petroleum gas		Scotlish Gas
Water mains / private water supply		
Electricity	/	
Mains drainage		
Telephone		VICEN
Cable TV / satellite	/	VIRGIN
	e e	· · · · ·

	Broadband		VIRGIN	
b.	Is there a septic tank sy	_		Yes/No
	If you have answered ye questions below:	<u>es,</u> please an	swer the two	
C.	Do you have appropri from your septic tank?	ate consent	s for the discharge	Yes/No/ Don't Know
d.	Do you have a mainte tank?	enance cont	ract for your seption	Yes/No
	If you have answered company with which yo	<u>yes,</u> please u have a mai	give details of the ntenance contract:	
11.	Responsibilities for Sha	red or Comm	on Areas	
a.	Are you aware of any recost of anything used journal shared drive, private ro	ointly, such a	is the repair of a	Yes/No/ Don't Know
	If you have answered yo	<u>es,</u> please giv	ve details:	
b.	Is there a responsibility maintenance of the root common areas?			Yes/No. Not applicable
	If you have answered ye	<u>es,</u> please giv	/e details:	

	· ·	$\sim$
C.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes/No
i seel		
d.	Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?	Ye\$/No
	If you have answered yes, please give details:	
-		1
: }		
е.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	Yes/No
	If you have answered yes, please give details:	
	As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	Yes/No
	If you have answered yes, please give details:	
		4.5
12.	Charges associated with your property	
	Changes accessed in a property	$\sim$
а.	Is there a factor or property manager for your property?	Ye\$/No
	If you have answered yes, please provide the name and address and give details of any deposit held and approximate charges:	

b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	Yes/No
•	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property	
	rot, damp or any other specialist work ever been carried out to your property?	
13. a.	Specialist Works  As far as you are aware, has treatment of dry rot, wet	Yes/No)
•	NA.	
•	pay on a regular basis for the upkeep of common areas or repair works, e.g. to a Residents' Association, or maintenance or stair fund.	
C.	Please give details of any other charges you have to	know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Yes/No/ Don't
b.	Is there a common buildings insurance policy?	Yes/No/ Don't

-	If you have answered yes	<u>s,</u> piease giv	e detalls		·
				: 4.4	
<b>C.</b>	If you have answered yearny guarantees relating  If you have answered yearneeded by the purchase solicitor as soon as possonot have them yourself at these documents and yourself arrange for them to be oprovide a description of	to this work' s, these gua r and should sible for che olease write our solicitor o btained. You	rantees w l be given cking. If y below who or estate a u will also	ill be to your you do o has agent will need to	es/No
1	may be shown in the original may be shown in				erit i
14.					
14.	Guarantees are held by:  Guarantees  Are there any guarantee				
	Guarantees are held by: Guarantees				Lost
a.	Guarantees are held by:  Guarantees  Are there any guarantee following:	s or warrant	ies for any	y of the With title	Lost Lost
a. (i)	Guarantees are held by:  Guarantees  Are there any guarantee following:  Electrical work	s or warrant	ies for any Don't Know Don't	y of the  With title deeds With title	Lost
(i)	Guarantees  Guarantees  Are there any guarantee following: Electrical work  Roofing	s or warrant No Yes No Yes	ies for any Don't Know Don't Know Don't	y of the  With title deeds With title deeds With title	Lost

(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)		
b.	If you have answered 'yes' or 'with title deed of the work or installations to which the gua	ls', please g rantee(s) re	ive details late(s):
c.	Are there any outstanding claims under any guarantees listed above?	of the	Yes/No
	If you have answered yes, please give detail	s:	
15.	Boundaries		
	So far as you are aware, has any boundar property been moved in the last 10 years?	ry of your	Yes/No/ Don't
- - -	If you have answered yes, please give detail	s:	Know
3 			
·			

16.	Notices that affect your property	
	In the past 3 years have you ever received a notice:	
а.	advising that the owner of a neighbouring property has made a planning application?	Yes/No/ Don't know
b.	that affects your property in some other way?	Yes/No/ Don't know
C.	that requires you to do any maintenance, repairs or improvements to your property?	Yes/No/ Don't know
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.	

Declaration by the seller(s)/or other authorised body or person(s):

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) :		2
	McGICL	

Date: 17 7 2024

•		