English | Cymraeg

# Energy performance certificate (EPC) recommendation report

Bunbury Arms Little Stanney Lane Stoak CHESTER CH2 4HW

Report number **0586-3439-6807-3566-5262** 

Valid until
12 September 2034

# **Energy rating and EPC**

This property's energy rating is C.

Recommendation

For more information on the property's energy performance, see the EPC for this property (/energy-certificate/8466-9668-6600-0829-2073).

#### Recommendations

#### Changes that may pay for themselves within 3 years

Recommendation	Potential impact on carbon emissions
Improve insulation on HWS storage.	Low
Consider replacing T8 lamps with retrofit T5 conversion kit.	Medium
The default heat generator efficiency is chosen. It is recommended that the heat generator system be investigated to gain an understanding of its efficiency and possible improvements.	Low
Some walls have uninsulated cavities - introduce cavity wall insulation.	Medium
Some windows have high U-values - consider installing secondary glazing.	Medium
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	Low
Add weather compensation controls to heating system.	Medium
Some loft spaces are poorly insulated - install/improve insulation.	Medium
Add local time control to heating system.	Medium
Changes that may pay for themselves within 3 to 7 years	
Recommendation	Potential impact on carbon emissions
Some solid walls are poorly insulated - introduce or improve internal wall insulation.	Medium
Consider switching from gas to biomass.	High
Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.	Medium
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium
Consider installing an air source heat pump.	Medium
Consider installing a ground source heat pump.	High
Changes that may pay for themselves in over 7 years	

Potential impact on carbon emissions

Recommendation	Potential impact on carbon emissions
Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or exterior.	Medium
Roof is poorly insulated. Install or improve insulation of roof.	Medium
Consider installing building mounted wind turbine(s).	Low
Consider installing solar water heating.	Low
Consider installing DV	Low

# Property and report details

Report issued on	13 September 2024
Total useful floor area	344 square metres
Building environment	Heating and Natural Ventilation
Calculation tool	DesignBuilder Software Ltd, DesignBuilder SBEM, v7.2.0, SBEM, v6.1.e.0

### Assessor's details

Assessor's name	Laura Grundy
Telephone	01924 669941
Email	epc@compliance365.co.uk
Employer's name	Compliance365
Employer's address	
Assessor ID	EES/031774
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Elmhurst Energy Systems Ltd

# Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at <a href="mailto:mhclq.digital-services@communities.gov.uk">mhclq.digital-services@communities.gov.uk</a> or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

Valid until	28 June 2027
Report number	0090-0443-8109-8126-7006 (/energy-certificate/0090-0443-8109-8126-7006)
Valid until	29 December 2029
Report number	0790-0441-8109-8192-7092 (/energy-certificate/0790-0441-8109-8192-7092)

 Help (/help)
 Accessibility (/accessibility-statement)
 Cookies (/cookies)

 Give feedback (https://forms.office.com/e/KX25htGMX5)
 Service performance (/service-performance)

#### **OGL**

All content is available under the <u>Open Government Licence v3.0</u> (<a href="https://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/">https://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/</a>), except where otherwise stated



ht (https://www.nationalarchives.gov.uk/information-management/re-using-public-sector-information/uk-government-licensing-framewor