Find an energy certificate (/)

English | Cymraeg

# **Energy performance certificate** (EPC) recommendation report

The Lamb 12 Wistaston Road Willaston **NANTWICH** CW5 6PX

Report number 2808-6836-4563-2509-1550

> Valid until 13 March 2035

### **Energy rating and EPC**

This property's energy rating is D.

For more information on the property's energy performance, see the EPC for this property (/energy-certificate/8212-3243-8025-2686-5607).

### Recommendations

#### Changes that may pay for themselves within 3 years

Recommendation	Potential impact on carbon emissions
Replace 38mm diameter (T12) fluorescent tubes on failure with 26mm (T8) tubes.	Low
Improve insulation on HWS storage.	Low
Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.	Low
Add optimum start/stop to the heating system.	Medium
The default heat generator efficiency is chosen. It is recommended that the heat generator system be investigated to gain an understanding of its efficiency and possible improvements.	Low
Some walls have uninsulated cavities - introduce cavity wall insulation.	Medium

Recommendation	Potential impact on carbon emissions
Consider replacing T8 lamps with retrofit T5 conversion kit.	Low
In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to windows.	Medium
Some windows have high U-values - consider installing secondary glazing.	Medium
Add weather compensation controls to heating system.	Medium
Some loft spaces are poorly insulated - install/improve insulation.	Medium
Add local time control to heating system.	Medium
Some solid walls are poorly insulated - introduce or improve internal wall insulation.	Medium
Consider replacing heating boiler plant with a condensing type.	High
Consider switching from gas to biomass.	High
Changes that may pay for themselves within 3 to 7 years	
Recommendation	Potential impact on carbon emissions
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	Low
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium
Consider installing an air source heat pump.	N. 1.
Consider installing an all source near pump.	Medium
Consider installing an air source heat pump.  Consider installing a ground source heat pump.	Medium
Consider installing a ground source heat pump.  Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or	Medium
Consider installing a ground source heat pump.  Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or exterior.	Medium
Consider installing a ground source heat pump.  Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or exterior.  Changes that may pay for themselves in over 7 years	Medium  Medium  Potential impact on carbon
Consider installing a ground source heat pump.  Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or exterior.  Changes that may pay for themselves in over 7 years  Recommendation	Medium  Medium  Potential impact on carbon emissions
Consider installing a ground source heat pump.  Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or exterior.  Changes that may pay for themselves in over 7 years  Recommendation  Roof is poorly insulated. Install or improve insulation of roof.	Medium  Medium  Potential impact on carbon emissions  Medium
Consider installing a ground source heat pump.  Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or exterior.  Changes that may pay for themselves in over 7 years  Recommendation  Roof is poorly insulated. Install or improve insulation of roof.  Consider installing building mounted wind turbine(s).	Medium  Potential impact on carbon emissions  Medium  Low

# **Property and report details**

#### Report issued on

14 March 2025

Total useful floor area	321 square metres
Building environment	Heating and Natural Ventilation
Calculation tool	DesignBuilder Software Ltd, DesignBuilder SBEM, v7.2.0, SBEM, v6.1.e.0

### Assessor's details

Assessor's name	Laura Grundy
Telephone	01924 669941
Email	epc@compliance365.co.uk
Employer's name	Compliance365
Employer's address	3 Paragon Red Hall Cresecent
Assessor ID	EES/031774
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Elmhurst Energy Systems Ltd

## Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at <a href="mailto:mhclg.digital-services@communities.gov.uk">mhclg.digital-services@communities.gov.uk</a> or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

Report number	9147-4079-0637-0490-0575 (/energy-certificate/9147-4079-0637-0490-0575)
Valid until	10 December 2027
Report number	0310-0441-4670-7797-5002 (/energy-certificate/0310-0441-4670-7797-5002)
Expired on	18 March 2019



Help (/help) Accessibility (/accessibility-statement) Cookies (/cookies)

Give feedback (https://forms.office.com/e/KX25htGMX5)

Service performance (/service-performance)

#### **OGL**

All content is available under the <u>Open Government</u> <u>Licence v3.0 (https://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/)</u>, except where otherwise stated



© Crown copyright (https://www.nationalarchives.gov.uk/information-management/re-using-public-sector-information/uk-government-licensing-framework/crown-copyright/)