Find an energy certificate (/)

English | Cymraeg

Energy performance certificate (EPC) recommendation report

The Welbeck Inn 18-20 Soresby Street **CHESTERFIELD** S40 1JN

Report number 0050-4991-0413-4730-5080

> Valid until 18 May 2027

Energy rating and EPC

This property's energy rating is E.

For more information on the property's energy performance, see the EPC for this property (/energy-certificate/0740-0533-4919-8305-1006).

Recommendations

Changes that may pay for themselves within 3 years

| Recommendation | Potential impact on carbon emissions |
|--|--------------------------------------|
| Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use. | Low |
| Improve insulation on HWS storage. | Low |
| Consider replacing T8 lamps with retrofit T5 conversion kit. | Medium |
| Add time control to heating system. | Medium |
| Add optimum start/stop to the heating system. | Medium |
| Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required. | Low |

| Recommendation | Potential impact on carbon emissions |
|---|--------------------------------------|
| The default heat generator efficiency is chosen. It is recommended that the heat generator system be investigated to gain an understanding of its efficiency and possible improvements. | Low |
| Changes that may pay for themselves within 3 to 7 years | |
| Recommendation | Potential impact on carbon emissions |
| Some walls have uninsulated cavities - introduce cavity wall insulation. | Medium |
| Some windows have high U-values - consider installing secondary glazing. | Medium |
| Add local temperature control to the heating system. | Medium |
| Add weather compensation controls to heating system. | Medium |
| Add local time control to heating system. | Medium |
| Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. | Medium |
| Changes that may pay for themselves in over 7 years | |
| Recommendation | Potential impact on carbon emissions |
| Some glazing is poorly insulated. Replace/improve glazing and/or frames. | Medium |
| Consider installing an air source heat pump. | High |
| Consider installing a ground source heat pump. | High |
| Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or exterior. | Medium |
| Consider installing building mounted wind turbine(s). | Low |

Property and report details

| Report issued on | 19 May 2017 |
|-------------------------|--|
| Total useful floor area | 537 square metres |
| Building environment | Heating and Natural Ventilation |
| Calculation tool | DesignBuilder Software Ltd, DesignBuilder SBEM, v5.0.3, SBEM, v5.3.a.0 |

Assessor's details

| MATTHEW BURGESS |
|---|
| 08443 270365 |
| epc@compliance365.co.uk |
| Compliance365 |
| 6 Mariner Court Calder Park |
| QUID300243 |
| The assessor is not related to the owner of the property. |
| Quidos Limited |
| |

Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at mhclg.digital-services@communities.gov.uk or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related reports for this property.



Help (/help) Accessibility (/accessibility-statement) Cookies (/cookies)

Give feedback (https://forms.office.com/e/KX25htGMX5)

Service performance (/service-performance)

OGL

All content is available under the <u>Open Government</u> <u>Licence v3.0 (https://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/)</u>, except where otherwise stated



© Crown copyright (https://www.nationalarchives.gov.uk/information-management/reusing-public-sector-information/uk-government-licensing-framework/crown-copyright/)