YOUR ONESURVEY HOME REPORT

ADDRESS

36 Ballumbie Rise Gardens
Dundee
DD4 0FP

PREPARED FOR

S & A Heisler

INSPECTION CARRIED OUT BY:

SELLING AGENT:





HOME REPORT GENERATED BY:



Document Index

Document	Status	Prepared By	Prepared On
Single Survey	Final	Dundee - Allied Surveyors Scotland Ltd	12/08/2025
Mortgage Certificate	Final	Dundee - Allied Surveyors Scotland Ltd	12/08/2025
Property Questionnaire	Final	Mr & Mrs. S & A Heisler	11/08/2025
EPC	FileUploaded	Dundee - Allied Surveyors Scotland Ltd	12/08/2025

Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.**

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

PART 1.

SINGLE SURVEY

A report on the condition of the property, with categories being rated from 1 to 3.



Single Survey

Survey report on:

Surveyor Reference	EA4191
Customer	Mr & Mrs. S & A Heisler
Selling address	36 Ballumbie Rise Gardens
	Dundee
	DD4 0FP
Date of Inspection	11/08/2025
Prepared by	Gary Black, MRICS
	Dundee - Allied Surveyors Scotland Ltd

SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. ¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\overline{\Omega}$

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller:
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- ➤ *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	Two storey semi-detached modern villa.
Accommodation	GROUND FLOOR
	Lounge, Dining/Kitchen, Toilet.
	FIRST FLOOR
	Bedroom with Ensuite Shower Room, 2 additional Bedrooms, Bathroom.
Gross internal floor area (m2)	89
Neighbourhood and location	Private residential development around 3 miles north-east of central Dundee. Surrounding properties are of a similar age and character and all amenities can be found close by.
Age	4 years.
Weather	Dry.
Chimney stacks	None.

Roofing including roof space The roof is of pitched type clad in concrete tiles. The photovoltaic panels to the rear. Access to the roof void is by a hatch in the upper is pitched timber truss type. Insulation is laid over the eaves. A "head and shoulders" inspection was carr Sloping roofs were visually inspected with the where required. Roof spaces were visually inspected and were was safe and reasonable access, normally defind an alder within the property. If this is not possaccess to the roof space may be taken by other Surveyor deems it safe and reasonable to do stoned and is not always possible for surveyors to identify good or dry weather. All roofs should be inspected under the property of the property of the property is of timber frame/ brick roughcast conviction of the property is of timber frame/ brick roughcast convictions and concealed parts were not expected with the aid of binoculars with the property is of timber frame/ brick roughcast convictions and concealed parts were not expected with the property is of timber frame/ brick roughcast convictions and concealed parts were not expected with the aid of binoculars with foundations and concealed parts were not expected by a upVC glazed front door while there french doors to the rear. External facing areas are clad in plastic boarding. Internal and external doors were opened and clowere available. Random windows were opened and closed when Doors and windows were not forced open. External decorations Not applicable. Conservatories / porches Not applicable. Communal areas Not applicable. Communal areas Not applicable. There are no outbuildings of significance to value. Visually inspected.	
pitched timber truss type. Insulation is laid over the eaves. A "head and shoulders" inspection was carr Sloping roofs were visually inspected with the where required. Roof spaces were visually inspected and were was safe and reasonable access, normally defi 3m ladder within the property. If this is not possaccess to the roof space may be taken by other Surveyor deems it safe and reasonable to do so Roofs are prone to water penetration during add is not always possible for surveyors to identify good or dry weather. All roofs should be inspected using a not always possible for surveyors to identify good or dry weather. All roofs should be inspected using an annual basis and estable tradesmen on an annual basis and estable tr	ne roof incorporates
Where required. Roof spaces were visually inspected and were was safe and reasonable access, normally defit 3m ladder within the property. If this is not possaccess to the roof space may be taken by other Surveyor deems it safe and reasonable to do so Roofs are prone to water penetration during addis not always possible for surveyors to identify good or dry weather. All roofs should be inspected used in a national basis and estable tradesmen on an annual basis and estable tradesmen	joists and into the
was safe and reasonable access, normally defined and ladder within the property. If this is not possible access to the roof space may be taken by other Surveyor deems it safe and reasonable to do so the source of the surveyor deems it safe and reasonable to do so the surveyor deems it safe and reasonable to do so the surveyor so identify good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs were not expectively inspected with the aid of binoculars with sundains and concealed parts were not expectively good or dry weather. All roofs were not expectively good or dry weather. All roofs were not expectively good or dry weather. All roofs were not expectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspectively good or dry weather. All roofs should be inspected with the aid of binoculars with all good or dry weather. All roofs should be inspected with the aid of binoculars with all good or dry weather. All roofs should be inspected with the aid of binoculars with all good or dry weather. All roofs should be inspected with the aid of binoculars with all good or dry weather. All roofs should be inspected with the aid of binoculars with all good or dry weather. All roofs should be inspected wi	aid of binoculars
is not always possible for surveyors to identify good or dry weather. All roofs should be inspect reputable tradesmen on an annual basis and estable tradesmen on the read of the property is of timber frame/ brick roughcast coverable and concealed with the aid of binoculars with Foundations and concealed parts were not exp. The windows are of uPVC double glazed design. The estable tradesment and concealed parts were not exp. External facing areas are clad in plastic boarding. Internal and external doors were opened and closed when the property of the	ned as being from a sible, then physical r means if the
Main walls The property is of timber frame/ brick roughcast conviction of timber frame/ brick roughcast convi	this likelihood in cted and repaired by
Main walls The property is of timber frame/ brick roughcast co Visually inspected with the aid of binoculars wif- Foundations and concealed parts were not exp Windows, external doors and joinery The windows are of uPVC double glazed design. T accessed by a uPVC glazed front door while there French doors to the rear. External facing areas are clad in plastic boarding. Internal and external doors were opened and closed where available. Random windows were opened and closed where available. External decorations Not applicable. Conservatories / porches Not applicable. Communal areas Not applicable. There are no outbuildings of significance to value.	
Windows, external doors and joinery The windows are of uPVC double glazed design. T accessed by a uPVC glazed front door while there French doors to the rear. External facing areas are clad in plastic boarding. Internal and external doors were opened and clawere available. Random windows were opened and closed when Doors and windows were not forced open. External decorations Not applicable. Conservatories / porches Not applicable. Communal areas Not applicable. There are no outbuildings of significance to value.	here required.
Windows, external doors and joinery The windows are of uPVC double glazed design. T accessed by a uPVC glazed front door while there French doors to the rear. External facing areas are clad in plastic boarding. Internal and external doors were opened and clawere available. Random windows were opened and closed when Doors and windows were not forced open. External decorations Not applicable. Conservatories / porches Not applicable. Communal areas Not applicable. There are no outbuildings of significance to value.	nstruction.
and joinery accessed by a uPVC glazed front door while there French doors to the rear. External facing areas are clad in plastic boarding. Internal and external doors were opened and clowere available. Random windows were opened and closed when Doors and windows were not forced open. External decorations Not applicable. Conservatories / porches Not applicable. Communal areas Not applicable. There are no outbuildings of significance to value.	_
Internal and external doors were opened and closed when were available. Random windows were opened and closed when Doors and windows were not forced open. External decorations Not applicable. Conservatories / porches Not applicable. Communal areas Not applicable. There are no outbuildings of significance to value.	
were available. Random windows were opened and closed when Doors and windows were not forced open. External decorations Not applicable. Conservatories / porches Not applicable. Communal areas Not applicable. Garages and permanent outbuildings There are no outbuildings of significance to value.	
Doors and windows were not forced open. External decorations Not applicable. Conservatories / porches Not applicable. Communal areas Not applicable. Garages and permanent outbuildings of significance to value.	osed where keys
External decorations Not applicable. Conservatories / porches Not applicable. Communal areas Not applicable. Garages and permanent outbuildings of significance to value.	ere possible.
Conservatories / porches Not applicable. Communal areas Not applicable. Garages and permanent outbuildings There are no outbuildings of significance to value.	
Communal areas Not applicable. Garages and permanent outbuildings of significance to value.	
Garages and permanent Outbuildings There are no outbuildings of significance to value.	
outhuildings	
Outbuildings Visually inspected.	
Outside areas and boundaries There is garden ground to the front, side and rear, parking to the side. The rear garden is part sloping formed in brick and timber.	_
Visually inspected.	

Ceilings	The ceilings are plasterboard.
	Visually inspected from floor level.
Internal walls	The internal walls are plasterboard. The surfaces are decorated and partially clad.
	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
Floors including sub floors	The floors are solid concrete and suspended chipboard. Due to floor coverings and furnishings no detailed inspection was possible.
	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
Internal joinery and kitchen fittings	The internal doors are of timber design. The kitchen units are modern. The staircase is timber. The property has fitted storage space (restricted view due to stored items).
	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
Chimney breasts and fireplaces	None.
Internal decorations	Internal surfaces are decorated.
	Visually inspected.
Cellars	Not applicable.
Electricity	Mains supply.
	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.
	Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.

Gas	Mains supply. Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.
Water, plumbing and bathroom fittings	Mains supply. Where viewed the plumbing system is PVC and copper. There is a sink unit in the kitchen. Sanitary fittings in the property are modern. Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances. Concealed areas around baths and shower trays cannot be inspected however water spillage over a period of time can result in unexpected defects to hidden parts of the building fabric.
Heating and hot water	Heating is by a gas system. There is a condensing regular boiler wall mounted in the kitchen and hot water cylinder off the upper landing. Hot water is supplied by the heating system. Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.
Drainage	To a mains sewer. Drainage covers etc were not lifted. Neither drains nor drainage systems were tested.

Fire, smoke and burglar Alarms are installed. alarms Visually inspected. No test whatsoever were carried out to any systems or appliances. There is now a requirement in place for compliant interlinked fire. smoke and heat detectors in residential properties. The new fire smoke and alarm standard came into force in Scotland in February 2022, requiring a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also requires to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon fuelled appliance such as a boiler, open fire or wood burner etc. a carbon monoxide detector is also required. The surveyor will only comment on the presence of a smoke detector etc. but will not test them, ascertain if they are in working order, interlinked and / or fully compliant with the fire and smoke alarm standard that was introduced in 2022. We have for the purposes of the report, assumed the system is fully compliant, if not then the appropriate compliant system will required to be installed prior to sale. This of course should be confirmed by your legal advisor. Any additional limits to An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be inspection invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.

expensive.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the above 3 categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category:	
Notes:	There is no evidence of recent or ongoing movement.

Dampness, rot and	infestation
Repair category:	
Notes:	There is no evidence of dampness, rot or infestation affecting accessible areas.

Chimney stacks	
Repair category:	
Notes:	Not applicable.

Roofing including roof space	
Repair category:	
Notes:	No significant defects noted.
	It should be ensured that the valley gutters are kept clear of vegetation/debris.

Rainwater fittings	
Repair category:	
Notes:	No significant defects noted.

Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. Main walls Repair category: The main walls present in fair order, consistent with age. Windows, external doors and joinery Repair category: 1 Windows, external doors and joinery Repair category: 1				
Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. Main walls Repair category: Notes: The main walls present in fair order, consistent with age. Windows, external doors and joinery Repair category: Notes: Where tested, the windows were found to be in satisfactory working order than the property of the	Category 3		Category 2	Category 1
Repair category: Notes: The main walls present in fair order, consistent with age. Windows, external doors and joinery Repair category: Notes: Where tested, the windows were found to be in satisfactory working ord External doors were tested and were found to operate satisfactorily. External decorations Repair category: Notes: Not applicable. Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement		requiring future attention, but estimates are still	No immediate action or repair is needed.
Notes: The main walls present in fair order, consistent with age. Windows, external doors and joinery Repair category: Notes: Where tested, the windows were found to be in satisfactory working ord External doors were tested and were found to operate satisfactorily. External decorations Repair category: Notes: Not applicable. Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	Main walls			
Windows, external doors and joinery Repair category: Notes: Where tested, the windows were found to be in satisfactory working ord External doors were tested and were found to operate satisfactorily. External decorations Repair category: Notes: Not applicable. Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	Repair category:	1		
Repair category: Where tested, the windows were found to be in satisfactory working ord External doors were tested and were found to operate satisfactorily. External decorations	Notes:	The main walls present in	fair order, consistent with ag	e.
Repair category: Notes: Where tested, the windows were found to be in satisfactory working ord External doors were tested and were found to operate satisfactorily. External decorations Repair category: Notes: Not applicable. Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category: Repair	100° 1			
Notes: Where tested, the windows were found to be in satisfactory working ord External doors were tested and were found to operate satisfactorily. External decorations Repair category: Notes: Not applicable. Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category: Repair cat	vvindows, external	doors and joinery		
External doors were tested and were found to operate satisfactorily. External decorations Repair category: Notes: Not applicable. Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	Repair category:	1		
External decorations Repair category: Notes: Not applicable. Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	Notes:	Where tested, the windows were found to be in satisfactory working order. External doors were tested and were found to operate satisfactorily		
Repair category: Notes: Not applicable. Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category: Repair category:			<u> </u>	<u> </u>
Notes: Not applicable. Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	External decoration	IS		
Conservatories / porches Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	Repair category:			
Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	Notes:	Not applicable.		
Repair category: Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	Concernatories / no	araha a		
Notes: Not applicable. Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	-	orches		
Communal areas Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:		Not applicable		
Repair category: Notes: Not applicable. Garages and permanent outbuildings Repair category:	Notes.	посаррпсаме.		
Notes: Not applicable. Garages and permanent outbuildings Repair category:	Communal areas			
Garages and permanent outbuildings Repair category:	Repair category:			
Repair category:	Notes:	Not applicable.		
Repair category:				
	Garages and perma	anent outbuildings		
Notes: Not applicable.	Repair category:			
	Notes:	Not applicable.		

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Outside areas and boundaries	
Repair category:	1
Notes:	Boundaries appear well defined and fences/walls are in acceptable condition.

Ceilings	
Repair category:	
Notes:	No significant defects noted.

Internal walls	
Repair category:	
Notes:	No signficant defects noted.

Floors including sub-floors	
Repair category:	
Notes:	No immediate action necessary.

Internal joinery and kitchen fittings	
Repair category:	
Notes:	The internal joinery is in keeping with a property of this type and age and appears well presented.

Chimney breasts and fireplaces	
Repair category:	
Notes:	Not applicable.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Internal decorations	
Repair category:	
Notes:	To a good standard throughout.

Cellars	
Repair category:	
Notes:	Not applicable.

Electricity	
Repair category:	
Notes:	The system appears satisfactory, nonetheless current test certification should be obtained from the current Owner.
	It is generally recommended to check electrical systems every 5 years or upon taking possession of a property.

Gas	
Repair category:	
Notes:	It is appropriate to have gas fittings tested on a regular basis.

Water, plumbing and bathroom fittings	
Repair category:	
Notes:	The plumbing system appears functional, although was not tested.

Heating and hot was	ter
Repair category:	
Notes:	A gas heating system is installed. Annual servicing is recommended. Current test certification should be obtained from the current Owner.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Drainage	
Repair category:	
Notes:	There is no evidence to suggest the system is choked or leaking.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	
Conservatories / porches	
Communal areas	
Garages and permanent outbuildings	
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	
Internal decorations	1
Cellars	
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

<u>Three steps or fewer to a main entrance door of the property:</u> In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres:</u> For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Ground and First
2. Are there three steps or fewer to a main entrance door of the property?	[x]YES []NO
3. Is there a lift to the main entrance door of the property?	[]YES [x]NO
4. Are all door openings greater than 750mm?	[]YES [x]NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES []NO
6. Is there a toilet on the same level as a bedroom?	[x]YES []NO
7. Are all rooms on the same level with no internal steps or stairs?	[]YES [x]NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[x]YES []NO

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

Tenure is assumed absolute ownership.

We are unaware of any adverse proposals affecting the subjects although this can be confirmed by obtaining a Property Enquiry Certificate.

It is presumed that all consents and permissions were obtained for the construction of the property along with the relevant completion certification. The property is believed to have an NHBC guarantee.

Where items of maintenance or repair have been identified, the purchaser should satisfy themselves as to the costs and implications of these issues prior to making an offer to purchase.

Estimated re-instatement cost (£) for insurance purposes

The subjects should be insured for a sum of not less than £230,000.

Valuation (£) and market comments

Market value assuming vacant possession is £235,000.

Our valuation reflects current market conditions relating to this area. We would assume that current trends will prevail at the ultimate date of disposal with no adverse or onerous matters being introduced into the market during the intervening period which would have a detrimental effect on price.

Report author:	Gary Black, MRICS
Company name:	Dundee - Allied Surveyors Scotland Ltd
Address:	8 Whitehall Crescent Dundee DD1 4AU
Signed:	Electronically Signed: 294803-7c6569ca-554c
Date of report:	12/08/2025

MORTGAGE VALUATION **REPORT**

Includes a market valuation of the property.





	Mortgage Valuation Report				
Property:	36 Ballumbie Rise Gardens Dundee DD4 0FP		Mrs. S & A Heisler lute Ownership		
Date of Inspection:	11/08/2025	Reference:	GB/KG/EA4191		

This report has been prepared as part of the seller's instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising a potential lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.

1.0 LOCATION

Private residential development around 3 miles north-east of central Dundee. Surrounding properties are of a similar age and character and all amenities can be found close by.

2.0 DESCRIPTION 2.1 Age: 4 years.

Two storey semi-detached modern villa.

3.0 CONSTRUCTION

Timber frame/brick/tiled.

4.0 ACCOMMODATION

GROUND FLOOR

Lounge, Dining/Kitchen, Toilet.

FIRST FLOOR

Bedroom with Ensuite Shower Room, 2 additional Bedrooms, Bathroom.

5.0	SERVICES (No tests have been applied to any of the services)					
Water:	Mains	Electricity:	Electricity: Mains Gas: Mains Drainage: Mains			
Central Hea	Central Heating: Gas					
6.0	OUTBUILDIN	DINGS				
Garage:	•	Off-street parking provided.				
Others:		None of significance.				

7.0	GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.				
The property	was found to be in good over	all condition wi	th no evidence of significant	defects.	
8.0	ESSENTIAL REPAIR WORK (as a condition of any mortgage or, to preserve the condition of the property)				
None.					
	recommended:	N/A			
9.0	ROADS & FOOTPATHS				
Made up.		000 000	ODOGO EVTERNAL		0
10.0	BUILDINGS INSURANCE (£):	230,000	GROSS EXTERNAL FLOOR AREA	98	Square metres
	should be insured against to the property in its existing de No allowance has been inclu	ital destruction esign and mate uded for inflatio	sum for which the property ar on a re-instatement basis as erials. Furnishings and fittings on during the insurance period other than on professional fe	suming recons have not beer d or during re-o	truction of n included. construction
11.0	GENERAL REMARKS				
We are unawa Property Enqu It is presumed relevant comp	adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year				
42.4	2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.				
12.1	Market Value in present condition (£):	235,000	TWO HUNDRED AND THIF POUNDS STERLING	RIY-FIVE IHO	USAND
12.2	Market Value on completion of essential works (£):				
12.3	Suitable security for normal mortgage purposes?				
12.4	Date of Valuation: 11/08/2025				
Signature:	Electronically	Signed: 29480)3-7c6569ca-554c		
Surveyor:	Gary Black	MRICS		Date:	12/08/2025
Dundee - Alli	ied Surveyors Scotland Ltd				

Office: 8 Whitehall Crescent Dundee Fax: email: dundee@alliedsurveyorsscotland.com

PART 3.

ENERGY REPORT

A report on the energy efficiency of the property.



energy report

energy report on:

Property address	36 Ballumbie Rise Gardens Dundee DD4 0FP
Customer	Mr & Mrs. S & A Heisler
Customer address	36 Ballumbie Rise Gardens
	Dundee
	DD4 0FP
Prepared by	Gary Black, MRICS
	Dundee - Allied Surveyors Scotland Ltd

Energy Performance Certificate (EPC)

Dwellings

Scotland

36 BALLUMBIE RISE GARDENS, DUNDEE, DD4 0FP

Dwelling type: Semi-detached house
Date of assessment: 11 August 2025
Date of certificate: 11 August 2025

Total floor area: 89 m²

Primary Energy Indicator: 106 kWh/m²/year

Reference number: 9498-1056-0238-9105-0224
Type of assessment: RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains

gas


You can use this document to:

Compare current ratings of properties to see which are more energy efficient and environmentally friendly

Estimated energy costs for your home for 3 years*

£2,289

 st based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (83)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is band B (84)

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

There are currently no improvement measures recommended for your home.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction. See the addendum section on the last page of this report for further information relating to items in the table.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	****	****
Roof	Pitched, 300 mm loft insulation	****	****
Floor	Solid, insulated (assumed)	_	_
Windows	Fully double glazed	★★★☆☆	★★★☆☆
Main heating	Boiler and radiators, mains gas	****	★★★★ ☆
Main heating controls	Programmer, room thermostat and TRVs	****	★★★★ ☆
Secondary heating	None	_	_
Hot water	From main system	****	★★★★ ☆
Lighting	Good lighting efficiency	★★★★☆	★★★★ ☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 20 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 1.8 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings	
Heating	£1,485 over 3 years	£1,485 over 3 years		
Hot water	£618 over 3 years	£618 over 3 years		
Lighting	£186 over 3 years	£186 over 3 years	Not applicable	
Totals	£2,289	£2,289		

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

None

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present:

Solar photovoltaics

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use. which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation insulation		
Space heating (kWh per year)	4,676.26	N/A	N/A	N/A	
Water heating (kWh per year)	2,639.46				

Addendum

The assessment does not include any feed-in tariffs that may be applicable to this property.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Gary Black Assessor membership number: EES/009446

Allied Surveyors Scotland Ltd 8 Whitehall Crescent Company name/trading name:

Address:

Dundee DD1 4AU

01382 349930 Phone number:

gary.black@alliedsurveyorsscotland.com Email address:

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



Property Address	36 Ballumbie Rise Gardens
	Dundee
	DD4 0FP
Seller(s)	S & A Heisler
Completion date of property questionnaire	11/08/2025

Note for sellers

1.	Length of ownership	
	How long have you owned the property?	
	4 years	
2.	Council tax	
	Which Council Tax band is your propert	y in? (Please circle)
	[]A []B [x]C []D []E []F []G []H	
3.	Parking	
	What are the arrangements for parking a	at your property?
	(Please tick all that apply)	
	Garage	[]
	Allocated parking space	[]
	Driveway	[x]
	Shared parking	[]
	On street	[]
	Resident permit	
	Metered parking	[]
	Other (please specify):	

4.	Conservation area	
	Is your property in a designated Conservation Area (that is an area of	[]YES [x]NO
	special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	[]Don't know
5.	Listed buildings	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	[]YES [x]NO
6.	Alterations/additions/extensions	
а	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	[]YES [x]NO
	If you have answered yes, please describe below the changes which you have made:	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	[]YES[]NO
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property	[]YES [x]NO
	If you have answered yes, please answer the three questions below:	
	(i) Were the replacements the same shape and type as the ones you replaced?	[]YES[]NO
	(ii) Did this work involve any changes to the window or door openings?	[]YES[]NO
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):	
	Please give any guarantees which you received for this work to your solicitor or estate agent.	
7.	Central heating	
а	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of	[x]YES []NO
	the property - the main living room, the bedroom(s), the hall and the bathroom).	[]Partial

	If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	
	Gas fired	
	If you have answered yes, please answer the three questions below:	
	(i) When was your central heating system or partial central heating system installed?	
	2021	
	(ii) Do you have a maintenance contract for the central heating system?	[]YES [x]NO
	If you have answered yes, please give details of the company with which you have a maintenance contract	
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	[x]YES []NO
9.	Issues that may have affected your property	
а	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	[]YES [x]NO
	property write you have owned it?	., .,
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	[]YES[]NO
b	If you have answered yes, is the damage the subject of any outstanding insurance claim?	
b	If you have answered yes, is the damage the subject of any	[]YES[]NO
b	If you have answered yes, is the damage the subject of any outstanding insurance claim?	[]YES []NO []YES [x]NO
b 10.	If you have answered yes, is the damage the subject of any outstanding insurance claim? Are you aware of the existence of asbestos in your property?	[]YES []NO []YES [x]NO

	Services	Connected	Su	ıpplier
	Gas or liquid petroleum gas	Y	+	itish Gas
	Water mains or private water supply	Y	Sc	ottish Water
	Electricity	Y	Bri	itish Gas
	Mains drainage	Y	Sc	ottish water
	Telephone	N		
	Cable TV or satellite	N	+	
	Broadband	Y	ВТ	-
b	Is there a septic tank system at your property?			[]YES [x]NO
	If you have answered yes, please answer the tw	o questions below:		
	(i) Do you have appropriate consents for the disc	charge from your se	eptic	[]YES[]NO
	tank?		[]Don't know	
	(ii) Do you have a maintenance contract for your	septic tank?		[]YES[]NO
	If you have answered yes, please give details of which you have a maintenance contract:	the company with		
11.	Responsibilities for shared or common areas			
a	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? [x]YES []NO			
	If you have answered yes, please give details:			[]Don't know
	Factor fee for shared green area			
b	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?		[]YES [x]NO	
	If you have answered yes, please give details:			[]N/A
С	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?		[]YES [x]NO	
d	Do you have the right to walk over any of your no example to put out your rubbish bin or to maintain			[]YES [x]NO
	If you have answered yes, please give details:			[] = = [,]

е	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	[]YES [x]NO
	If you have answered yes, please give details:	
f	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privatelyowned.)	[]YES [x]NO
	If you have answered yes, please give details:	
12.	Charges associated with your property	
а	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	[x]YES []NO
	James Gibb, no deposit held , approx £20 pcm	
b	Is there a common buildings insurance policy?	[]YES [x]NO
	To there a commen bandings incurance pency.	[]Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factors charges?	
С	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
13.	Specialist works	
а	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	[]YES [x]NO
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
b	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	[]YES [x]NO
	If you have answered yes, please give details:	
С	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	[]YES[]NO
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:	

14.	Guarantees		
а	Are there any guarantees or warranties for any of the following:		
(i)	Electrical work []NO []YES [x]Don't know []With title deeds []Lost		
(ii)	Roofing	[]NO []YES [x]Don't know []With title deeds []Lost	
(iii)	Central heating	[]NO []YES [x]Don't know []With title deeds []Lost	
(iv)	National House Building Council(NHBC)	[]NO []YES []Don't know [x]With title deeds []Lost	
(v)	Damp course	[]NO []YES [x]Don't know []With title deeds []Lost	
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	[]NO []YES [x]Don't know []With title deeds []Lost	
b	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):		
	New build NHBCC building warranty		
С	Are there any outstanding claims under any of the guarantees listed above?		
	If you have answered yes, please give details:		

15.	Boundaries		
	So far as you are aware, has any boundary of your property been	[]YES [x]NO	
	moved in the last 10 years?	[]Don't know	
	If you have answered yes, please give details:		
16.	Notices that affect your property		
In th	In the past three years have you ever received a notice:		
а	advising that the owner of a neighbouring property has made a planning application?	[]YES [x]NO	
b	that affects your property in some other way?	[]YES [x]NO	
С	that requires you to do any maintenance, repairs or improvements to your property?	[]YES [x]NO	
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.		

Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.		
Signature(s): Aislinn Heisler		
Capacity:	[x]Owner	
Capacity.	[]Legally Appointed Agent for Owner	
Date: 11/08/2025		