Home Report

One triangle, all angles covered RESIDENTIAL / COMMERCIAL / PROPERTY & CONSTRUCTION

www.shepherd.co.uk



Contents

- 1. Single Survey
- 2. Energy Performance Certificate
- 3. Property Questionnaire



Scottish Single Survey



survey report on:

Property address	16 Cassillis Road Maybole KA19 7HF	CS Je
------------------	--	-------

Customer	Springbok Properties	20

Customer address	16 Cassillis Road Maybole KA19 7HF

Prepared by	Shepherd Chartered Surveyors

1

Date of inspection	06/02/2024	
	5	



www.shepherd.co.uk

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by marking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

Х

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report².

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;

- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments

being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 3 <u>Category 1:</u> No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

• There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use

communal grounds, parking areas, and other facilities;

- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

stsales

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a converted mid terraced house over ground, first and attic floors.
Accommodation	Ground Floor - Entrance Hall, Living Room, Kitchen, Cloakroom with WC and Utility Room, First Floor - Two Bedrooms, Shower Room with WC and Sitting Room. Attic Floor - Two Bedrooms and En-Suite.

Gross internal floor area	(m²)	171	Co	

-	Similar style residential dwellings within the village of Maybole where local amenities can be found.

Age	Pre 1900.	

Weather	Dry and fair.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.

Two chimney stacks of stone construction.

Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof is pitched and overlaid with slates. Access to a small area of apex space revealed the roof to be of timber framed construction overlaid with timber sarking. The rear projection has a flat roof overlaid with felt.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	Mixed cast iron and PVC goods.
Main walls	Visually inspected with the aid of binoculars where appropriate.
- and	Foundations and concealed parts were not exposed or inspected.
	The main walls are of solid stone construction part pointed stonework part smooth render. The rear projection is believed to be of single skin brick construction.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
- (3 ³	Windows are mixed style and comprise timber framed single glazed units some of which have secondary glazing and replacement UPVC double glazed units. Doors are timber and UPVC double glazed.
External decorations	Visually inspected.
	Painted cast iron and joinery.

Conservatories / porches	N/A
Communal areas	Circulation areas visually inspected.
	Shared entrance at front of the building.
Garages and permanent outbuildings	Visually inspected.
	Original stone built outhouse with pitched slate clad roofs. There is also a timber built summer house within the rear garden with a pitched felt clad roof.
Outside areas and boundaries	Visually inspected.
	Private gardens to the rear of the building overlaid in a mixture of lawn and paving. Boundaries are defined with masonry walls and timber fencing.
Ceilings	Visually inspected from floor level.
	Plaster lined.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Plaster lined.

Floors including sub floors	A mixture of solid flooring and suspended timber.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
F 35	Internal joinery comprises timber skirting and door surrounds, a timber tread and riser staircase and internal doors are timber. There is also a solid stone staircase leading from the ground floor to the first floor. Kitchen fittings comprise wall and floor mounted units.

Single Survey Chimney breasts and fireplaces Visually inspected. No testing of the flues or fittings was carried out. Within the living room there is a fireplace housing an electric fire. Within the sitting room there is an original fireplace housing an open fire in the grate.

Internal decorations	Visually inspected.
	Paper, paint and tile.

Cellars	N/A		

Electrici	ty	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
		Electricity is from the mains grid with the meter and fuse box located in a first floor cupboard.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Gas appears to be from the mains supply.


Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
Ço.	Cold water is from the mains supply and where seen plumber fittings are of copper and PVC pipework. The sanitary arrangements comprise at ground floor level a two piece suite within the cloakroom consisting of WC and wash hand basin. At first floor level there is a three piece suite within the shower room consisting of WC, wash hand basin and shower and at second floor level there is an en-suite bathroom.

Heating and hot water	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Gas central heating via radiators. The gas boiler also appears to provide hot water on demand.

Drainage	Drainage covers etc. were not lifted.	
	Neither drains nor drainage systems were tested.	
	All foul and surface water drainage is assumed to be to the main public sewer. The system was not tested.	

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	All Scottish homes require a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also needs to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon- fuelled appliance such as a boiler, open fire or wood burner, a carbon monoxide detector is also required. We have not assessed or tested any existing equipment and it is the purchasers responsibility to confirm that the property will comply with these standards following a change of ownership.
Fas	salespel

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.
	An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.
-37-5	The property was fully furnished and had fitted floor coverings, therefore no detailed inspection was possible of the floors and accordingly, no comment can be made on their condition. Internal cupboards were generally filled with storage items. No access was available beneath sanitary or kitchen fittings.
	Windows and external doors were not all fully opened or tested.
	No access was available to any sub-floor areas.
	Our inspection of roof coverings was from street level only. Our inspection of the roof void was limited to a small visual inspection from an apex hatch only.
	There were storage items to all rooms and cupboards.
535	



2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
3	Repairs or replacement requiring future attention, but estimates are still advised.	•

Structural movement	nt
Repair category	1
Notes	Evidence of settlement/movement has affected the building reflected by flooring and door frames being off level. On the basis of a single inspection this appears longstanding with no evidence of recent movement apparent.

Dampness, rot and	infestation
Repair category	3
Notes	High damp readings were recorded to various wall and ceiling linings throughout the property. A timber and dampness specialist should be instructed to check the entire property prior to purchase.

Chimney stacks	M . St
Repair category	2
Notes	Weathering and vegetation growth noted to chimney stacks. One of the chimney stacks appeared to be leaning.

Roofing including roof space		
Repair category	2	
Notes	Roof coverings are of an age and style where overhaul works should be anticipated.	

Rainwater fittings	
Repair category	2
Notes	Loose section of guttering. Corrosion to cast iron goods. Damaged pvc downpipe.

.

Main walls	
Repair category	2
Notes	Weathering to stonework along with cracking to smooth render.

Windows, external doors and joinery	
Repair category	2
Notes	One or two failed double glazed seals. Decay was noted to original timber framed windows. Overhaul work should be anticipated.

External decoration	s
Repair category	1
Notes	Paint finished and decorated external surfaces will require redecoration on a regular basis.

Conservatories/por	ches	0 × ×	
Repair category	N/A	632	
Notes			

Communal areas	
Repair category	1
Notes	Communal areas leading to and surrounding the subject property have been visually inspected where possible, however it should be appreciated that there may be a common repairing liability in respect of other parts of the building out with the scope of our inspection and this should be confirmed.

Garages and permanent outbuildings	
Repair category	2
Notes	Outbuildings are in a dilapidated state.

Outside areas and boundaries	
Repair category	2
Notes	Damage to timber fencing.

1

Ceilings	
Repair category	2
Notes	Cracked and damaged lath and plaster.

Internal walls	
Repair category	2
Notes	Cracked and damaged lath and plaster.

Floors including sub-floors			
Repair category	1	6	
Notes	One or two loose floorboards.		
	•		

Internal joinery and	kitchen fittings
Repair category	1
Notes	Missing door handle at utility room. Normal user wear to kitchen fittings.

Chimney breasts a	nd fireplaces
Repair category	1
Notes	All flue linings should be checked, repaired if necessary and swept prior to fires/appliances being reused.

Internal decoration	s
Repair category	2
Notes	Redecoration required in places

Cellars	
Repair category	N/A
Notes	

Repair category	2
Notes	The electrical system appears to have been upgraded at some stage however older style components still remain. The Institution of Engineering Technology recommends that inspections and testings are undertaken at least every five years and on a change of occupancy. It should be appreciated that only the most recently constructed or re-wired properties will have installations which fully comply with IET regulations.

Gas	
Repair category	1
Notes	In the interests of safety and in light of recent regulations it would be prudent to have all gas appliances checked by a Gas Safe registered contractor.

F Water, plumbing an	nd bathroom fittings		
Repair category	2		
Notes	Finishing works required to en-suite bathroom.		

Heating and hot wa	ter
Repair category	1
Notes	It is assumed that the central heating system has been properly installed, updated and maintained to meet with all current regulations and standards with particular regard to fluing and ventilation requirements. Service records should be obtained and checked. In the absence of service documentation further advice should be obtained from a qualified heating engineer to ascertain the condition, efficiency, and life expectancy of the system.

Drainage	
Repair category	1
Notes	All foul and surface water drainage is assumed to be to the main public sewer. The system was not tested.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1	Category 3
Dampness, rot and infestation	3	Urgent repairs or re
Chimney stacks	2	needed now. Failure them may cause prob parts of the property or hazard. Estimates for
Roofing including roof space	2	
Rainwater fittings	2	replacement are need
Main walls	2	Category 2
Windows, external doors and joinery	2	Repairs or replacen
External decorations	1	future attention, but still advised.
Conservatories/porches	N/A	Category 1
Communal areas	1	No immediate action
Garages and permanent outbuildings	2	needed.
Outside areas and boundaries	2	
Ceilings	2	
Internal walls	2	
Floors including sub-floors	1	
Internal joinery and kitchen fittings	1	
Chimney breasts and fireplaces	1	
Internal decorations	2	3
Cellars	N/A	. Gu
Electricity	2	
Gas	1	
Water, plumbing and bathroom fittings	2	
Heating and hot water		
Drainage	1	

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Wherea lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Grou	und, fir	st and a	attic
2. Are there three steps or fewer to a main entrance door of the property?	Yes	X	No	
3. Is there a lift to the main entrance door of the property?	Yes		No	X
4. Are all door openings greater than 750mm?	Yes		No	X
5. Is there a toilet on the same level as the living room and kitchen?	Yes	X	No	
6. Is there a toilet on the same level as a bedroom?	Yes	X	No	
7. Are all rooms on the same level with no internal steps or stairs?	Yes		No	X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes	X	No	

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The property is Cat B listed building and as such the cost of repair or reinstatement works are likely to be higher than normal. Any works considered necessary will require to be carried out in consultation with the Local Authority Planning Department and Historic Environment Scotland.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialist's or contractor's advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

Estimated reinstatement cost for insurance purposes

For Reinstatement Cost Assessment purposes, it is recommended that the subjects be insured for a sum of not less than £800000 (Eight Hundred Thousand Pounds)

This figure is the estimate of the cost of rebuilding the premises and bears no direct relationship to current market value.

Valuation and market comments

Having considered matters, taking account of our general observations on site, we are of the opinion that the Market Value of the subjects in their present condition and with the benefit of vacant possession may be fairly stated in the sum of £155,000 (ONE HUNDRED AND FIFTY FIVE THOUSAND POUNDS STERLING).

Signed	Kenneth Behan Electronically signed :- 08/02/2024 09:56
Report author	Kenneth Behan
Company name	J & E Shepherd Chartered Surveyors
Address	22 Miller Road Ayr KA7 2AY
Date of report	06/02/2024



www.shepherd.co.uk

Property Address		
Address	16 Cassillis Road, Maybole, KA19 7HF	
Seller's Name	Springbok Properties	
Date of Inspection	06/02/2024	
Property Details		
Property Type X House	Bungalow Purpose built maisonette	Converted maisonette
Purpose built flat	Converted flat Tenement flat	Flat over non-residential use
		Other (specify in General Remarks)
Property Style Detached	Semi detached X Mid terrace	Characteria Constant
Back to back		Other (specify in General Remarks)
	property was built for the public sector, e.g. l	local authority, Yes X No
military, police? Flats/Maisonettes only Floor(s) on whether the second se	nich located No. of floors in block	Lift provided? Yes No
	No. of units in block	
Approximate Year of Construction	1850	
Tenure		
X Absolute Ownership	Other	
		0
Accommodation		<u>v</u>
Number of Rooms 2 Living room	n(s) 4 Bedroom(s) 1 Kitchen(s)	
2 Bathroom(s	s) 1 WC(s) 0 Other (Specify in Gener	ral remarks)
Gross Floor Area (excluding garage	es and outbuildings) [171] m ² (Inter	rnal) m² (External)
		, , , , ,
Residential Element (greater than 4	0%) X Yes N	0
Output Derking (Output likes)		
Garage / Parking / Outbuildings		
Single garage Double gar	rage Parking space X	No garage / garage space / parking space
Available on site?	No	
Permanent outbuildings:	12	

Construction		
Walls Roof	Brick X Stone Concrete Timber frame Other (specify in General Remar Tile X Slate Asphalt Felt Other (specify in General Remar	
Special Risks		
Has the property	suffered structural movement?	
	ent or progressive?	
Is there evidence the immediate vio	, history, or reason to anticipate subsidence, heave, landslip or flood in \Box Yes X No sinity?	
If Yes to any of the	e above, provide details in General Remarks.	
Service Conne	ctions	
Based on visual i the supply in Ger	nspection only. If any services appear to be non-mains, please comment on the type and location neral Remarks	onof
Drainage Electricity	X Mains Private None Water X Mains Private Nor X Mains Private None Gas X Mains Private Nor	
Central Heating	X Yes Partial None	
Brief description	of Central Heating and any non mains services:	
	via radiators - not tested.	
Site		
	sues to be verified by the conveyancer. Please provide a brief description in General Remarks.	
Rights of way	Shared drives / access Garage or other amenities on separate site Shared service connections	
III-defined bounda	ries Agricultural land included with property Other (specify in General Remarks)	1
1		
X Residential subur		ıarks)
Planning Issue	s	
	been extended / converted / altered?	
Roads		
Made up road	Unmade road Partly completed new road Pedestrian access only X Adopted Unadopted	;d

General Remarks

The subjects are located within an established residential area of similar style residential dwellings within the town of Maybole and convenient for local amenities.

At the time of inspection several items of repair and maintenance were noted.

High damp readings were recorded to various wall and ceiling linings throughout the property. A timber and dampness specialist should be instructed to check the entire property prior to purchase.

Essential Repairs

Timber and dampness report.	
Estimated cost of essential repairs	
Retention recommended?	Yes X No
Retention amount	

Comment on Mortgageability

The property forms suitable se	curity for mort <mark>gage</mark> purposes su	bject to the specific lending criteria of any mortgage provider.
Valuation		

valuation	
Market value in present condition	£ 155,000
Market value on completion of essential repairs	£
Insurance reinstatement value	£ 800,000
(to include the cost of total rebuilding, site clearance, professional	I fees, ancillary charges plus VAT)
Is a reinspection necessary?	Yes X No

Declaration

Signed

Surveyor's name Professional qualifications Company name Address Telephone Email Address Date of Inspection Kenneth Behan Electronically signed :- 08/02/2024 09:56 Kenneth Behan BSc, MRICS J & E Shepherd Chartered Surveyors 22 Miller Road, Ayr, KA7 2AY 01292 267987 ayr@shepherd.co.uk 06/02/2024

ist sale S

Energy Performance Certificate



Energy Performance Certificate (EPC)

Scotland

Dwellings

16 CASSILLIS ROAD, MAYBOLE, KA19 7HF

Dwelling type:	Mid-terrace house
Date of assessment:	06 February 2024
Date of certificate:	07 February 2024
Total floor area:	171 m ²
Primary Energy Indicator:	324 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:

9014-0622-3100-0326-0206 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains gas

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*			£11,886	See your recommendations	
Over 3 years you could save*			£3,993	report for more information	
* based upon the cost of energy for heating, hot w	ater, lightin	g and ventilat	tion, calculated	using standard assumption	ns 🕥
Very energy efficient - lower running costs	Current	Potential	Energ	y Efficiency Rat	ing
(92 plus) A (81-91) B (69-80) C (55-68) D (39-54 E (21-38) F (1-20) C	55	76	taking into costs. The are likely to Your curre for EPCs in The potent of the impl	a shows the current effi- account both energy e higher this rating, the o be. ent rating is band D (55 n Scotland is band D (tial rating shows the eff rovement measures list adations report.	fficiency and fuel lower your fuel bills). The average rating 61). fect of undertaking all
Very environmentally friendly - lower CO ₂ emissions (92 plus) A (81-91) B (69-80) C (55-68) D (39-54 E (21-38) F (1-20) C	Current 39	Potential 64	This graph environme emissions on the env Your curre for EPCs in The potent of the impt	onmental Impact of shows the effect of you ent in terms of carbon d . The higher the rating, rironment. ent rating is band E (39 in Scotland is band D (tial rating shows the eff rovement measures list indations report.	ur home on the ioxide (CO ₂) the less impact it has). The average rating 59). fect of undertaking all

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Room-in-roof insulation	£1,500 - £2,700	£1785.00
2 Internal or external wall insulation	£4,000 - £14,000	£1923.00
3 Floor insulation (solid floor)	£4,000 - £6,000	£285.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282. THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

16 CASSILLIS ROAD, MAYBOLE, KA19 7HF

07 February 2024 RRN: 9014-0622-3100-0326-0206

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone or limestone, as built, no insulation (assumed)	**☆☆☆	★★ ☆☆☆
Roof	Pitched, no insulation (assumed) Roof room(s), ceiling insulated	★☆☆☆☆ ★★☆☆☆	★☆☆☆☆ ★★☆☆☆
Floor	Solid, no insulation (assumed)	-	
Windows	Mostly double glazing	★★☆☆☆	*****
Main heating	Boiler and radiators, mains gas	★★★☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★☆
Secondary heating	Room heaters, coal		
Hot water	From main system	★★★ ☆	★★★★ ☆
Lighting	Low energy lighting in all fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 70 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 12 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 5.2 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

16 CASSILLIS ROAD, MAYBOLE, KA19 7HF 07 February 2024 RRN: 9014-0622-3100-0326-0206

Estimated energy costs for this home				
	Current energy costs	Potential energy costs	Potential future savings	
Heating	£10,752 over 3 years	£6,756 over 3 years		
Hot water	£612 over 3 years	£615 over 3 years	You could	
Lighting	£522 over 3 years	£522 over 3 years	save £3,993	
Tota	s £11,886	£7,893	over 3 years	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Po	commended measures	Indicative cost	Typical saving	Rating after i	mprovement
Recommended measures		Indicative cost	per year	Environment	
1	Room-in-roof insulation	£1,500 - £2,700	£595	D 62	E 46
2	Internal or external wall insulation	£4,000 - £14,000	£641	C 69	D 56
3	Floor insulation (solid floor)	£4,000 - £6,000	£95	C 70	D 58
4	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£544	C 76	D 64

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

iast sale



saving

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Room-in-roof insulation

Insulating roof rooms will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. If it has a flat ceiling insulation can usually be added above the ceiling, and sloping ceilings and walls of roof rooms can be insulated using an internal lining board. Roof voids must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about roof room insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). Building regulations generally apply to this work so it is best to check this with your local authority building standards department.

2 Internal or external wall insulation

Internal or external wall insulation involves adding a layer of insulation to either the inside or the outside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. External solid wall insulation is the application of an insulant and a weather-protective finish to the outside of the wall. This may improve the look of the home, particularly where existing brickwork or rendering is poor, and will provide longlasting weather protection. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). It should be noted that a building warrant is required for the installation of external wall insulation. Planning permission may also be required and that building regulations apply to external insulation so it is best to check with your local authority on both issues.

3 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

4 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

16 CASSILLIS ROAD, MAYBOLE, KA19 7HF 07 February 2024 RRN: 9014-0622-3100-0326-0206

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	32,690	(1,149)	N/A	(5,742)
Water heating (kWh per year)	2,331			

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Assessor membership number: Company name/trading name: Address:	Mr. Kenneth Behan EES/016119 J & E Shepherd 22 Miller Road Ayrshire Ayr KA7 2AY
Phone number:	01292 267 987
Email address:	ayr@shepherd.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

16 CASSILLIS ROAD, MAYBOLE, KA19 7HF 07 February 2024 RRN: 9014-0622-3100-0326-0206

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

ast sales







Property address	16 Cassillis Road Maybole KA19 7HF
Seller(s)	Springbok Properties
Completion date of property questionnaire	07/02/2024



Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership	
	How long have you owned the proper	y? 18
2.	Council tax	
	Which Council Tax band is your prope	rty in? D
3.	Parking	
	 What are the arrangements for parking (Please tick all that apply) Garage Allocated parking space Driveway Shared parking On street Resident permit Metered Parking Other (please specify): 	g at your property? Yes No No No No
4.	Conservation area	
	Is your property in a designated Cons special architectural or historical inte which it is desirable to preserve or en	est, the character or appearance of

5.	Listed buildings				
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes			
6.	Alterations/additions/extensions	1			
а.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes			
	If you have answered yes, please describe below the changes which you have made:				
	put in one window in place of 2 separate ones and added one to the roof the rear attic bedroom, New partial DG throughout	Ŝ			
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes			
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	80			
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:				
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	Yes			
	If you have answered yes, please answer the three questions below:				
	(i) Were the replacements the same shape and type as the ones you replaced?	No			
	(ii) Did this work involve any changes to the window or door openings?	Yes			
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):				
	Please give any guarantees which you received for this work to your solicitor or estate agent.				
	as above				
7.	Central heating				
а.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the	Yes			

		partial – what kind of central h iel, electric storage heating, ga		
	Gas			
	If you have answered yes, ple	ease answer the three questio	ns below:	
	i) When was your central hea installed?	ting system or partial central I	neating system	
	2 years			
	(ii) Do you have a maintenand	ce contract for the central hea	ting system?	Yes
	If you have answered yes, ple you have a maintenance cont	ease give details of the compa tract:	ny with which	۲
	TBD			
	(iii) When was your maintena (Please provide the month an	nce agreement last renewed? Id year).	0.0	
	last year			
8.	Energy Performance Certifica	ate		0
	Does your property have an E than 10 years old?	Energy Performance Certificat	e which is less	Yes
9.	Issues that may have affected	d your property		
а.	Has there been any storm, flo property while you have own	ood, fire or other structural dated it?	mage to the	No
	If you have answered yes, is insurance claim?	the damage the subject of any	outstanding	
b.	Are you aware of the existence	ce of asbestos in your propert	y?	No
	<u>If you have answered yes</u> , ple	ease give details:		
10.	Services	5		
a.	Please tick which services ar supplier:	e connected to your property	and give details of	the
	Services	Connected	Supplier	
	Gas or liquid petroleum gas	Yes	EDF	
	Water mains or private water supply	Yes	Scottish Water	
	Electricity	Yes	edf	

	Mains drainage	Yes	Local Authority		
	Telephone	Yes	ee		
	Cable TV or satellite	No			
	Broadband	Yes	ee		
b.	Is there a septic tank syste	m at your property?		No	
	If you have answered yes,	please answer the two	questions below:		
	(i) Do you have appropriate consents for the discharge from your septic tank?				
	(ii) Do you have a maintena	ance contract for your	septic tank?		
	If have answered yes, details of the company with which you have a maintenance contract:				
11.	Responsibilities for shared	l or common areas		Ø	
a.	Are you aware of any resp used jointly, such as the boundary, or garden area If you have answered yes	repair of a shared driv ?		Yes	
	access to rear for the bins from Neighbour at 16a through archway.				
b.	Is there a responsibility to roof, common stairwell or	o contribute to repair	and maintenance of the	No	
	<u>If you have answered yes</u>	, please give details:	Sec		
с.	Has there been any major in during the time you have o		of any part of the roof	Yes	
d.	Do you have the right to w for example to put out you boundaries?			Νο	
	<u>If you have answered yes</u>	, please give details:			
e.	As far as you are aware, d walk over your property, f maintain their boundaries	for example to put out		Yes	
	If you have answered yes, please give details:				
	If you have answered yes	, please give details:			

f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	Νο		
	If you have answered yes, please give details:			
12.	Charges associated with the property			
a.	Is there a factor or property manager for your property?	No		
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:			
b.	Is there a common buildings insurance policy?	No		
	If you have answered yes, is the cost of the insurance included in monthly/annual factor's charges?	6		
с.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.			
13.	Specialist work	0		
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property. dry rot treated when they moved in 18 years ago, was certified	Yes		
a. b.	other specialist work ever been carried out to your property? <u>If you have answered yes</u> , please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	Yes		
	other specialist work ever been carried out to your property?If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.dry rot treated when they moved in 18 years ago, was certifiedAs far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?			

	(i) Electrical work	No			
	(ii) Roofing	No			
	(iii) Central heating	Yes			
	(iv) National House Building Council (NHBC)	No			
	(v) Damp course				
	(vi) Any other work installations? (for example, cavity wall installation, underpinning, indemnity policy)	No			
b.	If you have answered 'yes' or 'with title deeds', please give details of the installations to which the guarantee(s) relate(s):	e work or			
с.	Are there any outstanding claims under any of the guarantees listed above? <u>If you have answered yes,</u> please give details:	No			
15.	Boundaries				
	So far as you are aware, has any boundary of your property been moved in thelast 10 years?	No			
	If you have answered yes, please give details:				
16.	Notices that affect your property				
10.					
10.	In the past three years have you ever received a notice:				
a.	In the past three years have you ever received a notice: advising that the owner of a neighbouring property has made a planning application?	No			
	advising that the owner of a neighbouring property has made a planning	No No			
а.	advising that the owner of a neighbouring property has made a planning application?				

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief

Name(s): Alasdair MacLeod

Date: 07/02/2024



Residential

Home Report

Mortgage & Re-Mortgage Valuation Home & Flat Buyer Report Energy Performance Certificate (EPC) Private Sale Valuation Inheritance Tax Valuation Capital Gains Tax Valuation Separation Valuation **Driveby** Valuation Desktop Valuation New Build, Development & Plot Valuation Extension & Alteration Valuation Portfolio Valuation **Rental Valuation Expert Witness Report** Council Tax Appeal **Bespoke Condition Report**

Aberdeen ▲ △ 01224 202800 Ayr △ 01292 267987 Coatbridge △ 01236 436561 Cumbernauld △ 01236 780000 Dalkeith △ 0138 6153 2780 Cumbarton △ 01389 731682



 Dumfries

 ▲ 01387 264333

 Dundee

 ▲ 01382 200454

 ▲ 01382 220699

 Dunfermline

 ▲ 01383 722337

 ▲ 01383 731841

East Kilbride 01355 248535 Edinburgh

▲ 0131 2251234 ▲ 0131 557 9300





Commercial

Commercial Valuation

Acquisitions & Disposals

Commercial Lease Advisory

Commercial Agency

Asset Management

Project Consultancy

Rating

Falkirk

▲ 01324 635 999

Fraserburgh ▲ 01346 517456

A 01896 750150

▲ ▲ 0141 331 2807

Glasgow South ▲ 0141 649 8020

Galashiels

Glasgow

Development Appraisals

Property Management

Licensed Trade / Leisure

Professional Services

Commercial Property Auctions

Glasgow West End

A 0141 353 2080

A 01475 730717

▲ 01698 897548

Inverness ▲ ▲ 01463 712239

A 01563 520318

Kirkcaldy ▲ 01592 205442

Greenock

Hamilton

Kilmarnock

Property & Construction

Quantity Surveying Building Surveying Project Management Dispute Resolution Support Services Principal Designer Clerk of Works Commercial EPC Fire Engineering Health & Safety Management Employer's Agent Energy Department Housing Services Development Monitoring Mediation Services

Livingston ▲ 01506 416777 Montrose ▲ 01674 676788 Motherwell ▲ 01638 252229 Musselburgh ▲ 0131 653 3456 Oban ▲ 01631 707 800 Paisley ▲ 0141 889 8334 Perth ▲ 01738 638188 ▲ 01738 631631 Peterhead ▲ 01779 470766 St Andrews ▲ 01334 477773 ▲ 01334 476469 Saltcoats ▲ 01294 464228 Stirling ▲ 01786 476438 ▲ 01786 474476

www.shepherd.co.uk
 www.hardies.co.uk