

shepherd.co.uk



CHARTERED SURVEYORS

All Angles Covered

Residential | Commercial | Property & Construction





Contents

- 1. Scottish Single Survey
- 2. Energy Performance Certificate
- 3. Property Questionnaire



Scottish Single Survey



survey report on:

Property address	6 Thurston Place Livingston EH54 6RU
------------------	--

Customer	Craig Stirling

Customer address	43 Ravenswood Rise Livingston EH54 6PF
------------------	--

Prepared by	Shepherd Chartered Surveyors
-------------	------------------------------

Date of inspection	16/05/2025



6 Thurston Place, Livingston, EH54 6RU 16/05/2025

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by marking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

Х

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report².

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct.

they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;

- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments

being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 <u>Category 2:</u> Repairs or replacement requiring future attention, but estimates are still advised.
- 3 <u>Category 1:</u> No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

• There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use

communal grounds, parking areas, and other facilities;

- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	First floor studio flat in two storey block of six units.	
Accommodation	FIRST FLOOR - Entrance Vestibule, Living Room/Kitchen/Bedroom and Bathroom with WC.	
Gross internal floor area (m²)	31m ² or thereby.	
Neighbourhood and location	The subjects are situated in an established area of similar style properties in the Eliburn suburb of Livingston, convenient for good shopping, educational and social amenities.	
Age	Built around 1980.	
Weather	Dry and sunny.	
Chimney stacks	N/A	

Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof has a pitched profile overlaid in tiles with a tiled ridge section.
	Access is gained to the roof void area via a hatch formed in the hallway cupboard ceiling. The roof is of preformed timber trusses overlaid in felt and fibreboard panelling.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	PVC gutters and downpipes.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are constructed of timber framework enclosed in brick/block work, pointed and roughcast externally.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows are of uPVC tilt and turn design fitted with sealed unit double glazing. A timber door is formed between

sealed unit double glazing. A timber door is formed between the flat and stairwell. The fascia and soffits are finished in PVC.

External decorations	Visually inspected.
	Generally PVC.
Conservatories / porches	N/A

Garages and permanent outbuildings

Communal areas	Circulation areas visually inspected.
	Access to the block is via an entrance doorway which leads to a concrete staircase.

Outside areas and boundaries	Visually inspected.
	Communal grounds and parking surround the block.

There is no garage.

Ceilings	Visually inspected from floor level.
	The ceiling areas are lined in plasterboard sheeting.

Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The walls are lined in plasterboard sheeting. The kitchen is partly tiled with the bathroom partly wet walled.

Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Flooring throughout is of suspended timber construction.

Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	Skirtings and facings are of softwood. The doors are of timber panel and timber/glazed design.
	Kitchen units are provided at wall and base level.
Chimney breasts and fireplaces	N/A

	N/A
Internal decorations Visually inspected.	
	The walls and ceiling areas are papered and painted.
Cellars	N/A

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Electricity is from the mains grid with the meter being located in the vestibule cupboard.

Gas	No supply.	
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.	
	No tests whatsoever were carried out to the system or appliances.	
	Water is from the mains supply and where seen, the installation is of copper supply pipes and PVC waste pipes. The kitchen is fitted with a stainless steel sink unit. Sanitary arrangements comprise a two piece white suite with WC and bath/shower and a separate wash hand basin.	
Heating and hot water	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.	
	No tests whatsoever were carried out to the system or appliances.	
	Plug-in electric heaters are fitted. Hot water is provided by an immersion heater with the insulated tank being located in the bathroom cupboard.	
Drainage	Drainage covers etc. were not lifted.	
	Neither drains nor drainage systems were tested.	
	All foul and surface water drainage is assumed to be to the main public sewer. The system was not tested.	

Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	Smoke detectors are fitted at various points.
	All Scottish homes require a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also needs to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon- fuelled appliance such as a boiler, open fire or wood burner, a carbon monoxide detector is also required. We have not assessed or tested any existing equipment and it is the purchasers responsibility to confirm that the property will comply with these standards following a change of ownership.

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.
	Inspection of the flooring was restricted due to the nature of fitted floor coverings.
	Not all windows were tested.
	Inspection of the roof void was carried out from the hatch area only.
	An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor.



2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
e .		

Structural movement	nt
Repair category	1
Notes	There was no evidence of significant structural movement within the limitations of our inspection.

Dampness, rot and infestation	
Repair category	1
Notes	Damp meter readings were taken where considered appropriate within the property and moisture levels were found to be within an acceptable range. We have presumed that those areas not inspected are free of defects.

Chimney stacks	
Repair category	N/A
Notes	N/A

Roofing including roof space	
Repair category	2
Notes	Original roof tiles.
	Loose sections of fibreboard panelling.
	Loose mortar to ridge tiles.
	Moss to the roof covering.

Rainwater fittings	
Repair category	1
Notes	Within the limitations of our inspection rainwater goods were seen to be free from significant defect.

Main walls	
Repair category	2
Notes	Cracked roughcast.
	Conifers close to rear elevation.

Windows, external doors and joinery	
Repair category	2
Notes	Failed sealed unit to living room window.

External decorations	
Repair category	1
Notes	

Conservatories/porches	
Repair category	N/A
Notes	N/A

Communal areas	
Repair category	2
Notes	Windows in the stairwell are showing signs of deterioration.

Garages and permanent outbuildings	
Repair category	N/A
Notes	N/A

Outside areas and boundaries	
Repair category	1
Notes	Boundary walls and fences should be regularly checked and maintained as necessary.

Ceilings	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.
	Textured ceilings.

Internal walls	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.

Floors including sub-floors	
Repair category	1
	Due to fitted carpets and floor coverings no detailed inspection of floors was possible and accordingly no comment can be made on their condition. Off level sections of flooring.

Internal joinery and kitchen fittings	
Repair category	1
Notes	Within the limitations of our inspection no significant defects were noted.

Chimney breasts and fireplaces	
Repair category	N/A
Notes	N/A

Internal decorations	
Repair category	1
Notes	

Cellars	
Repair category	N/A
Notes	N/A

Electricity	
Repair category	1
Notes	The Institution of Engineering Technology recommends that inspections and testings are undertaken at least every five years and on a change of occupancy. It should be appreciated that only the most recently constructed or re-wired properties will have installations which fully comply with IET regulations.

Gas	
Repair category	N/A
Notes	N/A

Water, plumbing and bathroom fittings		
Repair category	1	
Notes	No tests have been undertaken of the system, however within the limitations of our inspection, no significant defects were noted. No inspection has been possible to enclosed timbers beneath wet appliances and no comment has been made on the condition of unseen areas. Watertight seals will require to be regularly checked and replaced, to prevent water damage to adjoining areas.	

Heating and hot water	
Repair category	1
Notes	Heating is provided by electric panel/storage radiators with an immersion heater for hot water. The system was not tested. It is assumed the system has been installed, serviced and maintained to comply with all regulations. Any service/maintenance records should be sought prior to purchase.

Drainage	
Repair category	1
Notes	All foul and surface water drainage is assumed to be to the main public sewer. The system was not tested.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	N/A
Roofing including roof space	2
Rainwater fittings	1
Main walls	2
Windows, external doors and joinery	2
External decorations	1
Conservatories/porches	N/A
Communal areas	2
Garages and permanent outbuildings	N/A
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	N/A
Internal decorations	1
Cellars	N/A
Electricity	1
Gas	N/A
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Wherea lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?		First.		
2. Are there three steps or fewer to a main entrance door of the property?	Yes		No	X
3. Is there a lift to the main entrance door of the property?	Yes		No	X
4. Are all door openings greater than 750mm?	Yes		No	X
5. Is there a toilet on the same level as the living room and kitchen?	Yes	X	No	
6. Is there a toilet on the same level as a bedroom?	Yes	X	No	
7. Are all rooms on the same level with no internal steps or stairs?	Yes	X	No	
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes	X	No	

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

It is presumed there is a mutual repairing liability in respect of roof and structural repairs.

Where defects or repairs have been identified within this report it is recommended that, prior to entering into any legally binding sale or purchase contract, further specialist's or contractor's advice and estimates should be obtained, to establish the implications, if any, on a potential offer to purchase or the sale price likely to be achieved for the property.

Estimated reinstatement cost for insurance purposes

For Reinstatement Cost Assessment purposes, it is recommended that the subjects be insured for a sum of not less than £80,000 (EIGHTY THOUSAND POUNDS STERLING).

This figure is the estimate of the cost of rebuilding the premises and bears no direct relationship to current market value.

Valuation and market comments

Having considered matters, taking account of our general observations on site, we are of the opinion that the Market Value of the subjects in their present condition and with the benefit of vacant possession may be fairly stated in the sum of £75,000 (SEVENTY FIVE THOUSAND POUNDS STERLING).

Signed	Craig Brown Electronically signed :- 20/05/2025 11:02
Report author	Craig Brown
Company name	J & E Shepherd Chartered Surveyors
Address	4 Grampian Court Beveridge Square Livingston EH54 6QF
Date of report	16/05/2025



www.shepherd.co.uk

Property Address			
Address	6 Thurston Place, Livingston, EH54 6RU		
Seller's Name Date of Inspection	Craig Stirling 16/05/2025		
Date of inspection	10/03/2025		
Property Details			
Property Type House	Bungalow Purpose built maisonette Converted maisonette		
X Purpose built flat	Converted flat Tenement flat		
	Other (specify in General Remarks)		
Property Style Detached	Semi detached Mid terrace End terrace		
Back to back	High rise block X Low rise block Other (specify in General Remarks)		
Does the surveyor believe that the pilitary, police?	property was built for the public sector, e.g. local authority,		
Flats/Maisonettes only Floor(s) on wh	nich located 1 No. of floors in block 2 Lift provided? Yes X No		
	No. of units in block 6		
Approximate Year of Construction	1980		
Tenure			
X Absolute Ownership	Dther		
Accommodation			
Number of Rooms 1 Living room	n(s) 0 Bedroom(s) 1 Kitchen(s)		
1 Bathroom(s	s) 0 WC(s) 0 Other (Specify in General remarks)		
Gross Floor Area (excluding garage	es and outbuildings) <u>31</u> m² (Internal) m² (External)		
Residential Element (greater than 4			
Garage / Parking / Outbuildings			
Single garage Double gar	rage X Parking space No garage / garage space / parking space		
Available on site?	No		
Permanent outbuildings:			
None.			

Construction								
Walls	Brick	Stone		X Timber	frame		(specify in Gener	
Roof	X Tile	Slate	Asphalt	Felt		Other	(specify in Gener	ral Remarks)
Special Risks								
Has the property suf	fered struct	ural movem	ent?] Yes 🛛 No)
If Yes, is this recent	or progress	ive?					Yes 🗌 No	C
Is there evidence, hi			ipate subside	nce, heave,	landslip or	flood in] Yes 🛛 No	D
the immediate vicinit	•							
If Yes to any of the a	ibove, provi	de details in	General Rem	narks.				
Service Connection	ons							
Based on visual insp		. If any servi	ces appear to	be non-mai	ins, please	comment o	n the type an	d locationof
the supply in Genera	al Remarks							
	X Mains	Priva		one		X Mains	Private	None
	X Mains Yes	Priva		one one	Gas	Mains	Private	X None
Central Heating								
Brief description of C		ung and any	non mains se	ervices.				
Plug-in electric heaters.								
Site								
Apparent legal issue	s to be veri	fied by the c	onveyancer.	Please prov	ide a brief	description	in General Re	emarks.
Rights of way	Shared dr	ives / access	Garage or othe	r amenities on	separate site	Shared se	ervice connection	S
Ill-defined boundaries	Agricultura	al land included	with property			Other (spe	ecify in General F	Remarks)
Location								
Residential suburb	XRe	sidential within	town / city	Mixed reside	ential / comme	ercial Shar	ed service conne	ections
Commuter village	Re	mote village		Isolated rura	l property	Othe	er (specify in Gen	eral Remarks)
					-			
Planning Issues								
Has the property bee	en extended	d / converted	I / altered?	Yes X] No			
If Yes provide details	s in Genera	l Remarks.						
Roads								
X Made up road	Unmade roa	ad Parti	y completed new	road Ped	estrian acces	s only A	dopted 🗌 l	Jnadopted

General Remarks

The property was found to be in a condition commensurate with its age. General routine maintenance works are however required.

It is presumed there is a mutual repairing liability in respect of roof and structural repairs.

Essential Repairs

None evident.		
Estimated cost of essential repairs	-	
Retention recommended?	Yes X No	
Retention amount	-]

Comment on Mortgageability

The property forms suitable security for mortgage purposes subject to the specific lending criteria of any mortgage provider.

Valuation		
Market value in present condition	£	75,000
Market value on completion of essential repairs	£	
Insurance reinstatement value	£	80,000
(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)		
Is a reinspection necessary?		Yes X No

Declaration	
Signed	<i>Craig Brown</i> Electronically signed :- 20/05/2025 11:02
Surveyor's name	Craig Brown
Professional qualifications	BSc, MRICS
Company name	J & E Shepherd Chartered Surveyors
Address	4 Grampian Court, Beveridge Square, Livingston, EH54 6QF
Telephone	01506 416777
Email Address	livingston@shepherd.co.uk
Date of Inspection	16/05/2025



Energy Performance Certificate



Energy Performance Certificate (EPC)

Scotland

Dwellings

6 THURSTON PLACE, ELIBURN, LIVINGSTON, EH54 6RU

Dwelling type:	Top-floor flat
Date of assessment:	16 May 2025
Date of certificate:	16 May 2025
Total floor area:	31 m ²
Primary Energy Indicator:	458 kWh/m ² /year

Reference number: Type of assessment: Approved Organisation: Main heating and fuel:


9163-1000-1205-4855-1204 RdSAP, existing dwelling Elmhurst Room heaters, electric

You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£3,360	See your recommendations	
Over 3 years you could save*	£1,506	report for more information	

 * based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Very environmentally friendly - lower CO₂ emissions



Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is band D (57). The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is band D (61). The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 High heat retention storage heaters	£400 - £600	£1344.00
2 Replacement glazing units	£1,000 - £1,400	£162.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE **DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

6 THURSTON PLACE, ELIBURN, LIVINGSTON, EH54 6RU 16 May 2025 RRN: 9163-1000-1205-4855-1204

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed) Cavity wall, as built, insulated (assumed)	★★★★☆ ★★★★☆	★★★★☆ ★★★★☆
Roof	Pitched, 200 mm loft insulation	★★★★☆	★★★★☆
Floor	(another dwelling below)	—	
Windows	Fully double glazed	★★★☆☆	★★★☆☆
Main heating	Room heaters, electric	****	★★☆☆☆
Main heating controls	Appliance thermostats	★★★★☆	★★★★☆
Secondary heating	None	—	
Hot water	Electric immersion, standard tariff	****	★★☆☆☆
Lighting	Low energy lighting in all fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 77 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.4 tonnes of carbon dioxide every year. You could reduce emissions by switching to renewable energy sources.

6 THURSTON PLACE, ELIBURN, LIVINGSTON, EH54 6RU 16 May 2025 RRN: 9163-1000-1205-4855-1204

Estimated energy costs for this home			
	Current energy costs	Potential energy costs	Potential future savings
Heating	£2,169 over 3 years	£1,116 over 3 years	
Hot water	£1,077 over 3 years	£609 over 3 years	You could
Lighting	£114 over 3 years	£129 over 3 years	save £1,506
Total	s £3,360	£1,854	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures		Indiantive anot	Typical saving	Rating after improvement		
		Indicative cost	per year	Energy	Environment	
1	High heat retention storage heaters and dual immersion cylinder	£400 - £600	£448	C 76	D 60	
2	Replacement glazing units	£1,000 - £1,400	£54	C 78	D 63	

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Biomass boiler (Exempted Appliance if in Smoke Control Area)
- Air or ground source heat pump

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 High heat retention storage heaters

Modern storage heaters are less expensive to run than the direct acting, on-peak heating system in the property. A dual-rate electricity supply is required to provide the off-peak electricity that these heaters use; this is easily obtained by contacting the energy supplier. Ask for a quotation for high heat retention heaters with automatic charge and output controls. A dual-immersion cylinder, which can be installed at the same time, will provide cheaper hot water than the system currently installed. Installations should be in accordance with the national wiring standards. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified electrical heating engineer. Ask the engineer to explain the options, which might also include switching to other forms of electric heating.

2 Replacement glazing units

Replacing existing double-glazed units with new high-performance units. Building regulations require that replacement glazing is to a standard no worse than previous; a building warrant is not required. Planning permission might be required for such work if a building is listed or within a conservation area so it is best to check with your local authority.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	2,991	N/A	N/A	N/A
Water heating (kWh per year) 1,485				

6 THURSTON PLACE, ELIBURN, LIVINGSTON, EH54 6RU 16 May 2025 RRN: 9163-1000-1205-4855-1204

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. Craig Brown
Assessor membership number: Company name/trading name:	EES/015082 J & E Shepherd
Address:	13 Albert Square
	Dundee
	DD1 1XA
Phone number:	01382 200454
Email address:	dundee@shepherd.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

6 THURSTON PLACE, ELIBURN, LIVINGSTON, EH54 6RU 16 May 2025 RRN: 9163-1000-1205-4855-1204

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.







Property Questionnaire



Property address	6 Thurston Place Livingston EH54 6RU
Seller(s)	Craig Stirling
Completion date of property questionnaire	13/05/2025

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership				
	How long have you owned the prop	erty? 17 years			
2.	Council tax				
	Which Council Tax band is your pro	perty in? A			
3.	Parking				
	What are the arrangements for parking at your property?				
	(Please tick all that apply)				
	Garage	No			
	Allocated parking space	Yes			
	• Driveway	Νο			
	Shared parking	Yes			
	On street	Yes			
	Resident permit	Νο			
	Metered Parking	Νο			
	Other (please specify):				
	Large car park to the re- much larger than neede	ar . We have an allocated section but the area is ed so it's not strict			
4.	Conservation area				

	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	No	
5.	Listed buildings	1	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	No	
6.	Alterations/additions/extensions	1	
а.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	No	
	If you have answered yes, please describe below the changes which you have made:		
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?		
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.		
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:		
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?	No	
	If you have answered yes, please answer the three questions below:		
	(i) Were the replacements the same shape and type as the ones you replaced?		
	(ii) Did this work involve any changes to the window or door openings?		
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):		
	Please give any guarantees which you received for this work to your solicito agent.	or or estate	
7.	Central heating		
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).	Yes	

	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).			
	Electric panels			
	If you have answered yes, please answer the three questions below:			
	i) When was your central hea installed?	ting system or partial	central heating system	
	2022-2025			
	(ii) Do you have a maintenance contract for the central heating system?			No
	If you have answered yes, please give details of the company with which you have a maintenance contract:			
	(iii) When was your maintena (Please provide the month ar		newed?	
8.	Energy Performance Certifica	ate		
	Does your property have an I than 10 years old?	Energy Performance C	Certificate which is less	Yes
9.	Issues that may have affected	d your property		•
a.	Has there been any storm, flood, fire or other structural damage to the property while you have owned it?			No
	If you have answered yes, is the damage the subject of any outstanding insurance claim?			
b.	Are you aware of the existence of asbestos in your property?		No	
	<u>If you have answered yes, ple</u>	ease give details:		
10.	Services			
a.	Please tick which services are connected to your property and give details of the supplier:			
	Services	Connected	Supplier	
	Gas or liquid petroleum gas	No		
	Water mains or private water supply	Yes	Scottish Water	
	Electricity	Yes	Octopus	
	Mains drainage	Yes	Local Authority	

	Telephone	No		
	Cable TV or satellite	No		
	Broadband	Yes	Virgin	
b.	Is there a septic tank system at your property?			
	If you have answered yes, please answer the two questions below:			
	(i) Do you have appropriate consents for the discharge from your septic tank?			
	(ii) Do you have a mainten	ance contract for your se	ptic tank?	
	<u>If have answered yes,</u> deta maintenance contract:	ails of the company with w	vhich you have a	
11.	Responsibilities for share	d or common areas		
a.	Are you aware of any res	nonsibility to contributo	to the cost of envithing	No
u	used jointly, such as the boundary, or garden area	repair of a shared drive,		NO
	used jointly, such as the	repair of a shared drive, a?		NO
b.	used jointly, such as the boundary, or garden area	repair of a shared drive, a? <u>s</u> , please give details: to contribute to repair an	private road,	No
	used jointly, such as the boundary, or garden area If you have answered yes Is there a responsibility t	repair of a shared drive, a? <u>s</u> , please give details: o contribute to repair an or other common areas?	private road,	
	used jointly, such as the boundary, or garden area If you have answered yes Is there a responsibility t roof, common stairwell o	repair of a shared drive, a? <u>5</u> , please give details: to contribute to repair an or other common areas? <u>5</u> , please give details: repair or replacement of a	private road, d maintenance of the	
b. c.	used jointly, such as the boundary, or garden area If you have answered yes Is there a responsibility t roof, common stairwell o If you have answered yes Has there been any major	repair of a shared drive, a? <u>s</u> , please give details: to contribute to repair an or other common areas? <u>s</u> , please give details: repair or replacement of a owned the property? walk over any of your nei	private road, d maintenance of the any part of the roof ighbours'property —	No
b. c.	 used jointly, such as the boundary, or garden area If you have answered yes Is there a responsibility troof, common stairwell or If you have answered yes Has there been any major during the time you have of Do you have the right to point out you 	repair of a shared drive, a? <u>5</u> , please give details: <u>5</u> , please give details: <u>5</u> , please give details: <u>6</u> , please give details: <u>7</u> repair or replacement of a pwned the property? walk over any of your neited our rubbish bin or to main	private road, d maintenance of the any part of the roof ighbours'property —	No
b.	 used jointly, such as the boundary, or garden area If you have answered yes Is there a responsibility troof, common stairwell or If you have answered yes Has there been any major during the time you have of for example to put out yo boundaries? 	repair of a shared drive, a? <u>5</u> , please give details: to contribute to repair and or other common areas? <u>6</u> , please give details: repair or replacement of a powned the property? walk over any of your nei bur rubbish bin or to main <u>6</u> , please give details:	private road, d maintenance of the any part of the roof ighbours'property —	No
b. c. d.	 used jointly, such as the boundary, or garden area If you have answered yes Is there a responsibility troof, common stairwell or If you have answered yes Has there been any major during the time you have of for example to put out you boundaries? If you have answered yes 	repair of a shared drive, a? <u>s</u> , please give details: to contribute to repair and or other common areas? <u>s</u> , please give details: repair or replacement of a owned the property? walk over any of your nei bur rubbish bin or to main <u>s</u> , please give details: areas are communal do any of your neighbour for example to put out th	private road, d maintenance of the any part of the roof ighbours'property — ntain your	No
b. c.	 used jointly, such as the boundary, or garden area If you have answered yes Is there a responsibility troof, common stairwell or If you have answered yes Has there been any major during the time you have the right to po you have the right to po you have the right to po you have answered yes Do you have the right to po you have answered yes If you have answered yes Not required as the outside As far as you are aware, owalk over your property, 	repair of a shared drive, a? <u>5</u> , please give details: <u>5</u> , please give details: <u>5</u> , please give details: <u>6</u> , please give details: <u>7</u> repair or replacement of a <u>5</u> owned the property? walk over any of your nei <u>5</u> , please give details: <u>6</u> , please give details: <u>7</u> or example to put out the s?	private road, d maintenance of the any part of the roof ighbours'property — ntain your	No No Yes

f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	No
	If you have answered yes, please give details:	
12.	Charges associated with the property	1
a.	Is there a factor or property manager for your property?	No
	If you have answered yes, please provide the name and address,and give details of any deposit held and approximate charges:	
b.	Is there a common buildings insurance policy?	No
	If you have answered yes, is the cost of the insurance included in monthly/annual factor's charges?	
с.	Please give details of any other charges you have to pay on a regular bas upkeep of common areas or repair works, for example to a residents' as or maintenance or stair fund.	
13.	Specialist work	
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	No
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
b.	As far as you are aware, has any preventative work for dry rot,wet rot, or damp ever been carried out to your property?	No
	If you have answered yes, please give details:	
C.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write below who</u> <u>has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the	
	work carried out. This may be shown in the original estimate.	
14.	Guarantees are held by: Guarantees	
1-7.		
	Are there any guarantees or warranties for any of the following?	

	<u>If you have answered yes to any of a-c above</u> , please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.			
C.	that requires you to do any maintenance, repairs or improvements to your property?	Νο		
b.	that affects your property in some other way?	No		
a.	advising that the owner of a neighbouring property has made a planning application?	No		
	In the past three years have you ever received a notice:			
16.	Notices that affect your property			
	If you have answered yes, please give details:			
	So far as you are aware, has any boundary of your property been moved in thelast 10 years?	No		
15.	Boundaries			
с.	Are there any outstanding claims under any of the guarantees listed above? <u>If you have answered yes,</u> please give details:	No		
b.	If you have answered 'yes' or 'with title deeds', please give details of the installations to which the guarantee(s) relate(s):	e work or		
	(vi) Any other work installations? (for example, cavity wall installation, underpinning, indemnity policy)			
	(v) Damp course	No		
	(iv) National House Building Council (NHBC)			
	(iii) Central heating	No		
	(ii) Roofing	No		
	(i) Electrical work	No		

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief

Name(s): Emma Stirling

Date: 13/05/2025

shepherd.co.uk



Home Report Valuation Report Executory Valuation Tax Valuations Separation Valuation Private Sale Valuation New Build & Plot Valuation New Build & Plot Valuation New Build & Plot Valuation Insurance Reinstatement Valuation Portfolio Valuation Portfolio Valuation Rental Valuation Drive By & Desktop Valuation Energy Performance Certificate (EPC) Level Two Survey & Valuation Report Level Two Condition Report



Commercial Valuation Commercial Agency Acquisitions Consultancy Commercial Lease Advisory Rent Reviews Asset Management Development Appraisals & Consultancy Auctions Property Management Professional Services Licensed Trade & Leisure Expert Witness Report Rating Property Investment Public Sector



Quantity Surveying Building Surveying Project Management Dispute Resolution Support Services Principal Designer Clerk of Works Commercial EPC Health & Safety Management Employer's Agent Energy Consultancy Housing Partnerships Housing Consultancy Development Monitoring Mediation Services

Aberdeen △ ▲ ▲ 01224 202800

Ayr ▲ ▲ 01292 267987

Bearsden △▲ 0141 611 1500

Belfast ▲ 02890 912975

Birmingham ▲ 0121 270 2266

Coatbridge △ ▲ 01236 436561

Cumbernauld △ ▲ 01236 780000 **Dalkeith** △▲ 0131 663 2780

Dumbarton△ ▲ 01389 731682

Dumfries △▲△ 01387 264333

Dundee △ ▲ 01382 200454 △ 01382 220699

Dunfermline △ ▲ 01383 722337 △ 01383 731841

East Kilbride △ ▲ 01355 229317 Edinburgh △ ▲ 0131 2251234 △ 0131 557 9300

Elgin △ ▲ 01343 553939

Falkirk △ ▲ 01324 635 999

Fraserburgh △ ▲ 01346 517456

Galashiels △▲ 01896 750150

Glasgow △▲△ 0141 331 2807

Glasgow South ▲ ▲ 0141 649 8020 Glasgow West End △ ▲ 0141 353 2080

Greenock △▲01475 730717

Hamilton △▲01698 891400

Inverness △ ▲ △ 01463 712239

Kilmarnock △ ▲ 01563 520318

Kirkcaldy △▲01592 205442

Lanark △▲01555 663058 **Leeds** △ 0113 322 5069

Livingston △ ▲ 01506 416777

London ▲△ 02033 761 236

Montrose △ ▲ 01674 676768

Musselburgh ▲ 0131 653 3456

Oban ▲▲ 01631 707 800

Paisley ▲ ▲ 0141 889 8334 **Perth** △ △ 01738 638188 △ 01738 631631

Peterhead △ ▲ 01779 470766

St Andrews ▲ ▲ 01334 477773 △ 01334 476469

Saltcoats ▲ ▲ 01294 464228

Stirling ▲ ▲ 01786 450438 △ 01786 474476