
# **Energy performance certificate (EPC)**




### Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.

You can read guidance for landlords on the regulations and exemptions (https://www.gov.uk/government/publications/non-domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance).

#### **Energy rating and score**

This property's energy rating is E.



Properties get a rating from A+ (best) to G (worst) and a score.

The better the rating and score, the lower your property's carbon emissions are likely to be.

### How this property compares to others

Properties similar to this one could have ratings:

## Breakdown of this property's energy performance

Main heating fuel	Grid Supplied Electricity	
Building environment	Air Conditioning	
Assessment level	3	
Building emission rate (kgCO2/m2 per year)	96.51	
Primary energy use (kWh/m2 per year)	571	

► About primary energy use

### Recommendation report

Guidance on improving the energy performance of this property can be found in the <u>recommendation report (/energy-certificate/4211-3569-5237-4156-7190)</u>.

#### Who to contact about this certificate

#### Contacting the assessor

If you're unhappy about your property's energy assessment or certificate, you can complain to the assessor who created it.

Assessor's name	Martin Baker	
Telephone	01536206300	
Email	martin@energyassist.online	

#### Contacting the accreditation scheme

If you're still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation scheme	Elmhurst Energy Systems Ltd	
Assessor's ID	EES/019595	
Telephone	01455 883 250	
Email	enquiries@elmhurstenergy.co.uk	***************************************

#### About this assessment

Employer	Energy Assist
Employer address	83 Charnwood Road
Assessor's declaration	The assessor is not related to the owner of the property.

Date of assessment	21 July 2021
Date of certificate	3 October 2021

### Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <a href="mailto:mhclg.digital-services@communities.gov.uk">mhclg.digital-services@communities.gov.uk</a> or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related certificates for this property.

<u>Help (/help)</u> <u>Accessibility (/accessibility-statement)</u> <u>Cookies (/cookies)</u>
Give feedback (https://forms.office.com/e/KX25htGMX5) Service performance (/service-performance)

#### OGL

All content is available under the <u>Open Government Licence v3.0</u> (https://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/), except where otherwise stated



ht (https://www.nationalarchives.gov.uk/information-management/re-using-public-sector-information/uk-government-licensing-framewor

# **Energy performance certificate (EPC)** recommendation report

42 London Road **KETTERING NN157QA** 

Report number 4211-3569-5237-4156-7190

> Valid until 2 October 2031

#### **Energy rating and EPC**

This property's energy rating is E.

For more information on the property's energy performance, see the EPC for this property (/energy-certificate/7901-3501-7068-0051-7775).

#### Recommendations

Changes that may pay for themselves within 3 years

Recommendation Potential impact on carbon emissions

Add time control to heating system. Medium

Changes that may pay for themselves within 3 to 7 years

Recommendation Potential impact on carbon emissions

Add optimum start/stop to the heating system. Medium

The default heat generator efficiency is chosen. It is recommended that the heat generator system be investigated to gain Low

an understanding of its efficiency and possible improvements.

Some windows have high U-values - consider installing secondary glazing. Medium

Add local temperature control to the heating system. Medium

Add weather compensation controls to heating system. Medium

Changes that may pay for themselves in over 7 years

Recommendation Potential impact on carbon emissions

Add local time control to heating system. Medium

Some solid walls are poorly insulated - introduce or improve internal wall insulation. Medium

Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation. Medium

The default chiller efficiency is chosen. It is recommended that the chiller system be investigated to gain an understanding Low of its efficiency and possible improvements.

Some glazing is poorly insulated. Replace/improve glazing and/or frames. Medium

## Property and report details

Report issued on 3 October 2021

Total useful floor area

51 square metres

Building environment	Air Conditioning
Calculation tool	CLG, iSBEM, v5.6.b, SBEM, v5.6.b.0

#### Assessor's details

01536206300
martin@energyassist.online
Energy Assist
83 Charnwood Road
EES/019595
The assessor is not related to the owner of the property.
Elmhurst Energy Systems Ltd

### Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at <a href="mailto:mhclg.digital-services@communities.gov.uk">mhclg.digital-services@communities.gov.uk</a> or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related reports for this property.

Help (/help) Accessibility (/accessibility-statement) Cookies (/cookies)

Give feedback (https://forms.office.com/e/KX25htGMX5) Service performance (/service-performance)

#### OGL

All content is available under the <u>Open Government Licence v3.0</u> (https://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/), except where otherwise stated



ht (https://www.nationalarchives.gov.uk/information-management/re-using-public-sector-information/uk-government-licensing-framewor