HOME REPORT

LIEVER VIEW FORD

LOCHGILPHEAD PA31 8RH





ENERGY PERFORMANCE CERTIFICATE



Energy Performance Certificate (EPC)

Dwellings

Scotland

LIEVER VIEW, FORD, LOCHGILPHEAD, PA31 8RH

Dwelling type: Detached house

Date of assessment: 04 November 2024

Date of certificate: 07 November 2024

Total floor area: 114 m²

Primary Energy Indicator: 305 kWh/m²/year

Reference number: 9100-2234-2190-2604-8381 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst


Main heating and fuel: Boiler and radiators, electric

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£5,301	See your recommendations
Over 3 years you could save*	£327	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (82)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (58)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Solar water heating	£4,000 - £6,000	£327.00
2 Wind turbine	£15,000 - £25,000	£3075.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	****	****
Roof	Pitched, 350 mm loft insulation Pitched, insulated (assumed) Roof room(s), insulated (assumed)	**** ****	**** **** ***
Floor	Suspended, insulated (assumed)	_	_
Windows	Fully double glazed	★★★★☆	★★★★ ☆
Main heating	Boiler and radiators, electric	★★★☆☆	***
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★ ☆
Secondary heating	Room heaters, dual fuel (mineral and wood)	_	_
Hot water	From main system	***	***
Lighting	Low energy lighting in all fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 52 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 6.0 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 2.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£4,011 over 3 years	£4,038 over 3 years	
Hot water	£885 over 3 years	£531 over 3 years	You could
Lighting	£405 over 3 years	£405 over 3 years	save £327
Totals	£5,301	£4,974	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

December ded massives	Indicative cost	Typical saving	Rating after improvement	
Recommended measures	Indicative cost	per year	Energy	Environment
1 Solar water heating	£4,000 - £6,000	£109	B 84	D 63
2 Wind turbine	£15,000 - £25,000	£1025	A 103	C 78

Choosing the right improvement package



For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

2 Wind turbine

A wind turbine provides electricity from wind energy. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Wind turbines are not suitable for all properties. The system's effectiveness depends on local wind speeds and the presence of nearby obstructions, and a site survey should be undertaken by an accredited installer. Planning permission might be required and building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for a wind turbine, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present:

Solar photovoltaics

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	10,430	N/A	N/A	N/A
Water heating (kWh per year)	2,392			

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Gary Duff Assessor membership number: EES/009333

Company name/trading name: D M Hall Chartered Surveyors LLP

Address: The Oban Times Building Corran Esplanade

Oban

PA34 5PX
Phone number: 0131 477 6000
Email address: dmhall@dmhall.co.uk
Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



SINGLE SURVEY



survey report on:

Property address	LIEVER VIEW FORD, LOCHGILPHEAD, PA31 8RH
Customer	MR ANTHONY BINGHAM
Customer address	LIEVER VIEW FORD, LOCHGILPHEAD, PA31 8RH
Prepared by	DM Hall LLP
Date of inspection	4th November 2024



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
 or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	A detached house.
Accommodation	ON GROUND FLOOR: Vestibule, Hall, Living Room, Two Bedrooms, Kitchen, Bathroom and Utility Room.
	ON UPPER FLOOR: Gallery Sitting Area open to the Lounge and One Further Bedroom with En Suite Shower Room.
Gross internal floor area (m²)	Approximately 114 square metres.
Neighbourhood and location	The property enjoys a rural location to the north of the village of Ford close to Loch Awe and enjoying a degree of natural amenity. Principal amenities can be found in Lochgilphead to the south or Oban to the north.
Age	Built around 2011.
Weather	Overcast but dry continuing an unsettled spell.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.
	There are two block rendered chimney heads with lead flashings.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.
	Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.
	If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.
	The roof is pitched and clad with slates incorporating lead valleys and zinc ridging.

Roofing including roof space	Access to the roof space is through a hatch over the gallery sitting area. The roof is formed with timber trusses and incorporates timber sarking and under slate felt. My inspection was restricted by plastic header tanks either side of the hatch and by insulation.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	The rainwater goods are plastic with gutters of half round design.
Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of timber frame construction with an outer leaf of rendered and painted block/brick.
Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	WINDOWS: PVC sealed unit double glazed windows.
	DOORS: The entrance door is of composite materials and is double glazed. Other doors are fully PVC double glazed French doors.
	JOINERY: There are timber roofline features.
External decorations	Vigually inquested
LAIGITIAI UCCOTALIOTIS	Visually inspected.
	Paint or preservative stain finish.
Conservatories / porches	None.
	110.10.
Communal areas	None.
Garages and permanent outbuildings	Visually inspected.
	There is a timber workshop with metal roof, PVC double glazing and timber glazed entrance door. There is a further substantial bike shed and car port plus further log stores and sheds.

Outside areas and boundaries	Visually inspected.
	There is garden ground to the front, sides and rear of the property laid under grass, planting areas, timber decking and stones. The garden has a burn running through it and boundaries are formed by the line of the road and by fences. There is a shared access.
Ceilings	Visually inspected from floor level.
	Plasterboard.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Plasterboard.
Flagra in alcolic or and the	
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Flooring is of timber construction.
	I was unable to locate any hatch to the sub floor area.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	The internal joinery timbers appear to be original.
	The kitchen has white floor and wall units with integrated appliances including oven, hob, hood, grill and dishwasher.
Chimney breasts and fireplaces	Visually inspected.
•	No testing of the flues or fittings was carried out.
	There is a wood burning stove in the living room on a tiled hearth. This was installed approximately one year ago according to the seller.

Internal decorations	Visually inspected.
	Paint, paper and tile finishes.
Cellars	None.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Mains supply. 13 amp plug sockets and plastic coating cabling where visible.
Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. Bottled gas supply.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks,
Trator, pranising, same com mange	cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Private water supply. Visible installation is in copper and plastic materials. The water treatment equipment is located in the utility room.
	The bathroom contains a white three piece suite with a mixer shower over the bath. The en suite shower room has a white two piece suite with a mixer shower over a wet room style floor.
Heating and hot water	Accessible parts of the system were visually inspected apart
	from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Electric hot water system to radiators controlled by programmer, room stat and TRVs. The heating system is supplemented by the wood burning stove in the living room.

Drainage

Drainage covers etc were not lifted.

Neither drains nor drainage systems were tested.

Drainage is to a shared septic tank. Mr Bingham confirms all appropriate paperwork has been made available.

Fire, smoke and burglar alarms

Visually inspected.

No tests whatsoever were carried out to the system or appliances.

Smoke and heat detection is provided.

Legislation by the Scottish Government, which took effect from February 2022, requires all residential properties to have a system of inter-linked smoke alarms and heat detectors. Carbon monoxide detectors are also required where appropriate. Purchasers should appraise themselves of the requirements of this legislation, and engage with appropriately accredited contractors to ensure compliance.

Any additional limits to inspection

Parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.

I have not carried out an inspection for Japanese Knotweed and unless otherwise stated, for the purposes of the valuation I have assumed that there is no Japanese Knotweed or other invasive plants within the boundaries of the property or in neighbouring properties.

Random testing for dampness was undertaken internally with the use of a moisture meter where accessible and considered appropriate.

The property was occupied, fully furnished and all floors were covered. Floor coverings restricted my inspection of flooring.

In accordance with Health and Safety guidelines I have not disturbed insulation, furniture or personal effects (particularly in cupboards). Floor coverings have not been moved.

My physical inspection of the roof void area was restricted due to insulation material, stored items and lack of suitable crawl boards. As a result the roof void area was only viewed from the access hatch.

My inspection of the roof covering was restricted from ground level and some parts were not visible. Trees/surrounding buildings/site topography partially blocked sight lines.

I was not able to inspect the sub floor area.


Concealed areas beneath and around bath/shower trays were not visible. Water spillage in these areas can often be discovered unexpectedly with resultant damage to concealed parts of the fabric.

The inspection is not a fire or life safety risk assessment and should not be relied on as a risk assessment inspection. Further advice should be sought if a specific risk assessment of the property and building that it forms part of is required.

Where repairs are required at height compliance with Health and

Any additional limits to inspection	Safety legislation often requires the use of scaffolding which can
	significantly impact on the cost of repair. Pricing repairs is out with
	the remit of this report but it would be prudent to consider costs
	and budgeting before offering. The various trades can advise
	further.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4 Flashing
- 5) Ridge ventilation
- 6) Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10 Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- (15) Collar
- 16 Insulation
- 17) Parapet gutter
- (18) Eaves guttering
- 19) Rainwater downpipe
- (20) Verge boards /skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- (25) Window pointing
- Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- 36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40) Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	No obvious evidence of significant movement noted within the limitations of my inspection.

Dampness, rot and infestation	
Repair category	1
Notes	No obvious evidence of significant dampness, rot or wood boring insect infestation.

Chimney stacks	
Repair category	1
Notes	No significant defects evident.

Roofing including roof space	
Repair category	1
Notes	No significant defects evident.

Rainwater fittings	
Repair category	1
Notes	Some seasonal leaves were noted in gutters and should be regularly cleaned out.

Main walls	
Repair category	1
Notes	No significant defects evident.

Windows, external doors and joinery	
Repair category	1
Notes	No significant defects evident.

External decorations	
Repair category	1
Notes	Generally fresh.

Conservatories/porches	
Repair category	-
Notes	N/A.

Communal areas	
Repair category	-
Notes	N/A.

Garages and permanent outbuildings	
Repair category	1
Notes	No significant defects evident.

Outside areas and boundaries	
Repair category	1
Notes	Mature trees in and around the garden ground will require careful monitoring. The

Outside areas and boundaries	
Repair category	1
Notes	retaining wall and decking will also require careful monitoring and ongoing maintenance respectively.

Ceilings	
Repair category	1
Notes	No significant defects evident.

Internal walls	
Repair category	1
Notes	No significant defects evident.

Floors including sub-floors	
Repair category	1
Notes	No significant defects evident.
	It is not unusual to discover areas of past water spillage when floor coverings are removed in kitchen and bathroom compartments, revealing the need for further repair and maintenance work.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No significant defects evident.

Chimney breasts and fireplaces	
Repair category	1
Notes	Flues should ideally be swept and tested on an annual basis.

Internal decorations	
Repair category	1
Notes	Generally fresh.

Cellars	
Repair category	-
Notes	N/A.

Electricity	
Repair category	1
Notes	It is recommended that all electrical installations be checked every five years or on change of ownership to keep up to date with frequent changes in Safety Regulations. Further advice will be available from a qualified NICEIC/ SELECT registered Contractor. It should be appreciated that only recently constructed or rewired properties will have installations which fully comply with IET regulations.

Gas	
Repair category	1
Notes	Trade bodies governing gas installations currently advise that gas appliances should be tested prior to change in occupancy and thereafter at least once a year by a Gas Safe registered contractor. It is assumed that gas appliances comply with relevant regulations.

Water, plumbing and bathroom fittings			
Repair category	1		
Notes	It should be ensured that the seals are maintained in a watertight condition.		

Heating and hot water			
Repair category	1		
Notes	It is assumed that the heating and hot water systems have been properly serviced and maintained on a regular basis and installed in accordance with the relevant regulations.		

Drainage	
Repair category	1
Notes	No surface evidence of blockage or leakage apparent.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground Floor		
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No		
3. Is there a lift to the main entrance door of the property?	Yes No X		
4. Are all door openings greater than 750mm?	Yes No X		
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No		
6. Is there a toilet on the same level as a bedroom?	Yes X No		
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X		
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No		

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

It is not possible to comment upon the quality or adequacy of the private water supply but it is assumed that it is wholesome and acceptable for normal consumption patterns. I am not aware of any supply issues but further information can be obtained from a suitably qualified specialist contractor.

Drainage is to a septic tank. Mr Bingham confirms necessary paperwork has been obtained. The position regarding age, location, condition and maintenance history should be clarified.

The access road appears to be shared. The completing conveyancer should verify rights of access and liability in respect of future maintenance.

Estimated reinstatement cost for insurance purposes

£500,000 (FIVE HUNDRED THOUSAND POUNDS).

It should be noted this sum is an estimate calculated by using a rate per square metre based on information provided by Building Cost Information Service (BCIS).

Valuation and market comments

£375,000 (THREE HUNDRED AND SEVENTY FIVE THOUSAND POUNDS).

There has been a downturn in activity in some sectors of the property market. This appears to have been due to changing economic circumstances and changing legislation locally. Interest rate rises have now stabilised in recent months and ongoing activity is anticipated.

Signed	Security Print Code [441472 = 6848] Electronically signed					
Report author	Gary P Duff					
Company name	DM Hall LLP					
Address	The Oban Times Building, Corran Esplanade, Oban, Argyll, PA34 5PX					
Date of report	7th November 2024					

Mortgage Valuation Report



Property Address					
Address LIEVER VIEW FORD, LOCHGILPHEAD, PA31 8RH Seller's Name MR ANTHONY BINGHAM Date of Inspection 4th November 2024					
Property Details					
Property Type	X House Bungalow Chalet Purpose built maisonette Coach Studio Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)				
Property Style	X Detached Semi detached Mid terrace End terrace Back to back High rise block Low rise block Other (specify in General Remarks)				
Does the surveyor be e.g. local authority, m	elieve that the property was built for the public sector, Yes X No nilitary, police?				
Flats/Maisonettes onl	ly Floor(s) on which located No. of floors in block Lift provided? Yes No				
Approximate Year of	No. of units in block Construction 2011				
Tenure					
X Absolute Ownership	Leasehold Ground rent £ Unexpired years				
Accommodation					
Number of Rooms	1 Living room(s) 3 Bedroom(s) 1 Kitchen(s) 2 Bathroom(s) 2 WC(s) 2 Other (Specify in General remarks)				
Gross Floor Area (ex	cluding garages and outbuildings) 114 m² (Internal) 130 m² (External)				
Residential Element ((greater than 40%) X Yes No				
Garage / Parking /	Outbuildings				
Single garage Available on site?	□ Double garage ▼ Parking space □ No garage / garage space / parking space ▼ Yes □ No				
Permanent outbuildings:					
Timber workshop, bike store and car port, further log stores and sheds.					

Mortgage Valuation Report

Construction								
Walls	Brick	Stone	Con	crete	Timber frame			
	Solid	Cavity		el frame	Concrete block	Othe	er (specify in Ger	neral Remarks)
Roof	Tile	X Slate	Aspl	_	Felt		. (-)	,
	Lead	Zinc		icial slate	Flat glass fibre	Othe	er (specify in Ger	neral Remarks)
Special Risks								
Has the property s			ent?				Yes	X No
If Yes, is this rece	. •						Yes	No No
Is there evidence, immediate vicinity	history, or rea?	son to antici	pate subsid	lence, he	ave, landslip o	or flood in th	e Yes	X No
If Yes to any of the	e above, provi	de details in	General Re	marks.				
Service Connec	tion							
Based on visual in of the supply in Ge			ces appear	to be nor	n-mains, pleas	e comment	on the type a	nd location
Drainage	Mains	X Private	None		Water	Mains	X Private	None
Electricity	X Mains	Private	None		Gas	Mains	X Private	None
Central Heating	X Yes	Partial	None				_	_
Brief description o	f Central Heat	ing:						
Electric heating t	to radiators.							
Site								
Apparent legal iss	ues to be verit	ied by the co	nveyancer	. Please	provide a brief	description	in General R	emarks.
Rights of way	X Shared drive	es / access	Garage or	r other ame	nities on separate	e site X Sha	ared service con	nections
Agricultural land in	cluded with prope	rty	Ill-defined	boundaries	3	Oth	ner (specify in Ge	neral Remarks)
Location								
Residential suburb	Resi	dential within to	wn / city	Mixed re	sidential / comme	rcial Ma	inly commercial	
Commuter village		ote village		_	rural property	_	ner (specify in Ge	neral Remarks)
Planning Issues	;							
Has the property b	peen extended	I / converted	/ altered?	Yes	X No			
If Yes provide details in General Remarks.								
Roads								
Made up road	X Unmade road	Partly	completed ne	w road	Pedestrian a	access only	Adopted	Unadopted

Mortgage Valuation Report

Canara	I D	an	nar	Ve

At the time of inspection the property was occupied, furnished and floors were covered. The condition of the property is generally satisfactory commensurate with age and type.

The property enjoys a rural location close to Loch Awe, north of the village of Ford. The property is relatively conveniently located for principal amenities in Lochgilphead or further afield in Oban.

The other accommodation noted above is a Utility Room and a Gallery Sitting Area.

Access to the property is by a shared road and it is assumed appropriate rights of access exist. The share of repair liability can be confirmed by the conveyancers.

Drainage is to a septic tank. It is understood that the tank is registered with SEPA. The position regarding age, location, condition and maintenance history should be clarified.

It is not possible to comment upon the quality or adequacy of the private water supply but it is assumed that it is wholesome and acceptable for normal consumption patterns. I am not aware of any supply issues but further information can be obtained from a suitably qualified specialist contractor.

Essential Repairs				
None.				
Estimated cost of essential repairs £	Retention recommended? Yes	X No	Amount £	

Mortgage Valuation Report

Comment on Mortgagea	bility	
	le security for normal mortgage finance.	
Valuations		
Is a reinspection necessary Buy To Let Cases	n of essential repairs lue rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 375,000 £ N/A £ 500,000 Yes X No
month Short Assured Tenai		~
Is the property in an area w Declaration	here there is a steady demand for rented accommodation of this type?	Yes No
Signed Surveyor's name	Security Print Code [441472 = 6848] Electronically signed by:- Gary P Duff	
Professional qualifications Company name Address Telephone	MRICS DM Hall LLP The Oban Times Building, Corran Esplanade, Oban, Argyll, PA34 5PX 01631 564225	
Fax Report date	01631 562373 7th November 2024	

PROPERTY QUESTIONNAIRE





Property Que	stionnaire
Update	Complete View PDF Help
	Quit
	Insert address of property and include postcode:
House/Flat	LIEVER VIEW FORD
Road	
Area	
Town	LOCHGILPHEAD
County	
Post Code	PA31 8RH
Is this form bein vendor?	yes No
	NO
	If 'Yes', which? Property in possession Absentee vendor
Seller(s) and dat	te of form completion:
Seller(s)	ANTHONY DAND GINGHAM
Completion date o questionnaire	f property 28-10-2024
Note for selle	
Please comp correct.	plete this form carefully. It is important that your answers are
	tion in your answers will help ensure that the sale of your house nly. Please answer each question with as much detailed as you can.
entry	changes after you fill in this questionnaire but before the date of of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

28/10/2024, 09:41 Page 1 of 12

Length of owner	ership				
1. How long	16	YEARS	(SINCE	NEW)	
have you owned the property?	Cannot ar	nswer			
Council tax					
2. Which Counci your property		□ A □ B □ C □ D ☑ E □ F □ G □ H □ Cannot ans	wer		
Parking					
3. What are the arrangements for parking at your property? (Please tick all that apply)	On street Resident	permit parking ease specify):			
Conservation a	rea				
4. Is your property in a designated Conservation Area (i.e. an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?		Yes No Don't know Cannot ans	wer		
Listed buildings					
5. Is your proper Building, or co within one (i.e	ontained	Yes VNo			

recognised an as being of sp architectural of interest)?	ecial	Cannot answer
Alterations / ac	lditions / exte	nsions
6. (a) (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes No Cannot ar If you have a you have made	nswered yes, please describe the changes which
(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	by the purcha soon as possi If you do not	nswered yes, the relevant documents will be needed aser and you should give them to your solicitor as ble for checking. have the documents yourself, please note below the documents and your solicitor or estate agent will
(b) Have you replacement of doors, pation of double glazing your property (i) Were the replacement of the same shad as the ones your property	windows, loors or g installed in ? eplacements pe and type	Yes Cannot answer If you have answered yes, please answer the three questions below: Yes No Cannot answer

28/10/2024, 09:41 Page 3 of 12

*

(ii) Did this wany changes window or do (iii) Please describe the changes made to the windows, doors or patio doors (with approximate dates when the work was completed):	to the or openings? Please give ar	Yes No Cannot answer ny guarantees which you received for this work to or estate agent.
Central heating	9	
7. (a) Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).	Partial Cannot and If you have are is there? (Example described)	nswered yes / partial - what kind of central heating mples: gas-fired, solid fuel, electric storage
(b) When was your central heating system or partial central heating system installed?	Cannot an	2010 swer

		nswer nswered yes, please give details of the company ou have a maintenance contract:
(d) When was your maintenance agreement last renewed? (Please provide the month and year).	Cannot ar	nswer
Energy Perform	nance Certifica	ate
8. Does your pro an Energy Per Certificate wh than 10 years	formance ich is less	Yes No Cannot answer
Issues that ma	y have affecte	ed your property
9. (a) Has there storm, flood, structural dan property while owned it?	fire or other nage to your	Yes Vivo Cannot answer
If you have and is the damage of any outstar insurance clai	e the subject nding	Yes No Cannot answer
(b) Are you aware of the existence of asbestos in your property?	Yes No Cannot an If you have a	nswer nswered <u>yes,</u> please give details:

Services	
10.(a) Please tick wh the supplier:	nich services are connected to your property and give details of
Services	Connected Supplier
Gas / liquid	Yes
petroleum gas	©No
	Cannot
Makes series /	answer Oyes Pawate Supply
Water mains /	ONO PRIVATE SUPPLY
private water supply	Cannot
	answer
Electricity	PYes SSE
	□No
	Cannot
	answer
Mains drainage	Yes
	₩ No
	Cannot
Telephone	DYes & T
	○No
	Cannot
	answer
Cable TV / satellite	U Yes □
	₩ No
	Cannot
Broadband	DYes QT
	○ No
	Cannot
	answer
(b) Is there a sep system at your pr	roperty? —
System at your pr	0100
	Cannot answer
	If you have answered yes, please answer the two questions below:
(c) Do you have	Yes
appropriate conse the discharge fror	
septic tank?	Don't know
	Cannot answer

(d) Do you have a maintenance contract for your septic tank?	Yes Cannot answer If you have answered yes, please give details of the company with which you have a maintenance contract:
Responsibilities	s for Shared or Common Areas
aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?	Yes No Don't know Cannot answer If you have answered yes, please give details:
(b) Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?	Yes Not applicable Cannot answer If you have answered yes, please give details:
(c) Has there major repair of replacement of the roof during you have own property? (d) Do you have the right to walk over any of	or of any part of Cannot answer
your neighbours' property -	If you have answered yes, please give details:

for example to put out your rubbish bin or to maintain your boundaries?	
(e) As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	☐ Yes ☐ Cannot answer If you have answered yes, please give details:
(f) As far as you are aware, is there a public right of way across any part of your property? (Public right of way is a way over which the public has a right to pass, whether or not the land is privatelyowned.)	☐ Yes ☐ Cannot answer If you have answered yes, please give details:
Charges assoc	ated with your property
12. (a) Is there a factor or property manager for your property?	Yes No Cannot answer If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:

preventative work for dry rot, wet rot, or damp ever been carried out to your property?	If you have a	nswere	ed yes,	please g	ive details:		
(c) If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	No Cannot answer If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:						
Guarantees	any quarante	es or v	warran	ties for a	nv of the fol	lowina:	
14. (a) Are there any guarantees or warranties for any of the following: Don't With title Cannot							
(i) Electrical wo	ork	0		know	deeds	0	Answer
(ii) Roofing		0		0	0		0
(iii) Central heat	ing	\bigcirc	0				0
(iv) NHBC			0	0			0
(v) Damp cours	e		0	\bigcirc			0
Any other w installations (vi) example, ca insulation, u indemnity p	? (for vity wall ınderpinning,	0	0	О	0	0	0
(b) If you have answered 'yes' or 'with title deeds', please give details of the work or	Cannot a	ies			og an	′	HAVE

*	(b) Is there a commo buildings insurance p	_				
	If you have answered is the cost of the insurance included in monthly/annual facto charges?	your				
	(c) Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.					
	Specialist works					
	dry rot, wet rot, damp or whether	Cannot answer If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.				
	(b) As far as Yes you are aware, has any Can	not answer				

installations to which the guarantee(s) relate(s): (c) Are there any outstanding claims under any of the guarantees listed above?	Yes No Cannot answer If you have answered yes, please give details:				
Boundaries					
15. So far as you are aware, has any boundary of your property been moved in the last 10 years?	Yes No Don't know Cannot an				
Notices that aff	ect your prop	erty			
16. In the past 3 years have you ever received a notice:(a) advising that the owner of a neighbouring property has made a planning application?		Yes No Don't know Cannot answer			
(b) that affects your property in some other way?		Yes No Don't know Cannot answer			
(c) that requires you to do any maintenance, repairs or improvements to your property?		Yes V No Don't know Cannot answer			

<u>If you have answered yes to any of a-c above</u>, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.

End	of report					
	Update	Complete	View PDF	Help	Quit	



ABERDEEN

aberdeen_residential@dmhall.co.uk01224 594172

AYR

ayr@dmhall.co.uk 01292 286974

DUMFRIES

dumfries@dmhall.co.uk 01387 254318

DUNDEE

dundee@dmhall.co.uk 01382 873100

DUNFERMLINE

dunfermline@dmhall.co.uk 01383 621262

EDINBURGH

edinburghresidential@dmhall.co.uk 0131 624 6600

FLGIN

elgin@dmhall.co.uk 01343 548501

FALKIRK

falkirk@dmhall.co.uk 01324 628321

GALASHIELS

galashiels@dmhall.co.uk 01896 752009

GLASGOW (Residential)

glasgowresidential@dmhall.co.uk 0141 636 4141

HAMILTON

hamilton@dmhall.co.uk 01698 284939

INVERNESS

inverness@dmhall.co.uk 01463 241077

INVERURIE

inverurie@dmhall.co.uk 01467 624393

IRVINE

irvine@dmhall.co.uk 01294 311070

KIRKCALDY

kirkcaldy@dmhall.co.uk 01592 598200

LIVINGSTON

livingston@dmhall.co.uk 01506 490404

OBAN

oban-admin@dmhall. co.uk 01631 564225

PAISLEY

Enquiries are now dealt with at our Glasgow Hub.

PERTH

perth@dmhall.co.uk 01738 562100

PETERHEAD

peterhead@dmhall.co.uk 01779 470220

ST ANDREWS

standrews@dmhall.co.uk 01334 844826

STIRLING

stirling@dmhall.co.uk 01786 475785

