YOUR ONESURVEY HOME REPORT

ADDRESS

Ellen Brae Nethy Bridge PH25 3DB

PREPARED FOR

Alan & Olwen Billington

INSPECTION CARRIED OUT BY:

DM HALL

SELLING AGENT:



HOME REPORT GENERATED BY:



Document Index

Document	Status	Prepared By	Prepared On
Single Survey	Final	D M Hall - Inverness	17/06/2024
Mortgage Certificate	Final	D M Hall - Inverness	17/06/2024
Property Questionnaire	Final	Mr & Mrs. Alan & Olwen Billington	17/06/2024
EPC	FileUploaded	D M Hall - Inverness	17/06/2024

Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.**

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

PART 1

SINGLE SURVEY

A report on the condition of the property, with categories being rated from 1 to 3.



Single Survey

Survey report on:

Customer	Mr & Mrs. Alan & Olwen Billington
Selling address	Ellen Brae
	Nethy Bridge
	PH25 3DB
Date of Inspection	13/06/2024
Prepared by	Calum Riach, MRICS D M Hall - Inverness

SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property. ¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

 $\overline{\Omega}$

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller:
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 2.3.1 <u>Category 3</u>: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2.3.2 <u>Category 2</u>: Repairs or replacement requiring future attention, but estimates are still advised.
- 2.3.3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an

arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- ➤ *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The subjects comprise a DETACHED TWO STOREY HOUSE of modern style.
Accommodation	Ground Floor: Entrance Porch, Living Room, Kltchen/Diner, Bedroom, Shower Room and Utility Room. First Floor: Master Bedroom with en-suite Shower Room, Two Further Bedrooms and Family Bathroom.
Gross internal floor area (m2)	155 sq m
Neighbourhood and location	The subjects are situated in a small modern residential development close to the centre of Nethy Bridge where surrounding properties are of a similar residential style and nature. Local facilities and amenities are available nearby.
Age	Built circa 2003.
Weather	Dry and bright.
Chimney stacks	Visually inspected with the aid of binoculars where required. The chimney stack is of concrete block construction, externally roughcast and incorporates metal flashings.

Roofing including roof space Sloping roofs were visually inspected with the aid of binoculars where required. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. The roof is of pitched design clad in slates with metal clad valleys and ridging. There are dormer projections with timber clad details. Access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. The roof is of timber frame construction incorporating close boarded sarking. Insulation material has been laid between the ceiling joists. The control unit for the heat exchange system is located within the roof void. Rainwater fittings Visually inspected with the aid of binoculars where required. Gutters and downpipes are formed in uPVC. Main walls Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. The main walls are of 330mm cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		
was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. The roof is of pitched design clad in slates with metal clad valleys and ridging. There are dormer projections with timber clad details. Access to the roof void is via a ceiling hatch and folding timber ladder on the landing. The roof is of timber frame construction incorporating close boarded sarking. Insulation material has been laid between the ceiling joists. The control unit for the heat exchange system is located within the roof void. Rainwater fittings Visually inspected with the aid of binoculars where required. Gutters and downpipes are formed in uPVC. Main walls Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. The main walls are of 330mm cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.	, ,	, ,
ridging. There are dormer projections with timber clad details. Access to the roof void is via a ceiling hatch and folding timber ladder on the landing. The roof is of timber frame construction incorporating close boarded sarking. Insulation material has been laid between the ceiling joists. The control unit for the heat exchange system is located within the roof void. Rainwater fittings Visually inspected with the aid of binoculars where required. Gutters and downpipes are formed in uPVC. Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. The main walls are of 330mm cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. Windows, external doors and windows were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the
the landing. The roof is of timber frame construction incorporating close boarded sarking. Insulation material has been laid between the ceiling joists. The control unit for the heat exchange system is located within the roof void. Rainwater fittings Visually inspected with the aid of binoculars where required. Gutters and downpipes are formed in uPVC. Main walls Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. The main walls are of 330mm cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. Windows, external doors and vindows were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		
sarking. Insulation material has been laid between the ceiling joists. The control unit for the heat exchange system is located within the roof void. Rainwater fittings Visually inspected with the aid of binoculars where required. Gutters and downpipes are formed in uPVC. Main walls Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. The main walls are of 330mm cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		
Rainwater fittings Visually inspected with the aid of binoculars where required. Gutters and downpipes are formed in uPVC. Main walls Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. The main walls are of 330mm cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. Windows, external doors and internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		, -
Gutters and downpipes are formed in uPVC. Main walls Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. The main walls are of 330mm cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		•
Main walls Visually inspected with the aid of binoculars where required. Foundations and concealed parts were not exposed or inspected. The main walls are of 330mm cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.	Rainwater fittings	Visually inspected with the aid of binoculars where required.
Foundations and concealed parts were not exposed or inspected. The main walls are of 330mm cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. Windows, external doors and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		Gutters and downpipes are formed in uPVC.
Outer leaf of concrete blockwork externally roughcast. Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.	Main walls	
and joinery ### were available. Random windows were opened and closed where possible. Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		<u> </u>
Doors and windows were not forced open. Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.	1	•
Windows are of timber casement design equipped with sealed unit double glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		Random windows were opened and closed where possible.
glazing. The front and side access doors are formed in timber and incorporate glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		Doors and windows were not forced open.
glazed panel inserts. In addition, there are timber frame double glazed French windows opening from the dining area. Fascia's and soffits are formed in timber with a painted finish. External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		j ' ' ' '
External decorations Visually inspected. Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		glazed panel inserts. In addition, there are timber frame double glazed
Painted finishes. Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		Fascia's and soffits are formed in timber with a painted finish.
Conservatories / porches Visually inspected. The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.	External decorations	Visually inspected.
The entrance porch is of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast. The roof is pitched and slated.		Painted finishes.
leaf of concrete blockwork externally roughcast. The roof is pitched and slated.	Conservatories / porches	Visually inspected.
Communal areas None.		leaf of concrete blockwork externally roughcast. The roof is pitched and
	Communal areas	None.

Garages and permanent	Visually inspected.
outbuildings	There is an attached single car garage of block and render construction under a pitched and slated roof.
	Internally, timber and glazed doors have been fitted to provide a work space. These could be easily removed returning the garage to its original use.
	In addition, there is a timber garden shed and several log stores.
Outside areas and	Visually inspected.
boundaries	The garden grounds are arranged on all sides and laid to grass with mature borders, paved patio area and a lock-block driveway.
	Boundaries, where formed are of timber fencing.
Ceilings	Visually inspected from floor level.
	Ceilings are lined in plasterboard.
Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	Internal walls are lined in plasterboard.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	Flooring at first floor level is of suspended timber design with solid concrete flooring at ground floor.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	There is a ceramic Belfast sink unit along with a range of floor and wall mounted storage units within the kitchen.
	Skirtings and architraves are formed in timber with a varnished finish and internal doors are of timber panel or of timber and glazed design.
	A timber tread and riser staircase links the ground and first floors.
Chimney breasts and fireplaces	Visually inspected. No testing of the flues or fittings was carried out.
Шоріассэ	There is a multi-fuel stove fitted within the living room.

Internal decorations	Visually inspected.		
	Painted finishes.		
Cellars	None.		
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.		
	Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.		
	The meter and consumer unit are located within the entrance porch.		
	There is a second consumer unit within the garage.		
Gas	No supply.		
Water, plumbing and bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.		
	No tests whatsoever were carried out to the system or appliances.		
	Water is from a mains supply.		
	Both shower rooms are fitted with a wc, wash-hand basin and shower cubicle with mixer fitting.		
	The family bathroom has a wc, wash-hand basin and freestanding bath.		
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.		
	No tests whatsoever were carried out to the system or appliances.		
	Heating is from an electric underfloor heating system at ground and first floor levels which are controlled by wall thermostats.		
	There are also a number of electric panel heaters distributed throughout the property and a heat exchange system.		
	There is an insulated hot water tank with dual immersion heaters within the ground floor hallway cupboard. This provides domestic hot water.		
Drainage	Drainage covers etc were not lifted.		
	Neither drains nor drainage systems were tested.		
	Drainage is connected to the main public sewer. I did not lift any hatches or view chambers.		

Fire, smoke and burglar alarms

Visually inspected.

No test whatsoever were carried out to any systems or appliances.

There is now a requirement in place for compliant interlinked fire, smoke and heat detectors in residential properties. The new fire smoke and alarm standard came into force in Scotland in February 2022, requiring a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also requires to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon fuelled appliance such as a boiler, open fire or wood burner etc. a carbon monoxide detector is also required.

The surveyor will only comment on the presence of a smoke detector etc. but will not test them, ascertain if they are in working order, interlinked and / or fully compliant with the fire and smoke alarm standard that was introduced in 2022.

We have for the purposes of the report, assumed the system is fully compliant, if not then the appropriate compliant system will required to be installed prior to sale. This of course should be confirmed by your legal advisor.

Inter-linked smoke detectors were noted.

Legislation by the Scottish Government, which took effect from February 2022, requires all residential properties to have a system of inter-linked smoke alarms and heat detectors. Carbon monoxide detectors are also required where appropriate. Purchasers should appraise themselves of the requirements of this legislation, and engage with appropriately accredited contractors to ensure compliance.

Any additional limits to inspection

Parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.

I have not carried out an inspection for Japanese Knotweed and unless otherwise stated, for the purposes of the valuation I have assumed that there is no Japanese Knotweed or other invasive plants within the boundaries of the property or in neighbouring properties.

Random testing for dampness was undertaken internally with the use of a moisture meter where accessible and considered appropriate.

The property was occupied, fully furnished and all floors were covered. Floor coverings restricted my inspection of flooring.

In accordance with Health and Safety guidelines I have not disturbed insulation, furniture or personal effects (particularly in cupboards). Floor coverings have not been moved.

My physical inspection of the roof void area was restricted due to insulation material and lack of suitable crawl boards. As a result the roof void area was only viewed from the access hatch.

My inspection of the roof covering was restricted from ground level and some parts were not visible.

Concealed areas beneath and around bath/shower trays were not visible. Water spillage in these areas can often be discovered unexpectedly with resultant damage to concealed parts of the fabric.

The inspection is not a fire or life safety risk assessment and should not be relied on as a risk assessment inspection. Further advice should be sought if a specific risk assessment of the property and building that it forms part of is required.

Where repairs are required at height compliance with Health and Safety legislation often requires the use of scaffolding which can significantly impact on the cost of repair. Pricing repairs is out with the remit of this report but it would be prudent to consider costs and budgeting before offering. The various trades can advise further.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the above 3 categories:

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movemen	t
Repair category:	
Notes:	No obvious evidence of significant movement noted within the limitations of my inspection.

Dampness, rot and infestation		
Repair category:		
Notes:	No obvious evidence of significant dampness, rot or wood boring insect infestation.	

Chimney stacks	
Repair category:	
Notes:	No significant defects evident.

Roofing including roof space		
Repair category:	1	
Notes:	There are several chipped and moved roof slates to the rear roof pitch.	
	There is some corrosion to the metal ridging.	

Category 3		Category 2	Category 1	
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.		Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.	
Rainwater fittings				
Repair category:	1			
Notes:	No significant defects evid	lent.		
Main walls				
Repair category:	1			
Notes:	There is some wear to are	eas of base course render.		
Windows, external Repair category:	doors and joinery			
Notes:	No significant defects evid	lent.		
External decoration	าร			
Repair category:	1			
Notes:	No significant defects evid	No significant defects evident.		
Oanaamustadia a				
Conservatories / po	orcnes			
Repair category:				
Notes:	No significant defects evid	lent.		
Communal areas				
Repair category:				
Notes:	None.			

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Garages and permanent outbuildings	
Repair category:	
Notes:	No significant defects evident.

Outside areas and boundaries	
Repair category:	
Notes:	There is some leaning to the rear timber fence.

Ceilings	
Repair category:	
Notes:	No significant defects evident.

Internal walls	
Repair category:	
Notes:	No significant defects evident.

Floors including sub-floors	
Repair category:	1
Notes:	No significant defects evident.
	It is not unusual to discover areas of past water spillage when floor coverings are removed in kitchen and bathroom compartments, revealing the need for further repair and maintenance work.

Internal joinery and kitchen fittings	
Repair category:	
Notes:	Glazed inserts to interior doors may not be of appropriate toughened glass or meet the recognised Building Standards.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Chimney breasts and fireplaces	
Repair category:	
Notes:	A multi-fuel stove has been installed within the living room. It is assumed that the installation complies with the Building Standards.
	Flues should ideally be swept and tested on an annual basis.

Internal decorations	
Repair category:	
Notes:	No significant defects evident.

Cellars	
Repair category:	
Notes:	None.

Electricity	
Repair category:	
Notes:	No significant defects evident.
	It is recommended that all electrical installations be checked every five years or on change of ownership to keep up to date with frequent changes in Safety Regulations. Further advice will be available from a qualified NICEIC/ SELECT registered Contractor. It should be appreciated that only recently constructed or rewired properties will have installations which fully comply with IET regulations.

Gas	
Repair category:	
Notes:	None.

Category 3	Category 2	Category 1
	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Water, plumbing and bathroom fittings		
Repair category:	pair category:	
Notes:	o significant defects evident.	

Heating and hot water		
Repair category:		
Notes:	It is assumed that the heating and hot water systems have been properly serviced and maintained on a regular basis and installed in accordance with the relevant regulations.	

Drainage	
Repair category:	
Notes:	No significant defects evident.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories / porches	1
Communal areas	
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	
Electricity	1
Gas	
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

<u>Three steps or fewer to a main entrance door of the property:</u> In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

<u>Unrestricted parking within 25 metres:</u> For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Ground.
2. Are there three steps or fewer to a main entrance door of the property?	[x]YES []NO
3. Is there a lift to the main entrance door of the property?	[]YES [x]NO
4. Are all door openings greater than 750mm?	[x]YES []NO
5. Is there a toilet on the same level as the living room and kitchen?	[x]YES []NO
6. Is there a toilet on the same level as a bedroom?	[x]YES []NO
7. Are all rooms on the same level with no internal steps or stairs?	[]YES [x]NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	[x]YES []NO

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The access driveway appears to be shared with the neighbouring property. The completing conveyancer should verify rights of access and liability in respect of future maintenance.

Estimated re-instatement cost (£) for insurance purposes

£450,000 (FOUR HUNDRED AND FIFTY THOUSAND POUNDS).

It should be noted this sum is an estimate calculated by using a rate per square metre based on information provided by Building Cost Information Service (BCIS).

Valuation (£) and market comments

£520,000 (FIVE HUNDRED AND TWENTY THOUSAND POUNDS).

Following buoyant market conditions over a prolonged period through the Covid 19 pandemic, there are now indications of a return to a more balanced level of supply and demand.

Report author:	Calum Riach, MRICS	
Company name:	D M Hall - Inverness	
Address:	Hope House Castlehill Drive Inverness IV2 5GH	
Signed:	Electronically Signed: 260903-878aa635-1c8d	
Date of report:	17/06/2024	

MORTGAGE VALUATION **REPORT**

Includes a market valuation of the property.





Mortgage Valuation Report				
Property:	Ellen Brae Nethy Bridge PH25 3DB	Client: Mr & Mrs. Alan & Olwen Billington Tenure: Absolute Ownership.		
Date of Inspection:	13/06/2024	Reference: IS241191		

This report has been prepared as part of your instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising your lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation — Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.

1.0 LOCATION

The subjects are situated in a small modern residential development close to the centre of Nethy Bridge where surrounding properties are of a similar residential style and nature.

Local facilities and amenities are available nearby.

2.0 DESCRIPTION 2.1 Age: Built circa 2003.

The subjects comprise a DETACHED TWO STOREY HOUSE of modern style.

3.0 CONSTRUCTION

The main walls are of cavity timber frame construction with an outer leaf of concrete blockwork externally roughcast.

The roof is pitched and slated.

4.0 ACCOMMODATION

Ground Floor: Entrance Porch, Living Room, Kltchen/Diner, Bedroom, Shower Room and Utility Room.

First Floor: Master Bedroom with en-suite Shower Room, Two Further Bedrooms and Family Bathroom.

5.0	SERVICES (No tests have been applied to any of the services)						
Water:	Mains	Electricity:	Mains	Gas:	None	Drainage:	Mains
Central Heating: Electric underfloor heating system and electric panel heaters.							
6.0	OUTBUILDINGS						
Garage:	Garage: Attached single car garage.						
Others:		Timber garden shed and log stores.					

7.0	GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.					
	was found to be in a condition g normal routine maintenance		th age and type. Items of rep	air should be o	apable of	
8.0	ESSENTIAL REPAIR WOR property)	K (as a conditi	ion of any mortgage or, to pre	serve the cond	dition of the	
None.						
8.1 Retention	n recommended:	No.				
9.0	ROADS & FOOTPATHS					
Adopted.						
10.0	BUILDINGS INSURANCE (£):	450,000	GROSS EXTERNAL FLOOR AREA	178	Square metres	
14.0	This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.					
11.0	GENERAL REMARKS	' ''' 41 i - i	The second		l , al	
	riveway appears to be shared		•	eting conveyar	ncer should	
12.0	VALUATION On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.					
12.1	Market Value in present condition (£):	520,000	FIVE HUNDRED AND TWE	NTY THOUSA	ND POUNDS	
12.2	Market Value on completion of essential works (£):					
12.3	Suitable security for normal mortgage purposes?					
12.4	Date of Valuation:	13/06/2024				
Signature:	Electronically	Signed: 26090	03-878aa635-1c8d			
Surveyor:	Calum Riach	MRICS		Date:	17/06/2024	
D M Hall - In	verness					
Office:	Hope House Castlehill Drive Inverness IV2 5GH		Tel: 01463 241 077 Fax: email: inverness@dmhall.co.uk,	paula.geegan	@dmhall.co.u	

PART 3

ENERGY REPORT

A report on the energy efficiency of the property.



energy report

energy report on:

Property address	Ellen Brae Nethy Bridge PH25 3DB	
Customer	Mr & Mrs. Alan & Olwen Billington	
Customer address	Ellen Brae	
	Nethy Bridge	
	PH25 3DB	
Prepared by	Calum Riach, MRICS	
	D M Hall - Inverness	

Energy Performance Certificate (EPC)

Dwellings

Scotland

ELLEN BRAE, NETHY BRIDGE, PH25 3DB

Dwelling type:Detached houseDate of assessment:13 June 2024Date of certificate:13 June 2024Total floor area:155 m²

Primary Energy Indicator: 470 kWh/m²/year

2: 13 June 2024 Appro 155 m² Main

Reference number: 3500-0674-0122-8296-1643

Type of assessment: RdSAP, existing dwelling

Approved Organisation: Elmhurst


Main heating and fuel: Electric underfloor heating

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£12,312	See your recommendations
Over 3 years you could save*	£354	report for more information

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (64)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band E (43)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Solar water heating	£4,000 - £6,000	£354.00
2 Solar photovoltaic (PV) panels	£3,500 - £5,500	£1440.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	★★★★☆	★★★ ☆
Roof	Pitched, insulated (assumed) Roof room(s), ceiling insulated	**** ****	★★★★☆ ★★★★☆
Floor	Solid, insulated (assumed)	_	_
Windows	Fully double glazed	****	★★★ ☆
Main heating	Electric underfloor heating	***	***
Main heating controls	Time and temperature zone control	****	****
Secondary heating	Room heaters, dual fuel (mineral and wood)	_	_
Hot water	Electric immersion, off-peak	***	***
Lighting	Low energy lighting in 95% of fixed outlets	****	****

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 80 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 12 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£10,650 over 3 years	£10,692 over 3 years	
Hot water	£1,089 over 3 years	£693 over 3 years	You could
Lighting	£573 over 3 years	£573 over 3 years	save £354
Total	£12,312	£11,958	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

December and ad management		Indicative cost	Typical saving	Rating after improvement		
RE	commended measures	Indicative cost	per year	Energy	Environment	
1	Solar water heating	£4,000 - £6,000	£118	D 66	(E 46	
2	Solar photovoltaic panels, 2.5 kWp	£3,500 - £5,500	£480	C 72	E 51	

Choosing the right improvement package



For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

2 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	19,367	N/A	N/A	N/A
Water heating (kWh per year)	2,303			

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Calum Riach
Assessor membership number: EES/018141

Company name/trading name:

D M Hall Chartered Surveyors LLP
Hope House Castlehill Drive

dress: Hope House Castlehill Drive Cradlehall Business Park

Cradlehall Busi Inverness IV2 5GH

Phone number: 0131 477 6000
Email address: dmhall@dmhall.co.uk
Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.





Property address	ELLEN-BRAE NETHYBRIDGE HIGHLANDS PH25 3DB
Seller(s) Completion date of property questionnaire	





Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1.	Length of ownership		4
	How long have you owned the property?		
2.	Council tax		
	Which Council Tax band is your property in? (Please tick)		
	A B C DW E F G H		
3.	Parking		
	What are the arrangements for parking at your property? (Please tick all that apply)		
	• Garage		
	Allocated parking space		
	• Driveway		
	Shared parking		
	On street		
	Resident permit		
	Metered parking		
	Other (please specify):		
4.	Conservation area		
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	Yes No Don't know	
5.	Listed buildings		104
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes No	
6.	Alterations/additions/extensions		
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes No	



	If you have answered yes, please describe below the changes which you have made:		
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	Yes No	
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property? If you have answered yes, please answer the three questions below:	Yes No	
	(i) Were the replacements the same shape and type as the ones you replaced?	Yes No	
	(ii) Did this work involve any changes to the window or door openings?	Yes No	
	(iii) Please describe the changes made to the windows doors, or approximate dates when the work was completed): Please give any guarantees which you received for this work to estate agent.		
7.	Central heating		
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).	Yes No Partial	
	If you have answered yes or partial – what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	electric	heating
	If you have answered yes, please answer the three questions below:		
	i) When was your central heating system or partial central		2003



	(ii) Do you have a maintenance contract for the central heating system?	Yes No	
	If you have answered yes, please give details of the company with which you have a maintenance contract:		
	(ili) When was your maintenance agreement last renewed? (Please provide the month and year).		
8.	Energy Performance Certificate		
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes No	
9.	Issues that may have affected your property		
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes No	
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	Yes No	
b.	Are you aware of the existence of asbestos in your property?		
	If you have answered yes, please give details:	Yes No	
I	I .	1	



10.	Services				
a. Ple supplie	ease tick which services a er:	re connected to your p	roperty and give d	letails of the	
Servi	ces	Connected	Supplier		
Gas o	r liquid petroleum gas				
	mains or private supply	1	Scottish	WATER	
Electr	ricity		Ovo		
Mains	drainage	/	Ніднимо	COVNCIL	
Telep	hone	/			
Cable	TV or satellite	V DISH	ALL ROOM	15 .1 KFTS	
Broad	iband	4			
			•		
b.	Is there a septic tank sys If you have answered ye below:			Yes No	
	(i) Do you have appropri your septic tank?	ate consents for the di	scharge from	Yes No Don't know	
	(ii) Do you have a mainte If you have answered ye with which you have a m	<u>s,</u> please give details o		Yes No	
11.	Responsibilities for share	ed or common areas			
a.	Are you aware of any resp anything used jointly, suc road, boundary, or garder If you have answered yes	ch as the repair of a sha n area?		Yes No Don't know	
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details:			Yes No Don't know	
C.	Has there been any major roof during the time you h			Yes No	



d.	Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries?	Yes No	
	If you have answered yes, please give details:		
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details:	Yes No	
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	Yes No	
	If you have answered yes, please give details:		
12.	Charges associated with your property		
a.	Is there a factor or property manager for your property?	Yes No	
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:		
b.	Is there a common buildings insurance policy?	Yes No	
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Don't know	
c.	Please give details of any other charges you have to pay on a regular upkeep of common areas or repair works, for example to a resident maintenance or stair fund.		or
13.	Specialist works		
а.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	Yes No	
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.		
	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	Yes No	
b.	If you have answered yes, please give details:		



C.	If you have answered yes to 13(a) or (b), or guarantees relating to this work? If you have answered yes, these guarantee purchaser and should be given to your sor possible for checking. If you do not have solicitor or estate agent will arrange for the will also need to provide a description of this may be shown in the original estimate. Guarantees are held by:	es will be dicitor as them you nem to be the work (needed soon as rself and obtained	your I. You	Yes No		
14.	Guarantees						
a.	Are there any guarantees or warranties fo	r any of tl	ne follow	ing:			
		No	Yes	Don't know	With title deeds	Lost	
(i)	Electrical work	Q					
(ii)	Roofing	V					
(iii)	Central heating	Ø					
(iv)	National House Building Council (NHBC)	Image: section of the sec					
(v)	Damp course	Ø					
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)						
b.	If you have answered 'yes' or 'with title de installations to which the guarantee(s) rel		se give (details of	the work or		
C.	Are there any outstanding claims under any of the guarantees listed above?				Yes No		
	If you have answered yes, please give details:				N/A		
15.	Boundaries						
	So far as you are aware, has any boundary of your property been moved in the last 10 years? If you have answered yes, please give details:				Yes No Don't know		
16.	Notices that affect your property						
	In the past three years have you ever received a notice:						
a.	advising that the owner of a neighbouring property has made a planning application?			Yes No			



b.	that affects your property in some other way?	Yes No	
C.	that requires you to do any maintenance, repairs or improvements to your property?	Yes No	
	If you have answered yes to any of a—c above, please give the no solicitor or estate agent, including any notices which arrive at ar date of entry of the purchaser of your property.		

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s):

Date:

