

Single Survey

survey report on:

Property address	Rouken Glen, 36 Balfour Road, Alford, AB33 8NF
-------------------------	---

Customer	Mr J Caron and Mrs F Caron
-----------------	----------------------------

Customer address	Rouken Glen, 36 Balfour Road, Alford, AB33 8NF
-------------------------	---

Prepared by	Allied Surveyors Scotland Ltd
--------------------	-------------------------------

Date of inspection	10th September 2026
---------------------------	---------------------



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box. ☒

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Terms and Conditions

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

Terms and Conditions

they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

Terms and Conditions

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

Terms and Conditions

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" *is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form* unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The property comprises a detached bungalow within grounds that extend to approximately 0.2 acres.
Accommodation	Summary of main accommodation within bungalow: 2 living rooms, 4 bedrooms, 2 bathrooms. Vestibule, hall, open plan living room/dining area, kitchen/dining room, utility room, bathroom, principal bedroom with ensuite shower room, 2 bedrooms, bedroom 4/snug.
Gross internal floor area (m²)	The gross internal floor area of the bungalow extends to approximately 135 square metres.
Neighbourhood and location	The property lies on a corner site at the junction of Balfour Road with Victoria Road and is otherwise adjoined on its west and south-west sides by the grounds of two residential properties. The area is primarily residential, though a butchers shop, small electricity sub-station and Ambulance/Police station are nearby. It is located near to the centre of Alford (population 2,700) which has a range of local shops, Medical and Dental Practices and a community campus on which there are nursery, primary and secondary schools, library and swimming pool. Major local centres of population and employment include: Inverurie (population 14,500) - 17 miles; Westhill (population 12,500) - 19 miles; Aberdeen City Centre - 26 miles.
Age	The bungalow is 35 years old, built in 1991 by Farquhar Homes.
Weather	The weather was dry and overcast during the inspection. The report should be read in context of these weather conditions.

Chimney stacks	Visually inspected with the aid of binoculars where appropriate. There is an external chimney stack at one side of the house. This is likely to be constructed with concrete blocks, is drydash rendered externally, has lead flashing around its junction with the bungalow roof, concrete coping and a clay pot fitted with a metal cowl.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. The roof is pitched and clad with concrete interlocking tiles. External roof detail includes: concrete ridge sections incorporating a dry ventilated ridge system; lead lined valley gutters at roof junctions; overhanging roof at gables and eaves with plywood fascias and soffits, some of the soffits have ventilation strips to provide roof space ventilation; plastic verge sections. A partial inspection of the roof space was made from a hatch in the passage ceiling, which is fitted with a fold-down timber ladder. The roof is formed with lightweight timber trusses, overlaid with plywood sarking. A part of the centre of the roof space was floored with chipboard, there was an average of 200mm of insulation between the joists (part glass wool, part sheep wool) and two pendant lights are fitted.
Rainwater fittings	Visually inspected with the aid of binoculars where appropriate. The rainwater fittings are brown plastic. Gutters are half round, deep flow and attached to the fascia boards. Downpipes are round and discharge into rainwater gullies.
Main walls	Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected. The bungalow is built with timber frame cavity construction with a load-bearing timber frame inner leaf and concrete block outer leaf. Externally most of the walls have a cement rendered base and above are covered with a drydash render. The exceptions are the front gable and the base of the front wall which are faced with decorative precast concrete blocks. The walls are approximately 300mm thick, including the internal wall lining.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. The windows and external doors are the original fittings. Windows are plastic framed double glazed casement windows. Most of the windows are of a good size and are single casements. Opening casements have tilt and turn mechanisms, with locks securing the turn opening operation. Glazing width is approximately 20mm. There are three external doors: (1) front door, into vestibule - solid timber door, with opaque double glazed side panel; (2) rear door, into utility room - timber door with opaque double glazed upper pane; (3) patio door, into dining area - aluminium framed double glazed sliding door, with fixed matching side panel.
External decorations	Visually inspected. The external joinery is painted/stained dark brown.
Conservatories / porches	There are no communal areas.
Communal areas	There are no communal areas.
Garages and permanent outbuildings	There are no garages or permanent outbuildings. The owners advised that foundations were laid for a single garage at the side of the house, but they opted not to proceed and these foundations were covered by a part of the tarred drive.
Outside areas and boundaries	Visually inspected. The property extends to approximately 0.2 acres. Boundaries include 700mm high drydash rendered concrete block walls along Balfour and Victoria Road and mostly timber fencing along its boundaries with the adjoining residential properties, except for a short section of hedge. Features of the grounds include: tarred drive; concrete slabbed path around the bungalow; rear gravel seating area; small timber shed at the rear of the drive with felt roof, supplied with electricity via underground cable; small timber garden shed at the rear with a pitched metal clad roof; garden laid out with lawns, shrub beds, some individual trees and some hedging around the rear perimeter.

Single Survey

Ceilings	Visually inspected from floor level. The ceilings are lined with plasterboard.
Internal walls	Visually inspected from floor level. Using a moisture meter, walls were randomly tested for dampness where considered appropriate. The internal walls are lined with plasterboard.
Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted. Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point. Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch. The floor is suspended timber and covered with chipboard. An inverted head and shoulders inspection of the sub-floor was made from a hatch at the front door. The sub-floor was approximately 500mm deep at that point, the solum is lined with concrete, the edges of a plastic damp proof membrane was visible and there was approximately 100mm of mineral wool insulation laid between the floor joists held up with netting. Sub-floor vents were noted through the external wall along three sides of the bungalow. At the time of the inspection, most floors were covered with fitted carpets or other floor coverings and the extent of the inspection of the floors was thus limited. Fixed floor coverings included: Pergo wood-effect flooring in the vestibule, hall and passage, living room/dining area; grey click board flooring in the kitchen/dining room and utility room; mosaic tile floor in the ensuite shower room.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved. Kitchen units were visually inspected excluding appliances. The kitchen and utility room were re-fitted around 14 years ago with a Laings of Inverurie kitchen. It has a range of gloss off-white faced units, grey patterned laminate worktops with glass wall splash tiling above. Built-in appliances include an oven with slide under door and an induction hob with extractor hood above. The utility room is fitted with the same units and laminate worktop as the kitchen. It has along one side a sink unit and section of laminate worktop and along the end wall a row of 4 wall units. The majority of the internal doors are flush timber doors. There are three timber framed opaque glazed doors off the hall and one

Single Survey

Internal joinery and kitchen fittings	between the kitchen and dining area (the latter narrow at 720mm wide).
Chimney breasts and fireplaces	Visually inspected. No testing of the flues or fittings was carried out. In the living room is a wood-burning stove inset into the chimney breast with a polished black granite hearth; this was installed in 2010. A plaque with safety information about the installation of the flue is mounted within a cupboard off the hall.
Internal decorations	Visually inspected. The majority of the internal linings are painted plasterboard. Several of the ceilings have patterned textured plaster.
Cellars	There are no cellars.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. The property is supplied with mains electricity. An underground mains cable is taken to an external meter box inset into the side wall of the bungalow. The consumer unit is within a cupboard off the hall; this includes the main switch and circuit breakers (which switch off a circuit if they detect a fault). A small consumer unit has been added on the same board for the photovoltaic panels, which includes a main switch, a residual current device (a switch that trips a circuit under dangerous conditions and disconnects the electricity) and circuit breakers. Sockets within the house are 13 amp rectangular pinned sockets. Sockets and light switch face plates in the kitchen are metal. There are 16 No 250W photovoltaic panels mounted on the south roof face of the bungalow, which have a maximum electricity output of 4.0kW. The inverter (which converts DC electricity to AC) is located within the roof space. The electricity generated by the panels can supply the property, with the surplus exported to the National Grid, for which feed-in tariff payments are made by an electricity supplier; the owners advised that recent annual feed-in-tariff payments have averaged £900-£1,000 per year.

Single Survey

Gas	Mains gas is not available to the property.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances. The property is supplied with mains water. There is a pipe loop within a cupboard off the hall, which is fitted with a stop-cock. The water system within the house is pressurised off a combination boiler - there are no cold and hot water storage tanks. The water pipework inspected within the house was copper. There are two bathrooms: (1) main bathroom - original fittings, light grey 3 piece suite, above the bath are tiled walls, an electric shower and glazed screen along the bath edge, chrome towel radiator, ceiling mechanical extract fan above the shower; (2) principal bedroom ensuite shower room - re-fitted, laminate cubicle with glazed door and mixer shower, w.c, hand basin, chrome towel radiator and ceiling mechanical extract fan above the shower. Sinks include a stainless steel sink in the kitchen and a stainless steel sink in the utility room with a large bowl. The owners advised that one of the cupboards off the hall has been made large enough to accommodate a w.c, should this be required in the future.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances. The house is heated by an oil central heating system from a Worcester Greenstar Heatslave 18/25 combination boiler, floor mounted in the utility room and fitted with a balanced flue through the external wall. It is understood that the boiler was installed in 2007. Behind the boiler the wall is lined with a fireboard of unknown material. Oil is supplied from a 1,300 litre bunded plastic tank within the rear garden, within a concrete block bund and mounted on concrete block piers and flags. The heating system is a wet system, via modern panel radiators. The system is controlled by a programmer in the utility room and by thermostatically controlled valves fitted to the radiators. There is a tall grey column radiator in the kitchen. Hot water is provided directly by the combination boiler.
Drainage	Drainage covers etc were not lifted. Neither drains nor drainage systems were tested. Drainage is understood to be connected to the main sewer. Drainage covers have not been lifted and neither the drains, nor any part of the drainage system have been tested.

Single Survey

Fire, smoke and burglar alarms	Visually inspected. No tests whatsoever were carried out to the system or appliances. Ceiling mounted detectors/alarms have been fitted as follows: smoke alarms in the hall and living room; heat detector in the kitchen; carbon monoxide detectors in the living room and utility room.
Any additional limits to inspection	The inspection was limited by the presence of fitted floor coverings, furnishings and personal effects within the property. Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

Single Survey

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.



Structural movement

Repair category	1
Notes	No evidence of settlement or structural movement was found affecting the building.



Dampness, rot and infestation

Repair category	1
Notes	Damp meter readings were taken at appropriate locations throughout the bungalow but no evidence of dampness was encountered. From a limited inspection that was possible of the structural timberwork within the house, no sign of decay or infestation was noted.



Chimney stacks

Repair category	1
Notes	From a ground level inspection of the chimney stack, no significant defects were noted.



Roofing including roof space

Repair category	1
Notes	No significant defects were noted to the roof exterior and to those parts of the roof space which were inspected. A small piece of roof tile was visible in the front valley gutter. The tiles below the photovoltaic panels could not be inspected. Ongoing roof maintenance will be required, including keeping valley gutters clear of debris and monitoring the condition of the roof tiles, metal flashings/valleys, and timber fascias and soffits. It is particularly important to regularly paint the plywood fascias and soffits (and repair where necessary) to preserve their integrity.



Roofing including roof space

Repair category	1
Notes	Concrete tiles are typically guaranteed for 30 years but have a reasonable life expectation around 50/60 years according to the Building Research Establishment. Life expectancy will often depend on their quality, weathering and damage from the prevailing weather. A roofing contractor will be able to advise on life expectancy and repair/replacement costs.



Rainwater fittings

Repair category	1
Notes	No significant defects were noted to the rainwater fittings. No assessment has been made on the operation and effectiveness of the rainwater system, including the drainage from the base of the downpipes. Plastic guttering can be susceptible to damage in periods of heavy snowfall or build up of ice in sub-zero temperatures.



Main walls

Repair category	1
Notes	No significant defects were noted to the main walls.



Windows, external doors and joinery

Repair category	1
Notes	No significant defects were noted to the windows and external doors. A selection of opening window casements and both the front and rear doors were opened and found to operate effectively. The windows are the original fittings and therefore 35 years old. At the inspection no internal condensation was noted within the double glazed casements. However, they are of an age where a degree of ongoing maintenance should be anticipated to the sealed units and opening mechanisms.



External decorations

Repair category	1
Notes	The decoration of the external joinery was found to be in good condition. All window frames are low maintenance plastic.



Conservatories/porches

Repair category	-
Notes	None.



Communal areas

Repair category	-
Notes	None.



Garages and permanent outbuildings

Repair category	-
Notes	None.



Outside areas and boundaries

Repair category	2
Notes	The driveway, hard-landscaped areas and garden ground have been well maintained and were found to be in a neat and tidy condition. Several cracks were noted through the external face of the drydash rendered concrete block boundary wall, with areas of adjoining bossed render.



Ceilings

Repair category	1
Notes	No significant defects were noted to the ceilings.



Internal walls

Repair category	1
Notes	No significant defects were noted to the internal wall linings.



Floors including sub-floors

Repair category	1
Notes	From the limited extent of the inspection that was possible of the floor and sub-floor, no defects were noted.



Internal joinery and kitchen fittings

Repair category	1
Notes	The fittings in the kitchen and utility room were found to be in good condition. No assessment has been made on the condition of the built-in kitchen appliances. The skirtings, facings and internal doors were found to be in good condition. The internal door glazing should be checked to assess whether it meets current building standards, which are that it must resist human impact and be safety glass.



Chimney breasts and fireplaces

Repair category	1
Notes	No defects were noted to the living room stove. No assessment has been made on the operation of the stove and whether its flue is adequately lined. It should be ensured that the flue is kept in a sound condition and is regularly checked and swept.



Internal decorations

Repair category	1
Notes	The internal decoration was found to be in good condition, with only minor wear and tear markings.



Cellars

Repair category	-
Notes	None.



Electricity

Repair category	1
Notes	No significant defects were noted to the visible parts of the electrical installation



Electricity

Repair category	1
Notes	that were inspected. It is recommended good practice that all electrical installations should be checked periodically by a qualified electrician, approximately every 10 years or when a property changes hands; this should be regarded as a routine safety and maintenance check. No assessment has been made on the condition and operation of the photovoltaic panels. The owners advised that the inverter was replaced in 2021.



Gas

Repair category	-
Notes	None.



Water, plumbing and bathroom fittings

Repair category	1
Notes	No significant defects were noted to the visible parts of the plumbing system that were inspected. The sanitary fittings in the two bathrooms were found to be in good condition. Concealed areas around baths and shower trays cannot be inspected; water spillage over a period of time can result in unexpected defects to hidden parts of the building fabric.



Heating and hot water

Repair category	1
Notes	No significant defects were noted to the visible parts of the central heating system that were inspected. The central heating boiler and system (including the oil tank), should be serviced annually by a qualified heating engineer to ensure its safe and efficient operation. The owners advise that they have a maintenance contract for the heating/hot water system. No assessment has been made on the operation, efficiency and adequacy of the central heating system. The combination boiler is relatively old at 19 years and, notwithstanding that it has been well maintained and serviced, may have a limited life.

Single Survey



Drainage

Repair category	1
Notes	No problems with the drainage were visible during the inspection. No assessment has been made on the size, capacity, condition and operation of the drainage system.

Single Survey

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	-
Outside areas and boundaries	2
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	-
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground	
2. Are there three steps or fewer to a main entrance door of the property?	Yes ☒	No ☐
3. Is there a lift to the main entrance door of the property?	Yes ☐	No ☒
4. Are all door openings greater than 750mm?	Yes ☐	No ☒
5. Is there a toilet on the same level as the living room and kitchen?	Yes ☒	No ☐
6. Is there a toilet on the same level as a bedroom?	Yes ☒	No ☐
7. Are all rooms on the same level with no internal steps or stairs?	Yes ☒	No ☐
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes ☒	No ☐

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The tenure is understood to be outright ownership. The titles have not been checked by the surveyor. It is assumed that there are no unduly onerous provisions in the title documents and management/service charge agreements. If the legal advisers find that there are significant variations from the standard assumptions then this should be referred back to the surveyor.

It is specifically assumed that the property and its value are unaffected by any matters which would, or should be revealed to a competent completing solicitor or by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

Estimated reinstatement cost for insurance purposes

This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a reinstatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during reconstruction and no allowance has been made for VAT, other than on professional fees. Further discussion with your insurers is advised.

£410,000 (Four Hundred and Ten Thousand Pounds)

Building costs are currently increasing significantly above inflation due to material and labour shortages as well as Brexit, the Pandemic, the wars in Ukraine and the Middle East, and world- wide trade upheavals. It is recommended that this figure be regularly updated to ensure that there is adequate cover or alternatively seek specialist advice from your insurer.

Valuation and market comments

In its present condition, it is our opinion that the market value of the heritable interest in the property with the benefit of vacant possession and as at the date of our inspection, is:

£315,000 (Three Hundred and Fifteen Thousand Pounds)

Our valuation has fully taken into account the prevailing market conditions.

Signed

Security Print Code [464294 = 8313]
Electronically signed

Report author

David Silcocks

Company name

Allied Surveyors Scotland Ltd

Address

Marywell House, 29-31 Marywell Street, Aberdeen, AB11 6JE

Single Survey

Date of report	17th September 2026
----------------	---------------------

Mortgage Valuation Report



Property Address

Address Rouken Glen, 36 Balfour Road, Alford, AB33 8NF
Seller's Name Mr J Caron and Mrs F Caron
Date of Inspection 10th September 2026

Property Details

Property Type ☐ House ☒ Bungalow ☐ Chalet ☐ Purpose built maisonette
☐ Coach ☐ Studio ☐ Converted maisonette ☐ Purpose built flat
☐ Converted flat ☐ Tenement flat ☐ Flat over non-residential use ☐ Other (specify in General Remarks)

Property Style ☒ Detached ☐ Semi detached ☐ Mid terrace ☐ End terrace
☐ Back to back ☐ High rise block ☐ Low rise block ☐ Other (specify in General Remarks)

Does the surveyor believe that the property was built for the public sector, e.g. local authority, military, police?

☐ Yes ☒ No

Flats/Maisonettes only Floor(s) on which located No. of floors in block Lift provided? ☐ Yes ☐ No
No. of units in block

Approximate Year of Construction

Tenure

☒ Absolute Ownership ☐ Leasehold Ground rent £ Unexpired years

Accommodation

Number of Rooms Living room(s) Bedroom(s) Kitchen(s)
 Bathroom(s) WC(s) Other (Specify in General remarks)

Gross Floor Area (excluding garages and outbuildings) m² (Internal) m² (External)

Residential Element (greater than 40%) ☒ Yes ☐ No

Garage / Parking / Outbuildings

☐ Single garage ☐ Double garage ☒ Parking space ☐ No garage / garage space / parking space
Available on site? ☒ Yes ☐ No

Permanent outbuildings:

There are no permanent outbuildings.

Mortgage Valuation Report

Construction

Walls ☐ Brick ☐ Stone ☐ Concrete ☒ Timber frame
☐ Solid ☐ Cavity ☐ Steel frame ☐ Concrete block ☐ Other (specify in General Remarks)

Roof ☒ Tile ☐ Slate ☐ Asphalt ☐ Felt
☐ Lead ☐ Zinc ☐ Artificial slate ☐ Flat glass fibre ☐ Other (specify in General Remarks)

Special Risks

Has the property suffered structural movement? ☐ Yes ☒ No

If Yes, is this recent or progressive? ☐ Yes ☐ No

Is there evidence, history, or reason to anticipate subsidence, heave, landslip or flood in the immediate vicinity? ☐ Yes ☒ No

If Yes to any of the above, provide details in General Remarks.

Service Connection

Based on visual inspection only. If any services appear to be non-mains, please comment on the type and location of the supply in General Remarks.

Drainage ☒ Mains ☐ Private ☐ None Water ☒ Mains ☐ Private ☐ None
Electricity ☒ Mains ☐ Private ☐ None Gas ☐ Mains ☐ Private ☒ None
Central Heating ☒ Yes ☐ Partial ☐ None

Brief description of Central Heating:

Full oil fired central heating from a combination boiler, via a wet radiator system, controlled by a programmer and radiator thermostatically controlled valves.

Site

Apparent legal issues to be verified by the conveyancer. Please provide a brief description in General Remarks.

☐ Rights of way ☐ Shared drives / access ☐ Garage or other amenities on separate site ☐ Shared service connections
☐ Agricultural land included with property ☐ Ill-defined boundaries ☐ Other (specify in General Remarks)

Location

☐ Residential suburb ☐ Residential within town / city ☐ Mixed residential / commercial ☐ Mainly commercial
☒ Commuter village ☐ Remote village ☐ Isolated rural property ☐ Other (specify in General Remarks)

Planning Issues

Has the property been extended / converted / altered? ☐ Yes ☒ No

If Yes provide details in General Remarks.

Roads

☐ Made up road ☐ Unmade road ☐ Partly completed new road ☐ Pedestrian access only ☒ Adopted ☐ Unadopted

Mortgage Valuation Report

General Remarks

Other accommodation referred to above includes a utility room.

The property lies on a corner site at the junction of Balfour Road with Victoria Road and is otherwise adjoined on its west and south-west sides by the grounds of two residential properties. The area is primarily residential, though a butchers shop, small electricity sub-station and Ambulance/Police station are nearby. It is located near to the centre of Alford (population 2,700) which has a range of local shops, Medical and Dental Practices and a community campus on which there are nursery, primary and secondary schools, library and swimming pool. Major local centres of population and employment include: Inverurie (population 14,500) - 17 miles; Westhill (population 12,500) - 19 miles; Aberdeen City Centre - 26 miles.

Significant factors which are likely to be relevant to the market value of the property include: 1) LOCATION: within commuting distance of Inverurie, Westhill and Aberdeen; positioned within the heart of the village with most amenities within walking distance. 2) SETTING: within relatively quiet residential street. 3) HOUSE TYPE, DESIGN AND SIZE: 35 year old bungalow with 6 habitable rooms, including a substantial open plan living room/dining area, 2 bathrooms and an internal floor area of approximately 135 square metres. 4) CONDITION AND REPAIR: (a) External - well maintained and in good condition, windows, external doors and facias and soffits are original fittings and appeared to be in sound condition - some ongoing maintenance is likely given their age; (b) Internal - in good condition, no significant defects noted. 5) STANDARD AND CONDITION OF FITTINGS: most internal fittings upgraded to a contemporary modern standard including kitchen, utility room, ensuite shower room, living room stove; main bathroom original fittings but perfectly functional. 6) BUILDINGS: No garage or permanent outbuildings. 7) LAND: good sized corner plot of around 0.2 acres, maintained to a good standard. 8) CURRENT MARKET CONDITIONS: In the aftermath of the initial Covid-19 lock-down period from July 2020 onwards, local rural residential market activity increased significantly, with this leading to shorter marketing periods and an increase in prices. However, from mid-2022 the residential property market generally experienced more difficult conditions caused by rising interest rates, inflation and the cost of living, and property taxes (Land Business Transaction Tax and Additional Dwelling Supplement). These conditions extended through 2023-25, although interest rates were steadily reduced during this period from a peak in August 2023. During this period there was at best little change in local rural residential property prices and most sectors saw a small reduction in prices; properties which have special features have fared better, such features might include location, view, setting, design and character, condition and repair, standard of fitting, size and quality of the grounds and its outbuildings. 2026 has brought further uncertainty to the property market caused by the war in the Middle East, which has led to a period of rising prices and cost of living and continued relatively high interest rates.

Essential Repairs

No essential repairs are required to the property.

Estimated cost of essential repairs £

Retention recommended? ☐ Yes ☒ No

Amount £

Mortgage Valuation Report

Comment on Mortgageability

The property is considered to be suitable security for mortgage purposes, subject to the specific lending criteria of the mortgage provider.

Valuations

Market value in present condition £ 315,000

Market value on completion of essential repairs £

Insurance reinstatement value £ 410,000
(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)

Is a reinspection necessary? ☐ Yes ☒ No

Buy To Let Cases

What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis? £

Is the property in an area where there is a steady demand for rented accommodation of this type? ☐ Yes ☐ No

Declaration

Signed Security Print Code [464294 = 8313]
Electronically signed by:-

Surveyor's name David Silcocks

Professional qualifications BSc, MRICS

Company name Allied Surveyors Scotland Ltd

Address Marywell House, 29-31 Marywell Street, Aberdeen, AB11 6JE

Telephone 01224 571163

Fax 01224 589042

Report date 17th September 2026

Energy Performance Certificate (EPC)

Scotland

Dwellings

ROUKEN GLEN, 36 BALFOUR ROAD, ALFORD, AB33 8NF

Dwelling type: Detached bungalow
Date of assessment: 10 September 2026
Date of certificate: 12 September 2026
Total floor area: 135 m²
Primary Energy Indicator: 163 kWh/m²/year

Reference number: 0100-2630-9210-2596-4475
Type of assessment: RdSAP, existing dwelling
Approved Organisation: Elmhurst
Main heating and fuel: Boiler and radiators, oil


You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£4,962	See your recommendations report for more information
Over 3 years you could save*	£396	

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions

Very energy efficient - lower running costs



Not energy efficient - higher running costs

Current	Potential
81	84


Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band B (81)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Very environmentally friendly - lower CO₂ emissions



Not environmentally friendly - higher CO₂ emissions

Current	Potential
65	68

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO₂) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (65)**

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Heating controls (room thermostat)	£220 - £250	£213.00
2 Replacement glazing units	£4,500 - £6,000	£177.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction. See the addendum section on the last page of this report for further information relating to items in the table.

Element	Description	Energy Efficiency	Environmental
Walls	Timber frame, as built, insulated (assumed)	★★★★☆	★★★★☆
Roof	Pitched, 200 mm loft insulation	★★★★☆	★★★★☆
Floor	Suspended, insulated	—	—
Windows	Fully double glazed	★★☆☆☆	★★☆☆☆
Main heating	Boiler and radiators, oil	★★★☆☆	★★★☆☆
Main heating controls	Programmer, TRVs and bypass	★★★☆☆	★★★☆☆
Secondary heating	None	—	—
Hot water	From main system	★★★☆☆	★★★☆☆
Lighting	Good lighting efficiency	★★★★☆	★★★★☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 42 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 5.6 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.5 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.




Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£3,528 over 3 years	£3,132 over 3 years	
Hot water	£1,221 over 3 years	£1,221 over 3 years	
Lighting	£213 over 3 years	£213 over 3 years	
Totals	£4,962	£4,566	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures	Indicative cost	Typical saving per year	Rating after improvement	
			Energy	Environment
1 Upgrade heating controls	£220 - £250	£71		
2 Replacement glazing units	£4,500 - £6,000	£59		

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

2 Replacement glazing units

Replacing existing double-glazed units with new high-performance units. Building regulations require that replacement glazing is to a standard no worse than previous; a building warrant is not required. Planning permission might be required for such work if a building is listed or within a conservation area so it is best to check with your local authority.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present:

- Solar photovoltaics

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	12,749.99	N/A	N/A	N/A
Water heating (kWh per year)	4,108.67			

Addendum

The assessment does not include any feed-in tariffs that may be applicable to this property.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. David Silcocks
Assessor membership number:	EES/008466
Company name/trading name:	Allied Surveyors Scotland Ltd
Address:	Marywell House 29-31 Marywell Street Aberdeen AB11 6JE
Phone number:	01224 571163
Email address:	aberdeen@alliedsurveyorsscotland.com
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



Property Questionnaire

PROPERTY ADDRESS: ROUKEN GLEN 36 BALFOUR RD. ALFORD ABERDEENSH AB33 8NF
--

SELLER(S): 	JEAN CARON AND FLORA MCKEAN CARON
--------------------	--------------------------------------

COMPLETION DATE OF PROPERTY QUESTIONNAIRE:

☐ PROPERTY QUESTIONNAIRE

NOTE FOR SELLERS

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the Date of Entry for the sale of your house, tell your solicitor or estate agent immediately.

☐

PROPERTY QUESTIONNAIRE Information to be given to prospective buyer(s)

1. Length of ownership	35 yrs

How long have you owned the property?	35 yrs
2. Council Tax	301.00
Which Council Tax band is your property in? A B C D <u>E</u> F G H	per month
3. Parking	
What are the arrangements for parking at your property? (Please indicate all that apply) • Garage • Allocated parking space • Driveway • Shared parking • On street • Resident permit • Metered parking • Other (please specify):	
4. Conservation Area	N/A
Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)?	Yes/No/D not know
5. Listed Buildings	
Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)?	Yes/No
6. Alterations / additions / extensions	
a. (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	Yes/No

<u>If you have answered yes</u>, please describe the changes which you have made:	N/A
(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	Yes/No
<u>If you have answered yes</u>, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent can arrange to obtain them.	
b. Have you had replacement windows, doors, patio doors or double glazing installed in your property? <u>If you have answered yes</u>, please answer the three questions below:	Yes/No
(i) Were the replacements the same shape and type as the ones you replaced?	Yes/No
(ii) Did this work involve any changes to the window or door openings?	Yes/No
(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):	

Please give any guarantees which you received for this work to your solicitor or estate agent.	
7. Central heating	✓

a. Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom). <u>If you have answered yes/partial – what kind of central heating is there?</u> (Examples: gas-fired, solid fuel, electric storage heating, gas warm air.) <u>If you have answered yes, please answer the 3 questions below:</u>	Yes/No/ Partial Oil
b. When was your central heating system or partial central heating system installed?	original 1991 present 2007
c. Do you have a maintenance contract for the central heating system? <u>If you have answered yes, please give details of the company with which you have a maintenance agreement:</u> DOMESTIC AND GENERAL WORCESTER BOSCH £53.03 PER MONTH	Yes/No
d. When was your maintenance agreement last renewed? (Please provide the month and year). 28/03/2026	
8. Energy Performance Certificate	
Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes/No
9. Issues that may have affected your property	
a. Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	Yes/No
<u>If you have answered yes, is the damage the subject of any outstanding insurance claim?</u>	Yes/No
b. Are you aware of the existence of asbestos in your property?	Yes/No

If you have answered yes, please give details:			
10. Services			
a. Please tick which services are connected to your property and give details of the supplier:			
Services	Connected	Supplier	
Gas / liquid petroleum gas			
Water mains / private water supply	✓		
Electricity	✓	BRITISH GAS	
Mains drainage	✓		
Telephone	no		
Cable TV / satellite	✓		
Broadband	YES	E. E.	
b. Is there a septic tank system at your property?			Yes /No
If you have answered yes, please answer the two questions below:			
c. Do you have appropriate consents for the discharge from your septic tank?			Yes/No/ Don't Know
d. Do you have a maintenance contract for your septic tank?			Yes/No
If you have answered yes, please give details of the company with which you have a maintenance contract:			
11. Responsibilities for Shared or Common Areas			

☐

a. Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?	Yes /No/ Don't Know
--	--

	<u>If you have answered yes</u>, please give details:	N/A
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? <u>If you have answered yes</u>, please give details:	Yes/No/ Not applicable N/A
c.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	Yes /No
d.	Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries? <u>If you have answered yes</u>, please give details:	Yes /No
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? <u>If you have answered yes</u>, please give details:	Yes /No
f.	As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.) <u>If you have answered yes</u>, please give details:	Yes /No
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property? <u>If you have answered yes</u>, please provide the name and address and give details of any	Yes /No

	deposit held and approximate charges:	
b.	Is there a common buildings insurance policy?	Yes /No/ Don't know
	<u>If you have answered yes</u> , is the cost of the insurance included in your monthly/annual factor's charges?	Yes/No/ Don't know
c.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, e.g. to a Residents' Association, or maintenance or stair fund.	
13. Specialist Works		
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? <u>If you have answered yes</u> , please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property	Yes/No
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? <u>If you have answered yes</u> , please give details	Yes/No
c.	<u>If you have answered yes</u> to 13(a) or (b), do you have any guarantees relating to this work?	Yes/No


If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:						
14. Guarantees						
a. Are there any guarantees or warranties for any of the following:						
(i)	Electrical work	No	Yes	Don't Know	With title deeds	Lost
(ii)	Roofing	No	Yes	Don't Know	With title deeds	Lost
(iii)	Central heating	No	Yes	Don't know	With title deeds	Lost
(iv)	NHBC	No	Yes	Don't know	With title deeds	Lost
(v)	Damp course	No	Yes	Don't know	With title deeds	Lost
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	No	Yes	Don't know	With title deeds	Lost
b. If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):						
c. Are there any outstanding claims under any of the guarantees listed above? If you have answered yes, please give details:					Yes/No	
15. Boundaries						

So far as you are aware, has any boundary of your property been moved in the last 10 years? <u>If you have answered yes, please give details:</u>	Yes/No/ Don't know
16. Notices that affect your property	
In the past 3 years have you ever received a notice:	
a. advising that the owner of a neighbouring property has made a planning application?	Yes/No/ Don't know
b. that affects your property in some other way?	Yes/No/ Don't know
c. that requires you to do any maintenance, repairs or improvements to your property?	Yes/No/ Don't know
<u>If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.</u>	

Declaration by the seller(s)/or other authorised body or person(s):

I / We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) :

.....


Date: 9th of Sept 2026

