

YOUR ONESURVEY  
**HOME REPORT**

---

ADDRESS

---

Flat 0/2  
234 Bearsden Road  
Glasgow  
G13 1LA

PREPARED FOR

---

Alasdair Keane

INSPECTION CARRIED OUT BY:



SELLING AGENT:

**YATES  
HELLIER**

HOME REPORT GENERATED BY:



# Document Index

Document	Status	Prepared By	Prepared On
Single Survey	Final	Glasgow North - Allied Surveyors Scotland Ltd	26/01/2026
Mortgage Certificate	Final	Glasgow North - Allied Surveyors Scotland Ltd	26/01/2026
Property Questionnaire	Final	Mr. Alasdair Keane	21/01/2026
EPC	FileUploaded	Glasgow North - Allied Surveyors Scotland Ltd	23/01/2026
Additional Documents	Final		

## Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto [www.onesurvey.org](http://www.onesurvey.org) (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.**

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

P A R T 1 .

# SINGLE SURVEY

---

A report on the condition of the property, with categories being rated from 1 to 3.



# Single Survey

Survey report on:

<b>Surveyor Reference</b>	GG/1951
---------------------------	---------

<b>Customer</b>	Mr. Alasdair Keane
-----------------	--------------------

<b>Selling address</b>	Flat 0/2 234 Bearsden Road Glasgow G13 1LA
------------------------	-----------------------------------------------------

<b>Date of Inspection</b>	22/01/2026
---------------------------	------------

<b>Prepared by</b>	Gary Haggarty, BSc (Hons) MRICS Glasgow North - Allied Surveyors Scotland Ltd
--------------------	----------------------------------------------------------------------------------

# SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

## PART 1 - GENERAL

### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property.<sup>1</sup>

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

---

<sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

### **1.3 LIABILITY**

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### **1.4 GENERIC MORTGAGE VALUATION REPORT**

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### **1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES**

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

#### **1.6 INTELLECTUAL PROPERTY**

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### **1.7 PAYMENT**

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### **1.8 CANCELLATION**

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

## **1.9 PRECEDENCE**

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

## **1.10 DEFINITIONS**

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is *The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion*
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

---

<sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the “Surveyors” are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the “Surveyors” means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

## **PART 2 – DESCRIPTION OF THE REPORT**

### **2.1 THE SERVICE**

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

### **2.2 THE INSPECTION**

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller’s permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

### **2.3 THE REPORT**

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor’s opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

2.3.1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

2.3.2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.

2.3.3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

## 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

## 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

## 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

## 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

*"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an*

*arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion.* In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- \*There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- \*There are no particularly troublesome or unusual legal restrictions;
- \*There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

*“Re-instatement cost” is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated.* This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

## 1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The property is a private, purpose-built flat located on the ground floor of a three-storey block containing six flats.
Accommodation	The property layout consists of a hallway, living room, internal kitchen, bedroom, and an internal bathroom.
Gross internal floor area (m <sup>2</sup> )	The gross internal floor area of the property is approximately 40m <sup>2</sup> .
Neighbourhood and location	The property is situated in Anniesland, a predominantly residential area characterised by a mix of property types, including flats and traditional houses. The neighbourhood benefits from convenient access to local amenities, which are located nearby. Anniesland is well-served by public transport links, providing straightforward connections to surrounding areas.
Age	The property is approximately 130 years old.
Weather	At the time of the inspection, the weather conditions were dry.
Chimney stacks	The chimney stacks at the property are constructed from render and brick, with lead flashing present. They were visually inspected.
Roofing including roof space	The main roof is of pitched construction and is finished with concrete tiles. No roof void access was possible. Sloping roofs were visually inspected with the aid of binoculars where required.  Roofs are prone to water penetration during adverse weather but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms.
Rainwater fittings	The rainwater fittings at the property comprise alloy and uPVC gutters, with downpipes constructed from both cast iron and uPVC.  Visually inspected.


Main walls	<p>The main walls of the property are of solid sandstone masonry construction, lathed and plastered internally. Fresh air ventilation is provided. The damp proof course isn't visible, but is assumed to be slate.</p> <p>The walls were visually inspected. Foundations and concealed parts were not exposed or inspected.</p>
Windows, external doors and joinery	<p>The property is fitted with replacement windows constructed from uPVC, featuring double glazing to the rear and triple glazing to the front. The entrance door is timber.</p> <p>Random windows were opened and closed where possible. Internal and external doors were opened and closed where keys were available.</p> <p>Visually inspected.</p>
External decorations	<p>The external decorations at the property consist of painted surfaces, joinery, and metalwork. These external decorations were visually inspected.</p>
Conservatories / porches	<p>Not applicable.</p>
Communal areas	<p>There is a shared entrance and staircase giving access to all floors, via a voice controlled security door entry system.</p> <p>Circulation areas visually inspected.</p>
Garages and permanent outbuildings	<p>Not applicable.</p>
Outside areas and boundaries	<p>A small area of private garden ground is available to the front, with communal gardens to the rear, suitably bounded.</p>
Ceilings	<p>The ceilings within the property are constructed from lath and plaster, plasterboard, and panelling. These materials were visually inspected during the assessment.</p>
Internal walls	<p>The internal walls in the property are plastered on the hard and constructed with plasterboard. The inspection method used was visually inspected.</p>
Floors including sub floors	<p>The property contains suspended timber flooring. There is accessible no sub-floor space.</p> <p>Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.</p> <p>Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.</p>
Internal joinery and kitchen fittings	<p>The internal joinery within the property incorporates timber doors, skirtings, and facings. The kitchen fittings include modern fitted wall units, base units, work surfaces, and a stainless steel sink. All materials were visually inspected, and no stored items were moved during the inspection.</p>

Chimney breasts and fireplaces	The property contains a chimney breast with an open fireplace located in the living room. The fireplace is vented but is not currently in use. Remaining fireplaces have been sealed without provision for ventilation. Visually inspected. No testing of the flues or fittings was carried out.
Internal decorations	The internal decorations of the property include papered and painted finishes. All materials were visually inspected.
Cellars	Not applicable.
Electricity	<p>The property is supplied with mains electricity, with the main supply located in the hall cupboard. The wiring within the property is of mixed age and is covered in PVC. Circuit breakers are installed as protection devices for the electrical system.</p> <p>Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.</p> <p>Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.</p> <p>It is recommended good practice that all electrical installations should be checked periodically, approximately every ten years or when a property changes hands. This should be regarded as a routine safety and maintenance check.</p> <p>The electrics were visually inspected.</p>
Gas	<p>The property is supplied with gas from the mains. The inspection method for the gas supply involved no tests.</p> <p>Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on. All gas appliances should be tested and thereafter regularly maintained by a Gas Safe registered contractor.</p>
Water, plumbing and bathroom fittings	<p>The property is supplied with mains water, and the plumbing system comprises PVC pipework of mixed age. The bathroom fittings include a WC, wash-hand basin, and bath. No tests were carried out on the water supply or plumbing system.</p> <p>Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances, Concealed areas around baths and shower trays cannot be inspected however water spillage over a period of time can result in unexpected defects to hidden parts of the building fabric.</p>

<p>Heating and hot water</p>	<p>The property is provided with full gas-fired central heating, delivered via a condensing boiler. Radiators are installed to distribute heat throughout the property. Hot water is supplied directly from the main heating system, with no separate hot water tank present.</p> <p>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. No tests whatsoever were carried out to the system or appliances.</p> <p>It is recommended good practice that gas boilers are serviced on an annual basis by an appropriately qualified person. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person.</p>
<p>Drainage</p>	<p>The property is served by mains drainage, discharging to a main sewer. The drainage system was visually inspected. Drainage covers etc. were not lifted. Neither drains nor drainage systems were tested.</p>
<p>Fire, smoke and burglar alarms</p>	<p>Smoke alarms and burglar alarms are present within the property. These alarms were inspected visually during the survey.</p> <p>No test whatsoever were carried out to any systems or appliances.</p> <p>There is now a requirement in place for compliant interlinked fire, smoke and heat detectors in residential properties. The new fire smoke and alarm standard came into force in Scotland in February 2022, requiring a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also requires to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon fuelled appliance such as a boiler, open fire or wood burner etc. a carbon monoxide detector is also required.</p> <p>The surveyor will only comment on the presence of a smoke detector etc. but will not test them, ascertain if they are in working order, interlinked and / or fully compliant with the fire and smoke alarm standard that was introduced in 2022.</p> <p>We have for the purposes of the report, assumed the system is fully compliant, if not then the appropriate compliant system will required to be installed prior to sale. This of course should be confirmed by your legal advisor.</p>

<p>Any additional limits to inspection</p>	<p>On the day of inspection, the property was occupied, fully furnished, and floors fully covered.</p> <p>Only the subject flat and internal communal areas giving access to the flat were inspected.</p> <p>If the roof space or under-building / basement is communal, reasonable and safe access is not always possible.</p> <p>If no inspection was possible, this will be stated. If no inspection was possible, the Surveyor will assume that there are no defects that will have a material effect on the valuation.</p> <p>The building containing the flat, including any external communal areas, was visually inspected only to the extent that the Surveyor is able to give an opinion on the general condition and standard of maintenance.</p> <p>An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property.</p> <p>Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.</p>
--------------------------------------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

## Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

## 2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the above 3 categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category:	1
Notes:	The property has incurred a degree of structural movement in the past. This is evidenced externally by distortion to stonework and internally by off level floors. On the date of inspection, this movement appeared to be of a longstanding nature with no obvious evidence of recent or continuing deterioration, although on the basis of a single inspection, no assurances can be given as to the future.

Dampness, rot and infestation	
Repair category:	2
Notes:	Localised areas of rising dampness were noted, typical of a building of this age and type. Specialist repair works would be prudent.  The vendor has commissioned Messrs Peter Cox to carry out remedial works, at a cost of £3,141.42, and this will be paid prior to sale, at which time a Guarantee will be issued. The specialist report is attached.

Chimney stacks	
Repair category:	2
Notes:	General damage to chimneyhead rendering was noted, and the need for cutting back to the bare masonry and recoating should not be discounted. This is likely to be a progressive defect.  Some dislodged television aerials are present.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Roofing including roof space	
Repair category:	1
Notes:	<p>The property would appear to have been re-roofed as part of a tenement refurbishment programme, possibly undertaken in the late 1980's, early 1990's. Concrete tiled roofs do have a limited life, of around 40 years and this can be restricted due to poor application, adverse weather conditions or general lack of maintenance. Whilst there is no evidence to suggest that such problems do exist, it should be noted that concrete tiled roofs do have a limited life.</p> <p>It should be fully appreciated that a flat roof, even when new does have a limited life and always requires regular and careful ongoing maintenance to ensure it remains in a wind and watertight condition.</p>

Rainwater fittings	
Repair category:	1
Notes:	<p>No significant disrepair was noted to rainwater goods. It will however be appreciated that the inspection was carried out during dry weather conditions. Sometimes defects in rainwater goods are only apparent during, or after heavy rainfall.</p> <p>Downpipes to the rear elevation show signs of leakage, which has resulted in staining to external wall finishes. In buildings of this form of construction, leakage from gutter joints can lead to damp penetration and decay to internal timbers, particularly where these are bedded into the inner face of external walls.</p>

Main walls	
Repair category:	1
Notes:	<p>The main walls are in reasonable condition allowing for age and weathering, however some patches of eroded stonework are evident in places and some of the mortar joints are defective, but this is considered commensurate with the age and type of property.</p> <p>As a result of leaking rainwater components, wall surfaces are affected by staining. The risk of concealed defects should be fully appreciated.</p>

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

## Windows, external doors and joinery

Repair category:

1

Notes:

No obvious significant defects noted.

Double glazing can be problematic and over time the operation of the windows can be affected and opening mechanisms damaged. It is therefore likely that maintenance repairs should be anticipated as part of an ongoing maintenance programme. Our valuation does assume that the installation of the windows does comply with the necessary regulations at the time of installation.

## External decorations

Repair category:

1

Notes:

No obvious significant defects noted.

## Conservatories / porches

Repair category:

Notes:

Not applicable.

## Communal areas

Repair category:

2

Notes:

Plaster cracking and deterioration has occurred, and windows are weathered and cracked, with defective mastic pointing evident.

## Garages and permanent outbuildings

Repair category:

Notes:

Not applicable.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Outside areas and boundaries	
Repair category:	1
Notes:	No obvious significant defects noted. However, some deterioration is evident to the front boundary wall.

Ceilings	
Repair category:	1
Notes:	Plaster cracking and deterioration was noted to ceiling surfaces, consistent with age. As age increases, it is not unusual for the plaster to lose its key with the timber lathing, and such defects are only revealed when decorative surfaces are stripped to allow redecoration to take place.

Internal walls	
Repair category:	1
Notes:	No obvious significant defects noted. Plaster work is saturated where dampness as present.

Floors including sub-floors	
Repair category:	1
Notes:	No obvious significant defects noted.

Internal joinery and kitchen fittings	
Repair category:	1
Notes:	No obvious significant defects noted. There is no automatic door closer to the internal kitchen, which is a requirement of today's building regulations.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Chimney breasts and fireplaces	
Repair category:	1
Notes:	No obvious significant defects noted. It is generally regarded as good building practice to keep disused flues permanently vented to prevent condensation damage.

Internal decorations	
Repair category:	1
Notes:	No obvious significant defects noted. If decorative finishes are removed, plaster repairs should be anticipated.

Cellars	
Repair category:	
Notes:	Not applicable.

Electricity	
Repair category:	1
Notes:	The electrical installation appeared to be in a condition commensurate with age and type with no visual defects being apparent. However, it should be fully appreciated that only the most recently re-wired or constructed properties will comply with current regulations.

Gas	
Repair category:	1
Notes:	No obvious significant defects noted. All gas appliances should be tested and thereafter regularly maintained by a Gas Safe registered contractor.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

## Water, plumbing and bathroom fittings

Repair category:

1

Notes:

No obvious significant defects noted.

## Heating and hot water

Repair category:

1

Notes:

No obvious significant defects noted.

## Drainage

Repair category:

1

Notes:

No obvious significant defects noted.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

<b>Structural movement</b>	1
<b>Dampness, rot and infestation</b>	2
<b>Chimney stacks</b>	2
<b>Roofing including roof space</b>	1
<b>Rainwater fittings</b>	1
<b>Main walls</b>	1
<b>Windows, external doors and joinery</b>	1
<b>External decorations</b>	1
Conservatories / porches	
<b>Communal areas</b>	2
Garages and permanent outbuildings	
<b>Outside areas and boundaries</b>	1
<b>Ceilings</b>	1
<b>Internal walls</b>	1
<b>Floors including sub-floors</b>	1
<b>Internal joinery and kitchen fittings</b>	1
<b>Chimney breasts and fireplaces</b>	1
<b>Internal decorations</b>	1
Cellars	
<b>Electricity</b>	1
<b>Gas</b>	1
<b>Water, plumbing and bathroom fittings</b>	1
<b>Heating and hot water</b>	1
<b>Drainage</b>	1

## Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

## Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

### 3. ACCESSIBILITY INFORMATION

#### Guidance Notes on Accessibility Information

**Three steps or fewer to a main entrance door of the property:** In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

**Unrestricted parking within 25 metres:** For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Ground
2. Are there three steps or fewer to a main entrance door of the property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
3. Is there a lift to the main entrance door of the property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
4. Are all door openings greater than 750mm?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
5. Is there a toilet on the same level as the living room and kitchen?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
6. Is there a toilet on the same level as a bedroom?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
7. Are all rooms on the same level with no internal steps or stairs?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

## 4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

### Matters for a solicitor or licensed conveyancer

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

The property is situated in an area of past mining activity. The conveyancer should obtain a mining report from The Mining Remediation Authority to provide information as to historical and future mining activity and whether the property has been the subject of any compensation claims, ensuring that the property is not adversely affected. The valuation assumes the content will reveal nothing adverse.

There have been alterations to the property, specifically the formation of an internal kitchen and bathroom. It is assumed that all necessary Local Authority and other consents have been obtained and the appropriate documentation, including Building Warrants and Completion Certificates issued. If any works did not require consent, then it has been assumed that they meet the standards required by the Building Regulations or are exempt.

A chemically injected damp proof course has been installed. Any Guarantees, specifications, etc should be obtained to determine the nature and extent of treatment/repair, and the validity of the Guarantee. Thereafter, these should be assigned.

Specialist damp proofing works are to take place prior to conclusion of the sale, the cost of which will be met by the vendor and a Guarantee issued. Legal advisor to verify.

The valuation assumes that the flat is burdened with a fair share of the cost of common repairs to the building of which it forms a part. Checks should be made as to whether there is a factor in place. A factor will be able to advise on any up and coming or ongoing costs/repairs.

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.

### Estimated re-instatement cost (£) for insurance purposes

£230,000

The estimated reinstatement cost for insurance purposes is £230,000 (Two Hundred And Thirty Thousand Pounds Sterling). This is for the subject property only and is given solely as a guide, as it is assumed the building as a whole is insured under a single policy. It is recommended that the figure is reviewed annually and in light of any future alterations or additions to ensure that you have adequate cover. Alternatively you should seek specialist advice from your insurer. This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction, on a reinstatement basis, assuming reconstruction of the property in its existing design and materials. Finishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during reconstruction and no allowance has been made for VAT, other than on professional fees.

### Valuation (£) and market comments

£115,000

The market value for the outright ownership interest of the property described in the report is £115,000 (One Hundred And Fifteen Thousand Pounds Sterling). This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, Title restrictions or servitude rights.

<b>Report author:</b>	Gary Haggarty, BSc (Hons) MRICS
<b>Company name:</b>	Glasgow North - Allied Surveyors Scotland Ltd
<b>Address:</b>	Herbert House 24 Herbert Street Glasgow G20 6NB
<b>Signed:</b>	Electronically Signed: 305032-1fa9f1cc-3919
<b>Date of report:</b>	26/01/2026

PART 2.

# MORTGAGE VALUATION REPORT

---

Includes a market valuation of the property.





**Mortgage Valuation Report**

Property:	Flat 0/2 234 Bearsden Road Glasgow G13 1LA	Client: Mr. Alasdair Keane Tenure: Absolute Ownership
Date of Inspection:	22/01/2026	Reference: GG/1951/GH

*This report has been prepared as part of the seller's instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising a potential lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.*

**1.0 LOCATION**

The property is situated in Anniesland, a predominantly residential area characterised by a mix of property types, including flats and traditional houses. The neighbourhood benefits from convenient access to local amenities, which are located nearby. Anniesland is well-served by public transport links, providing straightforward connections to surrounding areas.

<b>2.0 DESCRIPTION</b>	<b>2.1 Age:</b>	The property is approximately 130 years old.
------------------------	-----------------	----------------------------------------------

The property is a private, purpose-built flat located on the ground floor of a three-storey block containing six flats.

**3.0 CONSTRUCTION**

The main roof is of pitched construction and is finished with concrete tiles. No roof void access was possible. The main walls of the property are of solid sandstone masonry construction, lathed and plastered internally.

**4.0 ACCOMMODATION**

The property layout consists of a hallway, living room, internal kitchen, bedroom, and an internal bathroom.

**5.0 SERVICES (No tests have been applied to any of the services)**

<b>Water:</b>	Mains	<b>Electricity:</b>	Mains	<b>Gas:</b>	Mains.	<b>Drainage:</b>	Mains
<b>Central Heating:</b>	Gas fired boiler to radiators.						

**6.0 OUTBUILDINGS**

<b>Garage:</b>	None.
<b>Others:</b>	None.

<b>7.0</b>	<b>GENERAL CONDITION</b> - <i>A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.</i>
------------	------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

When inspected within limits imposed by occupation, the general condition of the property appears consistent with its age and type of construction, however some works of repair, maintenance and upgrading are required. This has been reflected in the mortgage valuation.

The property has been affected by structural movement in the past. This appears to be of a longstanding nature, and the risk of further movement is remote.

<b>8.0</b>	<b>ESSENTIAL REPAIR WORK</b> <i>(as a condition of any mortgage or, to preserve the condition of the property)</i>
------------	--------------------------------------------------------------------------------------------------------------------

Please refer to comments below.

<b>8.1 Retention recommended:</b>	-
-----------------------------------	---

<b>9.0</b>	<b>ROADS &amp; FOOTPATHS</b>
------------	------------------------------

Made up and adopted.

<b>10.0</b>	<b>BUILDINGS INSURANCE (£):</b>	230,000	<b>GROSS EXTERNAL FLOOR AREA</b>	48	<b>Square metres</b>
-------------	---------------------------------	---------	----------------------------------	----	----------------------

*This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.*

<b>11.0</b>	<b>GENERAL REMARKS</b>
-------------	------------------------

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

The property is situated in an area of past mining activity. The conveyancer should obtain a mining report from The Mining Remediation Authority to provide information as to historical and future mining activity and whether the property has been the subject of any compensation claims, ensuring that the property is not adversely affected. The valuation assumes the content will reveal nothing adverse.

There have been alterations to the property, specifically the formation of an internal kitchen and bathroom. It is assumed that all necessary Local Authority and other consents have been obtained and the appropriate documentation, including Building Warrants and Completion Certificates issued. If any works did not require consent, then it has been assumed that they meet the standards required by the Building Regulations or are exempt.

A chemically injected damp proof course has been installed. Any Guarantees, specifications, etc should be obtained to determine the nature and extent of treatment/repair, and the validity of the Guarantee. Thereafter, these should be assigned.

Specialist damp proofing works are to take place prior to conclusion of the sale, the cost of which will be met by the vendor and a Guarantee issued. Legal advisor to verify.

The valuation assumes that the flat is burdened with a fair share of the cost of common repairs to the building of which it forms a part. Checks should be made as to whether there is a factor in place. A factor will be able to advise on any up and coming or ongoing costs/repairs.

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.

<b>12.0</b>	<b>VALUATION</b> <i>On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.</i>		
<b>12.1</b>	<b>Market Value in present condition (£):</b>	<b>£115,000</b>	One Hundred And Fifteen Thousand Pounds Sterling
<b>12.2</b>	<b>Market Value on completion of essential works (£):</b>		
<b>12.3</b>	<b>Suitable security for normal mortgage purposes?</b>	Yes	
<b>12.4</b>	<b>Date of Valuation:</b>	23/01/2026	
<b>Signature:</b>		Electronically Signed: 305032-1fa9f1cc-3919	
<b>Surveyor:</b>	Gary Haggarty	BSc (Hons) MRICS	<b>Date:</b> 26/01/2026
<b>Glasgow North - Allied Surveyors Scotland Ltd</b>			
<b>Office:</b>	Herbert House 24 Herbert Street Glasgow G20 6NB	Tel: 0141 337 1133 Fax: email: <a href="mailto:glasgow.north@alliedsurveyorsscotland.com">glasgow.north@alliedsurveyorsscotland.com</a>	

PART 3.

# ENERGY REPORT

---

A report on the energy efficiency of the property.



# energy report

energy report on:

<b>Property address</b>	Flat 0/2 234 Bearsden Road Glasgow G13 1LA
-------------------------	-----------------------------------------------------

<b>Customer</b>	Mr. Alasdair Keane
-----------------	--------------------

<b>Customer address</b>	Flat 0/2 234 Bearsden Road Glasgow G13 1LA
-------------------------	-----------------------------------------------------

<b>Prepared by</b>	Gary Haggarty, BSc (Hons) MRICS Glasgow North - Allied Surveyors Scotland Ltd
--------------------	----------------------------------------------------------------------------------

# Energy Performance Certificate (EPC)

# Scotland

Dwellings

FLAT 0/2 , 234 BEARSDEN ROAD, GLASGOW, G13 1LA

**Dwelling type:** Ground-floor flat  
**Date of assessment:** 23 January 2026  
**Date of certificate:** 23 January 2026  
**Total floor area:** 40 m<sup>2</sup>  
**Primary Energy Indicator:** 309 kWh/m<sup>2</sup>/year


**Reference number:** 0160-2827-9090-2726-2171  
**Type of assessment:** RdSAP, existing dwelling  
**Approved Organisation:** Elmhurst  
**Main heating and fuel:** Boiler and radiators, mains gas

## You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

<b>Estimated energy costs for your home for 3 years*</b>	<b>£2,628</b>	See your recommendations report for more information
<b>Over 3 years you could save*</b>	<b>£612</b>	

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




## Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (64)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



## Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (65)**

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

## Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Internal wall insulation	£7,500 - £11,000	£405.00
2 Floor insulation (suspended floor)	£5,000 - £10,000	£210.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit [greenerscotland.org](http://greenerscotland.org) or contact Home Energy Scotland on 0808 808 2282.

**THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE**

## Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Sandstone, as built, no insulation (assumed)	★★☆☆☆	★★☆☆☆
	Solid brick, as built, no insulation (assumed)	★★☆☆☆	★★☆☆☆
Roof	(another dwelling above)	—	—
Floor	Suspended, no insulation (assumed)	—	—
Windows	Multiple glazing throughout	★★★★☆	★★★★☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★☆
Secondary heating	None	—	—
Hot water	From main system	★★★★☆	★★★★☆
Lighting	Good lighting efficiency	★★★★☆	★★★★☆

## The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

## The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 57 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.3 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.7 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

### Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£2,085 over 3 years	£1,470 over 3 years	
Hot water	£453 over 3 years	£456 over 3 years	
Lighting	£90 over 3 years	£90 over 3 years	
<b>Totals</b>	<b>£2,628</b>	<b>£2,016</b>	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

### Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures	Indicative cost	Typical saving per year	Rating after improvement	
			Energy	Environment
1 Internal wall insulation	£7,500 - £11,000	£135		
2 Floor insulation (suspended floor)	£5,000 - £10,000	£70		

### Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to [www.greenerscotland.org](http://www.greenerscotland.org).



## About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

### 1 Internal wall insulation

Internal wall insulation involves adding a layer of insulation to the inside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. Further information can be obtained from the National Insulation Association ([www.nationalinsulationassociation.org.uk](http://www.nationalinsulationassociation.org.uk)).

### 2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including [www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation](http://www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation). Building regulations generally apply to this work so it is best to check with your local authority building standards department.

## Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

**LZC energy sources present:** There are none provided for this home

## Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	7,373.5	N/A	N/A	N/A
Water heating (kWh per year)	1,960.24			

## Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

## About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst ([www.elmhurstenergy.co.uk](http://www.elmhurstenergy.co.uk)), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk) and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. Gary Haggarty
Assessor membership number:	EES/016069
Company name/trading name:	Allied Surveyors Scotland Ltd
Address:	24 Herbert Street Glasgow G20 6NB
Phone number:	01413309950
Email address:	<a href="mailto:glasgow.north@alliedsurveyorsscotland.com">glasgow.north@alliedsurveyorsscotland.com</a>
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at [www.scottishepcregister.org.uk](http://www.scottishepcregister.org.uk), with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at [www.gov.scot/epc](http://www.gov.scot/epc).

## Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

**HOMEENERGYSCOTLAND.ORG**  
**0808 808 2282**  
FUNDED BY THE SCOTTISH GOVERNMENT




P A R T 4 .

# PROPERTY QUESTIONNAIRE

---

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



## Property Questionnaire

Property Address

Flat 0/2

234 Bearsden Road

Glasgow

G13 1LA

Seller(s)

Alasdair Keane

Completion date of property questionnaire

21/01/2026

Note for sellers

<b>1.</b>	<b>Length of ownership</b>
	<b>How long have you owned the property?</b> 6 years
<b>2.</b>	<b>Council tax</b>
	<b>Which Council Tax band is your property in? (Please circle)</b> <input type="checkbox"/> A <input checked="" type="checkbox"/> B <input type="checkbox"/> C <input type="checkbox"/> D <input type="checkbox"/> E <input type="checkbox"/> F <input type="checkbox"/> G <input type="checkbox"/> H
<b>3.</b>	<b>Parking</b>
	<b>What are the arrangements for parking at your property?</b> <b>(Please tick all that apply)</b> Garage <input type="checkbox"/> Allocated parking space <input type="checkbox"/> Driveway <input type="checkbox"/> Shared parking <input type="checkbox"/> On street <input checked="" type="checkbox"/> Resident permit <input type="checkbox"/> Metered parking <input type="checkbox"/> Other (please specify):

# property questionnaire

<b>4.</b>	<b>Conservation area</b>	
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> Don't know
<b>5.</b>	<b>Listed buildings</b>	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
<b>6.</b>	<b>Alterations/additions/extensions</b>	
a	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	If you have answered yes, please describe below the changes which you have made:	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	<input type="checkbox"/> YES <input type="checkbox"/> NO
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	If you have answered yes, please answer the three questions below:	
	(i) Were the replacements the same shape and type as the ones you replaced?	<input type="checkbox"/> YES <input type="checkbox"/> NO
	(ii) Did this work involve any changes to the window or door openings?	<input type="checkbox"/> YES <input type="checkbox"/> NO
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):  Please give any guarantees which you received for this work to your solicitor or estate agent.	
<b>7.</b>	<b>Central heating</b>	
a	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Partial

# property questionnaire

	If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).  <i>gas fired combi boiler</i>	
	If you have answered yes, please answer the three questions below:	
	(i) When was your central heating system or partial central heating system installed?  <i>Oct 2020</i>	
	(ii) Do you have a maintenance contract for the central heating system?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	If you have answered yes, please give details of the company with which you have a maintenance contract	
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).	
<b>8.</b>	<b>Energy Performance Certificate</b>	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
<b>9.</b>	<b>Issues that may have affected your property</b>	
a	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	<input type="checkbox"/> YES <input type="checkbox"/> NO
b	Are you aware of the existence of asbestos in your property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> Don't know
	If you have answered yes, please give details:	
<b>10.</b>	<b>Services</b>	

# property questionnaire

a	Please tick which services are connected to your property and give details of the supplier:		
	Services	Connected	Supplier
	Gas or liquid petroleum gas	Y	Scottish Power
	Water mains or private water supply	Y	
	Electricity	Y	Scottish Power
	Mains drainage	Y	
	Telephone	N	
	Broadband	Y	CityFibre
b	Is there a septic tank system at your property?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	If you have answered yes, please answer the two questions below:		
	(i) Do you have appropriate consents for the discharge from your septic tank?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Don't know
	(ii) Do you have a maintenance contract for your septic tank?		<input type="checkbox"/> YES <input type="checkbox"/> NO
	If you have answered yes, please give details of the company with which you have a maintenance contract:		
<b>11. Responsibilities for shared or common areas</b>			
a	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?  If you have answered yes, please give details:  <i>Garden maintenance</i>		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO  <input type="checkbox"/> Don't know
b	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?  If you have answered yes, please give details:  <i>Common close cleaning and maintenance</i>		<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO  <input type="checkbox"/> N/A
c	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
d	Do you have the right to walk over any of your neighbours' property- for example to put out your rubbish bin or to maintain your boundaries?  If you have answered yes, please give details:		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

# property questionnaire

e	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?  If you have answered yes, please give details:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
f	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.)  If you have answered yes, please give details:	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
<b>12. Charges associated with your property</b>		
a	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:  <i>Speirs Gumley, approx £60-70 quarter. Includes grass cutting and close cleaning</i>	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
b	Is there a common buildings insurance policy?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factors charges?	
c	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
<b>13. Specialist works</b>		
a	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
b	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	If you have answered yes, please give details:	
c	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	<input type="checkbox"/> YES <input type="checkbox"/> NO
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:	

# property questionnaire

<b>14. Guarantees</b>		
a	Are there any guarantees or warranties for any of the following:	
(i)	Electrical work	<input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost
(ii)	Roofing	<input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost
(iii)	Central heating	<input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost
(iv)	National House Building Council(NHBC)	<input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost
(v)	Damp course	<input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	<input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost
b	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):	
c	Are there any outstanding claims under any of the guarantees listed above?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	If you have answered yes, please give details:	

<b>15. Boundaries</b>		
	So far as you are aware, has any boundary of your property been moved in the last 10 years?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> Don't know
	If you have answered yes, please give details:	
<b>16. Notices that affect your property</b>		
In the past three years have you ever received a notice:		
a	advising that the owner of a neighbouring property has made a planning application?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
b	that affects your property in some other way?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
c	that requires you to do any maintenance, repairs or improvements to your property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.	

**Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.**

Signature(s):	Alasdair Keane
Capacity:	<input checked="" type="checkbox"/> Owner <input type="checkbox"/> Legally Appointed Agent for Owner
Date:	21/01/2026

**PETER  
COX**

raising standards in property preservation



# Survey Report & Proposal



raising standards in property preservation

Peter Cox  
Edinburgh Branch Office

Ground Floor  
1 Aquarius Court  
Viking Way  
Rosyth  
Fife  
KY11 2DW  
T: 01383 420563  
gl-contracts@petercox.com  
www.petercox.com/edinburgh/

9th February 2026

Reference No: ENQ829186  
Yates Hellier Estate Agency  
149 Hyndland Road  
GLASGOW  
G12 9JA

#### PROPERTY ADDRESS

234 Bearsden Road  
Flat 0-2  
GLASGOW  
G13 1LA

Dear Ms J Bryson

Following my survey of the above property on 2nd February 2026, I am pleased to enclose our Survey Report.

In accordance with your instructions, we have confined our inspection to the areas as indicated by you. If there are any omissions or if you believe that we have misinterpreted your survey instructions we apologise and if so we would be obliged if you could inform us as soon as possible so we can rectify any problems.

As soon as we receive your signed acceptance form, arrangements will be made to undertake the work.

This Survey Report has been sub-divided into convenient sections so that you may easily find details of the survey, our recommendations and any quotations as applicable as well as other useful information.

In the meantime, if there are any points that you wish to discuss, you can contact me using the details below.

Yours sincerely

**Mark Patrick BSc MRICS CSRT CSSW**

Specialist Property Preservation Surveyor  
07778141306  
mark.patrick@petercox.com

## PROPERTY DESCRIPTION

The property is a stone-built ground floor tenement flat.

## THE SURVEY

In accordance with your specific instructions, we carried out a survey of the undermentioned parts of 234 Bearsden Road, Flat 0-2, GLASGOW, G13 1LA on the 2nd February 2026. Our findings and recommendations are set out below and should be read in conjunction with the enclosed General Notes for clients and Health and Safety precautions.

We must draw to your attention that this survey was conducted only in those areas that we were requested to inspect. Solely to identify evidence of Damp.

NOTE: The terms left, right, front and rear are used as if facing the front elevation of the building from outside.

## External Survey

- **PROPERTY DESCRIPTION:** The property is a stone-built ground floor tenement flat (domestic).
- **OCCUPIED STATUS:** At the time of the survey inspection, the property was occupied.
- **WEATHER CONDITIONS:** The weather conditions at the time of the inspection were cold, overcast, and dry - temperature - 7 °c.



- Existing Remedial Damp Proof Course

Visual evidence of historic damp proofing works carried out to the front elevation, rear elevation and common close of the property was apparent.

With this being the case, we would suggest that you establish the extent (external and internal) of the historic damp proofing works, and if damp proofing Guarantees exist, and of course, if they are still valid.



- The external ground level is below the internal floor level of the ground floor flat.

- Sub-floor Ventilation

Existing sub-floor air ventilation to the front elevation of the property appeared clear.

However, the openings air vents to the rear elevation of the property are partially blocked by plant growth. This will significantly reduce airflow, putting sub-floor timbers at risk from fungal decay.

We recommend, as essential regular maintenance, that the client arranges for air vents to the property to be cleaned out in order to maintain air flow to the sub-floor to extend the life span of the timbers.



- Breathing buildings – Good Advice

Traditional buildings are usually built of stone, brick, timber and earth held together with earth or lime-based mortars. These materials are absorbent and allow moisture to penetrate the fabric and then evaporate away harmlessly when conditions are favourable. For this reason, traditional buildings are said to 'breathe'. In such buildings, dampness is controlled by the building's ability to allow moisture to evaporate. The wind and sun aid the evaporation of water from the external surfaces whilst internal air movement through the roof covering,

walls, windows and other openings help moisture evaporate from internal surfaces. As long as the moisture can evaporate freely, the traditional performance of the structure will function as intended and the walls of the building will remain acceptably dry.

To aid this natural process, traditional buildings were carefully detailed to encourage the shedding of water from their surfaces. Features such as deep overhanging eaves, protective lime renders, lead flashings, wide gutters and sturdy plinths at ground level were used to protect the wall surfaces as much as possible. If such details are altered or unable to function, the building might be put at risk.

Modern building materials, such as hard bricks; cement-based mortars and renders; modern masonry paints; and external sealants, are specifically designed to keep moisture out of the building by providing an impervious physical barrier.

Cavity walls and cement renders protect the building from driving rain, and damp-proof courses prevent moisture rising from the ground. Used correctly in the construction of new buildings, such materials and methods are perfectly acceptable and will exclude the elements (as long as they are maintained). However, it is important to understand that these methods are rarely appropriate for older buildings.

The following summarises the differences between traditional and modern building construction:

Traditional mass wall construction:

- Relies on the mass of the wall for 'weatherproofing';
- Built with soft, porous, flexible, 'breathable' materials;
- Absorbs moisture and allows quick, natural drying;
- Relies on natural ventilation to control the internal environment and prevent condensation and mould growth, etc.

Modern cavity wall construction:

- Relies on 'waterproof' materials;
- Built with hard, impervious, and inflexible materials;
- Physical break (cavity) to prevent moisture transferring to the inside of building;

- Relies on mechanical extraction and physical ventilation to control the internal environment and prevent condensation and mould growth, etc.

Whilst it may be tempting to use impervious modern materials on old buildings, this is not recommended because there is a serious risk that the balance between water entering the fabric and water evaporating from it will be disturbed. The use of impervious materials, even as part of a diligent maintenance or repair programme, can change the way the building functions and have an adverse effect on its performance. For example, using cement renders, masonry paints, or sealants on the walls of an old building will substantially reduce its ability to allow water to evaporate. As the amount of moisture in the wall rises, the possibility of decay increases. Vulnerable materials, such as timber and soft bricks or stones, are particularly at risk. This happens because the moisture that is naturally present in the historic fabric can not escape through the hard and impervious barriers. Instead, it evaporates through the softer stone or brick accelerating the rate of decay.

- Pointing

Mortar joint pointing to the property was noted to be perished in some instances and in need of attention from a reputable third-party party stonemason contractor.

It would appear that historic repairs have been carried out to areas of masonry in both the front and rear elevations.

It would seem that cement-based mortars have been utilised and not soft, porous, flexible, 'breathable' materials, such as a lime based mortar. Using cementitious materials on the walls of an old building will reduce its ability to allow water to evaporate naturally.

## Masonry

The apparent erosion by weathering of the stone facings is likely to have resulted in this masonry becoming porous and prone to rainwater penetration.

In terms of damage to external walls, if any water that has gotten into the masonry freezes during the colder months, it will expand outwards within the masonry, creating cracks. This is called 'freeze-thaw' action, which allows more water in, gradually making the problem worse and destabilising the face of the stonework; this is known as spalling. Mould and moss can also grow on damp areas on outside walls, which can also damage the face of stonework.

The most common visual symptom of rain penetration is damp patches on internal walls, often causing paint to flake or wallpaper to peel.

However, damp masonry caused by penetrating damp can also result in a wide range of other symptoms, including:

- Reduced thermal resistance of damp masonry causing heat loss and condensation;
- Moss and mould growth;
- Frost damage;
- Rotting of embedded timbers;
- Disfiguring carbonate deposits.

We would recommend that the client engages with reputable third-party contractors to fully inspect and undertake remedial repairs to all defects that are noted.

- Reputable third-party contractors should regularly check and maintain / repair as necessary all gutters, down-pipes, masonry, render, painted coatings, external joinery, roof coverings, etc.

## Internal Survey

### Ground floor

Entrance Hall

Front Room

Middle room right

Rear room right

Rear Room

### Floor(s)

- The floor of the property is suspended timber construction.

## Walls

- Internal Observations

Unless otherwise stated, our inspection of internal areas was restricted to the ground level only and is limited accordingly. Our inspection was severely restricted in some areas due to base units, wall coverings, white goods, dry lining, bulky furniture, and personal belongings/stored items.

Our inspection was restricted to the areas designated. If you require an inspection of any other area(s), we shall be pleased to carry this out upon receipt of your further instructions.

Please note: Where walls are lined internally, for example, with plasterboard or timber, the structure behind the lining could not be tested with an electronic moisture meter.

### Rising Dampness (Capillary Action):

Moisture profile readings from an electronic moisture meter, corroborated by visible damp staining, confirmed rising damp on the walls marked for treatment in the attached sketch plan. This is attributable to the apparent failure or absence of an effective damp-proof course (DPC), allowing groundwater to ascend via capillary action through the masonry.

Rising damp is a natural process in porous building materials, where moisture migrates upward from the subsoil, depositing hygroscopic salts (e.g., chlorides and nitrates) as it evaporates. These salts attract atmospheric humidity, perpetuating damp conditions. Common in older properties without a DPC, it manifests as tidemarks, efflorescence, and staining up to circa 1m above ground level.

Our proposed DPC injection will arrest rising damp above the treatment level but will not address sub-DPC moisture or pre-existing salt contamination.

Plaster and Salt Contamination: As moisture ascends, it solubilises salts from the soil and masonry, which crystallize upon evaporation within the wall fabric and plaster. Hygroscopic salts (notably chlorides and nitrates) absorb ambient moisture in high-humidity environments (>70% RH), exacerbating dampness and promoting mould growth. This can degrade lime-based plasters, leading to crumbling and delamination.

### Observed Effects

Decorative damage:

- Staining, peeling paint, and wallpaper lifting on affected walls.
- Plaster breakdown: Salt efflorescence causing bubbling, powdering, and structural weakening.
- Timber risk: Adjacent joists, skirtings, and floorboards are vulnerable to wet rot (*Coniophora puteana*) and dry rot (*Serpula lacrymans*), with potential for rapid spread if humidity exceeds 20% wood moisture content equivalent (%WME). These defects facilitate ongoing moisture ingress, risking not only aesthetic and

superficial damage but also long-term deterioration of the building fabric and health hazards from mould spores.

We urgently recommend remedial action to safeguard the property. Delays could escalate costs and compromise habitability.

Other Moisture Sources:

Rear Room - Rear Elevation Wall

Debris Bridging in lath and plaster or Dry-Lined Walls:

Debris bridging is prevalent in older properties with lath-and-plaster or dry-lined internal finishes, where age-related deterioration or minor structural movement causes fragments of horsehair-reinforced plaster (or accumulated building detritus, such as mortar droppings) to detach and migrate into concealed voids. This material settles behind the lath frame, studwork, or wall lining, forming bridges at the void base, typically just above skirting board level, that span the air gap and facilitate moisture transfer from the external masonry to internal surfaces.

Causes:

- Material degradation: Brittle horsehair plaster sheds particles over time, exacerbated by vibration or settlement.
- Detritus accumulation: Construction remnants (e.g., from original builds or retrofits) build up in inaccessible spaces.
- Movement factors: Subtle shifts in the building fabric dislodge debris, common in pre-1940s homes.

Effects:

- Moisture bridging: Debris acts as a wick, enabling lateral damp penetration and condensation, leading to staining and salt efflorescence.
- Timber risks: Concealed framing becomes prone to fungal decay if saturation persists.
- Finish damage: Internal linings may delaminate, with potential for mould proliferation in humid conditions.



## Recommendations

- Peter Cox is to:

We have allowed for the following items:

1. Removal of debris & waste material created during our treatments.
2. Localised task lighting.
3. Equipment for safe working at height complying with Health and Safety regulations.

### PREPARATORY WORKS BY PETER COX

Prepare site for work specification as described below.

- Provide protective sheeting to the floors in and around the treatment area(s), including from the nearest convenient external door.
- Seal off treatment areas with polythene sheeting, where deemed necessary.

Where possible and deemed worthwhile, our Technicians will make use of a dust extraction unit - HILTI AIC AIR CLEANER.

The unit will be placed centrally within the work area and will extract airborne dust particles from the atmosphere that will be created from our works, meaning less clean up and a reduction in the dust particles moving throughout the property. The presence of airborne dust particles is an inhalation risk, so the use of the unit will minimise exposure to our technicians and customers. Please note that the unit will not remove all dust from the work area, and the client should still take any additional precautions within the property to prevent dust from travelling to remote areas.

Peter Cox can not accept any responsibility for any dust resulting from our works.

- Remove skirting boards and lay aside for reinstatement where 'fit for purpose'.
- Hack-off / remove the wall plaster to the areas highlighted on the sketch plan.

NB - In hacking off / removing plaster, it is not unusual for dust to find its way to the remotest parts of the property. We will take the precaution to minimise this nuisance where practical within the immediate area of our work, but we respectfully suggest that you should also take some precautions to protect furniture and the like elsewhere in the property. - Diligently brush down exposed masonry substrate surfaces in preparation for the CDM lining installation; removing bridging debris, salt contamination, detritus and waste material.

### DAMP PROOF COURSE (DPC):

- Install a chemical damp proof course (DPC) to those walls indicated on the sketch plan.

Our DPC can be installed (subject to access) in solid walls from one side only of the wall to be treated, causing the minimum of disturbance. Non-flammable and non-toxic fluid is used in the installation. There is therefore no fire risk, the

property can remain occupied with a minimum of inconvenience to the occupants and will have no ill effects on you or occupants of the adjacent property.

DPC Installation Levels: Our specification is based on the assumption that we will drill and insert the DPC at a level up to 75mm above the floor or 150mm above ground level, whichever is the higher.

#### CDM LINING SYSTEM - WALL MEMBRANE:

- Install a 4mm slim PT Lath Cavity Drainage Membrane (CDM) to the exposed and prepared masonry substrates, as per the sketch plan. Our 4mm slim PT lath meshed CDM will be fixed to exposed wall surfaces using 'lath plugs'. All joints where flanged sections are located will be sealed with tape. Where studded sections meet, sealing rope will be used.

Fundamentally, there is no period of inaction whilst the damp wall is drying, as this occurs behind the DryRoom CDM Lining System, therefore saving on reinstallation time, an extensive natural drying out period and use of dehumidifiers. The DryRoom system is installed directly to the exposed masonry wall. The wall can then be re-plastered directly onto the membrane. When the plaster dries, the walls are fit to be redecorated. The drying out of properties can take many months, and in some cases, years depending on the extent and longevity of the former damp issue. The current recognised guideline is 1 month per 20-25mm thickness of walling to dry to a point where it will not allow the germination of fungal decay. Therefore, a 255mm solid wall will take circa 9 months to dry properly throughout the thickness of the wall.

- Clear and clean treatment area.
- Deposit debris and waste resulting from our works into bags and remove them from the site.

#### FINISHING SPECIFICATIONS:

- Where applicable, plasterboards to BS1230 to be 'dab fixed' to the meshed system, dabs are to be placed over fixing centres, and a finishing plaster is then applied.
- Where applicable, the meshed membrane is to be plastered directly. This is to be applied in two coats to a thickness of approximately 15 mm, followed by a coat of finishing plaster.
- Where applicable, timber framing, where removed, to be renewed in new sections of pre-treated timbers to the nearest dimensions allowed; provide and fix new timber framework to support new plasterboard linings. Then, apply new plasterboard linings to BS1230 with a bond and skim finishing coat plaster.
- Where applicable, a Drybase Flex membrane (a watertight low-profile sheet membrane for protection against dampness in walls without the need to drill and install plugs. The membrane is a 1.5 mm thick flexible polypropylene sheet with a fleeced surface on both sides. The two fleeces ensure good adhesion to the wall by means of Drybase Flex Adhesive, as well as the direct application of plaster to the face) will be applied to the exposed masonry walls, then a bonding coat and thereafter a finishing skim coat plaster.
- Reinstall (where sound and free from decay) or renew skirting boards ('off the

shelf' to meet the nearest dimensions) disturbed upon full completion of works, and a reasonable plaster drying time.

- Clear and clean treatment area.
- Deposit debris and waste resulting from our works into bags and remove them from the site.

After re-plastering, hairline cracking of the setting coat may occur. This will not present a problem regarding the efficiency of the new plaster and should be made good when redecorating.

## Customer Instructions

IMPORTANT INFORMATION – Client to Note

### CLIENT'S RESPONSIBILITIES:

1. To ensure the building is maintained in a watertight condition.
2. To inform Peter Cox immediately if there are any escapes of water or ingress of water within the treatment areas as detailed in this report.
3. To provide unrestricted access to allow the specifications to be completed in one continuous operation.

### Preparatory Works by & Requirements of the Client:

You should arrange for the following preparatory work to be undertaken in the treatment areas as stated below.

This should be completed prior to our arrival on site.

- CLIENT TO REMOVE, ISOLATE ELECTRICAL APPLIANCES, SOCKETS, CIRCUITS, SWITCHES FROM TREATMENT AREAS; PRIOR TO OUR ARRIVAL ON SITE. AND REINSTATE UPON COMPLETION.

- CLIENT TO REMOVE & ISOLATE CENTRAL HEATING RADIATORS FROM TREATMENT AREAS; PRIOR TO OUR ARRIVAL ON SITE. AND REINSTATE UPON COMPLETION.

- Removal of floor coverings, furniture, stored items, personal items, and any other obstructions from the rooms specified for treatment.
- Remove any fixtures, fittings, or any other items preventing access to the areas of application.
- Carefully protect and cover any remaining furnishings and personal belongings.
- Decoration, upon FULL completion of all treatments and repair works.
- Client to provide mains electricity and clean water supply.

As you will appreciate, the very nature of our work will involve disturbance from noise and dust. This dust pervades the atmosphere and covers a very large area. Whilst care will be taken, we can not accept responsibility for furniture, fittings, floor coverings, etc, left within the area affected by dust. The client should consider the welfare of any occupiers within close proximity to the work areas.

It will be seen from our specification that we have included for hacking off / removal of existing plaster. In hacking off plaster, it is not unusual for dust to find its way to the remotest parts of the property. We will take the precaution to minimise this nuisance where practical within the immediate area of our work, but we respectfully suggest that you should also take some precautions to protect furniture and the like elsewhere in the property.


No responsibility will be accepted by Peter Cox for cleaning or any damage caused by dust.



# Appendix - Floor Plan

## NOT TO SCALE

unless otherwise stated in the report, where our work is to be carried out internally we require you to arrange for the removal of carpets and furnishings, together with all fittings, fixed units and appliances, from walls designated for damp proof course insertion and/or replastering. This work MUST be done prior to our commencement.



Front Elevation

© Peer Co. Ltd

NOTES			
<b>T</b> Timber floor	Vertical Damp Proof Course	Hack-off wall plaster to 1.2 m high; apply Drybase Flex	Remove, isolate CH radiator & reinstate upon completion
	Dry-Nail Damp Proof Course	Re-plastering: Strip out wall fabric; clear debris to string; remove / replace studwork & plasterboard above; then skim coat plaster.	Remove, isolate electrical socket & reinstate upon completion
PPR-002-14	DryWall CDW Lining System with 4mm Stibeline Mesh Membrane		

## NOTES

- For specialist work a certificate of guarantee will be provided when the work has been completed and the account paid in full.
- After the installation of a damp proof course the wall will contain a considerable amount of water, which must dry out. The rate at which a wall dries out is dependant on various factors such as the nature, porosity and thickness of the walling material, hygroscopic salts content and the wall finishes. Generally a wall will dry out at a rate of 1 month for every 25mm of thickness. Externally rendered, coated or painted walls may take considerably longer to dry out.
- The nature of timber decay is such that it may be present in other timbers in the property that have not been inspected. We strongly advise, therefore, that further investigation be made and we shall be pleased to arrange this upon receipt of your instructions. We will then submit a supplementary report and quotation should treatment be necessary.
- In a building of this nature there may be many concealed and inaccessible built-in timbers. We are unable to comment on the condition of any such timbers nor have we allowed for any form of treatment to them in our quotation.
- Unless otherwise stated no allowance has been made in our quotation for the removal and replacement of floor coverings, furnishings, furniture, pipes, radiators, electrical fittings and other items that may obstruct our work. All electrical circuits should be isolated and fittings removed by a qualified electrician.
- Where carpets are removed during our work, they will be loosely re-laid on completion of our work. You will arrange for the carpets to be securely fitted at a later date.
- The work that we carry out to your property especially the removal of plaster, may result in dust finding its way into the remotest parts of the property. We will take reasonable precautions to minimise this problem wherever practical in the area of our work, and we recommend that you should also take sensible steps to protect furniture, and your other belongings elsewhere in the property. If requested our technicians will be pleased to provide you with polythene sheeting, with our compliments, for your use. We regret that we can take no responsibility for cleaning or for any damage caused by dust.
- Following plastering works, a temporary decoration such as a matt finish vapour permeable emulsion paint can be applied when the new plaster has dried out, usually in about two to four weeks after application. Final decoration should be delayed for at least a year, and the use of impermeable coatings such as gloss paint or impermeable wall coverings should be avoided.

Where the cost of the proposed works exceeds £1,500, our acceptance of your instruction to proceed with these works is subject to appropriate credit checks being obtained first.

- **Extent of Survey:** The areas we have reported upon are those inspected in accordance with your instructions. If there are any omissions or if you believe that we have misinterpreted your survey instruction, please let us know at once. Where treatment has been recommended, unless otherwise stated above, this is on the understanding that the specified area has not previously been treated and guaranteed.

You should be aware that we have reported upon problems evident to us at the time of our visit. We are not commenting in any general sense on the risks of fungal decay or any other defect not evident at this time or that may develop in the future.

Where we have drawn to your attention items that are outside the scope of our survey as defined earlier, these items should be regarded as helpful suggestions and not a full and complete assessment of any problems that may exist.

Please read carefully the content of this report and all of its enclosures.

This survey must not be regarded as a substitute for a structural survey



raising standards in property preservation

Client Ref. 19C42BF4C79

Peter Cox
Edinburgh Branch Office

Ground Floor
1 Aquarius Court
Viking Way
Rosyth
Fife
KY11 2DW
T: 01383 420563
gl-contracts@petercox.com
www.petercox.com/edinburgh/

Ref: ENQ829186

Date: 9th February 2026

Client

Yates Hellier Estate Agency
149 Hyndland Road
GLASGOW
G12 9JA

Property

234 Bearsden Road
Flat 0-2
GLASGOW
G13 1LA

Table with 7 columns: QUOTATION, WORK REQUIRED (Excluding VAT), VAT Amount, Total Amount Payable (Incl VAT), Tick box, OPTIONAL INSURANCE, Tick box. Row 1: Installation of our Damp Proof Course (DPC), DryRoom CDM Lining System & Re-plastering, as per specifications & sketch plan. Row 2: TOTAL

Are you going to be the end user of the services on this agreement? [ NO / YES ]
Are you VAT registered? [ NO / YES ]

Are you CIS registered? [ NO / YES ]
VAT Number : .....

Values in the column headed "Work Required" will be plus VAT at current rate at the time of invoicing. Values in the column headed "Optional Insurance" are not subject to VAT but do include Insurance Premium Tax. The purchase of insurance is optional and is not a requirement of accepting the work recommended. Rentokil Insurance will contact you direct for payment.

Terms and Conditions apply.

I understand the observations and recommendations contained in this report and confirm that they correspond with my instructions to request an estimate for remedial work required in relation to the property. I fully understand and accept the terms of the transferable guarantee, where applicable, which only applies in relation to the areas of the property where remediation work has been identified as being required in the report. I accept that the proposed remediation work does not include carpeting, the moving of furniture, removal of fixtures and fittings, painting, electrical or plumbing work unless this has been specifically provided for in the quotation. I confirm that neither a full exploratory examination nor disruptive exposure has been carried out.

Surveyor Signature: [Handwritten signature]

Customer Signature: [Blank signature box]

Print Name.....Position.....
Invoice Address (If different from above).....
Date.....Preferred Contact Telephone No.....

Please return this completed form to the above Branch Office address.

## PETER COX LIMITED STANDARD TERMS AND CONDITIONS

### 1. THESE TERMS

1.1 These are the terms and conditions on which we undertake any works identified in our survey report which you ask us to carry out.

1.2 In particular your attention is drawn to paragraph 5 which relates to the price payable, paragraphs 8 and 9 which set out your rights to cancel this contract, paragraph 12 which sets out the limit of our liability to you and paragraph 13 which sets out how we may use your personal information.

### 2. INFORMATION ABOUT US AND HOW TO CONTACT US

2.1 We are Peter Cox Limited, a company registered in England and Wales. Our company registration number is 2438126 and our registered office is at Riverbank, Meadows Business Park, Camberley, Surrey, GU17 9AB. Our registered VAT number is 523902659.

2.2 You can contact us by telephoning our customer service team on the number set out on our quotation or by writing to us at the address on the same form.

2.3 "Writing" includes emails. When we use the words "writing" or "written" in these terms, this includes emails.

2.4 "Works" includes any works or treatments we provide to you as set out in our survey report and could include some materials and or goods needed to complete those Works.

### 3. OUR CONTRACT WITH YOU

3.1 Following your enquiry to us, we may decide to send a surveyor to your property to evaluate and assess your requirements. If it is critical that the Works are completed by a particular date you must advise us of this at the time of the survey. The surveyor may give you a quotation on the day as to the likely costs of the Works.

3.2 You may be required to pay a fee for the survey report. If this is required, you will be told at the time of your enquiry. This fee will be refunded in full should you cancel the survey or if you proceed with all the Works recommended in the survey report. However we will not refund the fee if the survey report is for a condensation control system for your property.

3.3 After the visit by our surveyor, we will send to you the survey report confirming our recommendations, our Works and our price.

3.4 The survey report will contain important information describing our Works, the information we may need from you in preparation for the Works and the actions you may need to take to help us. It will also tell you what we are not doing.

3.5 If at the time of receiving the survey report you have not already signed the order giving us permission to proceed with the Works, then if you would like us to perform the Works, you must confirm this in writing. Our acceptance of your order will take place when we contact you whether by email, telephone or letter to accept it, at which point a contract will come into existence. That contract will incorporate these terms and conditions.

### 4. CHANGES

4.1 If you wish to make a change to the Works, please contact us. If the change is possible, we will let you know about any changes to the price, the timing of supply or anything else which may alter as a result of your request and ask you to confirm whether you wish to go ahead with the change.

4.2 We may change the Works to implement minor technical adjustments and improvements. If we do this then we shall notify you of the changes and any impact on the Works, timing of supply or anything else.

4.3 We will not notify you if we are only substituting materials or equipment of similar quality and performance to those specified in the survey report or any other document issued to you.

### 5. PRICE AND PAYMENT

5.1 The price of the Works identified in our survey report (which includes VAT) will be the price set out in our quotation or as set out in our survey report to you.

5.2 Sometimes it is not possible to calculate the full price of the Works. Our survey report will clearly set out the price for the Works and materials set out in it. If additional materials or Works are required we will provide you with a new quotation setting out the price for such additional materials/Works in writing and will not proceed with any such additional work without your written acceptance.

5.3 If the rate of VAT changes between your order date and the date we supply the Works, we will adjust the rate of VAT that you pay, unless you have already paid for the order in full before the change in the rate of VAT takes effect.

5.4 We shall require payment in full before we commence the Works or, where appropriate, a deposit. The balance shall be due to us immediately on completion of the Works and on receipt of such payment we shall issue to you an invoice for the whole value of the Works.

5.5 If you do not make payment to us on completion of the Works we may charge you interest on the overdue amount at the rate of 4% a year above the base lending rate of HSBC PLC from time to time. This interest shall accrue on a daily basis from the due date until the date of actual payment of the overdue amount, whether before or after judgment. You must pay us interest together with any overdue amount.

5.6 If you have any queries regarding the payment then please contact us promptly explaining why you think it is wrong and we will not charge you interest until we have resolved the issue

### 6. PROVIDING THE WORKS

6.1 We will begin the Works on the date agreed with you at the time of the survey or following your acceptance of the Works set out in the survey report. We will let you know before the start of the Works the estimated completion date.

6.2 We may need certain information from you or we may require you to carry out certain actions so that we can carry out the Works, for example, clearing rooms or emptying cupboards. If we require your assistance, this will be stated in the survey report.

6.3 We will contact you to ask for this information or for you to confirm that you have carried out the actions. If you do not give us this information, or if you give us incomplete or incorrect information or if you have not carried out your actions, we may either end the contract or make an additional charge of a reasonable sum to compensate us for any extra work that is required as a result. We will not be responsible for completing Works late or not supplying any part of them if this is caused by you not giving us the information or failing to carry out the actions within a reasonable time of us asking.

6.4 As our access to all parts of your property may have been limited or restricted during our survey, if when we start providing the Works, we discover that the problem is more extensive than we originally thought then we reserve the right to provide a quote to you for this additional work.

6.5 If our completion of the Works is delayed by an event outside our control (including for example unavailability of service staff due to illness) then we will let you know as soon as possible and we will take steps to minimise the effect of the delay. Provided we do this we will not be liable for delays caused by the event, but if there is a risk of substantial delay you may contact us to end the contract and receive a refund for any Works you have paid for but not received.

6.6 If you do not allow us access to your property to perform the works as arranged (and you do not have a good reason for this) we may charge you additional costs incurred by us as a result. If, despite our reasonable efforts, we are unable to contact you or re-arrange access to your property we may end the contract and paragraph 10.2 will apply.

6.7 If we are unable to complete the Works on the date we originally advised to you, unless this is due to circumstances outside our control, then you may end the contract but only if you have told us in writing before we accepted your order that the Works had to be completed by that date.

6.8 If you do not wish to end the contract, you can give us a new deadline to complete the Works, which must be reasonable, and if we do not meet this new deadline you can also end the contract.

6.9 If you do choose to end the contract under paragraphs 6.7 or 6.8 you can cancel your order for any Works only partially completed but we will invoice you for those partially completed Works at the date you have ended the contract.

### 7. GUARANTEES

7.1 Where the survey report states that our Works come with a guarantee, we shall issue to you the guarantee upon receipt of payment in full. The terms of the Guarantee are shown on the relevant certificate of Guarantee.

### 8. CANCELLATION RIGHTS

8.1 If you end the contract for a reason set out at (a) to (e) below the contract will end immediately. The reasons are:

- (a) we have told you about an upcoming change to the Works or these terms which you do not accept;
- (b) we have told you about an error in the price or description of the Works you have ordered and you do not wish to proceed;

**PETER COX LIMITED STANDARD TERMS AND CONDITIONS**

- (c) there is a risk that the supply of the Works may be significantly delayed because of events outside our control;
- (d) we have or we wish to suspend the supply of the Works for technical reasons (for example due to the presence of asbestos or bats), in each case for a period of more than twenty-eight days or until we get the appropriate statutory consent, whichever is the later; or
- (e) you have a legal right to end the contract because of something we have done wrong including because we will be unable to complete the Works by the date you specified when you confirmed your acceptance under paragraph 3.5.

8.2 To end the contract, please contact the local service office on the telephone number or e-mail address set out in the quotation. Please provide your name, home address, details of the order and, where available, your phone number and email address.

8.3 We will refund to you the price you paid for the Works not yet provided, by the method you used for payment. However, we may make deductions from the price (or, if you have not made an advance payment, charge you) the reasonable costs we will incur as a result of you ending the contract.

**9. STATUTORY RIGHTS TO CANCEL**  
**THIS PARAGRAPH 9 ONLY APPLIES IF YOU ARE A CONSUMER AND YOU HAVE ENTERED INTO A DISTANCE OR OFF-PREMISES CONTRACT.**

9.1 **If this applies**, then under the Consumer Contracts (Information, Cancellation and Additional Charges) Regulations 2013 you have a legal right to change your mind within 14 days.

9.2 Because you have this legal right to change your mind, we will not provide the Works to you until after the 14 day period has expired (the "Cooling off period").

9.3 If you believe the Works are urgent and you would like us to commence the Works during the Cooling off period then you must sign a waiver giving us permission to start early.

9.4 You must realise that by giving us permission during the Cooling off period you may lose your right to cancel and this will mean that:

- (a) if we have completed the Works in full you cannot change your mind, even if the 14 day Cooling off period is still running; or
- (b) if you cancel after we have started the Works but before the Works are completed during the Cooling off period, you must pay us for the Works to the extent completed at the time you tell us that you have changed your mind.

9.5 If you are ending within 14 days of signing the contract under paragraph 9.2, please complete the cancellation form at the end of the order form or contact us on the number set out in the quotation

**10. OUR RIGHTS TO END THE CONTRACT**

- 10.1 We may end the contract for works at any time by writing to you if:
- (a) you do not make any payment to us when it is due and you still do not make payment within seven days of us reminding you;
  - (b) you do not, within a reasonable time of us asking, provide information we require or carry the actions that are necessary for us to provide the Works; or
  - (c) you do not, within a reasonable time, allow us access to your premises.

10.2 If we end the contract in the situations set out in paragraph 10.1 we will refund any money you have paid in advance for the Works we have not provided but we may deduct or charge you reasonable compensation for the net costs we will incur as a result of your breaking the contract.

**11. IF THERE IS A PROBLEM WITH THE WORKS**

11.1 If you have any concerns or complaints about the Works, you can contact us in accordance with our complaints procedure which can be found at: [https://www.petercox.com/assets/content/files/complaints\\_procedure.pdf](https://www.petercox.com/assets/content/files/complaints_procedure.pdf) or you can request a copy of our complaints procedure by telephoning our customer service team on the number set out on our quotation or by writing to us at the address on the same form.

11.2 If you believe there is a fault or problem with the Works we have provided, then you must contact us promptly so that we have an opportunity to fix the problem. If you fail to give this opportunity and instead use another company then any additional charges or losses you have suffered will not be recoverable from us.

11.3 If you have not contacted us with any complaint within 6 months of completion of the Works we will be entitled to assume that the Works were performed satisfactorily.

**12. OUR LIABILITY FOR LOSS OR DAMAGE SUFFERED BY YOU**

12.1 If we fail to comply with these terms, we are responsible for loss or damage you suffer that is a foreseeable result of our breaking this contract or our failing to use reasonable care and skill, but we are not responsible for any loss or damage that is not foreseeable.

12.2 If we are undertaking Works in your property, we will make good any damage to your property caused by us but our total liability to you arising from the damage will be limited to twenty thousand pounds (£20,000). We shall not in any circumstances be liable for any (a) costs of repairing any pre-existing faults or damage to your property that we discover while providing the Works; (b) loss of profits, economic or financial loss, loss of sale or business, loss of use or business interruption, loss of goodwill; or (c) indirect or consequential loss.

12.3 Nothing in this paragraph 12 or elsewhere in this contract excludes or limits our liability for death or personal injury caused by our negligence; for fraud or fraudulent misrepresentation; or to the extent such liability may not be excluded or limited at law.

**13. HOW WE MAY USE YOUR PERSONAL INFORMATION**

13.1 We shall process your personal data, including sending you marketing information, in accordance with applicable data protection legislation and our privacy notice which is located at: <https://www.rentokil-initial.com/site-services/cookie-and-privacy-policy/privacy-policy.aspx>.

13.2 If you do not wish to receive marketing information from us you can opt out here: [opt-out@petercox.com](mailto:opt-out@petercox.com). We will continue to send you communications as necessary for the performance of the contract and/or the services we are providing to you.

**14. OTHER IMPORTANT TERMS**

14.1 We may transfer our rights and obligations under these terms to another organisation.

14.2 You may only transfer your rights or your obligations under these terms to another person if we agree to this in writing. However, you may transfer our guarantee at paragraph 7.1 to a person who has acquired your property. We may require the person to whom the guarantee is transferred to provide reasonable evidence that they are now the owner of the property.

14.3 This contract is between you and us. No other person shall have rights to enforce the terms.

14.4 Each of the paragraphs of these terms operates separately. If any court or relevant authority decides that any of them are unlawful, the remaining paragraphs will remain in full force and effect.

14.5 If we do not insist immediately that you do anything you are required to do under these terms, or if we delay in taking steps against you in respect of your breaking this contract, that will not mean that you do not have to do those things and it will not prevent us taking steps against you at a later date.

14.6 The parties shall comply with laws relating to this agreement and the Works. Each party shall promptly report to the other party any request or demand for any undue financial or other advantage in connection with this agreement.

14.7 Other than payment for the Works, neither party shall be liable for any failure or delay which is caused by circumstances beyond its reasonable control. If the circumstances continue for more than 30 days, either party may terminate this agreement by giving notice.

14.8 These terms are governed by English law and legal proceedings will be in the English courts.

**EXPRESS REQUEST TO COMMENCE THE DELIVERY OF WORKS EARLY**

I hereby request the immediate performance of the works and acknowledge that I will lose my right of withdrawal from the contract once the works are fully performed. I also understand that if I cancel and the works are part complete I will be liable to pay for any works up to the date I cancelled.

Please commence the works within the Cooling off Period

Signed.....

Date.....

## **GENERAL NOTES FOR CLIENT**

These notes contain important information for clients and must be read in conjunction with the Survey Report. Please see the Survey Report for any variations on these General Notes.

### **1. Instrumental readings or moisture content.**

Where we refer to instrumental readings or moisture content in our report, we will have used a resistance meter to ascertain the moisture content of timber and a carbide meter to ascertain the moisture content of mortar samples taken from the walls of the property.

### **2. Relaying carpets.**

Where our Technicians have treated the top surface of a floor or staircase, they will protect treated areas, where necessary, so that carpets may be relaid loosely without delay. In the case of foam/synthetic backed carpets, it is inadvisable to lay these on treated floors until a period of four weeks has elapsed after treatment. For the same reason, vinyl floor coverings should not be laid until three months have elapsed.

### **3. Roof insulation.**

Where insulation material has been removed from a roof, it can be re-laid immediately after treatment by our Technician. If the insulation material is to be relaid by some other party, the work must be delayed until after the expiry of the appropriate safety precautions period.

### **4. Polythene sheet below suspended timber floors.**

Where we have laid polythene sheet on the oversight beneath a suspended timber floor at ground floor level, its purpose is to reduce the evaporation of water from the surface of the oversight. It is essential that the polythene sheet is not disturbed or removed from the oversight otherwise fungal decay may occur in the floor timbers.

### **5. Other contractors.**

Where we have recommended work that is to be carried out by others, arrangements for such work are the client's responsibility. No allowance for this work is included in our quotation.

### **6. Water and electricity supply.**

The client should ensure that there is an adequate supply of mains water and electricity available prior to the arrival of our Technician to carry out the treatments recommended in the survey report. If electricity is not available, it will be necessary for us to supply a portable generator and this will be subject to an additional charge on completion of the contract.

### **7. Peter Cox Insurance.**

Where optional insurance is offered under the terms of a Rentokil Insurance policy, the offer will only apply to the relevant areas, which have been inspected and which are detailed within the survey report, and the category or categories of insurance cover referred to on the quotation under the heading "optional insurance".

### **8. Third party liability.**

The survey report is for the sole and confidential use of the client and no liability will be accepted in relation to third parties. Any such persons relying on the survey report do so entirely at their own risk.

## **HEALTH AND SAFETY PRECAUTIONS**

Peter Cox Ltd has always been conscious of its health and safety responsibilities to both its clients and staff. Our prices reflect the need to ensure your safety.

The Control of Substances Hazardous to Health (COSHH) Regulations relate to the use and handling of hazardous substances, including pesticides. The law clearly defines the responsibility of companies involved in industries such as the treatment of timber and the installation of damp proof courses.

In the last few years, Peter Cox Ltd has developed a range of treatment techniques aimed at reducing the amount of pesticides and solvent used without affecting the quality of protection offered to our clients.

Our treatments are designed to cause the minimum of inconvenience and our technicians are trained to use our formulations safely and with care. All treatments have been approved for use by the Health and Safety Executive under the Control of Pesticides Regulations, where appropriate.

You should observe the warning signs that will be displayed in a prominent place before work commences.

1. Access to all work areas:- you should not enter an area whilst work is in progress.
2. Allergies:- it is recommended that people who suffer from respiratory problems, such as asthma, should not enter the property whilst work is in progress.
3. Pets:- cats, dogs, birds and other household pets should be removed from the work area.
4. Fish:- should be removed from the work area.
5. Plants:- should be removed from the work area.
6. Food and drink:- should be removed from the work area.
7. Other items:- should be protected or removed from work area, where necessary
8. Naked flames:- all naked flames (fires, pilot lights, boilers) in or adjacent to the work area should be extinguished.

You should also observe the warning signs that will be displayed in a prominent place after the work has been completed.

The type of work undertaken and the ability to ventilate the work areas will determine the time for which the safety precautions will need to apply after completion of the work. The minimum access restriction that will apply after treatment and of which you need to be aware is two hours.

However, it may be necessary to restrict access to certain areas for longer periods of time. For example, we would recommend that the minimum access restriction be extended to 24 hours for people who are known to suffer from allergies.

**PETER COX LTD LONG TERM GUARANTEES**

**1. WOODBORING INSECT TREATMENTS**

We undertake the necessary treatment should an attack by woodboring insects reoccur in the timbers treated by us. Your protection lasts for 20 years.

**2. WOOD-ROTTING FUNGI TREATMENTS**

We undertake any necessary treatment, including timber replacement, should an attack by wood-rotting fungi reoccur in the timbers treated or replaced by us. We ask you to keep the property in good repair so as to keep the water out. Your protection lasts 20 years.

**3. RISING DAMP**

We undertake to repair our damp proof course should any defect occur in our work. Your protection lasts for 20 years.

**4. WALL TIE CORROSION**

We undertake to replace any of our stainless steel wall ties should they corrode. Your protection lasts 20 years.

Image Appendix 1. Survey images:











raising standards in property preservation

# Accreditations

## ▶ A long tradition

As the experts in our field, Peter Cox aim to offer the right service and price for your needs. Over 500,000 long term guarantees, up to 20 years for some of our services, have been issued since the company was founded in 1951.

You can use our guarantee certificates with confidence if you ever wanted to sell your house, or have any future renovations.

## ▶ National Coverage, Local Surveyors

Peter Cox branches cover England, Scotland and Wales, meaning a branch on your doorstep and surveyors with local knowledge and expertise. With over **75** CSRT/CSTDB or CSSW qualified surveyors and **100** specially trained technicians who are directly employed, you can rely on our professionals to complete projects on time at an exceedingly high standard.

## ▶ Industry-leading Associations

Peter Cox are CHAS, Constructionline and Safecontractor approved.

## ▶ Trustmark

Peter Cox is an approved contractor under the TrustMark Scheme.

## ▶ ISO 9001

We have been committed to quality for many years and currently hold ISO 9001 accreditation.

## ▶ BS 6576:2005

The Peter Cox DryWall DPC system carries a British Board of Agrément Certificate and complies with BS 6576:2005.

## ▶ A Safe Contractor

All Peter Cox surveyors and technicians are fully trained in safe working practices while our treatment fluids are HSE approved and generally odourless and non-flammable.

## ▶ Trustpilot

We pride ourselves on being the market leaders in property preservation, and this comes from our passion for quality customer service. With over 800 reviews our customers have rated us **'Excellent'** - meaning from start to finish we are the company to trust.



## ▶ Peter Cox Products and Services



Damp Proofing



Wet & Dry Rot Control



Basement & Structural Waterproofing



Woodworm & Timber Treatments



Cavity Wall Tie Repair



Condensation Control

## ▶ A Nationwide Team of Experts

Manchester  
Birmingham  
Bristol  
Edinburgh  
Glasgow  
Leeds  
Lincoln  
Liverpool  
Newcastle  
Uxbridge

