

YOUR ONESURVEY
HOME REPORT

ADDRESS

12 Cedar Crescent
Whitburn
Bathgate
EH47 8LN

PREPARED FOR

Leslie Meek

INSPECTION CARRIED OUT BY:



SELLING AGENT:



HOME REPORT GENERATED BY:



Document Index

Document	Status	Prepared By	Prepared On
Single Survey	Final	Bathgate - Allied Surveyors Scotland Ltd	09/04/2026
Mortgage Certificate	Final	Bathgate - Allied Surveyors Scotland Ltd	09/04/2026
Property Questionnaire	Final	Mr. Leslie Meek	08/04/2026
EPC	FileUploaded	Bathgate - Allied Surveyors Scotland Ltd	16/04/2026

Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.**

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

P A R T 1 .

SINGLE SURVEY

A report on the condition of the property, with categories being rated from 1 to 3.



Single Survey

Survey report on:

Surveyor Reference	XP151790
---------------------------	----------

Customer	Mr. Leslie Meek
-----------------	-----------------

Selling address	12 Cedar Crescent Whitburn Bathgate EH47 8LN
------------------------	---

Date of Inspection	08/04/2026
---------------------------	------------

Prepared by	Aisha Akram, MRICS Bathgate - Allied Surveyors Scotland Ltd
--------------------	--

SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property.¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is *The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion*
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the “Surveyors” are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the “Surveyors” means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller’s permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor’s opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

2.3.1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

2.3.2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.

2.3.3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an

arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

“Re-instatement cost” is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

Description	The subjects comprise a two-storey semi-detached house.
Accommodation	Ground Floor - Entrance hall, living room and kitchen. First Floor - Landing, two bedrooms, box room and wet room.
Gross internal floor area (m ²)	Circa 69m ² .
Neighbourhood and location	The property is situated within an established residential area of mixed public sector, tenanted and privately owner-occupied housing to the southeast of Whitburn town centre. Local amenities and facilities are available and there is a regular public transport service to neighbouring communities and to the nearby cities of Edinburgh and Glasgow.
Age	The property was built circa 1955 and therefore it is approximately 71 years old.
Weather	It was dry during the course of the inspection.
Chimney stacks	From our ground level inspection only, the mutual chimney stack appears to be of brick construction having two clay pots and metal flashings.
Roofing including roof space	Our inspection of the roof was from ground floor level only. The roof is pitched and covered with tiles. The roof space can be accessed via an attic hatch on the landing ceiling. A partial inspection was undertaken as the roof space is partially floored with stored items. The roof space is also insulated between the ceiling joists. There is an old PVC cold water tank which is currently not in use.
Rainwater fittings	Visually inspected from ground level these were seen to be of cast iron.

Main walls	The main walls are of "non traditional" construction (assumed to be "Weir Timber" construction; not confirmed), having a single skin timber framed character with a timber board cladding externally and a plasterboard finish internally.
Windows, external doors and joinery	The front and rear external doors are of PVC double glazed units. The windows throughout the property are of a mixed age and mainly are of PVC double glazed units with a section of the window in the living having a timber framed double glazed unit.
External decorations	Decorated areas have a paint and PVC finish.
Conservatories / porches	N/A
Communal areas	N/A
Garages and permanent outbuildings	N/A
Outside areas and boundaries	The property benefits from a corner plot. There is a concrete slab driveway providing off-street parking and is bounded by a timber fencing and a timber gate. The side and front of the garden is laid in stone chips, concrete slabs and lawn and is bounded by a timber fence. The rear garden is laid in stone chips and concrete slabs and is bounded by a metal gate and timber fencing. There is a kennel and shed in the rear garden which are of timber construction with one having a metal clad roof and the other having a low pitched felt roof.
Ceilings	Visually inspected from floor level these were seen to be of plasterboard lined with the ceiling in the hallway and landing having a timber clad finish. There is a textured finish to some ceilings within the property.
Internal walls	The internal walls are mainly plasterboard lined.
Floors including sub floors	The flooring throughout the property appears to be of suspended timber construction. No inspection of any sub-floor area has been undertaken. There was fitted floor coverings throughout the property at the time of our inspection.
Internal joinery and kitchen fittings	Internal joinery consists of timber doors/skirtings/facings etc. The kitchen has an older style fitted floor/wall units which are in serviceable condition.
Chimney breasts and fireplaces	There is a fireplace in the living room with an electric heater. The electric heater has not been tested. All flues within the property have been blocked up.

Internal decorations	Decorated areas include walls/ceilings.
Cellars	N/A
Electricity	There is a mains electricity supply and the circuit breaker unit and the meter is located in the under-stair cupboard.
Gas	There is a mains gas supply and the meter is located externally.
Water, plumbing and bathroom fittings	There is a mains cold water supply with pipework where seen, being mainly of copper/plastic. The wet room has a white sink, toilet and an electric shower.
Heating and hot water	Central heating is provided by a Potterton Promax Combi 28HE A boiler which is wall mounted in the under-stair cupboard. The boiler serves panel radiators throughout the property and also appears to provide the domestic hot water.
Drainage	Drainage is understood to be a public sewer.
Fire, smoke and burglar alarms	We will not pass any comment with regards to a burglar alarm for security reasons. There are smoke alarms in the property. The new Fire and Smoke Alarm Standard came into force in February 2022. This new standard requires a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also needs to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon-fuelled appliance such as a boiler, open fire, or wood burner a carbon monoxide detector is also required.

<p>Any additional limits to inspection</p>	<p>It was not possible to inspect floor surfaces due to fitted floor coverings.</p> <p>No inspection of any sub-floor area has been undertaken.</p> <p>Our inspection of the roof space was a partial inspection.</p> <p>Our inspection of the roof was from ground floor level only.</p> <p>Some materials used in the building and maintenance industry until 1999 contain asbestos. Asbestos fibres released into the air, and which are breathed in, are dangerous to health. Decorative finishes in common use in the period from about 1950 to about 1985 included artex, used as a coating on ceilings and sometimes walls. Older artex can contain asbestos and if sanding or removal of this material is intended, then appropriate precautions should be taken, if necessary with advice from the Environmental Health Department of the Local Authority.</p> <p>An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to controlled regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists, removal must be undertaken in a controlled manner by a specialist contractor. This can prove to be expensive.</p>
--	---

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the above 3 categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category:	1
Notes:	There was no evidence of any significant structural movement noted at the time of our inspection.

Dampness, rot and infestation	
Repair category:	1
Notes:	No significant defects noted.

Chimney stacks	
Repair category:	1
Notes:	The chimney stack, from our ground level inspection, appeared to be in a condition consistent with age and type of construction. However, due to the age ongoing maintenance/repair works should be anticipated.

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Roofing including roof space	
Repair category:	2
Notes:	<p>The roof coverings are likely to be original.</p> <p>With any property of this age and type regular expenditure on roof repair/maintenance works as a whole including chimneys and rainwater gutters should be anticipated.</p> <p>Roofs are prone to water penetration during adverse weather but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms.</p> <p>Condensation stains were noted within the roof space and some older stains were noted near the chimney stack but when tested with a moisture meter the areas were dry.</p>

Rainwater fittings	
Repair category:	1
Notes:	<p>It was dry during the course of the inspection and therefore it was not possible to identify any leaks.</p> <p>The rainwater gutters where visible, appear to be in a condition consistent with age and type of construction. The rainwater gutters should be monitored during heavy rainfall and thereafter any repair works should be undertaken.</p>

Main walls	
Repair category:	2
Notes:	<p>Timber decay was noted to some panels to the external timber cladding. Care should be taken to ensure that external timbers are maintained at regular intervals using a suitable preservative to prevent any possibility of further deterioration.</p>

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Windows, external doors and joinery

Repair category:	2
Notes:	<p>The windows and external doors were in working order at the time of our inspection. The external timber frame of the double glazed window is showing evidence of decay.</p> <p>It should be appreciated that double-glazed sealed units do have a limited life expectancy and defective seals can lead to condensation between the panes, necessitating in replacement of the units. This can sometimes only be obvious during adverse weather conditions.</p>

External decorations

Repair category:	2
Notes:	Timber decay was noted to some sections of the external timbers.

Conservatories / porches

Repair category:	
Notes:	N/A

Communal areas

Repair category:	
Notes:	N/A

Garages and permanent outbuildings

Repair category:	
Notes:	N/A

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Outside areas and boundaries

Repair category:	2
Notes:	<p>The felt roof over the shed is showing age related wear and tear. Weathering was also noted to the timber framework. Repair works should therefore be anticipated.</p> <p>The concrete slabs in the driveway are uneven/lifted in areas.</p> <p>The brickwork to the brick wall in the rear garden is defective and spalled in areas. Repair works should be anticipated.</p>

Ceilings

Repair category:	1
Notes:	Some ceilings within the property have a textured finish and early forms of textured finishings may incorporate small amounts of asbestos based bonding material.

Internal walls

Repair category:	1
Notes:	There was no evidence of any significant defects but some of the grout to the tiling within the property requires attention.

Floors including sub-floors


Repair category:	2
Notes:	Sections of flooring are creaky/uneven under foot, particularly at first floor level. Due to fitted floor coverings we are unable to comment further. Some repair works should be anticipated.

Internal joinery and kitchen fittings


Repair category:	2
Notes:	<p>Age related wear and tear noted to internal joinery and kitchen fittings.</p> <p>The kitchen fittings are of an older style but are in serviceable condition.</p>


Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Chimney breasts and fireplaces	
Repair category:	
Notes:	The electric heater has not been tested and therefore we are unable to comment on the condition.

Internal decorations	
Repair category:	
Notes:	Redecoration will be required.

Cellars	
Repair category:	
Notes:	N/A

Electricity	
Repair category:	
Notes:	<p>The trade bodies governing electrical installations currently advise that these should be tested prior to a change of occupancy and, thereafter, at least once every five years, by a competent Electrician.</p> <p>The electrical wiring system should therefore be checked, tested and upgraded if necessary by an NIC/EIC Registered electrician. Any recommendations made with regard to the safety of the installation should be undertaken.</p>

Gas	
Repair category:	
Notes:	<p>The trade bodies governing gas installations currently advise that these should be tested prior to a change of occupancy and, thereafter, at least once per year, by a Gas Safe Registered Contractor.</p> <p>The gas system should therefore be checked and tested by a Gas Safe registered contractor.</p>

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Water, plumbing and bathroom fittings

Repair category:

1

Notes:

There was no evidence of any significant defects noted at the time of our inspection.

Routine maintenance works should be anticipated.

Heating and hot water

Repair category:

1

Notes:

It has been assumed that the heating installation has been regularly serviced and that recent service history records will be made available. This should be checked by the conveyancer.

Drainage

Repair category:

1

Notes:

At the time of our inspection, we did not lift any drainage inspection covers or carry out any drainage tests and we cannot therefore comment with any authority on the condition of the drainage system. We would add that there was no evidence on the surface to suggest any major problems in this connection, but if you wish further investigations undertaken, then a competent plumber should be instructed.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	2
Rainwater fittings	1
Main walls	2
Windows, external doors and joinery	2
External decorations	2
Conservatories / porches	
Communal areas	
Garages and permanent outbuildings	
Outside areas and boundaries	2
Ceilings	1
Internal walls	1
Floors including sub-floors	2
Internal joinery and kitchen fittings	2
Chimney breasts and fireplaces	
Internal decorations	2
Cellars	
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

1. Which floor(s) is the living accommodation on?	Ground & First Floor
2. Are there three steps or fewer to a main entrance door of the property?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
3. Is there a lift to the main entrance door of the property?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
4. Are all door openings greater than 750mm?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
5. Is there a toilet on the same level as the living room and kitchen?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
6. Is there a toilet on the same level as a bedroom?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO
7. Are all rooms on the same level with no internal steps or stairs?	<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

All boundaries, rights of way and maintenance liability with regards to this property should be checked.

The property is located in an area where mineral extraction has taken place in the past.

The property is located below a flight path.

It should also be noted that the nature of this construction is such that a number of lenders will, as a matter of policy, not consider the property to form adequate loan security.

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a Category 1 rating is used this means that the building must continue to be maintained in the normal way.

It is recommended that where repairs, defects or maintenance items have been identified within this report that interested parties make appropriate enquiries in order to satisfy themselves of potential costs or the extent of works required prior to submitting a legal offer to purchase.

Estimated re-instatement cost (£) for insurance purposes

The estimated reinstatement cost for insurance purposes is £200,000 (Two Hundred Thousand Pounds Sterling), exclusive of VAT other than on fees.

This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction, on a reinstatement basis, assuming reconstruction of the property in its existing design and materials.

Valuation (£) and market comments

The market value of the described property in the report is £120,000 (One Hundred & Twenty Thousand Pounds Sterling)

This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights.

Report author:	Aisha Akram, MRICS
Company name:	Bathgate - Allied Surveyors Scotland Ltd
Address:	66 South Bridge Street Bathgate EH48 1TL
Signed:	Electronically Signed: 310932-ac8de797-60c4

Date of report:

09/04/2026

P A R T 2 .

MORTGAGE VALUATION REPORT

Includes a market valuation of the property.



Mortgage Valuation Report

Mortgage Valuation Report

Property:	12 Cedar Crescent Whitburn Bathgate EH47 8LN	Client: Mr. Leslie Meek Tenure: Absolute Ownership
Date of Inspection:	08/04/2026	Reference: XP151790 AA/CMW

This report has been prepared as part of the seller's instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising a potential lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.

1.0 LOCATION

The property is situated within an established residential area of mixed public sector, tenanted and privately owner-occupied housing to the southeast of Whitburn town centre.

Local amenities and facilities are available and there is a regular public transport service to neighbouring communities and to the nearby cities of Edinburgh and Glasgow.

2.0	DESCRIPTION	2.1 Age:	The property was built circa 1955 and therefore it is approximately 71 years old.
------------	--------------------	-----------------	---

The subjects comprise a two-storey semi-detached house.

3.0 CONSTRUCTION

The main walls are of "non traditional" construction (assumed to be "Weir Timber" construction; not confirmed), having a single skin timber framed character with a timber board cladding externally and a plasterboard finish internally.

The roof is pitched and covered with tiles.

4.0 ACCOMMODATION

Ground Floor - Entrance hall, living room and kitchen.

First Floor - Landing, two bedrooms, box room and wet room.

5.0 SERVICES (No tests have been applied to any of the services)

Water:	Mains	Electricity:	Mains	Gas:	Mains	Drainage:	Mains
Central Heating:	Gas fired						

6.0 OUTBUILDINGS

Garage:	None
Others:	Off-street parking

7.0	GENERAL CONDITION - <i>A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.</i>				
Externally, with any property of this age and type regular expenditure on roof repair/maintenance works as a whole including the chimney and rainwater gutters should be anticipated. Some sections of the panelling to the external walls are showing evidence of decay. Care should be taken to ensure that external timber are maintained at regular intervals using suitable preservative to prevent any possibility of deterioration.					
Internally, the property has been kept in a condition consistent with age and type of construction but some maintenance/repair works are required and these items have been reflected within our valuation figure provided.					
8.0	ESSENTIAL REPAIR WORK <i>(as a condition of any mortgage or, to preserve the condition of the property)</i>				
None.					
8.1 Retention recommended:			Nil		
9.0	ROADS & FOOTPATHS				
Made and assumed to be adopted.					
10.0	BUILDINGS INSURANCE (£):	200,000	GROSS EXTERNAL FLOOR AREA	Circa 76m2	Square metres
<i>This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.</i>					
11.0	GENERAL REMARKS				
All boundaries, rights of way and maintenance liability with regards to this property should be checked.					
The property is located in an area where mineral extraction has taken place in the past.					
The property is located below a flight path.					
It should also be noted that the nature of this construction is such that a number of lenders will, as a matter of policy, not consider the property to form adequate loan security.					
Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a Category 1 rating is used this means that the building must continue to be maintained in the normal way.					
It is recommended that where repairs, defects or maintenance items have been identified within this report that interested parties make appropriate enquiries in order to satisfy themselves of potential costs or the extent of works required prior to submitting a legal offer to purchase.					
12.0	VALUATION <i>On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.</i>				
12.1	Market Value in present condition (£):	120,000	One Hundred & Twenty Thousand Pounds		

12.2	Market Value on completion of essential works (£):		
12.3	Suitable security for normal mortgage purposes?	Yes	
12.4	Date of Valuation:	08/04/2026	
Signature:		Electronically Signed: 310932-ac8de797-60c4	
Surveyor:	Aisha Akram	MRICS	Date: 09/04/2026
Bathgate - Allied Surveyors Scotland Ltd			
Office:	66 South Bridge Street Bathgate EH48 1TL	Tel: 01506 631717 Fax: email: carol.whelan@alliedsurveyorsscotland.com	

PART 3.

ENERGY REPORT

A report on the energy efficiency of the property.



energy report

energy report on:

Property address	12 Cedar Crescent Whitburn Bathgate EH47 8LN
-------------------------	---

Customer	Mr. Leslie Meek
-----------------	-----------------

Customer address	12 Cedar Crescent Whitburn Bathgate EH47 8LN
-------------------------	---

Prepared by	Aisha Akram, MRICS Bathgate - Allied Surveyors Scotland Ltd
--------------------	--

Energy Performance Certificate (EPC)

Scotland

Dwellings

12 CEDAR CRESCENT, WHITBURN, BATHGATE, EH47 8LN

Dwelling type: Semi-detached house
Date of assessment: 08 April 2026
Date of certificate: 16 April 2026
Total floor area: 69 m²
Primary Energy Indicator: 304 kWh/m²/year


Reference number: 4900-5881-0922-1105-1463
Type of assessment: RdSAP, existing dwelling
Approved Organisation: Elmhurst
Main heating and fuel: Boiler and radiators, mains gas

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£5,784	See your recommendations report for more information
Over 3 years you could save*	£477	

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (56)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO₂) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (66)**

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Floor insulation (suspended floor)	£5,000 - £10,000	£342.00
2 Low energy lighting	£270 - £315	£138.00
3 Solar photovoltaic (PV) panels	£8,000 - £10,000	£657.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	System built, as built, no insulation (assumed)	★☆☆☆☆	★☆☆☆☆
Roof	Pitched, 225 mm loft insulation	★★★★☆	★★★★☆
Floor	Suspended, no insulation (assumed)	—	—
Windows	Fully double glazed	★★★★☆☆	★★★★☆☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★☆
Secondary heating	Room heaters, electric	—	—
Hot water	From main system	★★★★☆	★★★★☆
Lighting	Below average lighting efficiency	★★☆☆☆	★★☆☆☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.


The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 51 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.5 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.3 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.







Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£4,680 over 3 years	£4,365 over 3 years	
Hot water	£804 over 3 years	£804 over 3 years	
Lighting	£300 over 3 years	£138 over 3 years	
Totals	£5,784	£5,307	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures	Indicative cost	Typical saving per year	Rating after improvement	
			Energy	Environment
1 Floor insulation (suspended floor)	£5,000 - £10,000	£114		
2 Low energy lighting for all fixed outlets	£270 - £315	£46		
3 Solar photovoltaic panels, 2.5 kWp	£8,000 - £10,000	£219		

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Cavity, internal or external wall insulation

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

2 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (<http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting>).

3 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	13,777.96	N/A	N/A	N/A
Water heating (kWh per year)	1,526.16			

Addendum

This dwelling is a system built property or some of its walls are of non-conventional construction and requires further investigation to establish the type of construction, the type of wall insulation best suited (cavity insulation or internal/external insulation) and the savings it might deliver. Please contact the Home Energy Scotland hotline on 0808 808 2282 to find out more.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Miss Aisha Akram
Assessor membership number:	EES/008214
Company name/trading name:	Allied Surveyors Scotland Ltd
Address:	22 Walker Street Edinburgh EH3 7HR
Phone number:	01312266518
Email address:	edinburgh.central@alliedsurveyorsscotland.com
Related party disclosure:	Employed by the professional dealing with the property transaction

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



P A R T 4 .

PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



Property Questionnaire

Property Address: 12 CEDAR CRES
WHITBURN

Seller/s: LESLIE J MEEK

Completion date of Property Questionnaire:

Property Questionnaire

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

1	Length of ownership		
	How long have you owned the property?	36 years	
2	Council Tax		
	Which Council tax band is your property in?	A.	
3	Parking (tick all applicable)		
	<input type="checkbox"/> Garage <input type="checkbox"/> Allocated Parking Space <input checked="" type="checkbox"/> Driveway <input type="checkbox"/> Shared Parking <input type="checkbox"/> On Street <input type="checkbox"/> Resident Permit <input type="checkbox"/> Metered Parking <input type="checkbox"/> Other (Please specify) <div style="border: 1px solid black; height: 30px; width: 100%; margin-top: 5px;"></div>		
4	Conservation area		
	Is your property in a designated Conservation area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	Yes	
		No	✓
		Unknown	

Property Questionnaire

5	Listed buildings		
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	Yes	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
		Unknown	<input type="checkbox"/>
6	Alterations/additions/extensions		
a (i)	During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet or bedroom)? <u>If you have answered Yes</u> , please describe below the changes which you have made:	Yes	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
		Unknown	<input type="checkbox"/>
(ii)	Did you obtain planning permission, building warrant, completion certificate and other consents for this work? If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	Yes	<input type="checkbox"/>
		No	<input type="checkbox"/>
		Unknown	<input type="checkbox"/>
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property? <u>If you have answered Yes</u> , please answer the 3 questions below:	Yes	<input checked="" type="checkbox"/>
		No	<input type="checkbox"/>
		Unknown	<input type="checkbox"/>
(i)	Were the replacements the same shape and type as the ones you replaced?	Yes	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
		Unknown	<input type="checkbox"/>
(ii)	Did this work involve any changes to the window or door openings?	Yes	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
		Unknown	<input type="checkbox"/>
(iii)	Please describe the changes made to the windows, doors, or patio doors (with approximate dates when the work was completed): Please give any guarantees which you received for this work to your solicitor or estate agent.		

Property Questionnaire

7	Central heating										
a	<p>Is there a central heating system in your property?</p> <p>(Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom/s, the hall and the bathroom)</p> <p>If you have answered Yes or Partial – what kind of central heating is there?</p> <p>(Examples: gas-fired, solid fuel, electric storage heating, gas, warm air).</p> <p>If you have answered Yes, please answer the 3 questions below:</p>	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="text-align: center;">Yes</td><td style="text-align: center;"><input checked="" type="checkbox"/></td></tr> <tr><td style="text-align: center;">No</td><td style="text-align: center;"><input type="checkbox"/></td></tr> <tr><td style="text-align: center;">Partial</td><td style="text-align: center;"><input type="checkbox"/></td></tr> <tr><td style="text-align: center;">Unknown</td><td style="text-align: center;"><input type="checkbox"/></td></tr> </table>	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>	Partial	<input type="checkbox"/>	Unknown	<input type="checkbox"/>	<p style="font-size: 1.5em;">GAS.</p>
Yes	<input checked="" type="checkbox"/>										
No	<input type="checkbox"/>										
Partial	<input type="checkbox"/>										
Unknown	<input type="checkbox"/>										
(i)	<p>When was your central heating system or partial central heating system installed?</p>	<p style="font-size: 1.5em;">2009</p>									
(ii)	<p>Do you have a maintenance contract for the central heating system?</p> <p>If yes, please give details of the company with which you have a maintenance contract:</p>	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="text-align: center;">Yes</td><td style="text-align: center;"><input checked="" type="checkbox"/></td></tr> <tr><td style="text-align: center;">No</td><td style="text-align: center;"><input type="checkbox"/></td></tr> <tr><td style="text-align: center;">Unknown</td><td style="text-align: center;"><input type="checkbox"/></td></tr> </table>	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>	Unknown	<input type="checkbox"/>	<p style="font-size: 1.5em;">BRITISH GAS</p>		
Yes	<input checked="" type="checkbox"/>										
No	<input type="checkbox"/>										
Unknown	<input type="checkbox"/>										
(iii)	<p>When was your maintenance agreement last renewed? (please provide the month and year)</p>	<p style="font-size: 1.5em;">2026</p>									
8	Energy Performance Certificate										
	<p>Does your property have an Energy Performance Certificate which is less than 10 years old? (PLEASE NOTE: Please tick 'YES' as the surveyor will complete this at the time of inspection)</p>	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="text-align: center;">Yes</td><td style="text-align: center;"><input checked="" type="checkbox"/></td></tr> </table>	Yes	<input checked="" type="checkbox"/>							
Yes	<input checked="" type="checkbox"/>										
9	Issues that may have affected your property										
a	<p>Has there been any storm, flood, fire or other structural damage to your property while you have owned it?</p> <p>If you have answered Yes, is the damage the subject of any outstanding insurance claim?</p>	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="text-align: center;">Yes</td><td style="text-align: center;"><input type="checkbox"/></td></tr> <tr><td style="text-align: center;">No</td><td style="text-align: center;"><input checked="" type="checkbox"/></td></tr> <tr><td style="text-align: center;">Unknown</td><td style="text-align: center;"><input type="checkbox"/></td></tr> </table>	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	Unknown	<input type="checkbox"/>			
Yes	<input type="checkbox"/>										
No	<input checked="" type="checkbox"/>										
Unknown	<input type="checkbox"/>										
b	<p>Are you aware of the existence of asbestos in your property?</p> <p>If you have answered Yes, please give details:</p>	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr><td style="text-align: center;">Yes</td><td style="text-align: center;"><input type="checkbox"/></td></tr> <tr><td style="text-align: center;">No</td><td style="text-align: center;"><input checked="" type="checkbox"/></td></tr> <tr><td style="text-align: center;">Unknown</td><td style="text-align: center;"><input type="checkbox"/></td></tr> </table>	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>	Unknown	<input type="checkbox"/>			
Yes	<input type="checkbox"/>										
No	<input checked="" type="checkbox"/>										
Unknown	<input type="checkbox"/>										

Property Questionnaire

10 Services								
a	Please tick which services are connected to your property and give details of the supplier							
Services	Connected	Supplier						
Gas or liquid petroleum gas	GAS	BRITISH GAS						
Water mains or private water supply	✓	WATER BOARD						
Electricity	✓	SCOTTISH GAS						
Mains drainage	✓	WATER BOARD						
Telephone	✓	BT						
Cable TV or satellite	N/A							
Broadband	N/A							
b	Is there a septic tank system at your property?	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 80%; text-align: right;">Yes</td> <td style="width: 20%;"></td> </tr> <tr> <td style="text-align: right;">No</td> <td style="text-align: center;">✓</td> </tr> <tr> <td style="text-align: right;">Unknown</td> <td></td> </tr> </table>	Yes		No	✓	Unknown	
Yes								
No	✓							
Unknown								
	If you have answered Yes, please answer the 2 questions below:							
(i)	Do you have appropriate consents for the discharge from your septic tank?	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 80%; text-align: right;">Yes</td> <td style="width: 20%;"></td> </tr> <tr> <td style="text-align: right;">No</td> <td></td> </tr> <tr> <td style="text-align: right;">Unknown</td> <td></td> </tr> </table>	Yes		No		Unknown	
Yes								
No								
Unknown								
(ii)	Do you have a maintenance contract for your septic tank?	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 80%; text-align: right;">Yes</td> <td style="width: 20%;"></td> </tr> <tr> <td style="text-align: right;">No</td> <td></td> </tr> </table>	Yes		No			
Yes								
No								
	If you have answered Yes, please give details of the company with which you have a maintenance contract:							

Property Questionnaire

11	Responsibilities for shared or common areas		
a	<p>Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?</p> <p>If you have answered Yes, please give details:</p>	Yes	
		No	✓
		Unknown	
b	<p>Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?</p> <p>If you have answered yes, please give details:</p>	Yes	
		No	✓
		Unknown	
		N/A	
c	<p>Has there been any major repair or replacement to any part of the roof during the time you have owned the property?</p>	Yes	
		No	✓
		Unknown	
d	<p>Do you have the right to walk over any of your neighbours' property – for example to put out your rubbish bin or maintain your boundaries?</p> <p>If you have answered Yes, please give details:</p>	Yes	
		No	✓
		Unknown	
e	<p>As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?</p> <p>If you have answered Yes, please give details:</p>	Yes	
		No	✓
		Unknown	
f	<p>As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.)</p> <p>If you have answered Yes, please give details:</p>	Yes	
		No	✓
		Unknown	
12 Charges associated with your property			
a	<p>Is there a factor or property manager for your property?</p> <p>If you have answered Yes, please provide the name and address, and give details of any deposit held and approximate charges:</p>	Yes	
		No	✓
		Unknown	

Property Questionnaire

b	Is there a common buildings insurance policy?	Yes	<input checked="" type="checkbox"/>
		No	<input checked="" type="checkbox"/>
		Unknown	<input type="checkbox"/>
	If you have answered Yes, is the cost of the insurance included in your monthly/annual factor's charges?	Yes	<input type="checkbox"/>
		No	<input type="checkbox"/>
		Unknown	<input type="checkbox"/>
c	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.		
13 Specialist works			
a	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered Yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property:	Yes	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
		Unknown	<input type="checkbox"/>
b	As far as you are aware, has any preventative work for dry rot, wet rot or damp ever been carried out to your property? If you have answered Yes, please give details:	Yes	<input type="checkbox"/>
		No	<input checked="" type="checkbox"/>
		Unknown	<input type="checkbox"/>
c	If you have answered Yes to 13(a) or 13(b), do you have any guarantees relating to this work? If you have answered Yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself, <u>please write below who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:	Yes	<input type="checkbox"/>
		No	<input type="checkbox"/>
		Unknown	<input type="checkbox"/>
		N/A	

Property Questionnaire

14 Guarantees																																																		
a	Are there any guarantees or warranties for any of the following?																																																	
	<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;"></th> <th style="width: 45%;"></th> <th style="width: 8%;">No</th> <th style="width: 8%;">Yes</th> <th style="width: 8%;">Don't know</th> <th style="width: 12%;">With title deeds</th> <th style="width: 8%;">Lost</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">i)</td> <td>Electrical Work</td> <td style="text-align: center;">✓</td> <td style="text-align: center;">✓</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">ii)</td> <td>Roofing</td> <td style="text-align: center;">✓</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">iii)</td> <td>Central Heating</td> <td style="text-align: center;">✓</td> <td style="text-align: center;">✓</td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">iv)</td> <td>National House Building Council (NHBC)</td> <td style="text-align: center;">✓</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">v)</td> <td>Damp course</td> <td style="text-align: center;">✓</td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td style="text-align: center;">vi)</td> <td>Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)</td> <td style="text-align: center;">✓</td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>			No	Yes	Don't know	With title deeds	Lost	i)	Electrical Work	✓	✓				ii)	Roofing	✓					iii)	Central Heating	✓	✓				iv)	National House Building Council (NHBC)	✓					v)	Damp course	✓					vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	✓				
		No	Yes	Don't know	With title deeds	Lost																																												
i)	Electrical Work	✓	✓																																															
ii)	Roofing	✓																																																
iii)	Central Heating	✓	✓																																															
iv)	National House Building Council (NHBC)	✓																																																
v)	Damp course	✓																																																
vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	✓																																																
b	If you have answered 'Yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):																																																	
c	<p>Are there any outstanding claims under any of the guarantees listed above?</p> <p>If you have answered Yes, please give details:</p>																																																	
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 80%;">Yes</td> <td style="width: 20%;"></td> </tr> <tr> <td>No</td> <td style="text-align: center;">✓</td> </tr> <tr> <td>Unknown</td> <td></td> </tr> </table>	Yes		No	✓	Unknown																																												
Yes																																																		
No	✓																																																	
Unknown																																																		
15 Boundaries																																																		
	<p>So far as you are aware, has any boundary of your property been moved in the last 10 years?</p> <p>If you have answered Yes, please give details?</p>																																																	
	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 80%;">Yes</td> <td style="width: 20%;"></td> </tr> <tr> <td>No</td> <td style="text-align: center;">✓</td> </tr> <tr> <td>Unknown</td> <td></td> </tr> </table>	Yes		No	✓	Unknown																																												
Yes																																																		
No	✓																																																	
Unknown																																																		

Property Questionnaire

16	Notices that affect your property		
In the past 3 years have you ever received notice:			
a	Advising that the owner of a neighbouring property has made a planning application?	Yes	
		No	✓
		Unknown	
b	That affects your property in some other way?	Yes	
		No	✓
		Unknown	
c	That requires you to do any maintenance, repairs or improvements to your property?	Yes	
		No	✓
		Unknown	
If you have answered Yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.			

Declaration by the seller(s)/or other authorised body or person(s)

I/~~WE~~ confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s): _____

Date: 2.4.26,

7	
7	
7	

Handwritten text at the bottom of the page, possibly a signature or date.