

**Tigh Ard
7 Blaich
Fort William
PH33 7AN**



Inspected on: 21st May 2026

Prepared by:
Samuel & Partners
First Surveyors Scotland
First Floor
20 High Street
FORT WILLIAM
PH33 6AT

H o m e R e p o r t - i n d e x

1. Property Questionnaire
2. Single Survey
3. Mortgage Valuation
4. Energy Report

Property Questionnaire

| | |
|-------------------|---|
| PROPERTY ADDRESS: | Tigh Ard 7 Blaich PH33 7AN |
|-------------------|---|

| | |
|------------|---|
| SELLER(S): | Helen McConachie Ian Pollard |
|------------|---|

| | |
|--|-----------------|
| COMPLETION DATE OF PROPERTY QUESTIONNAIRE: | 20.05.26 |
|--|-----------------|

PROPERTY QUESTIONNAIRE

Information to be given to prospective buyer(s)

| | | |
|-----------|--|-----------|
| 1. | Length of ownership | |
| | How long have you owned the property? 3 years 10 months | |
| 2. | Council Tax | |
| | Which Council Tax band is your property in? A B C <u>D</u> E F G H | |
| 3. | Parking | |
| | What are the arrangements for parking at your property? (Please indicate all that apply) <ul style="list-style-type: none"> • Garage • Allocated parking space • Driveway✓ • Shared parking • On street • Resident permit • Metered parking • Other (please specify): Parking and turning area on north side of house, created March 2023 | |
| 4. | Conservation Area | |
| | Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)? | No |
| 5. | Listed Buildings | |
| | Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)? | No |
| 6. | Alterations / additions / extensions | |
| a. | (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? | No |
| | <u>If you have answered yes</u>, please describe the changes which you have made: | |
| | (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? | |

| | | |
|-----------|--|------------|
| | <p><u>If you have answered yes</u>, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.</p> <p>If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent can arrange to obtain them.</p> | |
| b. | <p>Have you had replacement windows, doors, patio doors or double glazing installed in your property?</p> <p><u>If you have answered yes</u>, please answer the three questions below:</p> | Yes |
| | (i) Were the replacements the same shape and type as the ones you replaced? | Yes |
| | (ii) Did this work involve any changes to the window or door openings? | No |
| | <p>(iii) Please describe the changes made to the windows, doors, or patio doors (with approximate dates when the work was completed):</p> <p>Two kitchen window double glazed sections were replaced in 2023. Please give any guarantees which you received for this work to your solicitor or estate agent. None received.</p> | |
| 7. | Central heating | |
| a. | <p>Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom).</p> <p><u>If you have answered yes/partial</u> – what kind of central heating is there? Gas fired. New boiler installed March 2023 by Lochaber Gas Services with 9 year warranty.</p> <p>(Examples: gas-fired, solid fuel, electric storage heating, gas warm air.)</p> <p><u>If you have answered yes</u>, please answer the 3 questions below:</p> | Yes |
| b. | When was your central heating system or partial central heating system installed? Not known | |
| c. | <p>Do you have a maintenance contract for the central heating system? Boiler serviced by Lochaber Gas Services in March 2026.</p> <p><u>If you have answered yes</u>, please give details of the company with which you have a maintenance agreement:</p> | No |
| d. | When was your maintenance agreement last renewed? (Please provide the month and year). | N/A |
| 8. | Energy Performance Certificate | |
| | Does your property have an Energy Performance Certificate which is less than 10 years old? | Yes |
| 9. | Issues that may have affected your property | |
| a. | Has there been any storm, flood, fire or other structural damage to your property while you have owned it? | No |

| <u>If you have answered yes, is the damage the subject of any outstanding insurance claim?</u> | | | | | | | | | | | | | | | | | | | | | | | | | | |
|--|---|--|----------|-----------|----------|----------------------------|---|-----------|------------------------------------|---|-------|-------------|---|--|----------------|--|---------|-----------|---|------------|----------------------|---|------------|-----------|---|-----------|
| b. | Are you aware of the existence of asbestos in your property? <u>If you have answered yes, please give details:</u> | No | | | | | | | | | | | | | | | | | | | | | | | | |
| 10. Services | | | | | | | | | | | | | | | | | | | | | | | | | | |
| a. | Please tick which services are connected to your property and give details of the supplier: | | | | | | | | | | | | | | | | | | | | | | | | | |
| | <table border="1"> <thead> <tr> <th>Services</th> <th>Connected</th> <th>Supplier</th> </tr> </thead> <tbody> <tr> <td>Gas / liquid petroleum gas</td> <td style="text-align: center;">✓</td> <td>Calor Gas</td> </tr> <tr> <td>Water mains / private water supply</td> <td style="text-align: center;">✓</td> <td>Mains</td> </tr> <tr> <td>Electricity</td> <td style="text-align: center;">✓</td> <td>OVO (smart meter installed March 2026)</td> </tr> <tr> <td>Mains drainage</td> <td></td> <td>Private</td> </tr> <tr> <td>Telephone</td> <td style="text-align: center;">✓</td> <td>Not in use</td> </tr> <tr> <td>Cable TV / satellite</td> <td style="text-align: center;">✓</td> <td>Not in use</td> </tr> <tr> <td>Broadband</td> <td style="text-align: center;">✓</td> <td>Coms West</td> </tr> </tbody> </table> | | Services | Connected | Supplier | Gas / liquid petroleum gas | ✓ | Calor Gas | Water mains / private water supply | ✓ | Mains | Electricity | ✓ | OVO (smart meter installed March 2026) | Mains drainage | | Private | Telephone | ✓ | Not in use | Cable TV / satellite | ✓ | Not in use | Broadband | ✓ | Coms West |
| Services | Connected | Supplier | | | | | | | | | | | | | | | | | | | | | | | | |
| Gas / liquid petroleum gas | ✓ | Calor Gas | | | | | | | | | | | | | | | | | | | | | | | | |
| Water mains / private water supply | ✓ | Mains | | | | | | | | | | | | | | | | | | | | | | | | |
| Electricity | ✓ | OVO (smart meter installed March 2026) | | | | | | | | | | | | | | | | | | | | | | | | |
| Mains drainage | | Private | | | | | | | | | | | | | | | | | | | | | | | | |
| Telephone | ✓ | Not in use | | | | | | | | | | | | | | | | | | | | | | | | |
| Cable TV / satellite | ✓ | Not in use | | | | | | | | | | | | | | | | | | | | | | | | |
| Broadband | ✓ | Coms West | | | | | | | | | | | | | | | | | | | | | | | | |
| b. | Is there a septic tank system at your property? <u>If you have answered yes, please answer the two questions below:</u> | Yes | | | | | | | | | | | | | | | | | | | | | | | | |
| c. | Do you have appropriate consents for the discharge from your septic tank? | Yes | | | | | | | | | | | | | | | | | | | | | | | | |
| d. | Do you have a maintenance contract for your septic tank? <u>If you have answered yes, please give details of the company with which you have a maintenance contract:</u> | No | | | | | | | | | | | | | | | | | | | | | | | | |
| 11. Responsibilities for Shared or Common Areas | | | | | | | | | | | | | | | | | | | | | | | | | | |
| a. | Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? <u>If you have answered yes, please give details:</u> Duty to contribute to maintenance of access road (Land Registry document). We did contribute to resurfacing costs in 2024 and 2025. | Yes | | | | | | | | | | | | | | | | | | | | | | | | |

| | | |
|--|---|-----|
| b. | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? <u>If you have answered yes</u> , please give details: | N/A |
| c. | Has there been any major repair or replacement of any part of the roof during the time you have owned the property? | No |
| d. | Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries? <u>If you have answered yes</u> , please give details: House on croft, bins are at the bottom of the access road by the main road. | Yes |
| e. | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? <u>If you have answered yes</u> , please give details: | No |
| f. | As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.) <u>If you have answered yes</u> , please give details: | No |
| 12. Charges associated with your property | | |
| a. | Is there a factor or property manager for your property? <u>If you have answered yes</u> , please provide the name and address and give details of any deposit held and approximate charges: | No |
| b. | Is there a common buildings insurance policy? <u>If you have answered yes</u> , is the cost of the insurance included in your monthly/annual factor's charges? | No |
| c. | Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, e.g. to a Residents' Association, or maintenance or stair fund. | N/A |
| 13. Specialist Works | | |
| a. | As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? <u>If you have answered yes</u> , please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property | No |

| | | | | | | |
|--|--|------------|------------|------------|------------------|------|
| b. | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? <u>If you have answered yes, please give details</u> | No | | | | |
| c. | <u>If you have answered yes</u> to 13(a) or (b), do you have any guarantees relating to this work? <u>If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.</u> Guarantees are held by: | N/A | | | | |
| 14. Guarantees | | | | | | |
| a. | Are there any guarantees or warranties for any of the following: | | | | | |
| (i) | Electrical work | No | Yes | Don't Know | With title deeds | Lost |
| (ii) | Roofing | No | Yes | Don't Know | With title deeds | Lost |
| (iii) | Central heating | No | Yes | Don't know | With title deeds | Lost |
| (iv) | NHBC | No | Yes | Don't know | With title deeds | Lost |
| (v) | Damp course | No | Yes | Don't know | With title deeds | Lost |
| (vi) | Any other work or installations? (e.g: cavity wall insulation, underpinning, indemnity policy) | No | Yes | Don't know | With title deeds | Lost |
| b. | <u>If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):</u> Boiler: 9 years warranty from 09.03.23 with Intergas Heating Solutions. 10 year warranty on the Heat Exchanger. Solid Wall Insulation Guarantee Agency. Valid for 25 years. Installed 1 June 2019. Contractor: Eon Energy Solutions Ltd. Guarantee Number 53962. | | | | | |
| c. | Are there any outstanding claims under any of the guarantees listed above? <u>If you have answered yes, please give details:</u> | No | | | | |
| 15. Boundaries | | | | | | |
| So far as you are aware, has any boundary of your property been moved in the last 10 years? <u>If you have answered yes, please give details:</u> | | No | | | | |
| 16. Notices that affect your property | | | | | | |
| In the past 3 years have you ever received a notice: | | | | | | |
| a. | advising that the owner of a neighbouring property has made a planning application? | No | | | | |

| | | |
|--|--|----|
| b. | that affects your property in some other way? | No |
| c. | that requires you to do any maintenance, repairs or improvements to your property? | No |
| <u>If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.</u> | | |

Declaration by the seller(s)/or other authorised body or person(s):

I / We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) :

.....**Helen McConachie**.....

.....**Ian Pollard**.....

Date:20.05.26.....

single survey

survey report on:

| | |
|-------------------------|--|
| Property address | Tigh Ard 7 Blaich Fort William PH33 7AN |
|-------------------------|--|

| | |
|-----------------|---------------------------------|
| Customer | Helen McConachie Ian Pollard |
|-----------------|---------------------------------|

| | |
|-------------------------|--|
| Customer address | Tigh Ard 7 Blaich Fort William PH33 7AN |
|-------------------------|--|

| | |
|--------------------|---|
| Prepared by | John Strachan MRICS Samuel & Partners - FS Scotland |
|--------------------|---|

| | |
|---------------------------|---------------------------|
| Date of Inspection | 21 st May 2026 |
|---------------------------|---------------------------|

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without the need to move any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right are taken facing the front of the property.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc were not inspected or reported on.

| | |
|---|--|
| Description | A detached dwelling house |
| Accommodation | Ground floor: entrance hall, living room, kitchen/dining, utility, bedroom/study, bathroom and a conservatory. First floor: landing and 2 bedrooms. |
| Gross internal floor area (m ²) | 105 sq m |
| Neighbourhood and location | The property is set within the crofting township of Blaich. Surrounding properties are of a similar type. All essential services, amenities and transport links are available within the regional centre town of Fort William, which is 20 miles from the subjects. |
| Age | The original portion of the house is around 115 years of age. The front extension was built around 1986. The conservatory appears to be about 20 years of age. |
| Weather | Overcast with outbreaks of rain. The preceding weather was mixed. |
| Chimney stacks | <i>Visually inspected with the aid of binoculars where appropriate</i> There are masonry constructed chimney stacks to the gable ends. The stacks are rendered and topped with concrete copes and a clay pot. The junction of the stacks with the roof is weathered in lead. |
| Roofing including roof space | <i>Sloping roofs were visually inspected with the aid of binoculars where appropriate</i> <i>Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3 m ladder externally</i> <i>Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3 m ladder within the property</i> <i>If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so</i> The main roof is pitched and covered in a natural West Highland slate. The ridge is in a zinc capping. There are masonry built dormer windows to the front with pitched and slated roofs. There is a Velux rooflight to the rear. The roof to the front extension is of a lean-to profile covered in a fibre cement slate. The main roof space is accessed via a ceiling hatch to the right hand bedroom. The roof is of traditional joiner made construction with a softwood sarking board. The roof space houses the cold water storage tank and an expansion tank. There is a small roof space above the front extension. |
| Rainwater fittings | <i>Visually inspected with the aid of binoculars where appropriate</i> Upvc gutters and downpipes. These discharge to closed or grated gullies. Cast iron gutters to the dormers. |

single survey

| | |
|-------------------------------------|---|
| Main walls | <p><i>Visually inspected with the aid of binoculars where appropriate</i></p> <p><i>Foundations and concealed parts were not exposed or inspected</i></p> <p>External walls to the original portion are in solid stone construction. An insulated render system with a self-colouring dry dash render finish has been applied externally. Internal surfaces are mainly lined in plasterboard.</p> <p>The walls to the extension are in conventional modern timber frame cavity wall construction (2 walls with a narrow gap between). The outer brick or block wall is finished in a traditional wet dash render. The inner timber frame wall is structural and carries the weight of the roof. Internal surfaces are lined in plasterboard.</p> |
| Windows, external doors and joinery | <p><i>Internal and external doors were opened and closed where keys were available</i></p> <p><i>Random windows were opened and closed where possible</i></p> <p><i>Doors and windows were not forced open</i></p> <p>Window units are in a mix of timber frame and casement with sealed double glazed panels and replacement upvc with sealed double glazed panels. The front entrance door is in timber. There is a timber French patio door set with double glazed panels from the living room to the conservatory.</p> <p>Fascias, soffits and bargeboards appear generally to be in timber.</p> |
| External decorations | <p><i>Visually inspected</i></p> <p>External woodwork is stained or painted. The rendered walls to the extension and conservatory have a masonry painted finish.</p> |
| Conservatories/porches | <p><i>Visually inspected</i></p> <p>There is a conservatory to the rear constructed in timber frame cavity walls to cill height and proprietary upvc upper double glazed panels and windows and single leaf glazed doors. The roof is of a pitched profile covered in polycarbonate sheeting. Gutters and downpipes are in upvc.</p> <p>The floor is in suspended timber.</p> |
| Communal areas | <p><i>Circulation areas visually inspected</i></p> <p>Access to the property is over a private shared drive.</p> |
| Garages and permanent outbuildings | <p><i>Visually inspected</i></p> <p>None.</p> |
| Outside areas and boundaries | <p><i>Visually inspected</i></p> <p>There are gardens to the front, side and rear. These are generally sloping and covered in grass with mature bushes, small trees, etc. There is a timber decked patio to the rear. There is an extended stone chipped drive and parking area to the front. The front door is sheltered below a corrugated clear plastic sheeted roof on a timber frame.</p> <p>There is a timber garden shed and a polytunnel. Boundaries are a mix of timber, post and wire and hedgerow.</p> |
| Ceilings | <p><i>Visually inspected from floor level</i></p> <p>Plasterboard lined throughout. The ceiling to the kitchen/dining follows the profile of the roof. We suspect some plasterboard has been fixed to older timber linings.</p> |
| Internal walls | <p><i>Visually inspected from floor level</i></p> <p><i>Using a moisture meter, walls were randomly tested for dampness where considered appropriate</i></p> <p>Timber frame with plasterboard linings.</p> |
| Floors including sub floors | <p><i>Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted</i></p> <p><i>Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point</i></p> <p><i>Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1 m between the underside of floor joists and the solum as determined from the access hatch</i></p> <p>The ground floor to the main house is in suspended timber (boarded joists). The floor to the front extension appears to be in a floating floor (chipboard on battens on a concrete base). The first floor is in boarded joists.</p> <p>Floors were fully covered and carpeted at the time of inspection. Cupboards where boards are exposed were full of household goods at the time of inspection.</p> |

single survey

| | |
|---------------------------------------|---|
| Internal joinery and kitchen fittings | <p><i>Built in cupboards were looked into but no stored items were moved</i></p> <p><i>Kitchen units were visually inspected excluding appliances</i></p> <p>Facings and skirtings are in timber. Internal doors are in a mix of flush panel and multi glazed. The stair is in timber construction in 2 flights with quarter landing. The stair is carpeted. Part of the underside of the stair can be viewed via a cupboard below.</p> <p>Kitchen fittings comprise of a plastic vinyl faced range of proprietary base and wall units with a timber door, proprietary worktop and inset sink. There is a space for the Calor gas cooker and white goods.</p> |
| Chimney breasts and fireplaces | <p><i>Visually inspected</i></p> <p><i>No testing of the flues or fittings were carried out</i></p> <p>The chimney breast is lined in plasterboard. There is a fireplace opening to the living room that houses a wood burning stove. The hearth is in slate.</p> |
| Internal decorations | <p><i>Visually inspected</i></p> <p>Ceilings and walls are in emulsion paint finish. Internal joinery is mainly painted. The skirtings to the first floor left hand bedroom are stained.</p> |
| Cellars | <p><i>Visually inspected where there was a safe and purpose built access</i></p> <p>None</p> |
| Electricity | <p><i>Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on</i></p> <p>Mains electricity supply. The meter and fuse board are located at high level at the base of the stairs. Electrical fittings are a mix of age.</p> |
| Gas | <p><i>Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on</i></p> <p>There is an LPG Calor gas supply to the boiler and cooker. The cylinder tank is located to the front of the house.</p> |
| Water, plumbing, bathroom fittings | <p><i>Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation</i></p> <p><i>No tests whatsoever were carried out to the system or appliances</i></p> <p>Mains water supply. Plumbing supplies where viewed are in copper, wastes are in plastic. There is a plastic cold water storage tank in the roof space.</p> <p>Bathroom fittings comprise of an enamelled steel bath, ceramic wash basin and a ceramic wc. There is a shower over the bath via the mixer taps. Surfaces around the bath are in mosaic tile.</p> |
| Heating and hot water | <p><i>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected</i></p> <p><i>No tests whatsoever were carried out to the system or appliances</i></p> <p>Central heating is provided by a replacement wall mounted LPG gas fired boiler which heats steel radiators throughout the property. There is a programmer located adjacent to the boiler, a thermostat and TRVs to radiators. There are a couple of new electric panel heaters.</p> <p>Hot water is heated and stored in a copper cylinder located within the cupboard to the first floor right hand bedroom. Hot water is mainly heated by the gas boiler</p> |
| Drainage | <p><i>Drainage covers etc were not lifted</i></p> <p><i>Neither drains nor drainage systems were tested</i></p> <p>Drainage connects to a private septic tank located to the rear of the property.</p> |

single survey

| | |
|--|--|
| <p>Fire, smoke and burglar alarms</p> | <p><i>Visually inspected</i></p> <p><i>No tests whatsoever were carried out to the system or appliances</i></p> <p>There are no fire or burglar alarms. There are smoke detectors and carbon monoxide detectors in places.</p> <p>Fire Safety Legislation effective from February 2022 requires a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat detection alarm must be installed in every kitchen area and all smoke and heat alarms must be ceiling mounted and interlinked. Where there is a carbon fuelled appliance e.g. central heating boiler, open fire, wood burning stove, etc, a carbon monoxide detector is also required. The purchaser(s) should appraise themselves of the requirements of this legislation and engage with appropriate accredited contractors to ensure compliance.</p> |
| <p>Any additional limits to inspection</p> | <p><i>For flats/maisonettes</i></p> <p><i>Only the subject flat and internal communal areas giving access to the flat were inspected</i></p> <p><i>If the roof space or underbuilding/basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation</i></p> <p><i>The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance</i></p> <p><i>We have not carried out an inspection for Japanese Knotweed or other invasive plant species and unless otherwise stated for the purpose of this report we have assumed that there is no Japanese Knotweed or other invasive plant species within the boundaries of the property or in neighbouring properties. the identification of Japanese Knotweed or other invasive plant species should be made by a Specialist Contractor.</i></p> <p>As mentioned above floors were fully covered and carpeted at the time of inspection.</p> <p>The house was occupied and fully furnished at the time of inspection.</p> |

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

| Category 3 | | Category 2 | | Category 1 | |
|--|--|---|--|--|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | | Repairs or replacement requiring future attention, but estimates are still advised. | | No immediate action or repair is needed. | |
| Structural movement | | | | | |
| Repair category | 1 | | | | |
| Notes | No evidence of any significant cracking, current settlement and no conditions present to suggest the foundations are defective or inadequate. | | | | |
| Dampness, rot and infestation | | | | | |
| Repair category | 1 | | | | |
| Notes | No evidence of any significant damp, rot or infestation in any areas inspected. There are traces of old woodworm to the underside of the stairs and within the roof space. This did not look active at the time of inspection. See legal matters. | | | | |
| Chimney stacks | | | | | |
| Repair category | 1 | | | | |
| Notes | The render surfaces display signs of wear compatible with age. There is moss and minor hairline cracking to the render in the inner face. | | | | |
| Roofing including roof space | | | | | |
| Repair category | 2 | | | | |
| Notes | <p>A few individual slates require attention as part of programme of routine maintenance.</p> <p>A couple of fibre cement slates over the front extension are cracked. Heavy deposits of moss. These slates are nearing the end of their anticipated life cycle. Fibre cement slates of a particular age can contain asbestos.</p> <p>Insulation standards to the roof spaces is below modern standards.</p> | | | | |
| Rainwater fittings | | | | | |
| Repair category | 2 | | | | |
| Notes | Rainwater is ponding to the front. Small section uneven to the front. Guttering to the dormers ageing. | | | | |
| Main walls | | | | | |
| Repair category | 1 | | | | |
| Notes | No evidence of any significant disrepair. There is some minor hairline cracking and a small isolated area of boss (debonded) render to the front extension. | | | | |
| Windows, external doors and joinery | | | | | |
| Repair category | 3 | | | | |
| Notes | There is rot and softening of the cills and frames to the kitchen, utility and dining room windows. The seals to several double glazing panels have failed. These will require repairing or replacing soon. | | | | |
| External decorations | | | | | |
| Repair category | 2 | | | | |
| Notes | Decorations to the external woodwork is beginning to weather in places. | | | | |

single survey

| Conservatories/porches | |
|--|--|
| Repair category | 3 |
| Notes | There is cracked and boss render at low level on the west side of the conservatory. The seals to several double glazed panels have failed causing misting between the panes of glass. These will require to be replaced. There is damp to a window cill to the rear. |
| Communal areas | |
| Repair category | 1 |
| Notes | The access road is generally in a condition compatible with its setting. |
| Garages and permanent outbuildings | |
| Repair category | Not applicable |
| Notes | |
| Outside areas and boundaries | |
| Repair category | 2 |
| Notes | No evidence of any significant disrepair. Some boundary fencing is worn in places and repairs are ongoing. The fabric of the garden shed is fairly worn but we were informed that repairs have been carried out recently and the shed is watertight. |
| Ceilings | |
| Repair category | 1 |
| Notes | No evidence of any significant disrepair. |
| Internal walls | |
| Repair category | 1 |
| Notes | No evidence of any significant disrepair. |
| Floors including sub-floors | |
| Repair category | 1 |
| Notes | No obvious evidence of any obvious disrepair having regard to the limits of our inspection. It appears that the ground floor structure to the original portion of the property is original. The edge of some traditional type floorboards can be seen within the ground floor cupboards. There is a slight lack of sub floor vents to the sub floor space below. We were unable to report on the true condition of the floor giving the limitations to our inspection. Although probably not practical at this stage it would be wise to have the floors inspected in a property of this age. There is a slight deflection to the first floor when walked upon. |
| Internal joinery and kitchen fittings | |
| Repair category | 1 |
| Notes | The kitchen fittings are beginning to display signs of wear compatible with age but no immediate action is required. |
| Chimney breasts and fireplaces | |
| Repair category | 1 |
| Notes | No evidence of any significant disrepair. |
| Internal decorations | |
| Repair category | 1 |
| Notes | No evidence of any significant wear. Some minor localised wear beginning to show in places. Some taping will require attention at the next redecorations. |

single survey

| Cellars | |
|--|---|
| Repair category | Not applicable |
| Notes | |
| Electricity | |
| Repair category | 2 |
| Notes | Modern installation. Although probably in an acceptable condition there is no record of when an electrical test was last carried out. It is good practice to test electrical installations to domestic properties on a 5 year cycle or upon an exchange of ownership. |
| Gas | |
| Repair category | 1 |
| Notes | It is good practice to service gas fittings on a regular basis. We were informed by the seller that the cooker was serviced in May 2025. |
| Water, plumbing and bathroom fittings | |
| Repair category | 1 |
| Notes | No evidence of any significant disrepair. The plastic cold water storage tank in the roof space is not insulated. |
| Heating and hot water | |
| Repair category | 1 |
| Notes | It is good practice to service gas boilers on a regular basis. We were informed by the seller that the boiler was serviced in March 2026. |
| Drainage | |
| Repair category | 1 |
| Notes | It is good practice to service/de-sludge septic tanks on a regular basis. The cover to the septic tank is a loose concrete slab. This should be replaced in a proprietary cover bedded in concrete. |

single survey

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

| | |
|---------------------------------------|-----|
| Structural movement | 1 |
| Dampness, rot and infestation | 1 |
| Chimney stacks | 1 |
| Roofing including roof space | 2 |
| Rainwater fittings | 2 |
| Main walls | 1 |
| Windows, external doors and joinery | 3 |
| External decorations | 2 |
| Conservatories / porches | 3 |
| Communal areas | 1 |
| Garages and permanent outbuildings | N/a |
| Outside areas and boundaries | 2 |
| Ceilings | 1 |
| Internal walls | 1 |
| Floors including sub-floors | 1 |
| Internal joinery and kitchen fittings | 1 |
| Chimney breasts and fireplaces | 1 |
| Internal decorations | 1 |
| Cellars | N/a |
| Electricity | 2 |
| Gas | 1 |
| Water, plumbing and bathroom fittings | 1 |
| Heating and hot water | 1 |
| Drainage | 1 |

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

| | |
|--|---|
| 1. Which floor(s) is the living accommodation on? | Ground floor |
| 2. Are there three steps or fewer to a main entrance door of the property? | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| 3. Is there a lift to the main entrance door of the property? | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| 4. Are all door openings greater than 750mm? | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| 5. Is there a toilet on the same level as the living room and kitchen? | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| 6. Is there a toilet on the same level as a bedroom? | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| 7. Are all rooms on the same level with no internal steps or stairs? | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

It is assumed that the subjects are held on an absolute ownership basis [formerly feudal]. This should be confirmed by your solicitor.

In addition to the standard searches and enquiries to be carried out by your solicitor we would recommend that the following matters are confirmed:

1. Details concerning the shared private access road should be confirmed together with the liabilities for the contribution to the maintenance and upkeep of the same.
2. A service record should be provided for the gas fired boiler and the septic tank.
3. Statutory consent would have been required for the erection of the conservatory and for the installation of the insulated render system.

Estimated reinstatement cost for insurance purposes

It is recommended that the subjects be insured for a sum of not less than £380,000 [three hundred & eighty thousand pounds]

This figure is the estimate of the cost of rebuilding the property and bears no direct relationship to the current market value.

Valuation and market comments

£265,000 [two hundred & sixty five thousand pounds]

There is a steady demand for properties of this size and type within easy commuter distance of the town of Fort William.

| | |
|----------------|--|
| Report author | John Strachan MRICS |
| Address | Samuel & Partners FS Scotland, First Floor, 20 High Street, Fort William, Scotland, PH33 6AT |
| Signed | Electronically prepared by Samuel & Partners |
| Date of report | 26 May 2026 |

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report is transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in the expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

1 Which shall be in accordance with the current RIGS Valuation Standards (The Red Book) and RIGS Rules of Conduct.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.5 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.6 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.7 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.8 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;

- a "prospective Purchaser" is anyone considering buying the Property;
 - the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
 - the "Seller" is/are the proprietor(s) of the Property;
 - the "Surveyor" is the author of the Report on the Property; and
 - the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- + the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

1. Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
2. Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
3. Category 1: No immediate action or repair is needed.

WARNING:

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- * There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

Samuel & Partners Generic Valuation

Mortgage Valuation Report

| | | | |
|----------------------------|--|--------------------|------------------------------|
| Property: | Tigh Ard 7 Blaich Fort William PH33 7AN | Customer: | |
| | | Owner: | |
| | | Introducer: | |
| | | Tenure: | Standard Ownership (assumed) |
| Date of Inspection: | 21.05.26 | Reference: | |

This Mortgage Valuation Report has been issued as part of The Home Report prepared on the property referred to above. This report and associated Home Report together with the inspection has been carried out in accordance with the RICS Appraisal and Valuation Standards (The Red Book) and the RICS Rules of Conduct. Potential purchasers must not read this report in isolation and your attention is drawn to the additional comments contained in The Single Survey and also the Terms and Conditions of the associated Home Report. This report has been prepared solely for mortgage lenders to consider the property's suitability for mortgage finance. Your attention is also drawn to the fact that neither the whole nor any part of the report or any reference thereto may be included in any document, circular or statement without prior approval in writing as to the form in which it will appear.

| | |
|------------|-----------------|
| 1.0 | LOCATION |
|------------|-----------------|

The property is set within the crofting township of Blaich. All essential services, amenities and transport links are available within the regional centre town of Fort William, which is 20 miles from the subjects

| | | | |
|------------|--------------------|-----------------|------|
| 2.0 | DESCRIPTION | 2.1 Age: | 1910 |
|------------|--------------------|-----------------|------|

Detached house, extended around 35 years ago. The conservatory appears to be around 20 years of age.

| | |
|------------|---------------------|
| 3.0 | CONSTRUCTION |
|------------|---------------------|

Solid stone walls with insulated render system, pitched and slated roofs, timber floors.

| | |
|------------|----------------------|
| 4.0 | ACCOMMODATION |
|------------|----------------------|

Ground floor: entrance lobby, living room, kitchen/dining, utility, bedroom/study, bathroom and a conservatory.
First floor: landing and 2 bedrooms.

| | | | | | | |
|------------|---|--|--|--|--|--|
| 5.0 | SERVICES (No tests have been applied to any of the services) | | | | | |
|------------|---|--|--|--|--|--|

| | | | | | | | |
|---------------|-------|---------------------|-------|-------------|-----|----------------|---------|
| Water: | Mains | Electricity: | Mains | Gas: | LPG | Drains: | Private |
|---------------|-------|---------------------|-------|-------------|-----|----------------|---------|

| | |
|-------------------------|------------------------------------|
| Central Heating: | Full – LPG gas boiler to radiators |
|-------------------------|------------------------------------|

| | |
|------------|---------------------|
| 6.0 | OUTBUILDINGS |
|------------|---------------------|

| | |
|----------------|------|
| Garage: | None |
|----------------|------|

| | |
|----------------|------|
| Others: | None |
|----------------|------|

| | |
|------------|--|
| 7.0 | GENERAL CONDITION - <i>A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.</i> |
|------------|--|

The property is in a satisfactory condition for lending purposes.

| | | | | |
|--|--|------------------|---|--|
| 8.0 | ESSENTIAL REPAIR WORK (as a condition of any mortgage or, to preserve the condition of the property) | | | |
| None required as a condition of the mortgage | | | | |
| 8.1 Retention recommended: | | | Reflected in the valuation. | |
| 9.0 | ROADS & FOOTPATHS | | | |
| Have the roads and footpaths adjacent to the property been adopted and maintained by the Local Authority? | | | [] YES [X] NO | <i>If No, comment to be made in Section 11</i> |
| 10.0 | BUILDINGS INSURANCE | £380,000 | GROSS EXTERNAL FLOOR AREA | 125 Sq m |
| <i>This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.</i> | | | | |
| 11.0 | GENERAL REMARKS | | | |
| <p>Drainage is to a private septic tank.</p> <p>Access is over a shared drive. The full details should be confirmed.</p> <p>Statutory consent would have been required for the external insulated render system.</p> | | | | |
| 12.0 | VALUATION <i>On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.</i> | | | |
| 12.1 | Market Value in present condition | £265,000 | Two hundred & sixty five thousand pounds | |
| 12.2 | Market Value on completion of essential works: | £ | See remarks in Section 11 of this report. | |
| 12.3 | Suitable security for normal mortgage purposes? | [X] YES [] NO | | |
| Signature | Electronically signed = John Strachan | | | |
| Surveyor: | John Strachan, MRICS | | Date: | 26 May 2026 |
| Surveyor Company: | Samuel & Partners, First Surveyors Scotland | | | |
| Address: | First Floor, 20 High Street Fort William, PH33 6AT | | | |
| Telephone: | 01397 702686 | | | |
| E-mail | info@samuelandpartners.co.uk | | | |

Energy Performance Certificate (EPC)

Scotland

Dwellings

TIGH ARD, BLAICH, FORT WILLIAM, PH33 7AN

Dwelling type: Detached house
Date of assessment: 21 May 2026
Date of certificate: 27 May 2026
Total floor area: 95 m²
Primary Energy Indicator: 278 kWh/m²/year


Reference number: 2399-1019-7205-9356-1204
Type of assessment: RdSAP, existing dwelling
Approved Organisation: Elmhurst
Main heating and fuel: Boiler and radiators, LPG

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

| | | |
|--|---------------|--|
| Estimated energy costs for your home for 3 years* | £6,747 | See your recommendations report for more information |
| Over 3 years you could save* | £2,700 | |

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band F (28)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO₂) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band E (51)**

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

| Recommended measures | Indicative cost | Typical savings over 3 years |
|--------------------------------------|------------------|------------------------------|
| 1 Room-in-roof insulation | £900 - £1,200 | £789.00 |
| 2 Internal wall insulation | £7,500 - £11,000 | £1152.00 |
| 3 Floor insulation (suspended floor) | £5,000 - £10,000 | £327.00 |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction. See the addendum section on the last page of this report for further information relating to items in the table.

| Element | Description | Energy Efficiency | Environmental |
|-----------------------|--|-------------------|---------------|
| Walls | Granite or whin, as built, no insulation (assumed) | ★★☆☆☆ | ★★☆☆☆ |
| | Timber frame, as built, insulated (assumed) | ★★★★☆ | ★★★★☆ |
| Roof | Pitched, insulated | ★★★★☆☆ | ★★★★☆☆ |
| | Roof room(s), ceiling insulated | ★★☆☆☆ | ★★☆☆☆ |
| Floor | Suspended, no insulation (assumed) | — | — |
| | Solid, no insulation (assumed) | — | — |
| Windows | Fully double glazed | ★★★★☆☆ | ★★★★☆☆ |
| Main heating | Boiler and radiators, LPG | ★★☆☆☆ | ★★★★☆ |
| Main heating controls | Programmer, room thermostat and TRVs | ★★★★☆ | ★★★★☆ |
| Secondary heating | Room heaters, wood logs | — | — |
| Hot water | From main system | ★★☆☆☆ | ★★★★☆ |
| Lighting | Good lighting efficiency | ★★★★☆ | ★★★★☆ |

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.


The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 53 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 5.0 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 2.6 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

| | Current energy costs | Potential energy costs | Potential future savings |
|---------------|----------------------|------------------------|---|
| Heating | £5,496 over 3 years | £3,039 over 3 years |  |
| Hot water | £1,065 over 3 years | £822 over 3 years | |
| Lighting | £186 over 3 years | £186 over 3 years | |
| Totals | £6,747 | £4,047 | |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

| Recommended measures | Indicative cost | Typical saving per year | Rating after improvement | |
|--|------------------|-------------------------|--------------------------|-------------|
| | | | Energy | Environment |
| 1 Room-in-roof insulation | £900 - £1,200 | £263 | F 34 | D 56 |
| 2 Internal wall insulation | £7,500 - £11,000 | £384 | E 43 | D 64 |
| 3 Floor insulation (suspended floor) | £5,000 - £10,000 | £109 | E 47 | D 67 |
| 4 Floor insulation (solid floor) | £5,000 - £10,000 | £63 | E 49 | D 68 |
| 5 Draughtproofing | £150 - £250 | £3 | E 50 | D 68 |
| 6 Solar water heating | £4,000 - £7,000 | £36 | E 52 | C 70 |
| 7 Heat recovery system for mixer showers | £600 - £1,500 | £41 | E 53 | C 71 |
| 8 Solar photovoltaic panels, 2.5 kWp | £8,000 - £10,000 | £196 | D 57 | C 72 |
| 9 Wind turbine | £5,000 - £20,000 | £693 | C 71 | C 75 |

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Room-in-roof insulation

Insulating roof rooms will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. If it has a flat ceiling insulation can usually be added above the ceiling, and sloping ceilings and walls of roof rooms can be insulated using an internal lining board. Roof voids must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about roof room insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). Building regulations generally apply to this work so it is best to check this with your local authority building standards department.

2 Internal wall insulation

Internal wall insulation involves adding a layer of insulation to the inside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

3 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

4 Floor insulation (solid floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulating solid floors can present challenges; insulation laid on top of existing solid floors may impact on existing doors and finishes whilst lifting of a solid floor to insert insulation below will require consideration of the potential effect on both structural stability and damp proofing. It is advised to seek advice from a Chartered Structural Engineer or a registered Architect about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work and may also require a building warrant so it is best to check with your local authority building standards department.

5 Draughtproofing

Fitting draughtproofing, strips of insulation around windows and doors, will improve the comfort in the home. A contractor can be employed but draughtproofing can be installed by a competent DIY enthusiast.

6 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

7 Heat recovery system for mixer showers

A shower heat recovery system extracts heat from the water in the shower drain and transfers it to incoming cold water. This reduces the amount of energy needed per shower. Building regulations generally apply to this work, so it is best to check with your local authority building standards department and seek advice from a qualified plumber or heating engineer.

8 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

9 Wind turbine

A wind turbine provides electricity from wind energy. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Wind turbines are not suitable for all properties. The system's effectiveness depends on local wind speeds and the presence of nearby obstructions, and a site survey should be undertaken by an accredited installer. Planning permission might be required and building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for a wind turbine, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present:

- Biomass secondary heating

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

| Heat demand | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 15,390.67 | N/A | N/A | N/A |
| Water heating (kWh per year) | 2,995.7 | | | |

Addendum

When considering the PV installation consider installing PV battery and a PV diverter for water heating

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

| | |
|-----------------------------|--|
| Assessor's name: | Mr. John Strachan |
| Assessor membership number: | EES/009418 |
| Company name/trading name: | Samuel and Partners |
| Address: | 20 High Street Fort William PH33 6AT |
| Phone number: | 01397 702686 |
| Email address: | john@samuelandpartners.co.uk |
| Related party disclosure: | No related party |

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT

