



Home Report

136 Falside Crescent Bathgate West Lothian

EH48 2DS

Offices throughout Scotland alliedsurveyorsscotland.com

survey report on:

| our voy roport on: | | |
|--------------------|---|--|
| Property address | 136 Falside Crescent, BATHGATE, EH48 2DS | |
| | | |
| Customer | The Late Henrietta Mazs | |
| | | |
| Customer address | C/O Sneddon Morrison, 36-46 North Bridge Street, Bathgate, West Lothian, EH48 4PP | |
| • | | |
| Prepared by | Allied Surveyors Scotland Ltd | |
| | | |
| Date of inspection | 13th September 2024 | |



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
 or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

| Description | This is a two storey semi-detached house. |
|--------------------------------|---|
| Accommodation | GROUND FLOOR - Hallway, living/dining room, kitchen. FIRST FLOOR - Landing, two bedrooms, shower room/WC. |
| Gross internal floor area (m²) | This is estimated at 62m2. |
| Neighbourhood and location | The property is situated within an established residential area of mixed public sector, tenanted and privately owner occupied housing on the southwestern periphery of the town of Bathgate. All the usual facilities and amenities are available locally and there is a regular public transport service to neighbouring communities and to the nearby cities of Edinburgh and Glasgow. |
| Age | This is estimated at 74 years. |
| Weather | At the time of inspection it was dry but dull and overcast. |
| Chimney stacks | Visually inspected with the aid of binoculars where appropriate. The chimney stack is of brick construction with concrete coping and clay pots. |
| Roofing including roof space | Sloping roofs were visually inspected with the aid of binoculars where appropriate. Flat roofs were visually inspected from vantage points within the property and where safe and reasonable to do so from a 3m ladder externally. Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. |

| Roofing including roof space | If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so. |
|-------------------------------------|---|
| | The roof is pitched with a tile covering over timber roof trusses. |
| | Access to the roof void is by means of a hatch located within the first floor landing ceiling. Fibre wool insulative material and stored personal items were present within the roof void area. |
| Rainwater fittings | Visually inspected with the aid of binoculars where appropriate. |
| | These are of a cast iron or PVC construction with guttering connected to downpipes. |
| | |
| Main walls | Visually inspected with the aid of binoculars where appropriate. |
| | Foundations and concealed parts were not exposed or inspected. |
| | These are of cavity brick with a render finish applied externally. |
| | |
| Windows, external doors and joinery | Internal and external doors were opened and closed where keys were available. |
| | Random windows were opened and closed where possible. |
| | Doors and windows were not forced open. |
| | The windows are of a PVC framed pivot or casement character with double glazed sealed units installed. |
| | The external doors are PVC framed and double glazed. |
| External decorations | Vigually inequated |
| LACTION GEOGRAPHIC | Visually inspected. |
| | Decorative finishes are in paint. |
| Conservatories / porches | There are no concernatories and there are no norches with this |
| Conservatories / porches | There are no conservatories and there are no porches with this property. |
| Communal areas | There are no communal areas. |
| Garages and permanent outbuildings | There is no garage and there are no significant permanent outbuildings. |
| | |

| Outside areas and boundaries | Visually inspected. |
|---------------------------------------|--|
| | Garden areas exist to the front, side and rear of the property. |
| | Boundaries, where present, are formed in timber and metal fences and brick and block walls. |
| Ceilings | Visually inspected from floor level. |
| | These are of a plasterboard nature. |
| | |
| Internal walls | Visually inspected from floor level. |
| | Using a moisture meter, walls were randomly tested for dampness where considered appropriate. |
| | These are of a plaster or plasterboard character. |
| Floors including sub floors | Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted. |
| | Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point. |
| | Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch. |
| | These are of a solid concerete or suspended timber nature. |
| | Floor coverings were fitted and no sub-floor inspection has been made. |
| | |
| Internal joinery and kitchen fittings | Built-in cupboards were looked into but no stored items were moved. |
| | Kitchen units were visually inspected excluding appliances. |
| | Internal doors are timber framed. |
| | Timber facings and skirting boards are present withnin the property. |
| | The staircase to first floor level is also of timber construction. |
| | There are fitted floor and wall units in the kitchen area. |
| Chimney breasts and fireplaces | Visually inspected. |
| | No testing of the flues or fittings was carried out. |
| | The chimney breast is of brick construction with a slab based fireplace. |

The fireplace itself is currently blocked and an electric fire is present in this area.

| Internal decorations | Visually inspected. |
|---|--|
| | Decorative finishes are in paint, paper or both. Some tiling and boarding have also been used. |
| Cellars | There are no cellars with this property. |
| Electricity | Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. |
| | There is a mains supply of electricity connected to the property. |
| | The distribution board, housing a fuse box, is located within an under-stair cupboard. Visible wiring was PVC coated. |
| Gas Water, plumbing, bathroom fittings | Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. There is a mains gas supply connected to the property. The gas meter is located within an external storage box. The gas supply serves the central heating boiler. Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. |
| | No tests whatsoever were carried out to the system or appliances. |
| | There is a mains water supply connected to the property. |
| | Visible plumbing fitments were of a copper or PVC nature. |
| | The shower room fittings, although not tested, appeared serviceable. |
| Heating and hot water | Accessible parts of the system were visually inspected apart from communal systems, which were not inspected. |
| | No tests whatsoever were carried out to the system or appliances. |
| | There is a gas fired central heating system serving panel radiators. |
| | The boiler for this is a Worcester Greenstar Unit located within a bedroom cupboard and vented externally by means of a balanced flue. |

The central heating boiler also provides domestic hot water.

Drainage covers etc were not lifted. Neither drains nor drainage systems were tested. This is understood to be connected to the main public sewer.

Fire, smoke and burglar alarms

Visually inspected.

No tests whatsoever were carried out to the system or appliances.

Smoke alarms, a heat detector and carbon monoxide detector were noted to be present within the property.

No comment is offered in respect of security systems.

The new Fire and Smoke Alarm Standard came into force in February 2022. This new standard requires a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also needs to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon-fuelled appliance such as a boiler, open fire, or wood burner a carbon monoxide detector is also required.


Any additional limits to inspection

The property was vacant but was furnished and did have fitted floor coverings.

No sub-floor inspection has been made and the roof void has been inspected on a head and shoulders basis only. It should also be stated that cupboard areas and the roof void contained stored personal items.

We do not carry out an inspection for Japanese Knotweed, which is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. We have assumed that there is no Japanese Knotweed within the boundaries of the property or in neighbouring properties. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists, removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4 Flashing
- 5) Ridge ventilation
- 6 Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- 10) Dormer flashing
- 11) Dormer cheeks
- (12) Sarking
- (13) Roof felt
- (14) Trusses
- (15) Collar
- (16) Insulation
- (17) Parapet gutter
- (18) Eaves guttering
- 19) Rainwater downpipe
- 20) Verge boards/skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- (24) Chimney breast
- (25) Window pointing
- 6) Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33) Damp proof course
- 34) Base course
- 35) Foundations
- (36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40 Hot water tank

2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

| Category 3 | Category 2 | Category 1 |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

| Structural movement | |
|---------------------|---|
| Repair category | 1 |
| Notes | There are no indications of significant structural movement within this or neighbouring properties. |

| Dampness, rot and infestation | |
|-------------------------------|---|
| Repair category | 1 |
| Notes | Moisture metere readings were obtained within the property, but at a level attributable to condensation or to the inheren moisture content of materials employed within the construction. Evidence of old water penetration was noted within the roof void area. |

| Chimney stacks | |
|-----------------|---|
| Repair category | 1 |
| Notes | There are no indications of defect requiring immediate action or repair. Ongoing maintenance should be anticipated in respect of pointing and flashings at the base of the chimney stack. |

| Roofing including roof space | |
|------------------------------|--|
| Repair category | 2 |
| Notes | Roof coverings appear to be original in nature. Care should be taken to ensure that adequate bedding is maintained at ridge tiles. Verge pointing was also noted to be cracked or missing. |
| | Some moss was present on roof coverings. |
| | Roofs are prone to water penetration during adverse weather, but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms. |

| Rainwater fittings | |
|--------------------|--|
| Repair category | 1 |
| Notes | Some organic material was noted to be present within guttering sections. |

| Main walls | |
|-----------------|--|
| Repair category | 2 |
| Notes | The render finish was noted to be cracked and boss in sections, particularly at lower levels. |
| | Cracked and weathered concrete sills were noted at window openings. |
| | Drill holes are also present indicating that cavity wall insulation has been installed. |
| | Care should be taken to ensure that adequate pionting is maintained at door and window openings. |

| Windows, external doors and joinery | |
|-------------------------------------|---|
| Repair category | 1 |
| Notes | There were no indications of defect requiring immediate action or repair. |

| External decorations | |
|----------------------|---|
| Repair category | 1 |
| Notes | Limited weathering was noted to decorative finishes externally. |

| Conservatories/porches | |
|------------------------|---|
| Repair category | - |
| Notes | There are no conservatories and there are no porches. |

| Communal areas | |
|-----------------|------------------------------|
| Repair category | - |
| Notes | There are no communal areas. |

| Garages and permanent outbuildings | |
|------------------------------------|---|
| Repair category | - |
| Notes | There is no garage and there are no significant permanent outbuildings. |

| Outside areas and boundaries | |
|------------------------------|--|
| Repair category | 2 |
| Notes | There are mature trees within the rear garden area. These will require careful management. |
| | Some damage was noted to brickwork and block work within boundary walls. It is understood that this wall is the responsibility of the neighbouring proprietor. |

| Ceilings | |
|-----------------|---|
| Repair category | 1 |
| Notes | Shrinkage cracking was noted. Textured finishes have been applied to some ceilings. Early forms of textured finish may contain asbestos material. |

| Internal walls | |
|-----------------|--|
| Repair category | 1 |
| Notes | Some unevenness was noted within plaster finishes. |

| Floors including sub-floors | |
|-----------------------------|--|
| Repair category | 1 |
| Notes | There were no indications of signifincant distortion or deflection found within flooring sections. |

| Internal joinery and kitchen fittings | |
|---------------------------------------|---|
| Repair category | 1 |
| Notes | Kitchen fittings are ageing. Some adjustment to cupboard hinges is anticipated. Some evidence of wear and tear was noted. |

| Chimney breasts and fireplaces | |
|--------------------------------|--|
| Repair category | 1 |
| Notes | There were no indications of defect requiring immediate action or repair. If a potential purchaser wishes to utilise the redundant flue, then it may be necessary to install a suitable flue liner. |

| Internal decorations | |
|----------------------|--|
| Repair category | 1 |
| Notes | Some limited marking was noted to decorative finishes. |
| | Paper seams are lifting slightly. |

| Cellars | |
|-----------------|--|
| Repair category | - |
| Notes | There are no cellars with this property. |

| Electricity | |
|-----------------|--|
| Repair category | 2 |
| Notes | The distribution board hosts a fuse box rather than a more modern circuit breaker unit. |
| | There are a limited number of power outlets in some apartments. |
| | Confirmation the system complies with current regulation and is in a serviceable condition can only be given by a qualified electrician. |
| | The trade bodies governing electrical installations currently advise that these should be tested prior to a change of occupancy and, thereafter, at least once every five years, by a competent Electrician. |

| Gas | |
|-----------------|---|
| Repair category | 1 |
| Notes | There were no visible indications of defect at the time of inspection. Confirmation the system complies with current regulation and is in a serviceable condition can only be given by a Gas Safe registered engineer. |

| Water, plumbing and bathroom fittings | | | | | | | |
|---------------------------------------|--|--|--|--|--|--|--|
| Repair category | category 1 | | | | | | |
| Notes | Care should be taken to ensuret that adequate sealant is maintained around the shower tray. It should be noted that flooring beneath the shower tray has not been subject to inspection. | | | | | | |

| Heating and hot water | | | | | | |
|-----------------------|--|--|--|--|--|--|
| Repair category | 1 | | | | | |
| Notes | There were no indications of defect requiring immediate action or repair. It has been assumed that the heating installation has been regularly serviced and that recent service history records will be made available. | | | | | |

| Drainage | |
|-----------------|--|
| Repair category | 1 |
| Notes | There were no indications of blockage or backup found at the time of inspection. |

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

| Structural movement | 1 |
|---------------------------------------|---|
| Dampness, rot and infestation | 1 |
| Chimney stacks | 1 |
| Roofing including roof space | 2 |
| Rainwater fittings | 1 |
| Main walls | 2 |
| Windows, external doors and joinery | 1 |
| External decorations | 1 |
| Conservatories/porches | - |
| Communal areas | - |
| Garages and permanent outbuildings | - |
| Outside areas and boundaries | 2 |
| Ceilings | 1 |
| Internal walls | 1 |
| Floors including sub-floors | 1 |
| Internal joinery and kitchen fittings | 1 |
| Chimney breasts and fireplaces | 1 |
| Internal decorations | 1 |
| Cellars | - |
| Electricity | 2 |
| Gas | 1 |
| Water, plumbing and bathroom fittings | 1 |
| Heating and hot water | 1 |
| Drainage | 1 |

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

| 1. Which floor(s) is the living accommodation on? | Ground floor & first floor | | |
|--|----------------------------|--|--|
| 2. Are there three steps or fewer to a main entrance door of the property? | Yes X No | | |
| 3. Is there a lift to the main entrance door of the property? | Yes No X | | |
| 4. Are all door openings greater than 750mm? | Yes No X | | |
| 5. Is there a toilet on the same level as the living room and kitchen? | Yes No X | | |
| 6. Is there a toilet on the same level as a bedroom? | Yes X No | | |
| 7. Are all rooms on the same level with no internal steps or stairs? | Yes No X | | |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | Yes X No | | |

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The property has been altered in the past in the provision of replacement windows and doors and in the conversion of the original bathroom to form a shower room. These works may have been undertaken more than 20 years ago.

The property is located in an area where mineral extraction has taken place. It would, therefore, be prudent to obtain a satisfactory Coal Authority Report.

Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a Category 1 rating is used this means that the building must continue to be maintained in the normal way. It is recommended that where repairs, defects or maintenance items have been identified within this report that interested parties make appropriate enquiries in order to satisfy themselves of potential costs or the extent of works required prior to submitting a legal offer to purchase.

Estimated reinstatement cost for insurance purposes

The estimated reinstatement cost for insurance purposes is £160,000 (One Hundred & Sixty Thousand Pounds Sterling).

This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction, on a reinstatement basis, assuming reconstruction of the property in its existing design and materials.

Valuation and market comments

The market value of the described property in the report is £150,000 (One Hundred & Fifty Thousand Pounds Sterling). This figure assumes vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights.

| Signed | Security Print Code [554631 = 6373] Electronically signed | | | | | |
|---------------|--|--|--|--|--|--|
| | | | | | | |
| Report author | R A Smith | | | | | |
| | | | | | | |
| Company name | Allied Surveyors Scotland Ltd | | | | | |
| | | | | | | |
| Address | 66 South Bridge Street, Bathgate, EH48 1TL | | | | | |

| Date of report | 17th September 2024 |
|----------------|---------------------|
|----------------|---------------------|



| Property Address | | | | | | | |
|---|---|--|--|--|--|--|--|
| Address 136 Falside Crescent, BATHGATE, EH48 2DS Seller's Name The Late Henrietta Mazs Date of Inspection 13th September 2024 | | | | | | | |
| Property Details | | | | | | | |
| Property Type | X House Bungalow Chalet Purpose built maisonette Coach Studio Converted maisonette Purpose built flat Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks) | | | | | | |
| Property Style | □ Detached X Semi detached ■ Mid terrace ■ End terrace □ Back to back □ High rise block □ Low rise block □ Other (specify in General Remarks) | | | | | | |
| Does the surveyor be e.g. local authority, m | elieve that the property was built for the public sector, X Yes No nilitary, police? | | | | | | |
| Flats/Maisonettes only | ly Floor(s) on which located No. of floors in block Lift provided? Yes No | | | | | | |
| Approximate Year of | No. of units in block Construction 1950 | | | | | | |
| Tenure | | | | | | | |
| X Absolute Ownership | Leasehold Ground rent £ Unexpired years | | | | | | |
| Accommodation | | | | | | | |
| Number of Rooms | 1 Living room(s) 2 Bedroom(s) 1 Kitchen(s) 1 Bathroom(s) 1 WC(s) 0 Other (Specify in General remarks) | | | | | | |
| Gross Floor Area (exc | cluding garages and outbuildings) 62 m² (Internal) 68 m² (External) | | | | | | |
| Residential Element (| (greater than 40%) X Yes No | | | | | | |
| Garage / Parking / | Outbuildings | | | | | | |
| Single garage Available on site? | □ Double garage ▼ Parking space ▼ Yes No | | | | | | |
| Permanent outbuildings: | | | | | | | |
| There are no signific | cant permanent outbuildings. | | | | | | |
| | | | | | | | |

| Construction | | | | | | | | | |
|--|--------------------|-------------------|------------|-----------------|--------------|----------------|----------------|--------------------|-----------------|
| Walls | X Brick | Stone | По | oncrete | Timbe | r frame | | | |
| | Solid | Cavity | | teel frame | | ete block | Oth | er (specify in Ge | neral Remarks) |
| Roof | X Tile | Slate | | sphalt | Felt | J. G. D. G. G. | | o. (opco) co. | iorai riomamo) |
| | Lead | Zinc | | rtificial slate | | ass fibre | Oth | er (specify in Ge | neral Remarks) |
| Special Risks | | | | | | | | | |
| Has the property s | uffered structu | ral moveme | ent? | | | | | Yes | X No |
| If Yes, is this recer | nt or progressiv | ve? | | | | | | Yes | No |
| Is there evidence, immediate vicinity' | | son to antic | ipate sub | sidence, h | eave, la | ndslip c | or flood in th | ne Yes | X No |
| If Yes to any of the | above, provid | le details in | General | Remarks. | | | | | |
| | | | | | | | | | |
| Service Connec | tion | | | | | | | | |
| Based on visual in of the supply in Ge | | | ces appea | ar to be no | on-mains | , pleas | e comment | on the type a | nd location |
| Drainage | X Mains | Private | None | | V | Vater | X Mains | Private | None |
| Electricity | X Mains | Private | None | | G | as | X Mains | Private | None |
| Central Heating | X Yes | Partial | None | | | | | | |
| Brief description of | f Central Heati | ng: | | | | | | | |
| There is a gas fir | ed central hea | ting system | serving p | panel radia | ators. | | | | |
| Site | | | | | | | | | |
| | | 11 41 | | DI. | ., | | | . 0 | |
| Apparent legal issu | | - | | | - | | _ | | |
| Rights of way | Shared drives | | _ | or other am | | separate | _ | ared service con | |
| Agricultural land inc | cluded with proper | ty | III-defin | ed boundari | es | | X Oth | ner (specify in Ge | eneral Remarks) |
| Location | | | | | | | | | |
| X Residential suburb | Resid | dential within to | own / city | Mixed r | esidential . | / comme | rcial Ma | inly commercial | |
| Commuter village | Remo | ote village | | Isolated | d rural prop | erty | Oth | ner (specify in Ge | eneral Remarks) |
| Planning Issues | | | | | | | | | |
| Has the property b | een extended | / converted | / altered | ? X Yes | s No | | | | |
| If Yes provide deta | ails in General | Remarks. | | | | | | | |
| Roads | | | | | | | | | |
| X Made up road | Unmade road | Partly | completed | new road | Ped | lestrian a | ccess only | Adopted | Unadopted |

| General Remarks |
|--|
| The property is situated within an established residential area of mixed public sector, tenanted and privately owner occupied housing on the southwestern periphery of the town of Bathgate. All the usual facilities and amenities are available locally and there is a regular public transport service to neighbouring communities and to the nearby cities of Edinburgh and Glasgow. |
| The property was found to be in a condition consistent with age and construction. Some upgrading of fittings, fixtures and services has taken place in the past but with further works anticipated. Ongoing maintenance should be envisaged in respect of all elements of the building fabric. |
| The property has been altered in the past in the provision of replacement windows and doors and in the conversion of the original bathroom to form a shower room/WC. These works may have been undertaken more than 20 years ago. |
| The property is also located in an area where mineral extraction has taken place. |
| |
| |
| |
| |
| Essential Repairs |
| None. |
| |
| |
| |
| |
| |
| |
| |
| |
| Estimated cost of essential repairs £ Retention recommended? Yes X No Amount £ |

| Comment on Mortgagea | bility | |
|--|---|--------------------------|
| | for which, in normal marketing conditions, there is a steady demand. d to form adequate loan security, subject to individual lenders criteria. | |
| Valuations | | |
| Market value in present con Market value on completion Insurance reinstatement va (to include the cost of total it Is a reinspection necessary | n of essential repairs lue rebuilding, site clearance, professional fees, ancillary charges plus VAT) | £ 150,000 £ £ 160,000 |
| Buy To Let Cases | | |
| month Short Assured Tenai | ge of monthly rental income for the property assuming a letting on a 6 ncy basis? here there is a steady demand for rented accommodation of this type? | £ Yes No |
| Signed Surveyor's name Professional qualifications Company name Address Telephone Fax | Security Print Code [554631 = 6373] Electronically signed by:- R A Smith BSc MRICS Allied Surveyors Scotland Ltd 66 South Bridge Street, Bathgate, EH48 1TL 01506 631 717 01506 633 591 | |
| · | | |

Energy Performance Certificate (EPC)

Dwellings

Scotland

136 FALSIDE CRESCENT, BATHGATE, EH48 2DS

Dwelling type: Semi-detached house
Date of assessment: 13 September 2024
Date of certificate: 13 September 2024

Total floor area: 62 m²

Primary Energy Indicator: 265 kWh/m²/year

Reference number: 0180-2947-9010-2594-8451 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

| Estimated energy costs for your home for 3 years* | £3,708 | See your recommendations |
|---|--------|--------------------------------|
| Over 3 years you could save* | £582 | report for more information |

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (68)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO_2) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (68)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

| Recommended measures | Indicative cost | Typical savings over 3 years |
|--------------------------------------|-----------------|------------------------------|
| 1 Floor insulation (suspended floor) | £800 - £1,200 | £345.00 |
| 2 Low energy lighting | £20 | £90.00 |
| 3 Solar water heating | £4,000 - £6,000 | £147.00 |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element | Description | Energy Efficiency | Environmental |
|-----------------------|---|-------------------|---------------|
| Walls | Cavity wall, filled cavity | *** | ★★★☆☆ |
| Roof | Pitched, 300 mm loft insulation | **** | **** |
| Floor | Suspended, no insulation (assumed) | _ | _ |
| Windows | Fully double glazed | ★★★★ ☆ | ★★★★ ☆ |
| Main heating | Boiler and radiators, mains gas | ★★★★ ☆ | ★★★★ ☆ |
| Main heating controls | Programmer, room thermostat and TRVs | ★★★★ ☆ | ★★★★ ☆ |
| Secondary heating | Room heaters, electric | _ | _ |
| Hot water | From main system | **** | ★★★★ ☆ |
| Lighting | Low energy lighting in 56% of fixed outlets | ★★★★ ☆ | ★★★★ ☆ |

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 46 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.9 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

| | Current energy costs | Potential energy costs | Potential future savings |
|-----------|----------------------|------------------------|--------------------------|
| Heating | £2,949 over 3 years | £2,622 over 3 years | |
| Hot water | £411 over 3 years | £264 over 3 years | You could |
| Lighting | £348 over 3 years | £240 over 3 years | save £582 |
| Totals | £3,708 | £3,126 | over 3 years |


These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

| Recommended measures | | Indicative cost | Typical saving | Rating after improvement | |
|----------------------|---|-----------------|----------------|--------------------------|-------------|
| | | Indicative cost | per year | Energy | Environment |
| 1 | Floor insulation (suspended floor) | £800 - £1,200 | £115 | C 70 | C 72 |
| 2 | Low energy lighting for all fixed outlets | £20 | £30 | C 71 | C 72 |
| 3 | Solar water heating | £4,000 - £6,000 | £49 | C 72 | C 74 |
| 4 | Solar photovoltaic panels, 2.5 kWp | £3,500 - £5,500 | £467 | B 85 | B 86 |

Choosing the right improvement package





About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

2 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

3 Solar water heating

A solar water heating panel, usually fixed to the roof, uses the sun to pre-heat the hot water supply. This can significantly reduce the demand on the heating system to provide hot water and hence save fuel and money. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. You could be eligible for Renewable Heat Incentive payments which could appreciably increase the savings beyond those shown on your EPC, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

4 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

| Heat demand | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 8,129 | N/A | N/A | N/A |
| Water heating (kWh per year) | 1,664 | | | |

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name: Mr. Robert Smith Assessor membership number: EES/008344

Company name/trading name:
Allied Surveyors Scotland Ltd
Address:
Allied Surveyors Scotland Ltd
66 South Bridge Street

66 South Bridge Street Bathgate

EH48 1TL 01506631717

Phone number: 01506631717
Email address: bathqate@alliedsurveyorsscotland.com

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greeners cotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



| Property address | 136 Falside Crescent |
|-------------------------|----------------------|
| | BATHGATE |
| | West Lothian |
| | EH48 2TD |
| | |
| | |
| | |
| | |
| | |

| Sneddon Morrison |
|------------------|
| |

| Completion date of property questionnaire | 12/09/2024 |
|---|------------|
|---|------------|

Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

Information to be given to prospective buyer(s)

| 1. | Length of ownership | | |
|----|---|---------------------------|--|
| | How long have you owned the p | roperty? 32 years | |
| 2. | Council tax | | |
| | Which Council Tax band is your | | |
| 3. | Parking | | |
| | What are the arrangements for properties (Please tick all that apply) | parking at your property? | |
| | Garage | | |
| | Allocated parking space | | |
| | Driveway | \boxtimes | |
| | Shared parking | | |
| | On street | | |
| | Resident permit | | |
| | Metered parking | | |
| | Other (please specify): | | |
| 4. | Conservation area | | |
| | Is your property in a designated of special architectural or historic appearance of which it is desirable | ☐ Yes ☑ No ☐ Don't know | |

| 5. | Listed buildings | | | | |
|----|---|-----------------------|--|--|--|
| | Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)? | ☐ Yes ☑ No | | | |
| 6. | Alterations/additions/extensions | | | | |
| a. | (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? | ☐ Yes ☑ No | | | |
| | If you have answered yes, please describe below the changes which you have made: | | | | |
| | (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? | ☐ Yes ☑ No | | | |
| | If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. | | | | |
| | If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them: | | | | |
| b. | Have you had replacement windows, doors, patio doors or double glazing installed in your property? | ⊠ Yes □ No | | | |
| | If you have answered yes, please answer the three questions below: | | | | |
| | (i) Were the replacements the same shape and type as the ones you replaced? | ☐ Yes ☑ No | | | |
| | (ii) Did this work involve any changes to the window or door openings? | ☐ Yes ☑ No | | | |
| | (iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed): | | | | |
| | single glazed windows & back door replaced with UPVC double glazed units Apr 1999. Front wooden door replaced with UPVC double glazed units Sep 2022 | | | | |
| | Please give any guarantees which you received for this work to you agent. | r solicitor or estate | | | |

| 7. | Central heating | |
|----|--|---------------|
| | | |
| a. | Is there a central heating system in your property? | ⊠ Yes |
| | (Note: a partial central heating system is one which does not heat all the main rooms of the property — | □ No |
| | the main living room, the bedroom(s), the hall and the bathroom). | ☐ Partial |
| | If you have answered yes or partial – what kind of central heating is there? | |
| | (Examples: gas-fired, solid fuel, electric storage heating, gas warm air). | |
| | gas central heating & electric fire in living room. | |
| | If you have answered yes, please answer the three questions below: | |
| | (i) When was your central heating system or partial central heat installed? | ing system |
| | | CENTRA |
| | (ii) Do you have a maintenance contract for the central heating system? | ☐ Yes |
| | If you have answered yes, please give details of the company with which you have a maintenance contract: | ⊠ No |
| * | maintenance agreement ended on 29 July 2024 following the death of Mrs Rita Mazs. | |
| | (iii) When was your maintenance agreement last renewed? (Pleas month and year). | e provide the |
| | 09/07/2024 | |
| 8. | Energy Performance Certificate | |
| | Does your property have an Energy Performance Certificate which | Yes |
| | is less than 10 years old? | ⊠ No |
| 9. | Issues that may have affected your property | |
| a. | Has there been any storm, flood, fire or other structural damage to | |
| | your property while you have owned it? | ☐ Yes ☐ No |
| | If you have answered was in the d | ⊠ NO |
| | If you have answered yes, is the damage the subject of any outstanding insurance claim? | Yes |
| | | □ No |
| b. | Are you aware of the existence of asbestos in your property? | Yes |
| | If you have answered yes, please give details: | ⊠ No |
| | | |

| D | lease tick which services are con | nected to your prop | erty and give details | s of the supplier: |
|---|---|-------------------------|-----------------------|--------------------|
| • | Services | Connected | Supplier | |
| | Gas or liquid petroleum gas | yes | ovo | |
| | Water mains or private water supply | yes | West Lothia | n Council |
| | Electricity | yes | ονο | |
| | Mains drainage | yes | West Lothia | an Council |
| | Telephone | Yes | SKY | |
| | Cable TV or satellite | Yes | SKY | |
| | Broadband | yes | SKY | |
| æ | Is there a septic tank system If you have answered yes, pl | | o questions below: | ☐ Yes ☑ No |
| | (iv) Do you have appropri your septic tank? | ☐ Yes ☑ No ☐ Don't Know | | |
| | (v) Do you have a mainte If you have answered yes, p which you have a maintenar | lease give details of | | ☐ Yes ⊠ No |

| 1. | Responsibilities for shared or common areas | |
|-----|---|-------------------------------|
| | Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? | ☐ Yes ☑ No ☐ Don't Know |
| | If you have answered yes, please give details: | |
| b. | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? | ☐ Yes ☑ No |
| | If you have answered yes, please give details: | ☐ Not applicable |
| C. | Has there been any major repair or replacement of any part of the roof during the time you have owned the property? | ☐ Yes ⊠ No |
| d. | Do you have the right to walk over any of your neighbours' property — for example to put out your rubbish bin or to maintain your boundaries? If you have answered yes, please give details: | ☐ Yes ☑ No |
| e. | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details: | ☐ Yes ☑ No |
| f. | As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.) If you have answered yes, please give details: | ☐ Yes ☑ No |
| 12. | Charges associated with your property | |
| a. | Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges: C-URB Factoring £55.68 per annum | ⊠ Yes □ No |

| | Is there a common buildings insurance policy? | ☐ Yes ☑ No ☐ Don't Know |
|-----|---|-------------------------------|
| | If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges? | ☐ Yes ☐ No ☐ Don't Know |
| | Please give details of any other charges you have to pay on a regular upkeep of common areas or repair works, for example to a residents maintenance or stair fund. | basis for the association, or |
| 13. | Specialist works | |
| а. | As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property. | ☐ Yes ☑ No |
| b. | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? If you have answered yes, please give details: | Yes No |
| C. | If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. | ☐ Yes ☑ No |
| | original estimate. | |

| 14. | Guarantees | | | | | |
|-------|---|-----------------------|------------|---------------|-----------------------------|---------------|
| a. | Are there any guarantees or warranties fo | r any of | the follow | wing: | | |
| | | No | Yes | Don't know | With title deeds | Lost |
| (i) | Electrical work | \boxtimes | | | | |
| (ii) | Roofing | \boxtimes | | | | |
| (iii) | Central heating | | | | | AUARI ENTR |
| (iv) | National House Building Council (NHBC) | \boxtimes | | | | ENTR |
| (v) | Damp course | \boxtimes | | | | |
| (vi) | Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy) | \boxtimes | | | | |
| b. | If you have answered 'yes' or 'with title do installations to which the guarantee(s) rel | eeds', ple ate(s): | ease give | e details o | of the work o | r |
| c. | Are there any outstanding claims under any of the guarantees listed above? ☐ Yes ☐ Yes ☐ No | | | | | |
| 15. | Boundaries | | | | | |
| | So far as you are aware, has any boundar moved in the last 10 years? If you have answered yes, please give de | | r propert | y been | ☐ Yes ☑ No ☐ Don't kr | now |

| 16. | Notices that | affect your property | |
|-------------|------------------------------|---|--|
| | In the past the | ree years have you ever received a notice: | |
| a. | advising that planning appli | the owner of a neighbouring property has made a cation? | ☐ Yes ☑ No |
| b. | that affects ye | our property in some other way? | ☐ Yes ⊠ No |
| C. | that requires to your prope | you to do any maintenance, repairs or improvements rty? | ☐ Yes ☑ No |
| | or estate age | inswered yes to any of $a-c$ above, please give the noticent, including any notices which arrive at any time before of your property. | ces to your solicitor are the date of entry |
| | | | |
| T/V | Ve confirm th | ne seller(s)/or other authorised body or pers at the information in this form is true and co ledge and belief. | |
| I/Y of i | Ve confirm th | at the information in this form is true and co | |