



15 WEST MAINS ROAD EAST KILBRIDE GLASGOW G74 1NQ



### **Energy Performance Certificate (EPC)**

**Dwellings** 

# **Scotland**

#### 15 WEST MAINS ROAD, EAST KILBRIDE, GLASGOW, G74 1NQ

Dwelling type: Ground-floor flat
Date of assessment: 31 January 2025
Date of certificate: 04 February 2025

Total floor area: 74 m<sup>2</sup>

Primary Energy Indicator: 203 kWh/m²/year

**Reference number:** 0120-2829-7190-2775-1711 **Type of assessment:** RdSAP, existing dwelling

Approved Organisation: Elmhurst

Main heating and fuel: Boiler and radiators, mains


gas

#### You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

Estimated energy costs for your home for 3 years*	£2,592	See your recommendations
Over 3 years you could save*	£363	report for more information

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




#### **Energy Efficiency Rating**

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (74)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



#### **Environmental Impact (CO<sub>2</sub>) Rating**

This graph shows the effect of your home on the environment in terms of carbon dioxide  $(CO_2)$  emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (74)**. The average rating for EPCs in Scotland is **band D (59)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

### Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Floor insulation (suspended floor)	£800 - £1,200	£363.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, filled cavity	<b>★★★☆☆</b>	<b>★★★☆☆</b>
Roof	(another dwelling above)	_	_
Floor	Suspended, no insulation (assumed)	_	_
Windows	Fully triple glazed	****	<b>★★★★</b> ☆
Main heating	Boiler and radiators, mains gas	****	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	****	★★★★☆
Secondary heating	None	_	_
Hot water	From main system	****	★★★★☆
Lighting	Low energy lighting in all fixed outlets	****	****

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 36 kg CO<sub>2</sub>/m<sup>2</sup>/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 2.6 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

#### Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£1,977 over 3 years	£1,614 over 3 years	
Hot water	£363 over 3 years	£363 over 3 years	You could
Lighting	£252 over 3 years	£252 over 3 years	save £363
Totals	£2,592	£2,229	over 3 years

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

December ded massimes	commended measures Indicative cost per years		Rating after improvement		
Recommended measures			Energy	Environment	
1 Floor insulation (suspended floor)	£800 - £1,200	£121	C 78	C 78	

### Choosing the right improvement package



For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

#### **Recommendations Report**

#### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	7,910	N/A	N/A	N/A
Water heating (kWh per year)	1,865			

#### **About this document**

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:
Assessor membership number:
Company name/trading name:
Address:

Mr. Calum Steven
EES/022236
J & E Shepherd
67 Srathmore House

East Kilbride G74 1LQ

Phone number: 01698891400

Email address: calum.steven@wbcs.co.uk

Related party disclosure: No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

#### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT





### survey report on:

Property address	15 WEST MAINS ROAD, EAST KILBRIDE, GLASGOW, G74 1NQ

Customer	Ms Hollie Wilson

Customer address	15 West Mains Road, East Kilbride, Glasgow, G74 1NQ

Prepared by	J & E Shepherd
-------------	----------------

Date of inspection	31st January 2025
•	



Tel: 0845 263 7995

www.shepherd.co.uk

#### **PART 1 - GENERAL**

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

Х

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

<sup>&</sup>lt;sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether
  or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.<sup>2</sup>

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### 1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller:
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

#### PART 2 - DESCRIPTION OF THE REPORT

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	Ground floor flat in a two storey block of four similar properties.
Accommodation	The accommodation comprises:  Ground Floor: Entrance Hall, Living Room, 3 Bedrooms, Kitchen and Bathroom.
Gross internal floor area (m²)	74m2 approximately.
Neighbourhood and location	Mixed residential/commercial area in the original village of East Kilbride with shopping, educational, social and transport facilities available within close proximity.
Age	1920 approximately.
Weather	Dry and overcast.
Chimney stacks	Visually inspected with the aid of binoculars where appropriate.  There is a brick built chimney head with a painted render finish and lead flashings.
Roofing including roof space	Sloping roofs were visually inspected with the aid of binoculars where appropriate.  Pitched design clad in concrete interlocking tiles. No access was available to the common roof space.

Rainwater fittings  Visually inspected with the aid of binoculars where appropriate.  PVC and cast iron gutters and downpipes.  Main walls  Visually inspected with the aid of binoculars where appropriate.  Foundations and concealed parts were not exposed or inspected.  300mm cavity brick built with a painted render external finish.  Windows, external doors and joinery  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were not forced open.  UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The ear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  External decorations  Visually inspected.  Painted finishes.  Conservatories / porches  N/A  Outside areas and boundaries  Visually inspected.  There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level.  These are formed in plasterboard.		
Main walls  Visually inspected with the aid of binoculars where appropriate. Foundations and concealed parts were not exposed or inspected. 300mm cavity brick built with a painted render external finish.  Windows, external doors and joinery  Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The eraer entrance door is pvc framed double glazed. The eaves area are formed in painted concrete.  External decorations  Visually inspected. Painted finishes.  Conservatories / porches  N/A  Outside areas and boundaries  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.	Rainwater fittings	
appropriate.  Foundations and concealed parts were not exposed or inspected.  300mm cavity brick built with a painted render external finish.  Windows, external doors and joinery  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were not forced open.  UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  External decorations  Visually inspected.  Painted finishes.  Conservatories / porches  N/A  Communal areas  N/A  Outside areas and boundaries  Visually inspected.  There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level.  These are formed in plasterboard.		PVC and cast iron gutters and downpipes.
appropriate. Foundations and concealed parts were not exposed or inspected. 300mm cavity brick built with a painted render external finish.  Windows, external doors and joinery Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  External decorations Visually inspected. Painted finishes.  Conservatories / porches N/A  Communal areas N/A  Outside areas and boundaries Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings Visually inspected from floor level. These are formed in plasterboard.  Visually inspected from floor level. These are formed in plasterboard.		
inspected. 300mm cavity brick built with a painted render external finish.  Windows, external doors and joinery  Internal and external doors were opened and closed where keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open.  UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  External decorations  Visually inspected. Painted finishes.  Conservatories / porches  N/A  Communal areas  N/A  Outside areas and boundaries  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.  Visually inspected from floor level. These are formed in plasterboard.	Main walls	
Windows, external doors and joinery  Internal and external doors were opened and closed where keys were available.  Random windows were opened and closed where possible.  Doors and windows were not forced open.  UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  External decorations  Visually inspected.  Painted finishes.  Conservatories / porches  N/A  Outside areas and permanent outbuildings  Visually inspected.  There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level.  These are formed in plasterboard.  Visually inspected from floor level.  These are formed in plasterboard.		
keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  External decorations  Visually inspected. Painted finishes.  Conservatories / porches  N/A  Communal areas  N/A  Outside areas and permanent outbuildings  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.		300mm cavity brick built with a painted render external finish.
keys were available. Random windows were opened and closed where possible. Doors and windows were not forced open. UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  External decorations  Visually inspected. Painted finishes.  Conservatories / porches  N/A  Communal areas  N/A  Outside areas and permanent outbuildings  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.		
Doors and windows were not forced open.  UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  External decorations  Visually inspected. Painted finishes.  Communal areas  N/A  Communal areas  N/A  Outside areas and boundaries  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.  Visually inspected from floor level. Internal walls	Windows, external doors and joinery	•
UPVC triple glazed windows. The side entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The rear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  External decorations  Visually inspected. Painted finishes.  Conservatories / porches  N/A  N/A  Communal areas  N/A  Outside areas and permanent outbuildings  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.  Visually inspected from floor level.		Random windows were opened and closed where possible.
double glazed. The rear entrance door is pvc framed double glazed. The eaves areas are formed in painted concrete.  Visually inspected. Painted finishes.  Conservatories / porches  N/A  N/A  Garages and permanent outbuildings  N/A  Outside areas and boundaries  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.  Internal walls  Visually inspected from floor level.		Doors and windows were not forced open.
Painted finishes.  Conservatories / porches  N/A  Communal areas  N/A  Garages and permanent outbuildings  N/A  Outside areas and boundaries  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.  Internal walls  Visually inspected from floor level.		double glazed. The rear entrance door is pvc framed double
Painted finishes.  Conservatories / porches  N/A  Communal areas  N/A  Garages and permanent outbuildings  N/A  Outside areas and boundaries  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.  Internal walls  Visually inspected from floor level.		
Conservatories / porches  N/A  Communal areas  N/A  Garages and permanent outbuildings  N/A  Outside areas and boundaries  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.  Internal walls  Visually inspected from floor level.	External decorations	Visually inspected.
Communal areas  N/A  Garages and permanent outbuildings  N/A  Outside areas and boundaries  Visually inspected.  There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level.  These are formed in plasterboard.		Painted finishes.
Garages and permanent outbuildings  N/A  Visually inspected. There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level. These are formed in plasterboard.  Internal walls  Visually inspected from floor level.	Conservatories / porches	N/A
Outside areas and boundaries  Visually inspected.  There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level.  These are formed in plasterboard.  Visually inspected from floor level.	Communal areas	N/A
There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level.  These are formed in plasterboard.  Visually inspected from floor level.	Garages and permanent outbuildings	N/A
There are garden grounds to the front and rear generally laid to tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level.  These are formed in plasterboard.  Visually inspected from floor level.		
tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level.  These are formed in plasterboard.  Visually inspected from floor level.  Visually inspected from floor level.	Outside areas and boundaries	Visually inspected.
tarmac, stone chips, grass, timber decking and paving. Boundaries are generally marked by hedging, timber fencing, wire mesh/timber fencing and brick walling.  Ceilings  Visually inspected from floor level.  These are formed in plasterboard.  Visually inspected from floor level.  Visually inspected from floor level.		There are garden grounds to the front and rear generally laid to
Ceilings  Visually inspected from floor level.  These are formed in plasterboard.  Visually inspected from floor level.  Visually inspected from floor level.		tarmac, stone chips, grass, timber decking and paving. Boundaries
These are formed in plasterboard.  Internal walls  Visually inspected from floor level.		
These are formed in plasterboard.  Internal walls  Visually inspected from floor level.		
Internal walls  Visually inspected from floor level.	Ceilings	Visually inspected from floor level.
visually inspected near new		These are formed in plasterboard.
visually inspected nem need level	Internal walls	
	internal walls	Visually inspected from floor level.
dampness where considered appropriate.		Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
		The walls are a mixture of plastered masonry and plasterboard.

Floors including sub floors	Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.
	Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.
	Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.
	The flooring is generally of suspended timber construction with tongue and grooved boarding laid on timber joists. The remaining flooring is of concrete construction. Access to the floors was restricted by the presence of fitted coverings. There was no means of access to any sub floor areas.
Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were
memar joinery and known mange	moved.
	Kitchen units were visually inspected excluding appliances.
	Painted softwood finishes with timber panelled internal doors. The kitchen is fitted with a combination of base and wall mounted units.
Chimney breasts and fireplaces	Visually inspected.
	No tooting of the fluor or fittings was serviced out
	No testing of the flues or fittings was carried out.
	The chimney breasts are formed in plastered masonry and the fireplaces have been blocked up.
Internal decorations	The chimney breasts are formed in plastered masonry and the fireplaces have been blocked up.
Internal decorations	The chimney breasts are formed in plastered masonry and the fireplaces have been blocked up.  Visually inspected.
Internal decorations	The chimney breasts are formed in plastered masonry and the fireplaces have been blocked up.
Internal decorations  Cellars	The chimney breasts are formed in plastered masonry and the fireplaces have been blocked up.  Visually inspected.
Cellars	The chimney breasts are formed in plastered masonry and the fireplaces have been blocked up.  Visually inspected.  The decoration is a combination of painted and papered finishes.  None
	The chimney breasts are formed in plastered masonry and the fireplaces have been blocked up.  Visually inspected.  The decoration is a combination of painted and papered finishes.

Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	Mains supply. The gas meter is located externally.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.
	No tests whatsoever were carried out to the system or appliances.
	Mains supply. The plumbing installation is formed in a combination of metal and plastic pipework. A three piece white bathroom suite is installed with a mixer shower over the bath.
Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Gas boiler with radiators. The wall mounted boiler heats a series of radiators and provides an instantaneous hot water supply.
Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	To main sewer.
Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	Fire Safety Legislation effective from February 2022 requires a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat detecting alarm must be installed in every kitchen area and all smoke and heat alarms must be ceiling mounted and interlinked. Where there is a carbon-fuelled appliance e.g. central heating boiler, open fire, wood burning stove etc, a carbon monoxide detector is also required. The purchaser(s) should appraise themselves of the requirements of this legislation and engage with appropriately accredited contractors to ensure compliance.

#### Any additional limits to inspection

#### For flats / maisonettes

Only the subject flat and internal communal areas giving access to the flat were inspected.

If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.

The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.

The property was occupied, fully furnished and all floors were covered. Cupboards were filled with stored items. The hall cupboard was filled with stored items and so only a restricted view of the electrical apparatus was available. No access was available to the common roof space.

No inspection of floor surfaces was possible under WCs, baths, showers, or washing machines or similar water using appliances and these should be checked at regular intervals as water seepage can cause problems.

Services have not been tested. To have these tested arrangements should be made with suitably qualified electricians, plumbers, heating engineers etc.

Roofs are prone to water penetration during adverse weather but it is not always possible for surveyors to identify this likelihood in good or dry conditions. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after inclement weather. The construction materials described in this report should not be considered as an exact specification. They are described for general guide only and based on a non-disruptive, visual inspection as defined in the main Terms & Conditions. Some descriptions may be partial and/or assumed. No detailed analysis, sampling or testing of materials has been undertaken.


Due to the nature and/or age of some properties deleterious materials e.g. asbestos or Reinforced Autoclaved Aerated Concrete (RAAC) can be present in the building fabric and/or the finished surfaces to such e.g. hidden walls or roof sections, textured coatings such as Artex, floor/ceiling/wall tiles, claddings, linings etc. If any of these elements are applicable to the property under report and should you require certainty of the construction of any part of the property (including any outbuildings or garages) then a detailed Building Survey or sample testing of materials by qualified technicians/scientists should be undertaken prior to concluding purchase. This degree of reporting is clearly out-with the scope of this form of inspection. This is not an Asbestos survey and should not be construed as such in any degree. Should this form of inspection, or indeed any other form of inspection to identify deleterious materials within the property, e.g. Reinforced Autoclaved Aerated Concrete (RAAC), be required this should be provided by suitably qualified specialists under separate instructions.

No inspection for Japanese Knotweed or other invasive plant

#### Any additional limits to inspection

species has been carried out and unless otherwise stated, for the purposes of this report, it is assumed there is no Japanese Knotweed or other invasive plant species within the boundaries of the property or in neighbouring properties. The identification of Japanese Knotweed or other invasive plant species should be made by a specialist contractor.

### Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

- 1) Chimney pots
- 2) Coping stone
- 3) Chimney head
- 4 Flashing
- 5 Ridge ventilation
- 6) Ridge board
- 7) Slates / tiles
- 8 Valley guttering
- 9 Dormer projection
- (10) Dormer flashing
- 11) Dormer cheeks
- 12) Sarking
- (13) Roof felt
- (14) Trusses
- 15) Collar
- (16) Insulation
- (17) Parapet gutter
- (18) Eaves guttering
- (19) Rainwater downpipe
- 20) Verge boards/skews
- 21) Soffit boards
- 22) Partition wall
- 23) Lath / plaster
- 24) Chimney breast
- (25) Window pointing
- 6) Window sills
- 27) Rendering
- (28) Brickwork / pointing
- 29) Bay window projection
- 30 Lintels
- (31) Cavity walls / wall ties
- 32) Subfloor ventilator
- 33 Damp proof course
- 34) Base course
- 35) Foundations
- (36) Solum
- 37) Floor joists
- 38) Floorboards
- 39) Water tank
- 40 Hot water tank

#### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	There is evidence of previous movement to the building which is assumed to be of a longstanding nature. There was no evidence of significant ongoing movement.

Dampness, rot and infestation	
Repair category	1
Notes	No evidence of significant problems with dampness, dry rot or active woodworm infestation.

Chimney stacks	
Repair category	2
Notes	There is some cracked, missing and weathered render and the chimney head is affected by moss build-up.

Roofing including roof space		
Repair category	2	
Notes	The roof tiles are affected by weathering and moss build-up. There is some missing pvc verge tiling, some missing concrete hip tiling and there is a loose/uneven ridge tile adjacent to the chimney. The vendor advised that these tiles were dislodged during the violent storm on 24th January 2025.	

Rainwater fittings	
Repair category	2
Notes	The cast iron rainwater fittings are affected by corrosion.
	There is some vegetation build-up at downpipe joints.

Main walls	
Repair category	2
Notes	There is some weathered brickwork and open mortar pointing at the brick base.
	There is some weathered, cracked and loose render.

Windows, external doors and joinery	
Repair category	1
Notes	No significant defects.  Double/triple glazed units deteriorate as they age and can fail at any time.  Opening mechanisms and seals are particularly prone to unexpected failure.

External decorations	
Repair category	2
Notes	There are some weathered painted finishes.

Conservatories/porches	
Repair category	-
Notes	N/A

Communal areas	
Repair category	-
Notes	N/A

Garages and permanent outbuildings	
Repair category	-
Notes	N/A

Outside areas and boundaries	
Repair category	2
Notes	There are trees within close proximity to the block. Trees require to be regularly maintained.
	There is some incomplete, decayed and off level boundary fencing and there is some weathered brickwork at the brick walling.

Ceilings	
Repair category	2
Notes	There is staining on the kitchen ceiling. The affected area was found to be dry where tested with a moisture meter.
	There is staining on the living room ceiling and elevated moisture meter readings were obtained at the same location. It is good practice for this to be investigated and for any necessary repairs to be undertaken.
	There is staining on the rear bedroom ceiling. The affected area was found to be dry where tested with a moisture meter.

Internal walls	
Repair category	1
Notes	There is staining on upper walling in the kitchen. The affected area was found to be dry where tested with a moisture meter.
	There is staining on upper walling in the rear bedroom. The affected area was found to be dry where tested with a moisture meter.
	There is mould build-up surrounding the majority of the window openings and surrounding the rear entrance doorway.

Floors including sub-floors	
Repair category	1
Notes	No significant visible defects.

Internal joinery and kitchen fittings	
Repair category	1
Notes	The joinery is consistent with age and type and the kitchen fittings are affected by typical wear and tear.

Chimney breasts and fireplaces	
Repair category	1
Notes	No significant defects.

Internal decorations	
Repair category	1
Notes	No significant defects.

Cellars	
Repair category	-
Notes	N/A

Electricity	
Repair category	1
Notes	Where visible, the electrical switchgear was found to be of a modern nature.
	It is assumed that building regulation approval has been obtained for any electrical alteration or installation carried out after 1 January 2005.
	The Institution of Engineering and Technology (IET) recommends that inspections and testings are undertaken at least every five years and on a change of occupancy for tenanted property or every ten years or change of ownership for owner occupied properties. It should be appreciated that only the most recently constructed or re-wired properties will have installations which fully comply with IET regulations and codes of practice.

Gas	
Repair category	1
Notes	In the interests of safety and to meet current regulations, all gas appliances, pipework and fittings should be checked by a registered 'Gas Safe' engineer with any repairs or replacements recommended by the engineer carried out immediately.

► Water, plumbing and bathroom fittings						
Repair category	1					
Notes	No significant defects.					

Heating and hot water						
Repair category	1					
Notes	The central heating boiler is understood to be in the region of 10 years old. It is good practice to have the heating system checked on change of occupancy and annually thereafter by a Gas Safe engineer.					

Drainage	
Repair category	1
Notes	No indications of problems with the drainage system.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	2
Roofing including roof space	2
Rainwater fittings	2
Main walls	2
Windows, external doors and joinery	1
External decorations	2
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	-
Outside areas and boundaries	2
Ceilings	2
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

#### **Category 3**

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground		
2. Are there three steps or fewer to a main entrance door of the property?	Yes No X		
3. Is there a lift to the main entrance door of the property?	Yes No X		
4. Are all door openings greater than 750mm?	Yes No X		
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No		
6. Is there a toilet on the same level as a bedroom?	Yes X No		
7. Are all rooms on the same level with no internal steps or stairs?	Yes X No		
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No		

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

The property is located within a Conservation Area which may restrict future development/alteration of the subjects and this should be confirmed by the conveyancer. It is assumed that all necessary Local Authority consents have been duly sought and gained for any alterations.

Unless stated otherwise within this report and in the absence of any information to the contrary, we have assumed that:

All buildings have been erected either prior to planning control, or in accordance with planning permissions, and have the benefit of permanent planning consents or existing use rights for their current use;

The property is not adversely affected by town planning or road proposals;

All alterations, additions or extensions to the property have received all necessary Town Planning Consents, Building Authority Approvals (Building Warrants) and Completion Certificates;

The property complies with all relevant statutory and local authority requirements, including but not limited to Fire Regulations, The Equality Act, The Control of Asbestos Act, Health and Safety Regulations, Environmental Health Regulations, Regulations governing Residential Tenancies and similar.

#### Estimated reinstatement cost for insurance purposes

The property should be insured on a reinstatement basis for not less than £178,000 (ONE HUNDRED AND SEVENTY EIGHT THOUSAND POUNDS).

This is an indicative figure only, based on the current Building Cost Information Service (BCIS) published rates. It is good practice to regularly review this figure as building costs can increase rapidly. Specific specialist advice should be obtained from the building insurers where necessary.

#### Valuation and market comments

The market value of the property, at the present time, may be fairly stated in the sum of £145,000 (ONE HUNDRED AND FORTY FIVE THOUSAND POUNDS).

The housing market has been buoyant since reopening after the Covid19 pandemic with demand levels often exceeding supply, resulting in some record sales levels. However, there is currently a degree of economic uncertainty, with rising costs and it is prudent to keep the valuation under constant review.

Signed	Security Print Code [495151 = 5468 ] Electronically signed			
Report author	Calum Steven			
Company name	J & E Shepherd			

Address	65-67 Strathmore House, The Plaza East Kilbride Shopping Centre, East Kilbride, G74 1LF

Date of report	4th February 2025



Tel: 0845 263 7995

www.shepherd.co.uk

Property Address								
Address 15 WEST MAINS ROAD, EAST KILBRIDE, GLASGOW, G74 1NQ								
Seller's Name	Ms Hollie Wilson							
Date of Inspection	31st January 2025							
<b>Property Details</b>								
Property Type	House Bungalow Chalet Purpose built maisonette							
, , , ,	Coach Studio Converted maisonette X Purpose built flat							
	Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)							
5 ( 2) 1-								
Property Style	Detached Semi detached Mid terrace End terrace							
	Back to back High rise block X Low rise block Other (specify in General Remarks)							
Does the surveyor be e.g. local authority, m	elieve that the property was built for the public sector, X Yes No nilitary, police?							
Flats/Maisonettes on	ly Floor(s) on which located Ground No. of floors in block 2 Lift provided? Yes X No							
	No. of units in block 4							
Approximate Year of	Construction 1920							
Tenure								
V Absolute Ournarchin	Leasehold Ground rent £ Unexpired years							
X Absolute Ownership	Leasehold Ground rent £ Unexpired years Unexpired years							
Accommodation								
Number of Rooms	1 Living room(s) 3 Bedroom(s) 1 Kitchen(s)							
	1 Bathroom(s) 1 WC(s) 0 Other (Specify in General remarks)							
Gross Floor Area (ex	cluding garages and outbuildings) 74 m² (Internal) m² (External)							
Residential Element	(greater than 40%) X Yes No							
Garage / Parking /	Outbuildings							
Single garage	Double garage Parking space X No garage / garage space / parking space							
Available on site?	Yes No							
Permanent outbuildir								
None								
None								

Construction										
						,				
Walls	X Brick	Stone		Concrete		er frame				15 1)
Roof	Solid	Cavity		Steel frame		rete block		tner (spe	city in Gen	eral Remarks)
ROOI	X Tile	Slate		Asphalt	Felt	laaa Chaa				D  - \
	Lead	Zinc	/	Artificial slate	e 🔛 Flat g	lass fibre		ther (spe	ecity in Gen	eral Remarks)
Special Risks										
Has the property s	suffered struct	ural movem	ent?						X Yes	No
If Yes, is this rece	nt or progress	ive?							Yes	X No
Is there evidence, immediate vicinity	history, or rea?	son to antic	ipate sub	sidence, h	neave, la	andslip c	or flood in	the	Yes	X No
If Yes to any of the	e above, provi	de details in	General	Remarks.						
Service Connec	rtion									
		If any comi						a4 a a 4la		
Based on visual ir of the supply in G			ces appe	ar to be no	on-main	s, pieas	e comme	it on th	e type ar	id location
Drainage	X Mains	Private	None		,	Water	X Mains		Private	None
Electricity	X Mains	Private	None			Gas	X Mains		Private	None
Central Heating	X Yes	Partial	None							
Brief description of	of Central Heat	ing:								
Gas boiler with r	adiators.									
Site										
Apparent legal iss	ues to be verit	ied by the c	onvevan	cer. Please	e provide	e a brief	description	on in G	eneral Re	emarks.
Rights of way	X Shared drive	-		e or other an	-		_		ervice conn	
Agricultural land in	<del></del>			ned boundar						neral Remarks)
		•						` '	,	
Location										
Residential suburb	X Res	dential within to	own / city	_	residentia			-	mmercial	
Commuter village	Rem	ote village		Isolate	d rural pro	perty		Other (sp	ecify in Gei	neral Remarks)
Planning Issues	5									
Has the property b	peen extended	I / converted	/ altered	? X Ye	s No					
If Yes provide deta	ails in General	Remarks.								
Poods -										
Roads										
Made up road	Unmade road	Partly	completed	new road	Pe	destrian a	ccess only	[X]	Adopted	Unadopted

General Remarks
The condition of the property is consistent with age and type requiring some routine maintenance which has been accounted for in our opinion of value.
The property is located within a mixed residential/commercial area in the original village of East Kilbride with shopping, educational, social and transport facilities available within close proximity.
The property is located within a Conservation Area which may restrict future development/alteration of the subjects and this should be confirmed by the conveyancer. It is assumed that all necessary Local Authority consents have been duly sought and gained for any alterations.
There is evidence of previous movement to the building which is assumed to be of a longstanding nature. There was no evidence of significant ongoing movement.
Essential Repairs
None
Estimated cost of essential repairs £ N/A Retention recommended? Yes X No Amount £ N/A

Comment on Mortgagea	bility	
The property forms adequ	late security for mortgage purposes.	
Valuations		
Market value in present condition  Market value on completion of essential repairs  Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT) Is a reinspection necessary?		£ 145,000 £ N/A £ 178,000
Buy To Let Cases		
month Short Assured Tenai	ge of monthly rental income for the property assuming a letting on a 6 ncy basis? There there is a steady demand for rented accommodation of this type?	£ N/A Yes No
Signed Surveyor's name Professional qualifications Company name Address	Security Print Code [495151 = 5468] Electronically signed by:- Calum Steven BA(Hons) MSc MRICS J & E Shepherd 65-67 Strathmore House, The Plaza East Kilbride Shopping Centre, East 1LF	st Kilbride, G74
Telephone Fax	01355 248535	

4th February 2025

Report date



PROPERTY QUESTIONNAIRE

Property address	15 WEST MAINS ROAD, EAST KILBRIDE, GLASGOW, G74 1NQ
Seller(s)	Hollie Marie Wilson
Completion date of property questionnaire	30/01/2025

### **Note for sellers**

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer
  each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell
  your solicitor or estate agent immediately.

### Information to be given to prospective buyer(s)

1.	Length of ownership
	How long have you owned the property? 6 years 8 months
2.	Council tax
	Which Council Tax band is your property in? (Please circle)
	A B C D E F G H
3.	Parking
	What are the arrangements for parking at your property?  (Please tick all that apply)  • Garage  • Allocated parking space  • Driveway  • Shared parking  • On street  • Resident permit  • Metered parking  • Other (please specify):
4.	Conservation area
	Is your property in a designated Conservation Area (i.e. an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?

5.	Listed buildings	
	Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)?	<del>Yes</del> / No
6.	Alterations/additions/extensions	
a.	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?  If you have answered yes, please describe below the changes which you have made:	<del>Yos</del> / No
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?  If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.  If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	<del>Yes</del> / <del>No</del>
b.	Have you had replacement windows, doors, patio doors or double glazing installed in your property?  If you have answered yes, please answer the three questions below:	<del>Yes</del> / No
	(i) Were the replacements the same shape and type as the ones you replaced?	<del>Yes</del> / Ne
	(ii) Did this work involve any changes to the window or door openings?	<del>Yes</del> / <del>No</del>
	(iii) Please describe the changes made to the windows, doors or patio doors (vidates when the work was completed):	vith approximate
	Please give any guarantees which you received for this work to your solicitor or e	estate agent.

7.	Central heating	
a.	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).	Yes / <del>No</del> / <del>Partial</del>
	If you have answered yes / partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).	
	Combi Boiler Installed	
	If you have answered yes, please answer the three questions below:	
b.	When was your central heating system or partial central heating system installed?	circa 2017
C.	Do you have a maintenance contract for the central heating system?	Yes / No
	If you have answered yes, please give details of the company with which you have a maintenance contract:	
	British Gas Home Cover including Annual Boiler Service	
d.	When was your maintenance agreement last renewed? (Please provide the month and year).	July 2024
8.	Energy Performance Certificate	
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes / <del>No</del>
9.	Issues that may have affected your property	
a.	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	<del>Yos</del> / No
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	<del>Yes</del> / <del>No</del>
b.	Are you aware of the existence of asbestos in your property?	<del>Yes</del> / No
	If you have answered yes, please give details:	

sup	se tick which services are olier:	connected to y	our property and give details	of the
	Services	Connected	Supplier	
	Gas / liquid petroleum gas	✓	British Gas	
	Water mains / private water supply	<b>√</b>	S. Lanarkshire Council/Scottish	n Water
	Electricity	✓	British Gas	
	Mains drainage	✓	S. Lanarkshire Council/Scottisl	n Water
	Telephone	_		
	Cable TV / satellite	_		
	Broadband	✓	Virgin Media	
	u have answered yes, please  o you have appropriate conse		-	Yes / N
If yo	o you have a maintenance co u have answered yes, please e a maintenance contract:	-	eptic tank? the company with which you	Yes / N

11.	Responsibilities for Shared or Common Areas	
a.	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?	<del>Yes</del> / No / <del>Den't Knew</del>
	If you have answered yes, please give details:	
b.	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?	Yes / No / Not applicable
	If you have answered yes, please give details:	
	There is a shared roof covering the 4 flats in the block of cottage flats. There is a pathway shared by 2 flats (this flat and the upstairs flat).	
C.	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	<del>Yes</del> / No
d.	Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?	Yes / <del>No</del>
	If you have answered yes, please give details:	
	Right of access to joint pathway.	
e.	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?	Yes / <del>No</del>
	If you have answered yes, please give details:	
	Right of access to joint pathway.	
f.	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately-owned.)	<del>Yes</del> / No
	If you have answered yes, please give details:	
12.	Charges associated with your property	
a.	Is there a factor or property manager for your property?	<del>Yes</del> / No
	If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	

b.	Is there a common buildings insurance policy?	<del>Yes</del> / No / <del>Den't Knew</del>
	If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?	Yes / No / Den't Knew
C.	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
	None	
13.	Specialist works	
a.	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	<del>Yes</del> / No
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property:	
b.	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	<del>Yes</del> / No
	If you have answered yes, please give details:	
C.	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	Yes / No
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.	
	Guarantees are held by:	

14.	Guarantees						
a.	Are there any guarantees or warranties for any of the following:						
(i)	Electrical work	No	Yos	Don't know	With title doods	Lost	Cannot Answer*
(ii)	Roofing	No	Yes	Don't know	With title doods	Lost	Cannot Answor*
(iii)	Central heating	No	Yes	<del>Don't</del> <del>know</del>	With title doods	Lost	Cannot Answor*
(iv)	NHBC	No	Yos	Don't know	With title doods	Lost	Cannot Answor*
(v)	Damp course	No	Yes	Don't know	With title doods	Lost	Cannot Answor*
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	No	Yos	Don't know	With title doods	Lost	Cannot Answor*
b.	If you have answered 'yes' or 'with title deed or installations to which the guarantee(s) rela	ls', pleas te(s):	e give de	etails of t	he work		
c.	Are there any outstanding claims under any of the guarantees listed above?  If you have answered yes, please give details:					<del>Yes</del> / <del>Ne</del>	
15.	Boundaries						
	So far as you are aware, has any boundary o last 10 years?  If you have answered yes, please give details		operty be	een move	ed in the	<del>Yes</del> / No / <del>Den't knew</del>	

16.	Notices that affect your property	
	In the past 3 years have you ever received a notice:	
a.	advising that the owner of a neighbouring property has made a planning application?	Yes / No / Den't know
b.	that affects your property in some other way?	<del>Yes</del> / No / <del>Don't know</del>
C.	that requires you to do any maintenance, repairs or improvements to your property?	<del>Yes</del> / No / <del>Den't knew</del>
	If you have answered yes to any of a-c above, please give the notices to your so agent, including any notices which arrive at any time before the date of entry of t your property.	olicitor or estate he purchaser of

Declaration by the seller(s)/or other authorised body or person(s)

I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s):			
·			
Date:			



Proud to be part of



CHARTERED SURVEYORS | WWW.WBCS.CO.UK

### **GLASGOW**

Suite 5, Legal House, 101 Gorbals Street, Glasgow G5 9DW

### 0141 404 6364

glasgow@wbcs.co.uk

### HAMILTON

Suites 7 & 8 Waverley House, Caird Park, Hamilton, ML3 0QA

### 01698 891 400

hamilton@wbcs.co.uk

### EAST KILBRIDE

67 Strathmore House East Kilbride G74 1LQ

### 01355 229 317

ek@wbcs.co.uk

### **LANARK**

50 Bannatyne Street Lanark ML11 7JS

### 01555 663 058

lanark@wbcs.co.uk