

Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. No detailed internal inspection of

flues (Integrity, Constructions and Lining) has been carried out.

Certificate Reference

54 Shortridge Terrace 201

Certificate No:Certificate -10139

Trading Title Address Address Transtwood Gardens Kenton Newcastle upon Tyne Post Code: NE3 3 DP Post Code: NE3 3 DP Post Code: NE2 2JE Telephone No:
Address IT Eastwood Gardens Kenton Newcastle upon Tyne Post Code: NE3 3 DP Post Code: NE3 3 DP Post Code: NE2 2JE Post Code: NE6 5SB Appliance Details Location Appliance Type Make Model Bed Room Combi boiler Baxi PLATINUM 35 HEA GC 8.9 9 61 RS YES 0.006 YES 33 kw YES YES NO PASS NO YES Kitchen Cooker Free Indesit Cucina NewCastle upon Tyne Post Code: NE6 5SB Post Code: NE6 5SB Telephone No: 01912656555 Telephone No: 01912656555 Telephone No: 01912656555 Inspection Details Inspection Details Appliance Type Make Model Bed Room Combi boiler Baxi PLATINUM 35 HEA GC 8.9 61 RS YES 0.006 YES 33 kw YES YES NO PASS NO YES Kitchen Cooker Free Indesit Cucina Na 2 N/A YES Na YES 20 mbar Faults/Notes Remedial Work Taken Warning Notice Fixed
Gas Safe No: 222266 Telephone No: 07904329008 Telephone No: 01912656555 Appliance Details Inspection Details
Appliance Details Location Appliance Type Make Model Department of the property Department
Location Appliance Type Make Model Debugger of Color of C
Bed Room Combi boiler Baxi PLATINUM 33 HEA GC 8.9 61 RS YES 0.006 YES 33 kw YES YES NO PASS NO YES Kitchen Cooker Free Indesit Cucina Na 2 N/A YES Na YES 20 mbar YES YES N/A N/A NO YES INDESTRUCTION OF THE PROPERTY OF THE
Kitchen Cooker Free Indesit Cucina Na 2 N/A YES Na YES 20 mbar YES YES N/A N/A NO YES Faults/Notes Remedial Work Taken Warning Notice Fixed 1 Boiler flue too close to boundary not 300 MM from next door property
Faults/Notes Remedial Work Taken Warning Notice Fixed Boiler flue too close to boundary not 300 MM from next door property
Boiler flue too close to boundary not 300 MM from next door property
Boiler flue too close to boundary not 300 MM from next door property
Boiler flue too close to boundary not 300 MM from next door property
2 Cooker does not have stability bracket or chain attached No
3 No earth bonding visible on gas meter pipe work Notified landlord/ management team Notified landlord/ management team
4
5
Emergency Control Valve accessible: YES Gas Tightness Satisfactory: YES Signatures Report Issued By: Signatures Report Issued By:
Gas Installation Pipework Visual Inspection Satisfactory: YES Name: Colin Crozier Signed: A Carry Date: Fri-07-04-2017
Number Of Appliances Tested: 2 Equipotential Bonding: NO Report Received By:
NEXT INSPECTION DUE ON OR BEFORE: CO Alarm fitted and working? NO service and working? This Gas Safety Report was created by Gas Checker Software 2016 all rights reserved, www.gaschecker.co.uk