



ALLIED
SURVEYORS
SCOTLAND

Home Report

Wealthiton Croft

Keig

Alford

AB33 8BH

Offices throughout Scotland

alliedsurveyorsscotland.com

Wealthiton Croft
Keig
Alford
AB33 8BH

Section 1

Single Survey and Mortgage Valuation Report



Single Survey

survey report on:

Property address	Wealthiton Croft, Keig, Alford, AB33 8BH
-------------------------	---

Customer	Mr N Watson and Mrs A Watson
-----------------	------------------------------

Customer address	Wealthiton Croft, Keig, Alford, AB33 8BH
-------------------------	---

Prepared by	Allied Surveyors Scotland Ltd
--------------------	-------------------------------

Date of inspection	31st March 2026
---------------------------	-----------------



PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property¹.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

¹ Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Terms and Conditions

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report.²

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless

² Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

Terms and Conditions

they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;
- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;

Terms and Conditions

- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 - DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" *The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein*

Terms and Conditions

the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" *is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form* unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The property comprises a detached 1.5 storey house with integral garage/workshop within grounds extending to approximately 0.38 acres.
Accommodation	<p>Summary of main accommodation: 4 living rooms, 4 bedrooms, 2 bathrooms.</p> <p>Ground floor: hall, sitting room, bathroom, living room, dining room with cloak/boot room off, rear lobby and passage, kitchen/dining room/family room, utility room.</p> <p>First floor: front part - landing with store off, 2 bedrooms; rear wing - landing, 2 bedrooms, shower room.</p>
Gross internal floor area (m²)	The gross internal floor area of the house extends to approximately 197 square metres, split between the ground floor of 111 square metres and the first floor of 86 square metres. This floor area excludes the garage/workshop.
Neighbourhood and location	<p>The property lies within the rural settlement of Keig. It fronts onto the Alford-Insch public road which passes through the settlement, is adjoined on both sides by the grounds of residential properties and is adjoined at the rear by agricultural land. Keig Primary School is 100 metres from the property.</p> <p>The property is located 4 miles from Alford (population 2,700), which has a range of local shops, Medical and Dental Practices and a community campus on which there are nursery, primary and secondary schools, library and swimming pool. Major local centres of population and employment include: Inverurie (population 14,500) - 14 miles; Westhill (population 12,500) - 19 miles; Aberdeen City Centre - 26 miles.</p>

<p>Age</p>	<p>The original, front, part of the property is understood to have been built in 1884, 142 years ago. Extensions include: (i) the rear wing added 36 years ago (1990) and (ii) the conversion of a part of the integral garage into a utility room 19 years ago (2007).</p>
<p>Weather</p>	<p>The weather was dry and sunny during the inspection. The report should be read in context of these weather conditions.</p>
<p>Chimney stacks</p>	<p>Visually inspected with the aid of binoculars where appropriate.</p> <p>There are two chimney stacks, one above each gable wall of the original part of the house. They are built with dressed stone blocks, which are pointed, have a mix of cement and lead flashing around their bases and clay pots bed in cement haunching. The unused pots are fitted with ventilated pepper-pot caps and the used pots (1 on each chimney) are fitted with metal cowls.</p> <p>A steel flue rises through the rear wing roof from the kitchen Rayburn.</p>
<p>Roofing including roof space</p>	<p>Sloping roofs were visually inspected with the aid of binoculars where appropriate.</p> <p>Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property.</p> <p>If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.</p> <p>The roofs are pitched and slated.</p> <p>External detail of the original roof includes: clay ridge sections bed in cement; at gables skewers lined with dressed stone coping, with cement flashing; lead lined valley gutters at roof junctions; 2 front bay windows with slated sides and roofs, zinc ridging valleys and side slips, hipped ends, lead front flashing and timber facias soffits and window facings; 1 central metal framed single glazed skylight (boarded up internally).</p> <p>A limited head and shoulders inspection of the original roof was made from a ceiling hatch in the landing and 2 wall hatches, one off the half landing and one in the rear wall of a bedroom. The roof is formed with timber trusses overlaid with timber sarking boards. A layer of slate underfelt was visible to part of the rear face inspected. Mineral wool insulation was found to the original part of the house as follows: 400mm between and over the joists of the flat part of the roof space, 50mm behind the vertical rear wall lining, from the bedroom hatch 300mm between and over first floor joists and from the landing hatch a lesser amount was visible (though could not be measured).</p> <p>External detail of the rear wing roof includes: clay ridge sections with ventilated sections at intervals, 1 bay window in each face, of similar design to the front bays, except for having a timber lined gable; two velux roof windows in each face; raised skew at the rear gable covered with lead and with lead flashing; timber facias; pitched slated roof to kitchen bay.</p>

<p>Roofing including roof space</p>	<p>A limited head and shoulders inspection of the rear wing roof was made from a hatch in the shower room ceiling. The roof is of similar construction to the original roof and there is approximately 300mm of mineral wool insulation laid between and over the joists of the flat part of the roof space and slate underfelt was visible between the gaps of the sarking boards.</p>
<p>Rainwater fittings</p>	<p>Visually inspected with the aid of binoculars where appropriate.</p> <p>The rainwater fittings to the original part of the house are cast iron; gutters are half round and supported by rafter brackets and downpipes are round.</p> <p>The rainwater fittings to the rear wing are black plastic; half round gutters are fixed to fascia boards and downpipes are round.</p>
<p>Main walls</p>	<p>Visually inspected with the aid of binoculars where appropriate.</p> <p>Foundations and concealed parts were not exposed or inspected.</p> <p>The walls of the original part of the house are built with solid stone and are harled externally. They are approximately 650mm thick, including the internal wall lining.</p> <p>The walls of the rear wing are built with concrete blocks, are roughcast externally and are approximately 330mm thick, including the internal wall lining.</p>
<p>Windows, external doors and joinery</p>	<p>Internal and external doors were opened and closed where keys were available.</p> <p>Random windows were opened and closed where possible.</p> <p>Doors and windows were not forced open.</p> <p>The windows are timber framed double glazed casement windows, likely to be around 36 years old. Opening casements are top hinged - the front windows have casement sizes that replicate traditional window appearance and have large opening casements, whereas the rear windows have top hopper opening casements.</p> <p>The owners advised that the window glazing was renewed in 2010.</p> <p>External doors include: (i) front door - solid timber door with small leaded double glazed pane; (ii) rear door, into lobby - solid timber door with double glazed upper pane, reinforced door, multiple locking mechanism, fitted with cat flap; (iii) from the integral garage into the utility room an external grade plywood door fitted with a mortice lock.</p>

Single Survey

External decorations	Visually inspected. The external joinery is painted dark brown. The walls of the front part of the house and one side of the rear wing are painted a cream colour.
Conservatories / porches	There are no conservatories or porches.
Communal areas	There are no communal areas.
Garages and permanent outbuildings	Visually inspected. There is an integral garage/workshop, which is L shaped as a result of the utility room extension. It is within the structure of the house, with the principal bedroom above. It has a concrete floor, unlined block internal walls, plasterboard lined ceiling, 2 timber up and over vehicle doors, sockets and lights and an internal floor area of 26 square metres.
Outside areas and boundaries	Visually inspected. The grounds are rectangular with approximate dimensions of 25 metres wide by 60 metres long. They are enclosed by a mix of stone walls and fences. Some features include: first section of drive tarred, changing to gravel, with a gravelled vehicular area along one side of the house, flanked by some areas of cobbling; at the front is a cobbled path along the front of the house, garden sub- divided by box-hedging with lawns, inset beds bordered by cobbles and perimeter beds, gravel paths and seating area; at the east side of the house is a stone flagged patio; at the rear is a lawn with birch trees and several small raised beds; structures include (i) a wooden shed with a corrugated onduline roof divided between a workshop and store, in total measuring 3.8 metres x 3 metres, (ii) a 10'x6' aluminium greenhouse with concrete floor and (iii) a timber framed log store.
Ceilings	Visually inspected from floor level. The ceilings of the original part are understood to be lined with lathe and plaster and those to the rear wing to be lined with plasterboard.
Internal walls	Visually inspected from floor level. Using a moisture meter, walls were randomly tested for dampness where considered appropriate. The majority of the internal walls in the original part are lined with lathe and plaster and those to the rear wing are lined with plasterboard. There are sections of pine wall linings to dado height in the hall, stairway, rear landing, 3 sides of the living room, ground floor bathroom and rear passage.


<p>Floors including sub floors</p>	<p>The ground floor of the original part of the house is part solid and part suspended timber. Sub- floor vents were noted in the front and west gable walls.</p> <p>The ground floor of the rear wing is concrete.</p> <p>At the time of the inspection, most floors were covered with fitted carpets or other floor coverings and the extent of the inspection of the floors was thus limited.</p> <p>It was not possible to gain access to the sub-floor area as there was no apparent means of access.</p> <p>Fixed floor coverings included: pine parquet block flooring in the kitchen/dining room, rear passage and dining room; wooden flooring in the ground floor bathroom; laminate flooring in the first floor shower room; tiled floor in the utility room; stone flagged floor in the rear lobby.</p>
<p>Internal joinery and kitchen fittings</p>	<p>Built-in cupboards were looked into but no stored items were moved.</p> <p>Kitchen units were visually inspected excluding appliances.</p> <p>The kitchen was fitted by the present owners in 2001. It is a wooden Mother Hubbard of Torphins kitchen which includes floor units around two sides, with wooden worktops and upstand, and two corner wall units. There is also a peninsula worktop which acts as a breakfast bar. The units and worktops have been finished with Danish Oil. Built-in appliances include an oil fired, deep blue 2 oven Rayburn (installed in 2001), with patterned wall splash tiling above.</p> <p>The utility room was fitted around 2007 and includes a double drawer unit which incorporates a sink and a section of worktop, a section of laminate worktop along the external wall with below space for a washing machine and tumble drier, and a tall bank of storage cupboards along one side.</p> <p>The majority of the internal doors are pine panel doors. The door from the utility room into the kitchen is an external plywood door with a mortice lock and the door into the cloak/boot room is a pine linings doors.</p> <p>The stairway has painted steps, pine linings along one side and a timber balustrade along the other.</p> <p>There is a built-in cupboard/wardrobe in the principal bedroom and storage cupboards off the front and rear landings and in the kitchen.</p>
<p>Chimney breasts and fireplaces</p>	<p>Visually inspected.</p> <p>No testing of the flues or fittings was carried out.</p> <p>In the living room is an oval multi-fuel Morso stove, installed around 10 years ago, which is set on a slate hearth within a fireboard lined recess and with a timber mantelpiece.</p> <p>In the sitting room is an open fire, with a slate tiled hearth, cast iron fire and surround and a timber mantelpiece.</p>

Single Survey

Internal decorations	Visually inspected. The majority of the internal linings are painted lining paper or painted plaster.
Cellars	There are no cellars.
Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on. The property is supplied with electricity. An underground mains cable rises at the base of the east gable wall, is taken loosely up the wall and through into a living room alcove cupboard, where there is an older style meter and a consumer unit. The consumer unit includes a main switch, a residual current device protecting some of the circuits (a switch that trips a circuit under dangerous conditions and disconnects the electricity) and circuit breakers (which switch off a circuit if they detect a fault). The owners advised that the wiring in the original part of the house was completely renewed in 2004. Sockets within the house are 13 amp rectangular pinned sockets.
Gas	Mains gas is not available to the property.
Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances. The property is supplied with mains water. The owners advised that there are two pipes entering the house: (i) below the kitchen sink, which is pipe off the main serving the kitchen and (ii) behind the bathroom rear wall, which is fitted with a stop-cock and runs up to the cold water tank. There are plastic cold water tank(s) in the rear wing roof space, which are fitted with lids. There are two bathrooms: (i) ground floor bathroom - free standing cast iron roll-top bath on 4 legs with mixer tap and shower attachment, hand basin, w.c with high level cistern; (ii) first floor shower room - tiled and glazed shower cubicle with sliding glass door and electric power shower (fed from the hot water cylinder), w.c and hand basin. Sinks include in the kitchen a Belfast sink and in the utility room a double bowl ceramic sink.

<p>Heating and hot water</p>	<p>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.</p> <p>No tests whatsoever were carried out to the system or appliances.</p> <p>The house is heated by an oil central heating system from a Boulter Buderus 70-90 Economy boiler, floor mounted in a boxed off corner of the utility room and fitted with a balanced flue through the external wall. Oil is supplied from a 1,300 plastic tank at the rear of the house, mounted on concrete flags.</p> <p>The heating system is a wet system, via modern panel radiators, controlled by a programmer in a kitchen cupboard and by radiator thermostatically controlled valves.</p> <p>The owners advised that all central heating pipework and radiators were renewed in 2010.</p> <p>The utility room is heated by electric underfloor heating.</p> <p>There is a 1500mm x 450mm foam insulated indirect copper hot water cylinder in a rear bedroom cupboard, which has a capacity of 205 litres and is fitted with a cylinder thermostat. The water is primarily heated by the central heating boiler, controlled by its programmer and is supplemented by an electric immersion heater.</p>
<p>Drainage</p>	<p>Drainage covers etc were not lifted.</p> <p>Neither drains nor drainage systems were tested.</p> <p>Drainage is connected to the main sewer.</p> <p>Drainage covers have not been lifted and neither the drains, nor any part of the drainage system have been tested.</p>
<p>Fire, smoke and burglar alarms</p>	<p>Visually inspected.</p> <p>No tests whatsoever were carried out to the system or appliances.</p> <p>Ceiling mounted detectors/alarms have been fitted as follows: smoke alarms to the ground and first floors; heat detector in the kitchen.</p>
<p>Any additional limits to inspection</p>	<p>The inspection was limited by the presence of fitted floor coverings, furnishings and personal effects within the property.</p> <p>Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.</p>

Sectional Diagram showing elements of a typical house



- ① Chimney pots
- ② Coping stone
- ③ Chimney head
- ④ Flashing
- ⑤ Ridge ventilation
- ⑥ Ridge board
- ⑦ Slates / tiles
- ⑧ Valley guttering
- ⑨ Dormer projection
- ⑩ Dormer flashing
- ⑪ Dormer cheeks
- ⑫ Sarking
- ⑬ Roof felt
- ⑭ Trusses
- ⑮ Collar
- ⑯ Insulation
- ⑰ Parapet gutter
- ⑱ Eaves guttering
- ⑲ Rainwater downpipe
- ⑳ Verge boards /skews
- ㉑ Soffit boards
- ㉒ Partition wall
- ㉓ Lath / plaster
- ㉔ Chimney breast
- ㉕ Window pointing
- ㉖ Window sills
- ㉗ Rendering
- ㉘ Brickwork / pointing
- ㉙ Bay window projection
- ㉚ Lintels
- ㉛ Cavity walls / wall ties
- ㉜ Subfloor ventilator
- ㉝ Damp proof course
- ㉞ Base course
- ㉟ Foundations
- ㊱ Solum
- ㊲ Floor joists
- ㊳ Floorboards
- ㊴ Water tank
- ㊵ Hot water tank


Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.


Single Survey


2. Condition


This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

 Structural movement	
Repair category	1
Notes	Given the age and type of the original part of the building, there is likely to have been past movement to its structure. However, there is no obvious evidence of any recent movement having occurred, with any movement noted appearing to be old and non-progressive.

 Dampness, rot and infestation	
Repair category	1
Notes	<p>Damp meter readings were taken at appropriate locations throughout the house but no significant evidence of dampness was encountered.</p> <p>Extensive signs of historic wood-boring insect activity were found to be affecting some of the visible roof timbers inspected though no sign of a recent/active attack was evident. The owners advised that they understand the property was treated against wood-worm around 30 years ago but have no guarantee for the work. It is recommended that a new owner have the timberwork within the house inspected at a change of ownership by a reputable Timber & Damp Specialist Firm to determine whether there is any active infestation or other defect.</p>

 Chimney stacks	
Repair category	1
Notes	From a ground level inspection of the chimneys, no significant defects were noted.

 Roofing including roof space	
Repair category	1
Notes	<p>No significant defects were noted to the roof exterior and those parts of the roof spaces that were inspected.</p> <p>Evidence of historic wood-boring insect activity has been described above in the</p>



Roofing including roof space

Repair category	1
Notes	<p>Dampness, rot and infestation section.</p> <p>Natural slates have a lifespan which is dependent upon the type and quality of the slate. Over the long term slates may deteriorate, their nail fixings may corrode, and the timber sarking boards may deteriorate particularly where exposed to penetrating moisture or condensation. Ongoing roof maintenance will be required, including keeping valley gutters clear of debris and monitoring the condition of the roof slates, metal flashings/valleys, roof joinery and cement work.</p>



Rainwater fittings

Repair category	1
Notes	<p>No significant defects were noted to the rainwater fittings.</p> <p>No assessment has been made on the operation and effectiveness of the rainwater system, including the drainage from the base of the downpipes.</p>



Main walls

Repair category	1
Notes	<p>No significant defects were noted to the main walls. Several fine cracks were noted through the harling/roughcast from window openings, though they did not appear to be of structural significance or to require remedial work at the present time; as a matter of routine maintenance in the future, should they widen or result in bossed render they should be repaired to prevent damp penetration.</p>




Windows, external doors and joinery


Repair category	1
Notes	<p>No significant defects were noted to the windows and external doors.</p> <p>The window frames are approximately 36 years old and their glazing was renewed approximately 16 years ago - they are of an age where a degree of ongoing maintenance should be anticipated to their external joinery and opening mechanisms.</p>





External decorations


Repair category	1
Notes	<p>The decoration of the external joinery and parts of the masonry was found to be in good condition.</p>


 Conservatories/porches	
Repair category	-
Notes	None.

 Communal areas	
Repair category	-
Notes	None.

 Garages and permanent outbuildings	
Repair category	1
Notes	No significant defects were noted to the garage/workshop.

 Outside areas and boundaries	
Repair category	1
Notes	<p>The boundary walls and fences, driveway and gravelled areas, hard landscaped areas and grounds appear to have been well maintained and were in a neat and tidy condition.</p> <p>The workshop/storage shed and the greenhouse were found to be in good condition.</p>

 Ceilings	
Repair category	1
Notes	<p>No significant defects were noted to the ceilings.</p> <p>Due to the age of the lathe and plaster ceilings in the original part of the house, it is possible that there are cracked and loose areas of plaster behind the decoration. The stability of ceilings was not tested.</p>

 Internal walls	
Repair category	1
Notes	<p>No significant defects were noted to the internal wall linings.</p> <p>Due to the age of the lathe and plaster internal linings in the original part of the house, it is possible that there are cracked and loose areas of plaster behind the</p>



Internal walls

Repair category	1
Notes	decoration. The stability of internal walls was not tested.



Floors including sub-floors

Repair category	1
Notes	From a limited inspection that was possible of the floors, no significant defects were noted.



Internal joinery and kitchen fittings

Repair category	1
Notes	<p>The kitchen fittings whilst 25 years old have been well maintained and were found to be in a good condition for their age. The wooden worktops will require periodic maintenance to remove stains and preserve their integrity (sanding and oiling). No assessment has been made on the condition of the kitchen Rayburn.</p> <p>The utility room fittings were in good condition, with minor wear and tear markings noted.</p> <p>The condition of skirtings, facings and internal doors were found to be generally good condition. Some historic wood-worm holes were visible in several of the doors.</p>



Chimney breasts and fireplaces

Repair category	1
Notes	<p>No significant defects were noted to the living room stove and sitting room open fireplace. No assessment has been made on the operation of the stove/open fire and whether their flues are adequately lined.</p> <p>The owners advised that the flues from the living room stove and kitchen Rayburn were last swept in February 2026.</p>



Internal decorations

Repair category	1
Notes	The internal decoration was found to be in generally good condition, with minor wear and tear markings.



Cellars

Repair category	-
Notes	None.



Electricity

Repair category	1
Notes	<p>No significant defects were noted to the visible parts of the electrical installation that were inspected.</p> <p>A sticker on the consumer unit board states that the installation was last inspected on 3/02/2004; it is recommended that a new owner have the installation checked over and tested by a Registered Electrical Engineer and that any recommendations made with regard to upgrading and the safety of the installation be carried out.</p> <p>Some of the sockets in the original part of the house are within skirting boards; this is not illegal, although current building standards guidance is that new sockets should be placed at least 400mm from the floor. When rooms are redecorated in the future, it should be considered whether these sockets are raised.</p> <p>The new Fire and Smoke Alarm Standard came into force in February 2022. This new standard requires a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also needs to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon-fuelled appliance such as a boiler, open fire or wood burner a carbon monoxide detector is also required. The purchaser should satisfy themselves in this regard.</p>



Gas

Repair category	-
Notes	None.



Water, plumbing and bathroom fittings

Repair category	1
Notes	<p>No significant defects were noted to the visible parts of the plumbing system that were inspected.</p> <p>The sanitary fittings in the two bathrooms were found to be in good condition.</p> <p>It was noted that neither bathroom has a mechanical extract fan; it would be prudent fans to be fitted by a new owner to prevent condensation.</p>



Heating and hot water

Repair category	1
Notes	<p>No significant defects were noted to the visible parts of the central heating and hot water systems that were inspected.</p> <p>The central heating boiler and system (including the oil tank), should be serviced annually by a qualified heating engineer to ensure its safe and efficient operation. The owners advised that the boiler and Rayburn were last serviced in December 2025.</p> <p>No assessment has been made on the operation, efficiency and adequacy of the central heating system.</p> <p>The central heating boiler is old, installed around 1995 and will be considerably less efficient than a modern condensing boiler.</p>



Drainage

Repair category	1
Notes	<p>No problems with the drainage were visible during the inspection.</p> <p>No assessment has been made on the size, capacity, condition and operation of the drainage system.</p>

Single Survey

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	1
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	1
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	1
Internal decorations	1
Cellars	-
Electricity	1
Gas	-
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

Category 3

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

Category 1

No immediate action or repair is needed.

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. Accessibility information

Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	Ground
2. Are there three steps or fewer to a main entrance door of the property?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
3. Is there a lift to the main entrance door of the property?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
4. Are all door openings greater than 750mm?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
5. Is there a toilet on the same level as the living room and kitchen?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
6. Is there a toilet on the same level as a bedroom?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
7. Are all rooms on the same level with no internal steps or stairs?	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

The tenure is understood to be outright ownership. The titles have not been checked by the surveyor. It is assumed that there are no unduly onerous provisions in the title documents and management/service charge agreements. If the legal advisers find that there are significant variations from the standard assumptions then this should be referred back to the surveyor.

It is specifically assumed that the property and its value are unaffected by any matters which would, or should be revealed to a competent completing solicitor or by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

The house has been extended twice: (i) the rear wing was added 36 years ago (1990) - it should be confirmed that the necessary planning and building warrant approvals were obtained for this work and that a completion certificate was issued in respect of all works requiring building warrant approval (in this regard a letter from Aberdeenshire Council's Head of Planning Services dated 16/11/1999 has been inspected confirming that a completion certificate was issued on 22/06/1990) and (ii) the conversion of a part of the integral garage into a utility room 19 years ago (2007), for which the owners were advised that planning permission was not required.

Estimated reinstatement cost for insurance purposes

This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a reinstatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during reconstruction and no allowance has been made for VAT, other than on professional fees. Further discussion with your insurers is advised.

£760,000 (Seven Hundred and Sixty Thousand Pounds)

Building costs are currently increasing significantly above inflation due to material and labour shortages as well as Brexit, the Pandemic, the war in Ukraine and world-wide trade upheavals. It is recommended that this figure be regularly updated to ensure that there is adequate cover or alternatively seek specialist advice from your insurer.

Valuation and market comments

In its present condition, it is our opinion that the market value of the heritable interest in the property with the benefit of vacant possession and as at the date of our inspection, is:

£410,000 (Four Hundred and Ten Thousand Pounds)

Our valuation has fully taken into account the prevailing market conditions.

Signed

Security Print Code [462667 = 5873]
Electronically signed

Report author

David Silcocks

Company name

Allied Surveyors Scotland Ltd

Single Survey

Address	Marywell House, 29-31 Marywell Street, Aberdeen, AB11 6JE
Date of report	9th April 2026

Mortgage Valuation Report



Property Address

Address Wealthiton Croft, Keig, Alford, AB33 8BH
Seller's Name Mr N Watson and Mrs A Watson
Date of Inspection 31st March 2026

Property Details

Property Type House Bungalow Chalet Purpose built maisonette
 Coach Studio Converted maisonette Purpose built flat
 Converted flat Tenement flat Flat over non-residential use Other (specify in General Remarks)

Property Style Detached Semi detached Mid terrace End terrace
 Back to back High rise block Low rise block Other (specify in General Remarks)

Does the surveyor believe that the property was built for the public sector, e.g. local authority, military, police? Yes No

Flats/Maisonettes only Floor(s) on which located No. of floors in block Lift provided? Yes No
No. of units in block

Approximate Year of Construction

Tenure

Absolute Ownership Leasehold Ground rent £ Unexpired years

Accommodation

Number of Rooms Living room(s) Bedroom(s) Kitchen(s)
 Bathroom(s) WC(s) Other (Specify in General remarks)

Gross Floor Area (excluding garages and outbuildings) m² (Internal) m² (External)

Residential Element (greater than 40%) Yes No

Garage / Parking / Outbuildings

Single garage Double garage Parking space No garage / garage space / parking space
Available on site? Yes No

Permanent outbuildings:

The garage is an L shaped integral garage/workshop within the main structure of the house, which was originally a double garage, but reduced in size when a part was converted into a utility room. Its internal floor area is 26 square metres.

Mortgage Valuation Report

Construction

Walls Brick Stone Concrete Timber frame
 Solid Cavity Steel frame Concrete block Other (specify in General Remarks)

Roof Tile Slate Asphalt Felt
 Lead Zinc Artificial slate Flat glass fibre Other (specify in General Remarks)

Special Risks

Has the property suffered structural movement? Yes No
If Yes, is this recent or progressive? Yes No
Is there evidence, history, or reason to anticipate subsidence, heave, landslip or flood in the immediate vicinity? Yes No
If Yes to any of the above, provide details in General Remarks.

Service Connection

Based on visual inspection only. If any services appear to be non-mains, please comment on the type and location of the supply in General Remarks.

Drainage Mains Private None Water Mains Private None
Electricity Mains Private None Gas Mains Private None
Central Heating Yes Partial None

Brief description of Central Heating:

Oil central heating via a wet radiator system, controlled by a programmer and radiator thermostatically controlled valves.

The utility room is fitted with electric underfloor heating.

Site

Apparent legal issues to be verified by the conveyancer. Please provide a brief description in General Remarks.

Rights of way Shared drives / access Garage or other amenities on separate site Shared service connections
 Agricultural land included with property Ill-defined boundaries Other (specify in General Remarks)

Location

Residential suburb Residential within town / city Mixed residential / commercial Mainly commercial
 Commuter village Remote village Isolated rural property Other (specify in General Remarks)

Planning Issues

Has the property been extended / converted / altered? Yes No

If Yes provide details in General Remarks.

Roads

Made up road Unmade road Partly completed new road Pedestrian access only Adopted Unadopted

Mortgage Valuation Report

General Remarks

The property comprises a detached 1.5 storey house with integral garage/workshop within grounds extending to approximately 0.38 acres.

The rear extension is built with concrete block walls and a pitched slated roof.

Other accommodation within the house referred to above includes a utility room.

The property lies within the rural settlement of Keig. It fronts onto the Alford-Insch public road which passes through the settlement, is adjoined on both sides by the grounds of residential properties and is adjoined at the rear by agricultural land. Keig Primary School is 100 metres from the property.

The property is located 4 miles from Alford (population 2,700), which has a range of local shops, Medical and Dental Practices and a community campus on which there are nursery, primary and secondary schools, library and swimming pool. Major local centres of population and employment include: Inverurie (population 14,500) - 14 miles; Westhill (population 12,500) - 19 miles; Aberdeen City Centre - 26 miles.

Given the age and type of the original part of the building, there is likely to have been past movement to its structure. However, there is no obvious evidence of any recent movement having occurred, with any movement noted appearing to be old and non-progressive.

The house has been extended twice: (i) the rear wing was added 36 years ago (1990) - it should be confirmed that the necessary planning and building warrant approvals were obtained for this work and that a completion certificate was issued in respect of all works requiring building warrant approval (in this regard a letter from Aberdeenshire Council's Head of Planning Services dated 16/11/1999 has been inspected confirming that a completion certificate was issued on 22/06/1990) and (ii) the conversion of a part of the integral garage into a utility room 19 years ago (2007), for which the owners were advised that planning permission was not required.

Significant factors which may be of relevance to the market value of the property include: within commuting distance of Inverurie, Westhill and Aberdeen; pleasant setting with panoramic southerly aspect at front; extended traditional house with 8 habitable rooms, 2 bathrooms and an internal floor area of 197 square metres; well maintained and in good repair, no significant defects noted - the windows are of an age at which some maintenance/renewal is likely in the near future; most internal fittings are of a good standard, including kitchen (wooden - 24 years old), utility room, bathrooms and heating system (pipework and radiators have been renewed but the boiler is relatively old, installed around 1995); grounds are of a good size and well maintained.

In the aftermath of the initial Covid-19 lock-down period from July 2020 onwards, local rural residential market activity increased significantly, with this leading to shorter marketing periods and an increase in prices. However, from mid-2022 the residential property market generally experienced more difficult conditions caused by rising interest rates, inflation and the cost of living, and property taxes (Land Business Transaction Tax and Additional Dwelling Supplement). These conditions extended through 2023-25, although interest rates were steadily reduced during this period from a peak in August 2023. During this period there was at best little change in local rural residential property prices and most sectors saw a small reduction in prices; properties which have special features have fared better, such features might include location, view, setting, design and character, condition and repair, standard of fitting, size and quality of the grounds and its outbuildings. 2026 is likely to bring further uncertainty to the property market caused by the war in the middle east, which may bring a period of rising prices, cost of living and interest rates.

Mortgage Valuation Report

Essential Repairs

No essential repairs are required to the property.

Estimated cost of essential repairs £ Retention recommended? Yes No Amount £

Comment on Mortgageability

The property is considered to be suitable security for mortgage purposes, subject to the specific lending criteria of the mortgage provider.

Valuations

Market value in present condition £
Market value on completion of essential repairs £
Insurance reinstatement value £
(to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)
Is a reinspection necessary? Yes No

Buy To Let Cases

What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis? £
Is the property in an area where there is a steady demand for rented accommodation of this type? Yes No

Mortgage Valuation Report

Declaration

Signed	Security Print Code [462667 = 5873] Electronically signed by:-
Surveyor's name	David Silcocks
Professional qualifications	BSc, MRICS
Company name	Allied Surveyors Scotland Ltd
Address	Marywell House, 29-31 Marywell Street, Aberdeen, AB11 6JE
Telephone	01224 571163
Fax	01224 589042
Report date	9th April 2026

Wealthiton Croft
Keig
Alford
AB33 8BH

Section 2

Energy Report



Energy Performance Certificate (EPC)

Scotland

Dwellings

WEALTHITON CROFT, KEIG, ALFORD, AB33 8BH

Dwelling type: Detached house
Date of assessment: 31 March 2026
Date of certificate: 02 April 2026
Total floor area: 197 m²
Primary Energy Indicator: 318 kWh/m²/year


Reference number: 7400-5099-0322-3078-1763
Type of assessment: RdSAP, existing dwelling
Approved Organisation: Elmhurst
Main heating and fuel: Boiler and radiators, oil

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£11,556	See your recommendations report for more information
Over 3 years you could save*	£4,896	

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions




Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band E (42)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.



Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO₂) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band F (38)**

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Room-in-roof insulation	£900 - £1,200	£1146.00
2 Internal wall insulation	£7,500 - £11,000	£1029.00
3 Floor insulation (suspended floor)	£5,000 - £10,000	£357.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Granite or whin, as built, no insulation (assumed)	★★☆☆☆	★★☆☆☆
	Solid brick, as built, insulated (assumed)	★★★★☆	★★★★☆
Roof	Pitched, insulated (assumed)	★★★★☆	★★★★☆
	Roof room(s), ceiling insulated	★★☆☆☆	★★☆☆☆
Floor	Suspended, no insulation (assumed)	—	—
	Solid, limited insulation (assumed)	—	—
Windows	Fully double glazed	★★☆☆☆	★★☆☆☆
Main heating	Boiler and radiators, oil	★★☆☆☆	★★★★☆
Main heating controls	Programmer, TRVs and bypass	★★★★☆	★★★★☆
Secondary heating	Room heaters, dual fuel (mineral and wood)	—	—
Hot water	From main system	★★☆☆☆	★★☆☆☆
Lighting	Below average lighting efficiency	★★★★☆	★★★★☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.


The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 75 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 15 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 7.4 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£10,095 over 3 years	£5,580 over 3 years	
Hot water	£1,149 over 3 years	£768 over 3 years	
Lighting	£312 over 3 years	£312 over 3 years	
Totals	£11,556	£6,660	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures	Indicative cost	Typical saving per year	Rating after improvement	
			Energy	Environment
1 Room-in-roof insulation	£900 - £1,200	£382	E 48	E 43
2 Internal wall insulation	£7,500 - £11,000	£343	E 54	E 48
3 Floor insulation (suspended floor)	£5,000 - £10,000	£119	D 55	E 49
4 Draughtproofing	£150 - £250	£32	D 56	E 50
5 Upgrade heating controls	£220 - £250	£191	D 59	E 53
6 Replace boiler with new condensing boiler	£2,200 - £3,500	£565	D 68	D 64
7 Solar photovoltaic panels, 2.5 kWp	£8,000 - £10,000	£225	C 71	D 64
8 Wind turbine	£5,000 - £20,000	£693	C 79	D 66

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- Biomass boiler (Exempted Appliance if in Smoke Control Area)

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Room-in-roof insulation

Insulating roof rooms will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. If it has a flat ceiling insulation can usually be added above the ceiling, and sloping ceilings and walls of roof rooms can be insulated using an internal lining board. Roof voids must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about roof room insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk). Building regulations generally apply to this work so it is best to check this with your local authority building standards department.

2 Internal wall insulation

Internal wall insulation involves adding a layer of insulation to the inside surface of the external walls, which reduces heat loss and lowers fuel bills. As it is more expensive than cavity wall insulation it is only recommended for walls without a cavity, or where for technical reasons a cavity cannot be filled. Internal insulation, known as dry-lining, is where a layer of insulation is fixed to the inside surface of external walls; this type of insulation is best applied when rooms require redecorating. Further information can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

3 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

4 Draughtproofing

Fitting draughtproofing, strips of insulation around windows and doors, will improve the comfort in the home. A contractor can be employed but draughtproofing can be installed by a competent DIY enthusiast.

5 Heating controls (room thermostat)

The heating system should have a room thermostat to enable the boiler to switch off when no heat is required. A competent heating engineer should be asked to do this work. Insist that the thermostat switches off the boiler as well as the pump and that the thermostatic radiator valve is removed from any radiator in the same room as the thermostat. Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

6 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

7 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

8 Wind turbine

A wind turbine provides electricity from wind energy. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Wind turbines are not suitable for all properties. The system's effectiveness depends on local wind speeds and the presence of nearby obstructions, and a site survey should be undertaken by an accredited installer. Planning permission might be required and building regulations generally apply to this work and a building warrant may be required, so it is best to check these with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for a wind turbine, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	30,503.32	N/A	N/A	N/A
Water heating (kWh per year)	3,371.41			

Addendum

This dwelling has stone walls and so requires further investigation to establish whether these walls are of cavity construction and to determine which type of wall insulation is best suited.

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. David Silcocks
Assessor membership number:	EES/008466
Company name/trading name:	Allied Surveyors Scotland Ltd
Address:	Marywell House 29-31 Marywell Street Aberdeen AB11 6JE
Phone number:	01224 571163
Email address:	aberdeen@alliedsurveyorsscotland.com
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



Wealthiton Croft
Keig
Alford
AB33 8BH

Section 3

Property Questionnaire



Property Questionnaire

PROPERTY ADDRESS:	Wealthiton Croft Keig Alford Aberdeenshire AB338BH
-------------------	--

SELLER(S):	Neil & Anne Watson
------------	--------------------

COMPLETION DATE OF PROPERTY QUESTIONNAIRE:	15 th March 2026
--	-----------------------------

PROPERTY QUESTIONNAIRE

NOTE FOR SELLERS

- **Please complete this form carefully. It is important that your answers are correct.**
- **The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.**
- **If anything changes after you fill in this questionnaire but before the Date of Entry for the sale of your house, tell your solicitor or estate agent immediately.**

PROPERTY QUESTIONNAIRE

Information to be given to prospective buyer(s)

1. Length of ownership

How long have you owned the property?

- 26 years, 4 months - Since November 1999

2. Council Tax

Which Council Tax band is your property in?

- Property Band F

A B C D E **F** G H

3. Parking

What are the arrangements for parking at your property?

(Please indicate all that apply)

- Garage
- Allocated parking space
- **Driveway**
- Shared parking
- On street
- Resident permit
- Metered parking
- Other (please specify):

4. Conservation Area

Is your property in a designated Conservation Area (i.e. an area of special architectural or historic interest, the character or appearance of which it is desirable to preserve or enhance)?

No

5. Listed Buildings

Is your property a Listed Building, or contained within one (i.e. a building recognised and approved as being of special architectural or historical interest)?

No

6. Alterations / additions / extensions

<p>a.</p>	<p>(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?</p> <p>If you have answered yes, please describe the changes which you have made:</p> <ol style="list-style-type: none"> 1. 2002 - Installed Rayburn cooker in kitchen with new external flue 2. 2007 - Converted part of integral garage into an Utility/Store Room <p>In both cases, no structural alterations were done but the appropriate planning consents were sought – see 6 a. (ii) below.</p>	<p>Yes</p>
	<p>(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?</p> <p>If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.</p> <p>If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent can arrange to obtain them.</p> <ul style="list-style-type: none"> • Copy of Planning approval for Rayburn installation available • Copy of letter from council confirming building warrant not required for Utility/store room available 	<p>Yes</p>
<p>b.</p>	<p>Have you had replacement windows, doors, patio doors or double glazing installed in your property?</p> <p>If you have answered yes, please answer the three questions below:</p>	<p>Yes</p>

(i) Were the replacements the same shape and type as the ones you replaced?	Yes
(ii) Did this work involve any changes to the window or door openings?	No
<p>(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed):</p> <p>Glazing in existing windows replaced with new glazing panes. No changes were made to the window pane sizes. Completed circa 2010.</p> <p>Please give any guarantees which you received for this work to your solicitor or estate agent.</p> <p>No guarantees available.</p>	
7. Central heating	

a.	<p>Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property – the main living room, the bedroom(s), the hall and the bathroom).</p> <p><u>If you have answered yes/partial</u> – what kind of central heating is there?</p> <p>(Examples: gas-fired, solid fuel, electric storage heating, gas warm air.)</p> <p>Oil Fired Central Heating</p> <p><u>If you have answered yes, please answer the 3 questions below:</u></p>	Yes
----	--	-----

b.	<p>When was your central heating system or partial central heating system installed?</p> <p>Boiler installed circa 1995 Radiators and Pipework replaced circa 2010</p>	
c.	<p>Do you have a maintenance contract for the central heating system?</p> <p>No</p> <p><u>If you have answered yes</u>, please give details of the company with which you have a maintenance agreement:</p> <p>No Maintenance contract in place but central heating boiler and rayburn serviced annually by certified company</p>	
d.	<p>When was your maintenance agreement last renewed? (Please provide the month and year).</p> <p>n/a</p>	
8. Energy Performance Certificate		
	<p>Does your property have an Energy Performance Certificate which is less than 10 years old?</p>	No
9. Issues that may have affected your property		
a.	<p>Has there been any storm, flood, fire or other structural damage to your property while you have owned it?</p> <p><u>If you have answered yes</u>, is the damage the subject of any outstanding insurance claim?</p>	No
b.	<p>Are you aware of the existence of asbestos in your property?</p> <p><u>If you have answered yes</u>, please give details:</p>	No
10. Services		

a. Please tick which services are connected to your property and give details of the supplier:

Services	Connected	Supplier
Gas / liquid petroleum gas	No	
Water mains / private water supply	Yes	Scottish Water
Electricity	Yes	OVO
Mains drainage	Yes	Scottish Water
Telephone	Yes	BT (line installed but not currently utilised)
Cable TV / satellite	No	
Broadband	Yes	BT Line installed but not currently utilised for Broadband. Broadband provided via 4G router.

b.	Is there a septic tank system at your property? <u>If you have answered yes, please answer the two questions below:</u>	No
c.	Do you have appropriate consents for the discharge from your septic tank?	Yes/No/ Don't Know

	<p>cost or anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area?</p> <p><u>If you have answered yes</u>, please give details:</p>	
b.	<p>Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas?</p> <p><u>If you have answered yes</u>, please give details:</p>	No
c.	<p>Has there been any major repair or replacement of any part of the roof during the time you have owned the property?</p>	No
d.	<p>Do you have the right to walk over any of your neighbours' property - for example to put out your rubbish bin or to maintain your boundaries?</p> <p><u>If you have answered yes</u>, please give details:</p>	No
e.	<p>As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries?</p>	No

d.	Do you have a maintenance contract for your septic tank? <u>If you have answered yes</u> , please give details of the company with which you have a maintenance contract:	Yes/No
----	--	--------

11. Responsibilities for Shared or Common Areas

a.	Are you aware of any responsibility to contribute to the cost of anything...	No
----	--	----

	<u>If you have answered yes, please give details:</u>	
f.	<p>As far as you are aware, is there a Public Right of Way across any part of your property? (A Public Right of Way is a way over which the public has a right to pass, whether or not the land is privately-owned.)</p> <p><u>If you have answered yes, please give details:</u></p>	No
12. Charges associated with your property		
a.	<p>Is there a factor or property manager for your property?</p> <p><u>If you have answered yes, please provide the name and address and give details of any deposit held and approximate charges:</u></p>	No
b.	<p>Is there a common buildings insurance policy?</p> <p><u>If you have answered yes, is the cost of the insurance included in your monthly/annual factor's charges?</u></p>	No
		Yes/No/ Don't know
c.	<p>Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, e.g. to a Residents' Association, or maintenance or stair fund.</p> <p>No additional Charges</p>	
13. Specialist Works		

a.	<p>As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?</p> <p><u>If you have answered yes</u>, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property</p> <p>We have owned the property for approximately 26 years and during my ownership no treatment for dry rot, wet rot, damp or other specialist works has been carried out. I believe that some form of woodworm treatment may possibly have been carried out before I purchased the property, however I have no paperwork or further information in relation to this.</p>	Yes
b.	<p>As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?</p> <p><u>If you have answered yes</u>, please give details</p>	No
c.	<p><u>If you have answered yes</u> to 13(a) or (b), do you have any guarantees relating to this work?</p> <p><u>If you have answered yes</u>, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself <u>please write below who has these documents</u> and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate.</p> <p>Guarantees are held by:</p>	No
14. Guarantees		
a.	Are there any guarantees or warranties for any of the following:	

(i)	Electrical work	No	Yes	Don't Know	With title deeds	Lost
(ii)	Roofing	No	Yes	Don't Know	With title deeds	Lost
(iii)	Central heating	No	Yes	Don't know	With title deeds	Lost
(iv)	NHBC	No	Yes	Don't know	With title deeds	Lost
(v)	Damp course	No	Yes	Don't know	With title deeds	Lost
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	No	Yes	Don't know	With title deeds	Lost
b.	<u>If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):</u>					
c.	<p>Are there any outstanding claims under any of the guarantees listed above?</p> <p><u>If you have answered yes, please give details:</u></p>					No
15. Boundaries						
<p>So far as you are aware, has any boundary of your property been moved in the last 10 years?</p> <p><u>If you have answered yes, please give details:</u></p>						No
16. Notices that affect your property						

In the past 3 years have you ever received a notice:		
a.	advising that the owner of a neighbouring property has made a planning application?	Yes
b.	that affects your property in some other way?	No
c.	that requires you to do any maintenance, repairs or improvements to your property?	No
<p>If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchase of your property.</p> <p>Planning Application for neighbours extension: APP/2024/1651 Alterations and Extension to Dwellinghouse Rosella Keig Alford AB33 8BH</p>		

Declaration by the seller(s)/or other authorised body or person(s):

I / We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s) :


.....

.....

Date:

