

YOUR ONESURVEY HOME REPORT

ADDRESS

58 Fifth Avenue
Glasgow
G12 0AT

PREPARED FOR

Les O'Brien

INSPECTION CARRIED OUT BY:



SELLING AGENT:

**YATES
HELLIER**

HOME REPORT GENERATED BY:



Document Index

| Document | Status | Prepared By | Prepared On |
|------------------------|--------------|---|-------------|
| Single Survey | Final | Glasgow North - Allied Surveyors Scotland Ltd | 18/08/2025 |
| Mortgage Certificate | Final | Glasgow North - Allied Surveyors Scotland Ltd | 18/08/2025 |
| Property Questionnaire | Final | Mr. Les O'Brien | 14/08/2025 |
| EPC | FileUploaded | Glasgow North - Allied Surveyors Scotland Ltd | 18/08/2025 |
| Additional Documents | FileUploaded | | |

Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.**

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

P A R T 1 .

SINGLE SURVEY

A report on the condition of the property, with categories
being rated from 1 to 3.



Single Survey

Survey report on:

| | |
|---------------------------|---------|
| Surveyor Reference | GG/0748 |
|---------------------------|---------|

| | |
|-----------------|-----------------|
| Customer | Mr. Les O'Brien |
|-----------------|-----------------|

| | |
|------------------------|---------------------------------------|
| Selling address | 58 Fifth Avenue Glasgow G12 0AT |
|------------------------|---------------------------------------|

| | |
|---------------------------|------------|
| Date of Inspection | 15/08/2025 |
|---------------------------|------------|

| | |
|--------------------|--|
| Prepared by | Gary Haggarty, BSc (Hons) MRICS Glasgow North - Allied Surveyors Scotland Ltd |
|--------------------|--|

SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property.¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is *The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion*
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

2.3.1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

2.3.2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.

2.3.3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an

arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

“Re-instatement cost” is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

1. INFORMATION AND SCOPE OF INSPECTION

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the Surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the Surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the Surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities will not be inspected or reported on.

| | |
|--------------------------------|--|
| Description | The subjects comprise a semi detached villa, two storey in height, with single storey rear extension, built by Messrs John Lawrence. |
| Accommodation | Ground floor: Entrance porch, hall, lounge, dining room (internal), rear hall, sitting room and shower room. First floor: Upper landing, bedroom one, bedroom two, bedroom three and shower room. |
| Gross internal floor area (m2) | 103m ² |
| Neighbourhood and location | The property is located in a popular and established residential location developed in a variety of property types within the Jordanhill district, lying to the west of the City. There are normal amenities within a reasonably short distance. |
| Age | 65 years or thereby. The extension is 31 years old. |
| Weather | Dry, sunny and warm. |
| Chimney stacks | The chimneyhead is of rendered construction, dressed in lead flashings, where visible from ground level. <i>Visually inspected with the aid of binoculars where required.</i> |

| | |
|-------------------------------------|--|
| Roofing including roof space | <p>The roof is hipped and pitched, timber supported and clad externally in concrete interlocking tiles, topped in concrete ridging. Access to the roof space is from a hatch in the upper landing ceiling. Inspection reveals a traditionally constructed roof structure comprising timber joists, rafters and sarking with a brick party wall. Thick insulation is present, as is flooring, which restricted our inspection.</p> <p>The rear extension has a mono pitched, presumed timber framed and concrete tile clad roof incorporating a timber framed double glazed window. There is no roof space.</p> <p><i>Sloping roofs were visually inspected with the aid of binoculars where required.</i></p> <p><i>Roof spaces were visually inspected and were entered where there was safe and reasonable access, normally defined as being from a 3m ladder within the property. If this is not possible, then physical access to the roof space may be taken by other means if the Surveyor deems it safe and reasonable to do so.</i></p> <p><i>Roofs are prone to water penetration during adverse weather but it is not always possible for surveyors to identify this likelihood in good or dry weather. All roofs should be inspected and repaired by reputable tradesmen on an annual basis and especially after storms.</i></p> |
| Rainwater fittings | <p>Rainwater discharge is via uPVC gutters and downpipes.</p> <p><i>Visually inspected with the aid of binoculars where required.</i></p> |
| Main walls | <p>The main walls of the property are of cavity blockwork construction, hard plastered internally. The rear extension is of traditional cavity brick construction rendered externally.</p> <p><i>Visually inspected with the aid of binoculars where required.</i></p> <p><i>Foundations and concealed parts were not exposed or inspected.</i></p> |
| Windows, external doors and joinery | <p>Replacement uPVC framed double glazed windows, doors and patio doors of mixed vintage. Aluminum framed double glazed inner entrance door. uPVC clad soffits and fascias.</p> <p><i>Internal and external doors were opened and closed where keys were available.</i></p> <p><i>Random windows were opened and closed where possible.</i></p> <p><i>Doors and windows were not forced open.</i></p> |
| External decorations | <p>External surfaces are painted, where applicable.</p> <p><i>Visually inspected.</i></p> |
| Conservatories / porches | None. |
| Communal areas | None. |

| | |
|---------------------------------------|---|
| Garages and permanent outbuildings | <p>Single car detached garage of brick construction under a pitched and asbestos clad roof. The rear projection of the garage has a mono pitched and felted roof.</p> <p><i>Visually inspected.</i></p> |
| Outside areas and boundaries | <p>There are garden grounds to the front, side and rear, with driveway parking, adequately bounded.</p> <p><i>Visually inspected.</i></p> |
| Ceilings | <p>Ceilings throughout the property are of plasterboard materials.</p> <p><i>Visually inspected from floor level.</i></p> |
| Internal walls | <p>The internal walls and partitions are of Bellrock construction, plastered. The extension internal walls and partitions are timber framed and plaster board lined.</p> <p><i>Visually inspected from floor level.</i></p> <p><i>Using a moisture meter, walls were randomly tested for dampness where considered appropriate.</i></p> |
| Floors including sub floors | <p>Flooring throughout the property is of suspended timber design, overlaid in tongue and groove boarding, all of which have fully fitted floor coverings, including carpeting and tiling. Due to the presence of fully fitted floor coverings, no underbuilding access was possible.</p> <p><i>Surfaces of exposed floors were visually inspected. No carpets or floor coverings were lifted.</i></p> <p><i>Sub-floor areas were inspected only to the extent visible from a readily accessible and unfixed hatch by way of an inverted "head and shoulders" inspection at the access point.</i></p> <p><i>Physical access to the sub floor area may be taken if the Surveyor deems it is safe and reasonable to do so, and subject to a minimum clearance of 1m between the underside of floor joists and the solum as determined from the access hatch.</i></p> |
| Internal joinery and kitchen fittings | <p>Internal joinery comprises timber skirtings, door facings and door surrounds, and timber framed and glazed or timber internal pass doors. Kitchen fittings comprise a range of wall and base units and work surfaces, incorporating a stainless steel sink and drainer, electric hob and oven.</p> <p><i>Built-in cupboards were looked into but no stored items were moved.</i></p> <p><i>Kitchen units were visually inspected excluding appliances.</i></p> |
| Chimney breasts and fireplaces | <p>Fireplaces throughout the property have been sealed and are unvented.</p> <p><i>Visually inspected. No testing of the flues or fittings was carried out.</i></p> |

| | |
|---------------------------------------|--|
| Internal decorations | <p>Papered and painted walls and ceilings, glossed and stained internal woodwork, etc.</p> <p><i>Visually inspected.</i></p> |
| Cellars | None. |
| Electricity | <p>A mains supply of electricity is connected to the property, the electrical meter and circuit breaker consumer unit located in the hall cupboard and serving 13 Amp square pin sockets throughout. Wiring, where visible, is sheathed in uPVC.</p> <p><i>Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.</i></p> <p><i>Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.</i></p> |
| Gas | <p>A mains supply of gas is connected, the gas meter located externally in a uPVC housing.</p> <p><i>Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances.</i></p> <p><i>Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the Surveyor will state that in the report and will not turn them on.</i></p> |
| Water, plumbing and bathroom fittings | <p>Cold water is from the mains supply. Visible plumbing comprises copper and uPVC supply pipework.</p> <p>The shower rooms contain low level WC, wash hand basins and shower cubicles. The ground floor shower room has an electric shower, whereas the upper floor shower room has a mixer shower.</p> <p><i>Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation.</i></p> <p><i>No tests whatsoever were carried out to the system or appliances.</i></p> <p><i>Concealed areas around baths and shower trays cannot be inspected however water spillage over a period of time can result in unexpected defects to hidden parts of the building fabric.</i></p> |

| | |
|-------------------------------------|--|
| Heating and hot water | <p>The property is centrally heated by means of a gas fired system, comprising a condensing combination boiler located in the upper landing cupboard. Heating to the rooms is provided by water filled radiators. The system is of a type designed to provide instantaneous hot water upon demand.</p> <p><i>Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.</i></p> <p><i>No tests whatsoever were carried out to the system or appliances.</i></p> |
| Drainage | <p>Mains drainage is understood to be connected.</p> <p><i>Drainage covers etc were not lifted.</i></p> <p><i>Neither drains nor drainage systems were tested.</i></p> |
| Fire, smoke and burglar alarms | <p>The property has a heat detector and smoke alarms installed. In addition, an intruder alarm system is present. The installation certification is appended to this report.</p> <p><i>Visually inspected.</i></p> <p><i>No test whatsoever were carried out to any systems or appliances.</i></p> <p><i>There is now a requirement in place for compliant interlinked fire, smoke and heat detectors in residential properties. The new fire smoke and alarm standard came into force in Scotland in February 2022, requiring a smoke alarm to be installed in the room most frequently used for living purposes and in every circulation space on each floor. A heat alarm also requires to be installed in each kitchen. The alarms need to be ceiling mounted and interlinked. Where there is a carbon fuelled appliance such as a boiler, open fire or wood burner etc. a carbon monoxide detector is also required.</i></p> <p><i>The surveyor will only comment on the presence of a smoke detector etc. but will not test them, ascertain if they are in working order, interlinked and / or fully compliant with the fire and smoke alarm standard that was introduced in 2022.</i></p> |
| Any additional limits to inspection | <p>It will be appreciated that parts of the property, which are covered, unexposed or inaccessible, cannot be guaranteed to be free from defect.</p> <p>An inspection for Japanese Knotweed was not carried out. This is a plant which is subject to control regulation, is considered to be invasive and one which can render a property unsuitable for some mortgage lenders. It is therefore assumed that there is no Japanese Knotweed within the boundaries of the property or its neighbouring property. Identification of Japanese Knotweed is best undertaken by a specialist contractor. If it exists removal must be undertaken in a controlled manner by specialist contractors. This can prove to be expensive.</p> <p><i>Normal maintenance is not treated as a repair for the purposes of the Single Survey. When a category 1 rating is provided this means the property must continue to be maintained in the normal way.</i></p> |

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

2. CONDITION

This section identifies problems and tells you about the urgency of any repairs by using one of the above 3 categories:

| Category 3 | Category 2 | Category 1 |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

| Structural movement | |
|---------------------|--|
| Repair category: | 1 |
| Notes: | No obvious significant structural movement noted, on the basis of a single inspection. |

| Dampness, rot and infestation | |
|-------------------------------|--|
| Repair category: | 1 |
| Notes: | <p>An electronic moisture meter was used to measure levels of dampness, at random locations, to lower wall surfaces and floors, where accessible and without moving furniture or lifting floor coverings, if present. No obvious significant dampness, timber decay or infestation noted, within the limitations imposed on the inspection.</p> <p>Staining was noted to within the front bedroom, however when tested with an electronic moisture meter, affected areas were dry.</p> |

| Chimney stacks | |
|------------------|---|
| Repair category: | 1 |
| Notes: | From a ground level inspection, no obvious significant defects were noted to the chimney head allowing for normal weathering. |

| Category 3 | Category 2 | Category 1 |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

Roofing including roof space

| | |
|------------------|---|
| Repair category: | 2 |
| Notes: | <p>Roof tiling, where viewed from ground level, appears to have been laid to generally even courses with no obvious significant defects noted.</p> <p>However, internally, deterioration is evident to sarking.</p> |

Rainwater fittings

| | |
|------------------|---|
| Repair category: | 1 |
| Notes: | <p>No significant disrepair was noted to rainwater goods. It will however be appreciated that the inspection was carried out during dry weather conditions. Sometimes defects in rainwater goods are only apparent during, or after heavy rainfall.</p> |

Main walls

| | |
|------------------|---|
| Repair category: | 1 |
| Notes: | <p>No obvious significant defects were noted to accessible wall surfaces.</p> <p>Some open jointing has occurred to blockwork, consistent with age.</p> |

| Category 3 | Category 2 | Category 1 |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

Windows, external doors and joinery

| | |
|------------------|--|
| Repair category: | 2 |
| Notes: | <p>No obvious significant defects noted to window or doors, although windows are not modern and the life expectancy of same should be fully appreciated.</p> <p>No provision for permanent ventilation was noted to the replacement windows.</p> <p>Condensation and black spot mould was noted around the upper floor shower room window frame, attributable to inadequate heating and ventilation.</p> <p>Double glazing can be problematic and over time the operation of the windows can be affected and opening mechanisms damaged. It is therefore likely that maintenance repairs should be anticipated as part of an ongoing maintenance programme. Our valuation does assume that the installation of the windows does comply with the necessary regulations at the time of installation.</p> |

External decorations

| | |
|------------------|---|
| Repair category: | 1 |
| Notes: | The external paintwork finishes are in reasonable condition but are beginning to deteriorate. |

Conservatories / porches

| | |
|------------------|-----|
| Repair category: | |
| Notes: | N/A |

Communal areas

| | |
|------------------|-----|
| Repair category: | |
| Notes: | N/A |

| Category 3 | Category 2 | Category 1 |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

Garages and permanent outbuildings

| | |
|------------------|--|
| Repair category: | 2 |
| Notes: | <p>The garage is in reasonable condition having regard to its the age and intended purpose.</p> <p>However, deterioration is evident to the window and gutters which are the original.</p> <p>The roof is made of corrugated asbestos cement which is not considered a health hazard provided it is not disturbed. It should only be removed and disposed of by a licensed contractor.</p> |

Outside areas and boundaries

| | |
|------------------|---|
| Repair category: | 1 |
| Notes: | Outside areas and boundaries appear adequate for purpose. |

Ceilings

| | |
|------------------|---|
| Repair category: | 1 |
| Notes: | <p>No obvious significant defects were noted to ceiling surfaces.</p> <p>Some plaster cracking has occurred, consistent with age.</p> |

Internal walls

| | |
|------------------|---|
| Repair category: | 1 |
| Notes: | No obvious significant defects were noted to the internal walls. Some plaster finishes are uneven, consistent with age. |

| Category 3 | Category 2 | Category 1 |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

Floors including sub-floors

| | |
|------------------|---|
| Repair category: | 1 |
| Notes: | <p>Within the limitations imposed on the inspection, no indications were noted to suggest any serious disrepair. It will however be appreciated that concealed floor timbers cannot be guaranteed to be free from defect.</p> <p>Areas of loose and uneven flooring were noted, consistent with age and assumed to be related to poor workmanship and not timber defect. Care should be taken during any intended re-fixing works to ensure that existing services are not disturbed.</p> |

Internal joinery and kitchen fittings

| | |
|------------------|--|
| Repair category: | 1 |
| Notes: | <p>No obvious significant defects were noted to internal joinery or kitchen fittings.</p> <p>Some internal pass doors have glazed panels which do not appear to be of an approved safety type.</p> |

Chimney breasts and fireplaces

| | |
|------------------|---|
| Repair category: | 1 |
| Notes: | <p>No obvious significant defects were noted to the chimney breasts or fireplaces.</p> <p>No provision for permanent ventilation is apparent to blocked/disused chimney flues. The lack of same can lead to condensation and dampness internally.</p> |

| Category 3 | Category 2 | Category 1 |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

| Internal decorations | |
|----------------------|--|
| Repair category: | 1 |
| Notes: | <p>No obvious significant defects were noted to the internal decoration. If decorative finishes are removed, plaster repairs should be anticipated.</p> <p>The ceiling finishes may contain asbestos fibres. This can only be determined by taking a sample for analysis. Even if the sitting room ceiling finishes does contain asbestos fibres it is not normally considered to be a health hazard provided it is not disturbed, for example it should not be rubbed down during redecoration.</p> |

| Cellars | |
|------------------|-----|
| Repair category: | |
| Notes: | N/A |

| Electricity | |
|------------------|---|
| Repair category: | 1 |
| Notes: | <p>The electrical installation appeared to be in a condition commensurate with age and type with no visual defects being apparent. However, it should be fully appreciated that only the most recently re-wired or constructed properties will comply with current regulations.</p> <p>The vendor advises that the property was rewired in 2022. Certification appended to this report.</p> <p>It is recommended good practice that all electrical installations should be checked periodically, approximately every ten years or when a property changes hands. This should be regarded as a routine safety and maintenance check.</p> |

| Gas | |
|------------------|---|
| Repair category: | 1 |
| Notes: | <p>No obvious significant defects noted. All gas appliances should be tested and thereafter regularly maintained by a Gas Safe registered contractor.</p> <p>A Gas Safety Certificate is appended to this report.</p> |

| Category 3 | Category 2 | Category 1 |
|--|---|--|
| Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now. | Repairs or replacement requiring future attention, but estimates are still advised. | No immediate action or repair is needed. |

Water, plumbing and bathroom fittings

| | |
|------------------|--|
| Repair category: | 1 |
| Notes: | <p>No obvious significant defects noted to accessible plumbing or sanitary fittings.</p> <p>Some mould growth was noted to the upper floor shower tray seal which indicates porosity. Concealed areas cannot be guaranteed to be free from defect.</p> |

Heating and hot water

| | |
|------------------|--|
| Repair category: | 1 |
| Notes: | <p>No obvious significant defects were noted to the heating system or hot water system, although these have not been tested.</p> <p>It is recommended good practice that gas boilers are serviced on an annual basis by an appropriately qualified person. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person.</p> <p>The vendor advises that the central heating system was renewed in 2022. Certification appended to this report.</p> |

Drainage

| | |
|------------------|---|
| Repair category: | 1 |
| Notes: | No obvious significant defects were noted to the drainage system, within the limitations of the inspection. |

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the comments above for detailed information.

| | |
|--|---|
| Structural movement | 1 |
| Dampness, rot and infestation | 1 |
| Chimney stacks | 1 |
| Roofing including roof space | 2 |
| Rainwater fittings | 1 |
| Main walls | 1 |
| Windows, external doors and joinery | 2 |
| External decorations | 1 |
| Conservatories / porches | |
| Communal areas | |
| Garages and permanent outbuildings | 2 |
| Outside areas and boundaries | 1 |
| Ceilings | 1 |
| Internal walls | 1 |
| Floors including sub-floors | 1 |
| Internal joinery and kitchen fittings | 1 |
| Chimney breasts and fireplaces | 1 |
| Internal decorations | 1 |
| Cellars | |
| Electricity | 1 |
| Gas | 1 |
| Water, plumbing and bathroom fittings | 1 |
| Heating and hot water | 1 |
| Drainage | 1 |

Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

3. ACCESSIBILITY INFORMATION

Guidance Notes on Accessibility Information

Three steps or fewer to a main entrance door of the property: In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

Unrestricted parking within 25 metres: For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coinoperated machines.

| | |
|--|---|
| 1. Which floor(s) is the living accommodation on? | Ground |
| 2. Are there three steps or fewer to a main entrance door of the property? | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| 3. Is there a lift to the main entrance door of the property? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| 4. Are all door openings greater than 750mm? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| 5. Is there a toilet on the same level as the living room and kitchen? | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| 6. Is there a toilet on the same level as a bedroom? | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| 7. Are all rooms on the same level with no internal steps or stairs? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| 8. Is there unrestricted parking within 25 metres of an entrance door to the building? | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |

4. VALUATION AND CONVEYANCER ISSUES

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated re-instatement cost for insurance purposes.

Matters for a solicitor or licensed conveyancer

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

The property is situated in an area of past mining activity. The conveyancer should obtain a mining report from The Mining Remediation Authority to provide information as to historical and future mining activity and whether the property has been the subject of any compensation claims, ensuring that the property is not adversely affected. The valuation assumes the content will reveal nothing adverse.

During the inspection it was noted that alterations have taken place, and in this regard it is assumed that all necessary Local Authority Consents and Certifications have been granted or will be made available. It is, therefore, recommended that this matter be investigated and clarified, in relation to the addition of a rear extension, circa 1994.

Where items of maintenance or repair have been identified, the purchaser should satisfy themselves as to the costs and implications of these issues prior to making an offer to purchase.

Estimated re-instatement cost (£) for insurance purposes

£240,000 (Two Hundred and Forty Thousand Pounds Sterling)

It is recommended that you update this figure regularly to ensure that you have adequate cover or alternatively seek specialist advice from your insurer.

Valuation (£) and market comments

In its present condition the opinion of valuation for the Outright Ownership interest with vacant possession is £350,000 (Three Hundred and Fifty Thousand Pounds Sterling).

| | |
|------------------------|--|
| Report author: | Gary Haggarty, BSc (Hons) MRICS |
| Company name: | Glasgow North - Allied Surveyors Scotland Ltd |
| Address: | Herbert House 24 Herbert Street Glasgow G20 6NB |
| Signed: | Electronically Signed: 295069-8040bd08-7b26 |
| Date of report: | 18/08/2025 |

P A R T 2 .

MORTGAGE VALUATION REPORT

Includes a market valuation of the property.





Mortgage Valuation Report

| | | |
|---------------------|---------------------------------------|--|
| Property: | 58 Fifth Avenue Glasgow G12 0AT | Client: Mr. Les O'Brien Tenure: Ownership |
| Date of Inspection: | 15/08/2025 | Reference: GG/0748/GH/PB |

This report has been prepared as part of the seller's instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising a potential lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.

1.0 LOCATION

The property is located in a popular and established residential location developed in a variety of property types within the Jordanhill district, lying to the west of the City. There are normal amenities within a reasonably short distance.

| | | | |
|-----|-------------|----------|---|
| 2.0 | DESCRIPTION | 2.1 Age: | 65 years or thereby. The extension is 31 years old. |
|-----|-------------|----------|---|

The subjects comprise a semi detached villa, two storey in height, with single storey rear extension, built by Messrs John Lawrence.

3.0 CONSTRUCTION

The walls are of traditional cavity brick construction under a pitched and tiled roof.

4.0 ACCOMMODATION

Ground floor: Entrance porch, hall, lounge, dining room (internal), rear hall, sitting room and shower room.

First floor: Upper landing, bedroom one, bedroom two, bedroom three and shower room.

5.0 SERVICES (No tests have been applied to any of the services)

| | | | | | | | |
|------------------|-------------------------------|--------------|-------|------|-------|-----------|-------|
| Water: | Mains | Electricity: | Mains | Gas: | Mains | Drainage: | Mains |
| Central Heating: | Gas fired boiler to radiators | | | | | | |

6.0 OUTBUILDINGS

Garage: None

Others: None

| | | | | | |
|--|--|-----------------|--|-----|----------------------|
| 7.0 | GENERAL CONDITION - <i>A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.</i> | | | | |
| The general condition of the property appears consistent with its age and type of construction, however some works of repair, maintenance and upgrading are required. This has been reflected in the mortgage valuation. | | | | | |
| 8.0 | ESSENTIAL REPAIR WORK <i>(as a condition of any mortgage or, to preserve the condition of the property)</i> | | | | |
| None noted. | | | | | |
| 8.1 Retention recommended: | | | | | |
| 9.0 | ROADS & FOOTPATHS | | | | |
| Made up and assumed adopted. | | | | | |
| 10.0 | BUILDINGS INSURANCE (£): | 240,000 | GROSS EXTERNAL FLOOR AREA | 113 | Square metres |
| | <i>This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.</i> | | | | |
| 11.0 | GENERAL REMARKS | | | | |
| In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal. | | | | | |
| The property is situated in an area of past mining activity. The conveyancer should obtain a mining report from The Mining Remediation Authority to provide information as to historical and future mining activity and whether the property has been the subject of any compensation claims, ensuring that the property is not adversely affected. The valuation assumes the content will reveal nothing adverse. | | | | | |
| During the inspection it was noted that alterations have taken place, and in this regard it is assumed that all necessary Local Authority Consents and Certifications have been granted or will be made available. It is, therefore, recommended that this matter be investigated and clarified, in relation to the addition of a rear extension, circa 1994. | | | | | |
| Where items of maintenance or repair have been identified, the purchaser should satisfy themselves as to the costs and implications of these issues prior to making an offer to purchase. | | | | | |
| 12.0 | VALUATION <i>On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.</i> | | | | |
| 12.1 | Market Value in present condition (£): | £350,000 | Three Hundred and Fifty Thousand Pounds Sterling | | |
| 12.2 | Market Value on completion of essential works (£): | | | | |

| | | | | |
|---|--|---|---|------------|
| 12.3 | Suitable security for normal mortgage purposes? | Yes | | |
| 12.4 | Date of Valuation: | 15/08/2025 | | |
| Signature: | | Electronically Signed: 295069-8040bd08-7b26 | | |
| Surveyor: | Gary Haggarty | BSc (Hons) MRICS | Date: | 18/08/2025 |
| Glasgow North - Allied Surveyors Scotland Ltd | | | | |
| Office: | Herbert House 24 Herbert Street Glasgow G20 6NB | | Tel: 0141 337 1133 Fax: email: glasgow.north@alliedsurveyorsscotland.com | |

P A R T 3 .

ENERGY REPORT

A report on the energy efficiency of the property.



energy report

energy report on:

| | |
|-------------------------|---------------------------------------|
| Property address | 58 Fifth Avenue Glasgow G12 0AT |
|-------------------------|---------------------------------------|

| | |
|-----------------|-----------------|
| Customer | Mr. Les O'Brien |
|-----------------|-----------------|

| | |
|-------------------------|---------------------------------------|
| Customer address | 58 Fifth Avenue Glasgow G12 0AT |
|-------------------------|---------------------------------------|

| | |
|--------------------|--|
| Prepared by | Gary Haggarty, BSc (Hons) MRICS Glasgow North - Allied Surveyors Scotland Ltd |
|--------------------|--|

Energy Performance Certificate (EPC)

Scotland

Dwellings

58 FIFTH AVENUE, GLASGOW, G12 0AT

Dwelling type: Semi-detached house
Date of assessment: 15 August 2025
Date of certificate: 15 August 2025
Total floor area: 103 m²
Primary Energy Indicator: 199 kWh/m²/year

Reference number: 0815-9028-9000-0645-8296
Type of assessment: RdSAP, existing dwelling
Approved Organisation: Elmhurst
Main heating and fuel: Boiler and radiators, mains gas

You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

| | | |
|---|--------|--|
| Estimated energy costs for your home for 3 years* | £4,338 | See your recommendations report for more information |
| Over 3 years you could save* | £756 | |

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions

Very energy efficient - lower running costs



Not energy efficient - higher running costs

| Current | Potential |
|---------|-----------|
| 68 | 77 |

Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (68)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Very environmentally friendly - lower CO₂ emissions



Not environmentally friendly - higher CO₂ emissions

| Current | Potential |
|---------|-----------|
| 67 | 75 |

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO₂) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (67)**

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

| Recommended measures | Indicative cost | Typical savings over 3 years |
|--------------------------------------|------------------|------------------------------|
| 1 Cavity wall insulation | £900 - £1,500 | £540.00 |
| 2 Floor insulation (suspended floor) | £5,000 - £10,000 | £219.00 |
| 3 Solar photovoltaic (PV) panels | £8,000 - £10,000 | £669.00 |

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

| Element | Description | Energy Efficiency | Environmental |
|-----------------------|--|-------------------|---------------|
| Walls | Cavity wall, as built, no insulation (assumed) | ★★☆☆☆ | ★★☆☆☆ |
| | Cavity wall, as built, insulated (assumed) | ★★★★☆ | ★★★★☆ |
| Roof | Pitched, 350 mm loft insulation | ★★★★★ | ★★★★★ |
| | Pitched, insulated | ★★★☆☆ | ★★★☆☆ |
| Floor | Suspended, no insulation (assumed) | — | — |
| | Suspended, limited insulation (assumed) | — | — |
| Windows | Fully double glazed | ★★☆☆☆ | ★★☆☆☆ |
| Main heating | Boiler and radiators, mains gas | ★★★★☆ | ★★★★☆ |
| Main heating controls | Programmer, room thermostat and TRVs | ★★★★☆ | ★★★★☆ |
| Secondary heating | None | — | — |
| Hot water | From main system | ★★★★☆ | ★★★★☆ |
| Lighting | Good lighting efficiency | ★★★★☆ | ★★★★☆ |

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.


The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 36 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.7 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.9 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.







Estimated energy costs for this home

| | Current energy costs | Potential energy costs | Potential future savings |
|---------------|----------------------|------------------------|---|
| Heating | £3,387 over 3 years | £2,628 over 3 years |  |
| Hot water | £756 over 3 years | £759 over 3 years | |
| Lighting | £195 over 3 years | £195 over 3 years | |
| Totals | £4,338 | £3,582 | |

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

| Recommended measures | Indicative cost | Typical saving per year | Rating after improvement | |
|--------------------------------------|------------------|-------------------------|---|---|
| | | | Energy | Environment |
| 1 Cavity wall insulation | £900 - £1,500 | £180 |  |  |
| 2 Floor insulation (suspended floor) | £5,000 - £10,000 | £73 |  |  |
| 3 Solar photovoltaic panels, 2.5 kWp | £8,000 - £10,000 | £223 |  |  |

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- External insulation with cavity wall insulation

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Cavity wall insulation

Cavity wall insulation, to fill the gap between the inner and outer layers of external walls with an insulating material, reduces heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the outer walls, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work and handle any building standards issues. Further information about cavity wall insulation and details of local installers can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

3 Solar photovoltaic (PV) panels

A solar PV system is one which converts light directly into electricity via panels placed on the roof with no waste and no emissions. This electricity is used throughout the home in the same way as the electricity purchased from an energy supplier. Planning permission might be required, building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority. The assessment does not include the effect of any Feed-in Tariff which could appreciably increase the savings that are shown on this EPC for solar photovoltaic panels, provided that both the product and the installer are certified by the Microgeneration Certification Scheme (or equivalent). Details of local MCS installers are available at www.microgenerationcertification.org.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

| Heat demand | Existing dwelling | Impact of loft insulation | Impact of cavity wall insulation | Impact of solid wall insulation |
|------------------------------|-------------------|---------------------------|----------------------------------|---------------------------------|
| Space heating (kWh per year) | 13,226.16 | N/A | N/A | N/A |
| Water heating (kWh per year) | 2,169.21 | | | |

Addendum

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

| | |
|-----------------------------|--|
| Assessor's name: | Mr. Gary Haggarty |
| Assessor membership number: | EES/016069 |
| Company name/trading name: | Allied Surveyors Scotland Ltd |
| Address: | 24 Herbert Street Glasgow G20 6NB |
| Phone number: | 01413309950 |
| Email address: | glasgow.north@alliedsurveyorsscotland.com |
| Related party disclosure: | No related party |

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



P A R T 4 .

PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



Property Questionnaire

| | |
|---|---|
| Property Address | 58 Fifth Avenue Glasgow G12 0AT |
| Seller(s) | Margaret O'Brien (Executor for Marion Todd) |
| Completion date of property questionnaire | 14/08/2025 |
| Note for sellers | |

| | |
|----|--|
| 1. | Length of ownership |
| | How long have you owned the property? 32 years |
| 2. | Council tax |
| | Which Council Tax band is your property in? (Please circle) []A []B []C []D []E [X]F []G []H |
| 3. | Parking |
| | What are the arrangements for parking at your property? (Please tick all that apply) Garage [X] Allocated parking space [] Driveway [X] Shared parking [] On street [X] Resident permit [] Metered parking [] Other (please specify): |

| | | |
|-----------|--|--|
| 4. | Conservation area | |
| | Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> Don't know |
| 5. | Listed buildings | |
| | Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| 6. | Alterations/additions/extensions | |
| a | (i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)? | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| | If you have answered yes, please describe below the changes which you have made: <i>Extension with garden room, WC with Shower to rear of property</i> | |
| | (ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work? | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| | If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. | |
| | If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them: <i>The works were carried out under the control of an architect and all rules and regulations were followed. Unknown where the required documents are located.</i> | |
| b | Have you had replacement windows, doors, patio doors or double glazing installed in your property | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| | If you have answered yes, please answer the three questions below: | |
| | (i) Were the replacements the same shape and type as the ones you replaced? | <input type="checkbox"/> YES <input type="checkbox"/> NO |
| | (ii) Did this work involve any changes to the window or door openings? | <input type="checkbox"/> YES <input type="checkbox"/> NO |
| | (iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed): Please give any guarantees which you received for this work to your solicitor or estate agent. | |
| 7. | Central heating | |

property questionnaire

| | | |
|------------|---|--|
| a | Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom). | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Partial |
| | If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air). <i>Gas fired</i> | |
| | If you have answered yes, please answer the three questions below: | |
| | (i) When was your central heating system or partial central heating system installed? <i>2022</i> | |
| | (ii) Do you have a maintenance contract for the central heating system? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| | If you have answered yes, please give details of the company with which you have a maintenance contract | |
| | (iii) When was your maintenance agreement last renewed? (Please provide the month and year). | |
| 8. | Energy Performance Certificate | |
| | Does your property have an Energy Performance Certificate which is less than 10 years old? | <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO |
| 9. | Issues that may have affected your property | |
| a | Has there been any storm, flood, fire or other structural damage to your property while you have owned it? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| | If you have answered yes, is the damage the subject of any outstanding insurance claim? | <input type="checkbox"/> YES <input type="checkbox"/> NO |
| b | Are you aware of the existence of asbestos in your property? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> Don't know |
| | If you have answered yes, please give details: | |
| 10. | Services | |
| | | |

| | | | |
|-----|---|---|--|
| a | Please tick which services are connected to your property and give details of the supplier: | | |
| | Services | Connected | Supplier |
| | Gas or liquid petroleum gas | Y | Do not know |
| | Water mains or private water supply | Y | Do not know |
| | Electricity | Y | Do not know |
| | Mains drainage | Y | Do not know |
| | Telephone | N | |
| | Cable TV or satellite | N | |
| | Broadband | N | |
| b | Is there a septic tank system at your property? | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| | If you have answered yes, please answer the two questions below: | | |
| | (i) Do you have appropriate consents for the discharge from your septic tank? | <input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Don't know | |
| | (ii) Do you have a maintenance contract for your septic tank? | <input type="checkbox"/> YES <input type="checkbox"/> NO | |
| | If you have answered yes, please give details of the company with which you have a maintenance contract: | | |
| 11. | Responsibilities for shared or common areas | | |
| a | Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details: | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> Don't know |
| b | Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details: | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> N/A |
| c | Has there been any major repair or replacement of any part of the roof during the time you have owned the property? | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| d | Do you have the right to walk over any of your neighbours' property- for example to put out your rubbish bin or to maintain your boundaries? If you have answered yes, please give details: | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| e | As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details: | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| | | |
|--|---|----------------------------------|
| f | As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.) If you have answered yes, please give details: | [] YES [x] NO |
| 12. Charges associated with your property | | |
| a | Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges: | [] YES [x] NO |
| b | Is there a common buildings insurance policy? | [] YES [x] NO [] Don't know |
| | If you have answered yes, is the cost of the insurance included in your monthly/annual factors charges? | |
| c | Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund. | |
| 13. Specialist works | | |
| a | As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property? | [] YES [x] NO |
| | If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property. | |
| b | As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property? | [] YES [x] NO |
| | If you have answered yes, please give details: | |
| c | If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work? | [] YES [] NO |
| | If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by: | |

| | | |
|------------|---|---|
| 14. | Guarantees | |
| a | Are there any guarantees or warranties for any of the following: | |
| (i) | Electrical work | <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost |
| (ii) | Roofing | <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost |
| (iii) | Central heating | <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost |
| (iv) | National House Building Council(NHBC) | <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost |
| (v) | Damp course | <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost |
| (vi) | Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy) | <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> Don't know <input type="checkbox"/> With title deeds <input type="checkbox"/> Lost |
| b | If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s): | |
| c | Are there any outstanding claims under any of the guarantees listed above? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| | If you have answered yes, please give details: | |

| | | |
|--|---|--|
| 15. | Boundaries | |
| | So far as you are aware, has any boundary of your property been moved in the last 10 years? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> Don't know |
| | If you have answered yes, please give details: | |
| 16. | Notices that affect your property | |
| In the past three years have you ever received a notice: | | |
| a | advising that the owner of a neighbouring property has made a planning application? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| b | that affects your property in some other way? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| c | that requires you to do any maintenance, repairs or improvements to your property? | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |
| | If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property. | |

| | |
|--|--|
| Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief. | |
| Signature(s): | Margaret O'Brien |
| Capacity: | [] Owner [x] Legally Appointed Agent for Owner |
| Date: | 14/08/2025 |



DOMESTIC ELECTRICAL INSTALLATION CERTIFICATE

1 Cert No:

124

E.L Electrical

2

Business Details

| | |
|--------------|--------------------------------|
| Register No. | APL 137274 |
| Operative | Jamie Lamb Murphy |
| Company | E.L Electrical |
| Address | 28 |
| | Lingerwood Road |
| | Newtongrange |
| | Midlothian |
| Postcode | EH22 4QG |
| Tel No. | 07914087011 |
| Email | jamie.l.murphy8@googlemail.com |

Job Address

| | |
|----------|--------------|
| Name | |
| Address | 58 |
| | Fifth Avenue |
| | Glasgow |
| | Glasgow |
| Postcode | G12 0AT |
| Tel No. | |
| Email | |

Client/Landlord's Details

| | |
|----------|--------------------------|
| Name | Owen Hughes |
| Company | Allied Trade Development |
| Address | 58 |
| | Fifth Avenue |
| | Glasgow |
| | Glasgow |
| Postcode | G12 0AT |
| Tel No. | |
| Email | |

3 DETAILS AND EXTENT OF THE INSTALLATION

Extent of the installation covered by this certificate: All Installation Apart For Existing Extension And Lighting Circuits

The installation is: New

4 COMMENTS ON EXISTING INSTALLATION

N/A

5 NEXT INSPECTION

I RECOMMEND that this installation is further inspected and tested after an interval of not more than : 10 Years

6 TEST INSTRUMENTS

Details of Tests Instruments used (state serial and/or asset numbers):

| | |
|------------------------|---------|
| Multi-functional: | 8902052 |
| Insulation resistance: | |
| Continuity: | |

| | |
|-----------------------------|--|
| Earth electrode resistance: | |
| Earth fault loop impedance: | |
| RCD | |

7 DESIGN, CONSTRUCTION, INSPECTION AND TESTING

I/We being the person(s) responsible for the design, construction, inspection and testing of the electrical installation (as indicated by my/our signatures below), particulars of which are described above, having exercised reasonable skill and care when carrying out the design, construction, inspection and testing, hereby CERTIFY that the design work for which I/we have been responsible is to the best of my/our knowledge and belief in accordance with BS 7671:2018, except for the departures, if any, detailed as follows.

Details of departures from BS 7671, as amended (Regulations 120.3, 133.5):

N/A

Details of permitted exceptions (Regulations 411.3.3):

Risk assessment attached: NA

N/A

The extent of liability of the signatory/signatories is limited to the work described above as the subject of this certificate.

For DESIGN, the CONSTRUCTION, and the INSPECTION AND TESTING of the installation:

Signature:

Date: 21/02/2022

8 SUPPLY CHARACTERISTICS AND EARTHING ARRANGEMENTS

| Earthing Arrangements | Number and Type of Live Conductors | Nature of Supply Parameters | Supply Protective Device |
|-----------------------|--|--|--|
| TN-C-S | 1-phase (2 wire): Yes 3-phase (3 wire): Other: N/A Confirmation of supply polarity: Yes | 1-phase (3 wire): 3-phase (4 wire): Nominal U: 230 V Uo: 230 V Nominal frequency, f: 50 V Prospective fault current, Ipf: 1.98 kA External earth fault loop impedance, Ze: 0.12 Ω | BS(EN): BS EN 1361 Type: 2 Rated current: 60 A Short-circuit capacity: kA |

9 PARTICULARS OF INSTALLATION REFERRED TO IN THE CERTIFICATE

| Means of Earthing | Details of Installation Earth Electrode (where applicable) |
|---|---|
| Distributor's facility: Yes Installation earth electrode: No Type: Resistance to Earth: Ω | Location: Method of measurement: |
| Maximum Demand (Load): 60 Protective measure(s) against electric shock: Automatic disconnection of Measured Ze: 0.12 | |
| Main Switch/Switch-Fuse/Circuit-Breaker/RCD Type BS (EN): A Number of poles: 2 Current rating: 100 A Fuse/device rating or setting: 100 A Voltage rating: 230 V | If RCD main switch Supply conductors material: Copper Supply conductors csa: 25 mm² Rated residual operating current (In): 30 mA Rated time delay: 4 ms Measured operating time (In): 145 ms |
| Earthing and Protective Bonding Conductors Earthing conductor Conductor Material: Copper csa: 16 mm² Connection/continuity verified: Yes | Bonding of extraneous-conductive parts To water installation pipes: N/A To oil installation pipes: To structural steel: To gas installation pipes: Yes To lightning protection: To other service(s): |
| Main protective bonding conductors Conductor material: Copper csa: 10 mm² Connection/continuity verified: Yes | |

10 SCHEDULE OF ITEMS INSPECTED

| Item | Description | Outcome |
|-------|--|---------|
| 1.0 | DISTRIBUTOR'S/SUPPLY INTAKE EQUIPMENT | |
| 1.1 | Condition of service cable | Yes |
| 1.2 | Condition of service head | No |
| 1.3 | Condition of distributor's earthing arrangement | Yes |
| 1.4 | Condition of tails - Distributor/Consumer | Yes |
| 1.5 | Condition of metering equipment | Yes |
| 1.6 | Condition of isolator (where present) | N/A |
| 2.0 | PARALLEL OR SWITCHED ALTERNATIVE SOURCES OF SUPPLY | |
| 2.1 | Adequate arrangements where a generating set operates as a switched alternative to the public supply (551.6) | N/A |
| 2.2 | Adequate arrangements where a generating set operates in parallel with the public supply (551.7) | N/A |
| 3.0 | AUTOMATIC DISCONNECTION OF SUPPLY | |
| 3.1 | Presence and adequacy of earthing and protective bonding arrangements: | |
| 3.1.1 | Installation earth electrode (where applicable) (542.1.2.3) | N/A |
| 3.1.2 | Earthing conductor and connections including accessibility (542.3; 542.3.2) | Yes |
| 3.1.3 | Main protective bonding conductors and connections, including accessibility (411.3.1.2; 543.3.3) | Yes |
| 3.1.4 | Provision of safety electrical earthing/bonding labels at all appropriate locations (514.13) | Yes |
| 3.1.5 | RCD(s) provided for fault protection (411.4.9; 411.5.3) | N/A |
| 4.0 | BASIC PROTECTION | |
| 4.1 | Presence and adequacy of measures to provide basic protection (prevention of contact with live parts) within the installation: | |
| 4.1.1 | Insulation of live parts e.g. conductors completely covered with durable insulation materials (416.1) | Yes |
| 4.1.2 | Barriers or enclosures e.g. correct IP rating (416.2) | Yes |

11 SCHEDULE OF ITEMS INSPECTED

| Item | Description | Outcome |
|------------|---|---------|
| 5.0 | ADDITIONAL PROTECTION | |
| 5.1 | Presence and effectiveness of additional protection methods: | |
| 5.1.1 | RCD(s) not exceeding 30mA operating current (415.1; Part 7), see Item 8.14 of this schedule | Yes |
| 5.1.2 | Supplementary bonding (415.2; Part 7) | N/A |
| 6.0 | OTHER METHODS OF PROTECTION | |
| 6.1 | Presence and effectiveness of methods which give both basic and fault protection: | |
| 6.1.1 | SELV systems, including the source and associated circuits (Section 414) | N/A |
| 6.1.2 | PELV systems, including the source and associated circuits (Section 414) | N/A |
| 6.1.3 | Double or reinforced insulation i.e. Class II or equivalent equipment and associated circuits (Section 412) | Yes |
| 6.1.4 | Electrical separation for one item or equipment e.g. shaver supply unit (Section 413) | Yes |
| 7.0 | CONSUMER UNIT(S)/DISTRIBUTION BOARD(S) | |
| 7.1 | Adequacy of access and working space for items of electrical equipment including switchgear (132.12) | Yes |
| 7.2 | Presence of linked main switch(s) (537.1.4; 5.7.1.5; 537.1.6) | N/A |
| 7.3 | Isolators, for every circuit or group of circuits and all items of equipment (537.2) | Yes |
| 7.4 | Suitability of enclosure(s) for IP and fire ratings (416.2; 421.1.6; 421.1.201) | Yes |
| 7.5 | Protection against mechanical damage where cables enter equipment (522.8.1; 522.8.11) | Yes |
| 7.6 | Confirmation that ALL conductor connections are correctly located in terminals and are tight and secure (526.1) | Yes |
| 7.7 | Avoidance of heating effects where cables enter ferromagnetic enclosures e.g. steel (521.5) | Yes |
| 7.8 | Selection of correct type and rating circuit protective devices for overcurrent and fault protection (411.3.2; 411.4, .5, .6; Section 432, 433) | Yes |
| 7.9 | Presence of appropriate circuit charts, warning and other notices: | |
| 7.9.1 | Provision of circuit charts/schedules or equivalent forms of information (514.9) | Yes |
| 7.9.2 | Warning notice of method of isolation where live parts not capable of being by a single device (514.11) | N/A |
| 7.9.3 | Periodic inspection and testing notice (514.12.1) | Yes |
| 7.9.4 | RCD six-monthly test notice; where required (514.12.2) | Yes |
| 7.9.5 | Warning notice of non-standard (mixed) colours of conductors present (514.14) | Yes |
| 7.10 | Presence of labels to indicate the purpose of switchgear and protective devices (514.1.1; 514.8) | Yes |
| 8.0 | CIRCUITS | |
| 8.1 | Adequacy of conductors for currents-carrying capacity with regards to type and nature of the installation (Section 523) | Yes |
| 8.2 | Cable installation methods suitable for the location(s) and external influences (Section 522) | Yes |
| 8.3 | Segregation/separation of Band I (ELV) and Band II (LV) circuits, and electrical and non-electrical services (528) | N/A |
| 8.4 | Cables correctly erected and supported throughout including escape routes, with protection against abrasion (Sections 521, 522) | Yes |
| 8.5 | Provision of fire barriers, sealing arrangements where necessary (527.2) | Yes |
| 8.6 | Non-sheathed cables enclosed throughout in conduit, ducting or trunking (521.10.1; 526.8) | N/A |
| 8.7 | Cables concealed under floors, above ceilings or in wall/partitions, adequately protected against damage (522.6.201, .202, .204) | Yes |
| 8.8 | Conductors correctly identified by colour, lettering or numbering (Section 514) | Yes |
| 8.9 | Presence, adequacy and correct termination of protective conductors (411.3.1.1; 542.1) | Yes |
| 8.10 | Cables and conductors correctly connected, enclosed and with no undue mechanical strain (Section 526) | Yes |
| 8.11 | No basic insulation of a conductor visible outside enclosure (526.8) | Yes |
| 8.12 | Single-pole devices for switching or protection in line conductors only (132.14.1; 530.3.2) | Yes |
| 8.13 | Accessories not damaged, securely fixed, correctly connected, suitable for external influences (134.1.1; 512.2; Section 526) | Yes |

12 SCHEDULE OF ITEMS INSPECTED

| Item | Description | Outcome |
|-------------|--|---------|
| 8.14 | Provision of additional protection by RCD not exceeding 30mA: | |
| 8.14.1 | Socket-outlet rated at 20 A or less unless exempt (411.3.3) | Yes |
| 8.14.2 | Mobile equipment with a current rating not exceeding 32 A for use outdoors (411.3.3) | N/A |
| 8.14.3 | Cables concealed in walls at a depth of less than 50 mm (522.6.202, .203) | Yes |
| 8.14.4 | Cables concealed in walls/partitions containing metal parts regardless of depth (522.6.202; 522.6.203) | Yes |
| 8.15 | Presence of appropriate devices for isolation and switching correctly located including: | |
| 8.15.1 | Means of switching off for mechanical maintenance (537.3) | Yes |
| 8.15.2 | Emergency switches (537.4) | N/A |
| 8.15.3 | Functional switches, for control of parts of the installation and current-using equipment (537.5) | Yes |
| 8.15.4 | Firefighter's switches (537.6) | N/A |
| 9.0 | CURRENT-USING EQUIPMENT (PERMANENTLY CONNECTED) | |
| 9.1 | Equipment not damaged, securely fixed and suitable for external influences (134.1.1; 416.2; 512.2) | Yes |
| 9.2 | Provision of overload and/or undervoltage protection e.g. for rotating machines, if required (Sections 445, 552) | N/A |
| 9.3 | Installed to minimise the build-up of heat and restrict the spread of fire (421.1.4; 559.4.1) | Yes |
| 9.4 | Adequacy of working space. Accessibility to equipment (132.12; 513.1) | Yes |
| 10.0 | LOCATION(S) CONTAINING A BATH OR SHOWER (SECTION 701) | |
| 10.1 | 30 mA RCD protection for all LV circuits, equipment suitable for the zones, supplementary bonding (where required) etc. | Yes |
| 10.2 | Where used as a protective measure, requirement for SELV or PELV met (701.414.4.5) | N/A |
| 10.3 | Shaver sockets comply with BS EN 61558-2-5 formerly BS 3535 (701.512.3) | N/A |
| 10.4 | Presence of supplementary bonding conductors, unless not required by BS 7671:2018 (701.415.2) | N/A |
| 10.5 | Low voltage (e.g. 230 volt) socket-outlets sited at least 3m from Zone 1 (701.512.3) | N/A |
| 10.6 | Suitability of equipment for external influences for installed location in terms of IP rating (701.512.2) | Yes |
| 10.7 | Suitability of accessories and control gear etc. for a particular zone (701.512.3) | Yes |
| 10.8 | Suitability of current-using equipment for particular position within the location (701.55) | Yes |
| 11.0 | OTHER PART 7 SPECIAL INSTALLATIONS OR LOCATIONS List all other special installation or locations present, if any. (Record separately the results of particular inspections applied.) | |
| 11.1 | N/A | |
| 11.2 | N/A | |

13 SCHEDULE OF ITEMS INSPECTED

| Item | Description | Outcome |
|-------|---|---------|
| 12.1 | External earth fault loop impedance, Z_e | Yes |
| 12.2 | Installation earth electrode resistance, R_a | N/A |
| 12.3 | Continuity of protective conductors | Yes |
| 12.4 | Continuity of ring final circuit conductors | Yes |
| 12.5 | Insulation resistance between live conductors | Yes |
| 12.6 | Insulation resistance between live conductors and earth | Yes |
| 12.7 | Polarity | Yes |
| 12.8 | Earth fault loop impedance, Z_s | Yes |
| 12.9 | Verification of phase sequence | N/A |
| 12.10 | Operation of residual current device(s) | Yes |
| 12.11 | Functional testing of assemblies | Yes |
| 12.12 | Verification of voltage drop | N/A |

14 SCHEDULE OF CIRCUIT DETAILS AND TEST RESULTS

Designation of consumer unit: 1

Location: Hall Cupboard

Prospective fault current: 1.98 kA

Type of Wiring O-Other: A - PVC/PVC cables

| Circuit number | Circuit designation | Type of wiring | Reference Method | Number of points served | Circuit conductors: css | | Max disconnect time permitted by BS7671 s | Overcurrent protective devices | | | | RCD | Maximum Zs permitted by BS7671 Ω | Circuit impedances (Ohms) | | | | | Insulation resistance | | Polarity | Maximum measured earth fault loop impedance Zs Ω | RCD | | | AFDD |
|----------------|-----------------------|----------------|------------------|-------------------------|-------------------------|------------|--|--------------------------------|---------|-------------|----------------|-------------------------|-------------------------------------|--|-----------------------------|-------------------------|--|----------------|-----------------------|--------------------|----------|---|---------------------------------|----------------------------------|-----------------------|-----------------------------------|
| | | | | | Live mm² | cpc mm² | | BS (EN) | Type No | Rating A | Capacity kA | Operating current mA | | Ring final circuit only (measured end to end) | | | All circuits (one column to be completed) | | Live - Live MΩ | Live - Earth MΩ | | | Disconnection time at IΔn ms | Disconnection time at 5IΔn ms | Test button Operation | Manual AFDD test button operation |
| | | | | | | | | | | | | | | r ₁ (Line) | r _n (Neutral) | r ₂ (cpc) | R ₁ +R ₂ | R ₂ | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | | |
| 1 | shower | A - | 101 | N/A | 6 | 2.5 | 4 | BS EN 60898 | B | 40 | 6 | 30 | 1.1 | | | | 0.47 | | >999 | >999 | yes | 0.59 | 138 | 32 | yes | |
| 2 | hob | A - | 101 | N/A | 6 | 2.5 | 4 | BS EN 60898 | B | 32 | 6 | 30 | 1.1 | | | | 0.23 | | >999 | >999 | yes | 0.35 | 138 | 32 | yes | |
| 3 | kitchen sockets | A - | 101 | N/A | 2.5 | 1.5 | 4 | BS EN 60898 | B | 32 | 6 | 30 | 1.1 | 0.37 | 0.35 | 0.56 | 0.32 | | >999 | >999 | yes | 0.40 | 138 | 32 | yes | |
| 4 | central heating | A - | 101 | N/A | 2.5 | 1.5 | 4 | BS EN 60898 | B | 16 | 6 | 30 | 2.2 | | | | 0.26 | | >999 | >999 | yes | 0.38 | 138 | 32 | yes | |
| 5 | extension lights | A - | 101 | N/A | 1.0 | 1.0 | 4 | BS EN 60898 | B | 6 | 6 | 30 | 5.87 | | | | 0.59 | | >999 | >999 | yes | 0.71 | 138 | 32 | yes | |
| 6 | front outside light | A - | 101 | N/A | 1.0 | 1.0 | 4 | BS EN 60898 | B | 6 | 6 | 30 | 5.87 | | | | 0.47 | | >999 | >999 | yes | 0.59 | 138 | 32 | yes | |
| 7 | spare | | | N/A | | | | | | | | | | | | | | | | | | | | | | |
| 8 | spare | | | N/A | | | | | | | | | | | | | | | | | | | | | | |
| 9 | ground floor sockets | A - | 101 | N/A | 2.5 | 1.5 | 4 | BS EN 60898 | B | 32 | 6 | 30 | 1.1 | 0.41 | 0.41 | 0.68 | 0.20 | | >999 | >999 | yes | 0.37 | 145 | 33.3 | yes | |
| 10 | first floor sockets | A - | 101 | N/A | 2.5 | 1.5 | 4 | BS EN 60898 | B | 32 | 6 | 30 | 1.1 | 0.60 | 0.59 | 0.96 | 0.44 | | >999 | >999 | yes | 0.52 | 145 | 33.3 | yes | |
| 11 | alarm | A - | 101 | N/A | 2.5 | 1.5 | 4 | BS EN 60898 | B | 16 | 6 | 30 | 2.2 | | | | 0.26 | | >999 | >999 | yes | 0.38 | 145 | 33.3 | yes | |
| 12 | smoke detectors | A - | 101 | N/A | 1.0 | 1.0 | 4 | BS EN 60898 | B | 6 | 6 | 30 | 5.87 | | | | 0.50 | | >999 | >999 | yes | 0.68 | 145 | 33.3 | yes | |
| 13 | ground floor lighting | A - | 101 | N/A | 1.0 | 1.0 | 4 | BS EN 60898 | B | 6 | 6 | 30 | 5.87 | | | | 0.38 | | >999 | >999 | yes | 0.50 | 145 | 33.3 | yes | |
| 14 | first floor lighting | A - | 101 | N/A | 1.0 | 1.0 | 4 | BS EN 60898 | B | 6 | 7 | 30 | 5.87 | | | | 0.62 | | >999 | >999 | yes | 0.74 | 145 | 33.3 | yes | |
| 15 | spare | | | N/A | | | | | | | | | | | | | | | | | | | | | | |
| 16 | spare | | | N/A | | | | | | | | | | | | | | | | | | | | | | |

CERTIFICATE OF DESIGN, INSTALLATION AND COMMISSIONING OF FIRE DETECTION AND FIRE ALARM SYSTEM OF GRADE A, B, C, D, E OR F GRADE SYSTEMS

Business Details

Register No.
 Operative
 Company
 Address

 Postcode
 Tel No.
 Email

Job Address

Name
 Address

 Postcode
 Tel No.
 Email

Client/Landlord's Details

Name
 Company
 Address

 Postcode
 Tel No.
 Email

2 DETAILS OF THE FIRE DETECTION SYSTEM

Extent of the fire detection and alarm system covered by this certificate: The installation is:

3 DESCRIPTION IF SYSTEM GRADE AND SYSTEM CATEGORY

System Grade: System Category:

4 COMMISSIONING

| | | | | | |
|-----------------------------------|----------------------------------|-----------------------------------|----------------------------------|--|----------------------------------|
| Test buttons checked | <input type="text" value="Yes"/> | Simulated smoke or aerosol test | <input type="text" value="Yes"/> | Dedicated circuit(s) provide | <input type="text" value="Yes"/> |
| All alarm warning devices operate | <input type="text" value="Yes"/> | Heat test | <input type="text" value="Yes"/> | Protected device labelled | <input type="text" value="Yes"/> |
| Silencing system checked | <input type="text" value="Yes"/> | Bedroom sound level (Clause 13.2) | <input type="text" value="Yes"/> | Audible and visual indication of mains failure | <input type="text" value="Yes"/> |

Sound level test instrument model and serial No: Serial No. of associated Electrical Installation or Minor Works Certs:

5 USER INSTRUCTIONS

I/We the undersigned declare that the occupier of the dwelling (or owner in the case of a house in multiple occupancy) has been provided with written information about essential aspects of the operation and maintenance of the system, as follows:

| | | | |
|---|----------------------------------|---|----------------------------------|
| Operation of the system | <input type="text" value="Yes"/> | The need to keep clear space around all detectors and manual call points | <input type="text" value="Yes"/> |
| Action to be taken in the event of a fire alarm signal | <input type="text" value="Yes"/> | Special precautions relevant to any lithium batteries used in the system | <input type="text" value="Yes"/> |
| Avoidance of false alarms and action in the event of a false alarm | <input type="text" value="Yes"/> | Checking the system on reoccupation of the dwelling after a vacation etc. | <input type="text" value="Yes"/> |
| Warning that apparent false alarm from carbon monoxide detector may not be false alarm | <input type="text" value="N/A"/> | The need to avoid contamination of detectors by paint | <input type="text" value="Yes"/> |
| Routine testing of the system | <input type="text" value="Yes"/> | As fitted drawing | <input type="text" value="N/A"/> |
| Servicing and maintenance of the system (including intervals at which any batteries should be replaced) | <input type="text" value="Yes"/> | | |


6 CERTIFICATE OF DESIGN, INSTALLATION AND COMMISSIONING

I/We, being the person(s) responsible (as indicated by my/our signature(s) below), for the design, installation, and commissioning of the fire alarm system, particulars of which are set out above, CERTIFY that the said work for which I/we have been responsible complies to the best of my/our knowledge and belief with the recommendations of BS 5839: Part 6 for the system described above, except for the variations, if any, stated below:

Variations (if any):

The extent of liability of the signatory is limited to do work described above as the subject of this certificate.

For the DESIGN, INSTALLATION AND COMMISSIONING of the system:

Name: Position: Signature:  Date:

Landlord Gas Safety Record

Cert. No. 26206

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

| Company / Installer | | Job Address | | Customer / Landlord | |
|---------------------|----------------|-------------|--------------|---------------------|--------------------|
| Engineer | Stefan Jenkins | Name | | Name | Mr Dj DJ Alexander |
| Company | Benaird Ltd | Address | 58 | Company | |
| Address | 10 | | Fifth Avenue | Address | John Cotton Centre |
| | Sunnyside | | Glasgow | | Sunnyside |
| | Edinburgh | | | | Edinburgh |
| | LOTHIANS | Post Code | G12 0AT | | |
| Post Code | EH7 5RA | Tel. No | | Post Code | EH7 5RA |
| Tel No. | 01315230200 | | | Tel. No | |
| Gas Safe Reg | 531372 | | | | |
| ID Card No. | 5310722 | | | | |

| Appliance Details | | | | | | Inspection Details | | | | | | | | | | | | | | | |
|-------------------|----------|----------------|--------|---------------------|-----------|----------------------|---------------------|---------------------------|-------------------|-------------------------|--------|-------|------------------------|--------|-------|------------------------------------|------------------------------------|---|-----------------------|--------------------|-----------------------|
| | Location | Appliance Type | Make | Model | Flue Type | Landlord's Appliance | Appliance Inspected | Operating Pressure (mbar) | Heat Input (kW/h) | High Combustion Reading | | | Low Combustion Reading | | | Safety device(s) correct operation | Ventilation Provision satisfactory | Visual condition of flue and termination satisfactory | Flue Performance test | Appliance Serviced | Appliance safe to use |
| | | | | | | | | | | Ratio | CO ppm | CO2 % | Ratio | CO ppm | CO2 % | | | | | | |
| 1 | Kitchen | Boiler | Vokera | Easi Heat Plus 29ci | RS | Yes | Yes | 20 | 28,3 | 0.0005 | 41 | 8.13 | NA | NA | NA | Yes | Yes | Yes | Pass | No | Yes |
| 2 | | | | | | | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | | | | | | | | | |

| Defects / Identified | | | | | | | | | | Labels and Warning Notice Issued | | | | | | CO Alarm(s) | | | |
|----------------------|--|--|--|--|--|--|--|--|--|----------------------------------|--|--|--|--|--|---|--|-----------------|--|
| 1 | | | | | | | | | | No | | | | | | CO Alarm(s) fitted CO Alarm(s) tested and Satisfactory | | Yes Pass | |
| 2 | | | | | | | | | | | | | | | | | | | |
| 3 | | | | | | | | | | | | | | | | | | | |
| 4 | | | | | | | | | | | | | | | | | | | |
| 5 | | | | | | | | | | | | | | | | | | | |
| 6 | | | | | | | | | | | | | | | | | | | |

| | | |
|--|--|---------------------------------------|
| Emergency Control Accessible <input checked="" type="checkbox"/> Yes | Gas Tightness Satisfactory <input checked="" type="checkbox"/> Yes | <div>Comments</div> <div>Co2032</div> |
| Gas Installation Pipework Visual Inspection Satisfactory <input checked="" type="checkbox"/> Yes | | |
| Equipotential Bonding <input checked="" type="checkbox"/> Yes | | |
| NEXT INSPECTION DUE BEFORE | 17-May-2026 | |

| Signatures | | | |
|------------|---|--------------|--|
| Issued by: | Signed | Received by: | Signed |
| |  | |  |
| Print Name | Stefan Jenkins | Print Name | Stefan Jenkins |
| | | Date | 10-Apr-2025 |

GAS BOILER SYSTEM COMMISSIONING CHECKLIST & WARRANTY VALIDATION RECORD

| | |
|---|--|
| Address: | |
| Boiler make and model: | VOKERA EASYHEAT PLUS 29C1 |
| Boiler serial number: | 120158334PR35Q004071 |
| Commissioned by (PRINT NAME): | IAN JONOR |
| Company name: | ALLIED PLUMBING + HEATING |
| Company email: | EH646ES |
| Gas Safe registration number: | 304829 |
| Telephone number: | 07161276395 |
| Company address: | 13 MENDON BANK LIVINGSTONE |
| Commissioning date: | 09/02/2022 |
| Heating and hot water system complies with the appropriate Building Regulations? Yes <input checked="" type="checkbox"/> | |
| Optional: Building Regulations Notification Number (if applicable): Yes <input checked="" type="checkbox"/> | |
| Time, temperature control and boiler interlock provided for central heating and hot water | |
| Boiler Plus requirements (tick the appropriate box(s)) | |
| Boiler Plus option chosen for combination boiler in ENGLAND | Weather compensation <input type="checkbox"/> Smart thermostat with automisation and optimisation <input type="checkbox"/> Load compensation <input type="checkbox"/> Flue Gas Heat Recovery <input type="checkbox"/> Combination boiler <input checked="" type="checkbox"/> |
| Time and temperature control to hot water | Cylinder thermostat and programmer/timer <input type="checkbox"/> Not required <input checked="" type="checkbox"/> |
| Zone valves | pre-existing <input type="checkbox"/> Fitted <input type="checkbox"/> Not required <input checked="" type="checkbox"/> |
| Thermostatic radiator valves | pre-existing <input type="checkbox"/> Fitted <input checked="" type="checkbox"/> Not required <input type="checkbox"/> |
| Automatic bypass to system | pre-existing <input type="checkbox"/> Fitted <input type="checkbox"/> Not required <input checked="" type="checkbox"/> |
| Underfloor heating | pre-existing <input type="checkbox"/> Fitted <input type="checkbox"/> Not required <input checked="" type="checkbox"/> |
| Water quality | |
| The system has been flushed, cleaned and a suitable inhibitor applied upon final fill, in accordance with BS7593 and boiler manufacturers' instructions Yes <input checked="" type="checkbox"/> | |
| What system cleaner was used? | Brand: CAL MAC Product: CM1 300 |
| What inhibitor was used? | Brand: CAL MAC Product: CM1-300 |
| Primary water system filter | pre-existing <input type="checkbox"/> Fitted <input checked="" type="checkbox"/> Not required <input type="checkbox"/> |
| CENTRAL HEATING MODE measure and record (as appropriate) | |
| Gas rate (for combination boilers complete DHW mode gas rate) | m ³ /hr or ft ³ /hr |
| Central heating output left at factory settings? | Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> |
| If no, what is the maximum central heating output selected? | 18.5 kW |
| Dynamic gas inlet pressure | 71.6 mbar |
| Central heating flow temperature | 56.2 °C |
| Central heating return temperature | 56.2 °C |
| System correctly balanced/rebalanced? | Yes <input checked="" type="checkbox"/> |
| COMBINATION BOILERS ONLY | |
| Is the installation in a hard water area (above 200ppm)? | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| Water scale reducer/softener | pre-existing <input type="checkbox"/> Fitted <input type="checkbox"/> Not required <input checked="" type="checkbox"/> |
| What type of scale reducer/softener has been fitted? | Brand: Product: |
| Water meter fitted? | Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> |
| If yes- DHW expansion vessel | pre-existing <input type="checkbox"/> Fitted <input type="checkbox"/> Not required <input type="checkbox"/> |
| Pressure reducing valve | pre-existing <input type="checkbox"/> Fitted <input type="checkbox"/> Not required <input checked="" type="checkbox"/> |
| DOMESTIC HOT WATER MODE Measure and record | |
| Gas rate | 2.64 m ³ /hr or ft ³ /hr |
| Dynamic gas inlet pressure at maximum rate | 18 mbar |
| Cold water inlet temperature | 8 °C |
| Hot water has been checked at all outlets | Yes <input checked="" type="checkbox"/> Temperature 50 °C |
| CONDENSATE DISPOSAL | |
| The condensate drain has been installed in accordance with the manufacturers' instructions and/or BS5546/BS6798 Yes <input checked="" type="checkbox"/> | |
| Point of termination | Internal <input type="checkbox"/> External (only where internal termination impractical) <input checked="" type="checkbox"/> |
| Method of disposal | Gravity <input checked="" type="checkbox"/> Pumped <input type="checkbox"/> |
| ALL INSTALLATIONS | |
| Record the following | At max rate: CO 45 ppm CO ₂ 8.5 % CO/CO ₂ 0.0005 Ratio At min rate (where possible) CO ppm CO ₂ % CO/CO ₂ Ratio |
| Where possible, has a flue integrity check been undertaken in accordance with manufacturers' instructions, and readings are correct? Yes <input checked="" type="checkbox"/> | |
| The operation of the boiler and system controls have been demonstrated to and understood by the customer Yes <input checked="" type="checkbox"/> | |
| The manufacturers' literature, including Benchmark Checklist and Service Record, has been explained and left with the customer Yes <input checked="" type="checkbox"/> | |
| Commissioning Engineer's signature <i>Ben G...</i> | |
| Customer's signature (To confirm satisfactory demonstration and receipt of manufacturers' literature) | |

* All installations in England and Wales must be notified to Local Authority Building Control (LABC) either directly or through a Competent Persons Scheme. A Building Regulations Compliance Certificate will then be issued to the customer.

© Heating and Hotwater Industry Council (HHIC)



www.centralheating.co.uk