Energy performance certificate (EPC) recommendation report

Trugym
Boston West Business Centre
Sleaford Road
BOSTON
PE21 8EG

Report number **6418-2085-2347-7469-6651**

Valid until **16 July 2033**

Energy rating and EPC

This property's energy rating is B.

For more information on the property's energy performance, see the EPC for this property.

Recommendations

Changes that may pay for themselves within 3 years

Recommendation	Potential impact on carbon emissions
Improve insulation on HWS storage.	Low
Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.	Low
Consider replacing T8 lamps with retrofit T5 conversion kit.	Medium
In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to windows.	Medium
Changes that may pay for themselves within 3 to 7 years	
Recommendation	Potential impact on carbon emissions
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	Low
Changes that may pay for themselves in over 7 years	
Recommendation	Potential impact on carbon emissions
The default chiller efficiency is chosen. It is recommended that the chiller system be investigated to gain an understanding of its efficiency and possible	Low

Low

The default heat generator efficiency is chosen. It is recommended that the heat generator system be investigated to gain an understanding of its efficiency and possible improvements.

Low

Consider installing building mounted wind turbine(s).

Low

Some walls have uninsulated cavities - introduce cavity wall insulation.

Low

Property and report details

Calculation tool	DesignBuilder Software Ltd, DesignBuilder SBEM, v7.1.4, SBEM, v6.1.e.0
Building environment	Air Conditioning
Total useful floor area	857 square metres
Report issued on	17 July 2023

Assessor's details

Roan Patrick
0115 7141123
mail@surveyhub.co.uk
Survey Hub
34 Regent Street Nottingham NG1 5BT
EES/028388
The assessor is not related to the owner of the property.
Elmhurst Energy Systems Ltd