# **Energy performance certificate (EPC) recommendation report**

The Four Horseshoes
The Street
Long Sutton
RG29 1TA

Report number **7198-2218-9149-1962-0439** 

Valid until 30 October 2035

#### **Energy rating and EPC**

This property's energy rating is C.

For more information on the property's energy performance, see the EPC for this property.

### Recommendations

Consider installing solar water heating.

## Changes that may pay for themselves within 3 years

Recommendation	Potential impact on carbon emissions
Add optimum start/stop to the heating system.	Medium
Consider replacing T8 lamps with retrofit T5 conversion kit.	Low
Some walls have uninsulated cavities - introduce cavity wall insulation.	Medium
In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to windows.	Medium
Some windows have high U-values - consider installing secondary glazing.	Medium
Add weather compensation controls to heating system.	Medium
Some loft spaces are poorly insulated - install/improve insulation.	Medium
Add local time control to heating system.	Medium
Osmaidan aviitakin n fuana naa ta kianaaa	High
	riigii
Changes that may pay for themselves within 3 to 7 years	Potential impact on carbon emissions
Changes that may pay for themselves within 3 to 7 years  Recommendation  Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC	Potential impact on carbon
Changes that may pay for themselves within 3 to 7 years  Recommendation  Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings	Potential impact on carbon emissions
Changes that may pay for themselves within 3 to 7 years  Recommendation  Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	Potential impact on carbon emissions Medium
Changes that may pay for themselves within 3 to 7 years  Recommendation  Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.  Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Potential impact on carbon emissions  Medium  Low
Changes that may pay for themselves within 3 to 7 years  Recommendation  Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.  Some glazing is poorly insulated. Replace/improve glazing and/or frames.  Consider installing an air source heat pump.	Potential impact on carbon emissions  Medium  Low  Medium
Changes that may pay for themselves within 3 to 7 years  Recommendation  Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.  Some glazing is poorly insulated. Replace/improve glazing and/or frames.  Consider installing an air source heat pump.  Consider installing a ground source heat pump.  Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the	Potential impact on carbon emissions  Medium  Low  Medium  Medium
Changes that may pay for themselves within 3 to 7 years  Recommendation  Carry out a pressure test, identify and treat identified air leakage. Enter result in EPC calculation.  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.  Some glazing is poorly insulated. Replace/improve glazing and/or frames.  Consider installing an air source heat pump.  Consider installing a ground source heat pump.  Some floors are poorly insulated - introduce and/or improve insulation. Add insulation to the exposed surfaces of floors adjacent to underground, unheated spaces or exterior.	Potential impact on carbon emissions  Medium  Low  Medium  Medium  Medium  Medium
	Potential impact on carbon emissions  Medium  Low  Medium  Medium  Medium  Medium

Low

Recommendation	Potential impact on carbon emissions
Consider installing PV.	Low

# Property and report details

Report issued on	31 October 2025
Total useful floor area	269 square metres
Building environment	Heating and Natural Ventilation
Calculation tool	CLG, iSBEM, v6.1.e, SBEM, v6.1.e.0

### Assessor's details

Assessor's name	Dean Hugill
Telephone	01276 503 153
Email	hugillpropertyinspections1@yahoo.co.uk
Employer's name	Hugill Property Inspections
Employer's address	77 Watchetts Drive, Camberley, Surrey,GU15 2PF.
Assessor ID	EES/019633
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Elmhurst Energy Systems Ltd