

YOUR ONESURVEY HOME REPORT

ADDRESS

27 Fod Street
Halbeath, Dunfermline
KY11 8EJ

PREPARED FOR

Steven Farish

INSPECTION CARRIED OUT BY:



SELLING AGENT:



HOME REPORT GENERATED BY:



Document Index

Document	Status	Prepared By	Prepared On
Single Survey	Final	Dunfermline - Allied Surveyors Scotland Ltd	24/11/2025
Mortgage Certificate	Final	Dunfermline - Allied Surveyors Scotland Ltd	24/11/2025
Property Questionnaire	Final	Mr. Steven Farish	21/11/2025
EPC	Final	Dunfermline - Allied Surveyors Scotland Ltd	24/11/2025

Important Notice:

This report has been prepared for the purposes and use of the person named on the report. In order to ensure that you have sight of a current and up to date copy of the Home Report it is **essential** that you log onto www.onesurvey.org (free of charge) to download a copy personalised in your own name. This enables both Onesurvey and the Surveyor to verify that you have indeed had sight of the appropriate copy of the Home Report prior to your purchasing decision. This personalised report can then be presented to your legal and financial advisers to aid in the completion of your transaction. **Failure to obtain a personalised copy may prevent the surveyor having any legal liability to you as they will be unable to determine that you have relied on this report prior to making an offer to purchase.**

Neither the whole, nor any part of this report may be included in any published document, circular or statement, nor published in any way without the consent of Onesurvey Ltd. Only the appointed Chartered Surveyor can utilise the information contained herein for the purposes of providing a transcription report for mortgage/loan purposes.

P A R T 1 .

SINGLE SURVEY

A report on the condition of the property, with categories
being rated from 1 to 3.



Single Survey

Survey report on:

Surveyor Reference	DD3000
Customer	Mr. Steven Farish
Selling address	27 Fod Street Halbeath, Dunfermline KY11 8EJ
Date of Inspection	20/11/2025
Prepared by	Peter Bennet, MRICS Dunfermline - Allied Surveyors Scotland Ltd

SINGLE SURVEY TERMS AND CONDITIONS (WITH MVR)

PART 1 - GENERAL

1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property.¹

If the Surveyors have had a previous business relationship within the past two years with the Seller or Sellers Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.



The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

¹ Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Codes of Conduct

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

To date, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions.

The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information contained in the Report and the generic Mortgage Valuation Report. 2

1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

1.8 CANCELLATION

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for

expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an Invoice equivalent to 80% of the agreed fee.

1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

1.10 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format.
- the "Market Value" is *The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion*
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property.
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and

² Which shall be in accordance with the current RICS Valuation Standards (the Red Book) and RICS Rules of Conduct.

- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

PART 2 – DESCRIPTION OF THE REPORT

2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, *visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.*

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not

significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

2.3.1 Category 3: Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

2.3.2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.

2.3.3 Category 1: No immediate action or repair is needed.

WARNING: If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an

arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- *There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- *There are no particularly troublesome or unusual legal restrictions;
- *There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

“Re-instatement cost” is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property

7KL V VHFVLRQ WHOOV \RX DERXW WKH W\SH DFFRPPRGDWLRQ ,QHLJ
DOVR WHOOV \RX DERXW WKH H[WHQW RI WKH LQVSHFVLRQ DQG KLJK

\$OO UHIHUHQFHV WR YLVXDO LQVSHFVLRQ UHIHU WR DQ LQVSHFVLRQ
REVWUXFVLRQV DQG H[WHUQDOO\ IURP JURXQG OH\H\OULW\WKH QFHV
RU ULJKW LQ D GHVFULSWLRQ RI WKH H[WHULRU RI WKH SURSHUW\ U
WKH SURSHUW\ IURP WKH RXWVLGH

7KH LQVSHFVLRQ LV FDUULHG RXW ZLWKRXW FDXVLQJ GDPDJH WR WK
WKH RFFXSLHUV RU WKH 6XU\H\RU VWRUHG LWHPV DQG LQVXODWL
WKH UHSRUW WKH 6XU\H\RU ZLOO DVVXPH WKDW QR KDUPIXO RU KDJ
WKH FRQVWUXSWHQFH RU SRVVLEOH FRQVHTXHQFHV RI DQ\ VLWH F

6HU\LFHV \XFD\H FRQQHFVLRQ LQWHUQHWH FRQQHFVLRQ VZLPPLO
EH LQVSHFWHG RU UHSRUWHG RQ

'HVFULSWLRQ	7KH VXEMHFW FRPSULVH D VHOI FRQWDLQH G IOD VWRUH\ SXUSRVH EXLOW GHWDFKHG EORFN RI IRX
\$FFRPPRGDWLRQ	*5281')/225 (QWUD\H\EXOH +DOO /LYLQJ 5RRPKUHDNIDVW %HGURRPV DQG %DWKURRP
*URVV LQWHUQDO P	IORRU DUHD
1HLJKERXUKRRG ORFDWLRQ	DQG VXEMHFW DUH VLWXDWHG ZLWKLQ WKH YLO IULQJHV RI WKH FLV\ORQJLQDOP\H\DO DPHQLWL FDQ EH IRXQG ZLWKLQ DQ HDV\ UHDFK ,Q DGGLW VKRUW GLVWDQFH DZD\ SURYLGLQJ JRRG DFFHVV
\$JH	\HDUV DSSUR[
: HDWKHU	'U\ EULJKW
&KLPQH\ VWDFNV	\$Q RULJLQDO EULFN URXJKFDVW PXWXDO FKLPQH 9LVXDOO\ LQVSHFWHG ZLWK WKH DLG RI ELQRFXO


5RRILQJ LQFOXGH VSDFH	LQJHURRI VWUXFWXUH LV RI D WLPEHU SLWFKHG H[WHUQDOO\ LQFRUSRUDWLQJ VRPH FOD\ ULGJH V 1R DFFHVV WR DQ\ SDUW RI WKH URRI YRLG DUHD RXU LQVSHFWLRQ 6ORSLQJ URRIV ZHUH YLVXDOO\ LQVSHFWHG ZLWK UHTXLUHG)ODW URRIV ZHUH YLVXDOO\ LQVSHFWHG IURP YD DQG ZKHUH VDIH DQG UHDVRQDEOH WR GR VR IUR)ODW URRIV KDYH D OLPLWHG OLIH DQG GHSHQGL ZRUNPDQVKLS FDQ IDLO DW DQ\ WLP 5RRI VSDFHV ZHUH YLVXDOO\ LQVSHFWHG DQG ZH VDIH DQG UHDVRQDEOH DFFHVV QrupDOO\ GHILQ ZLWKLQ WKH,ISWRSHULW\QRW SRVVLEOH WKHQ SKV VSDFH PD\ EH WDNHQ E\ RWKHU PHDQV LI WKH 6X UHDVRQDEOH WR GR VR
5DLQZDWHU ILWW	&DQW LURQ JXWWHUV GRZQSLSHV DUH SURYLGHG 9LVXDOO\ LQVSHFWHG ZLWK WKH DLG RI ELORFXO
0DLQ ZDOOV	7KH PDLQ ZDOOV RI WKH EXLOGGLQJ DUH RI WUDGI URXJKFDVW H[WHUQDOO\ ZLWK VRPH IDFLQJ EULF &DYLW\ ZDOO LQVXODWLRQ DSSHDUV WR KDYH EH 9LVXDOO\ LQVSHFWHG ZLWK WKH DLG RI ELORFXO DQG FRQFHDOHG SDUVV ZHUH QRW H[SRVHG RU L
:LQGRZV H[WHUQDO DQG MRLQHU\	:LQGRZV GRRUV DUH LQ 39& GRXEOH JOD]HG DQG JOD]HG PDWHULDOV ,QWHUQDO DQG H[WHUQDO GRRUV ZHUH RSHQH DYDLODEOH 5DQGRP ZLQGRZV ZHUH RSHQH DQG FORVHG ZKH 'RRUV DQG ZLQGRZV ZHUH QRW IRUFHG RSHQ
([WHUQDO GHFRUDW	HWBRQW HG DUHDV LQFOXGH WLPEHUZRUN DQG FI 9LVXDOO\ LQVSHFWHG
&RQVHUYDWRULH	VRRQSRUWKHG
&RPPXQDO DUHDV	V<RXU 6ROLFLWRU VKRXOG FRQILUP WKH IXOO H[W DUHDV &LUFXODWLRQ DUHDV YLVXDOO\ LQVSHFWHG
*DUDJHV DQG SHUR RXWEXLOGGLQJV	URDQKHSXUSRVH RI RXU 5HSRUW WKHUH DUH QR YDOXH

2XWVLGH DUHDV ERXQGDULHV	DQGHQ JURXQGV DUH GHILQH LQ ZDOOV DQG IH SDYH FKLS DQG VKUXE PDWHULDOV 9LVXDOO\ LQVSHFWHG
&HLOLQJV	&HLOLQJV DUH LQ SODVWHU ODWK DQG SODVWHU 9LVXDOO\ LQVSHFWHG IURP IORRU OHYHO
,QWHUQDO ZDOO	,QWHUQDO ZDOOV DUH RI EULFN SODVWHU ODWK 9LVXDOO\ LQVSHFWHG IURP IORRU OHYHO 8VLQJ D PRLVWZDGHU ZHUH UDQGRPO\ WHVWHG IURP FRQVLGHUH DSSURSULDWH
)ORRUV LQFOXGH	QWHUQDO IORRUV LQFOXGH LQVSHQGHG WLPEHU D RYHUODLG ZLWK IORruerdugv)ORRUV DUH FRYHU 6XUIDFHV RI H[SRVHG IORruv ZHUH YLVXDOO\ LQ FRYHULQJV ZHUH OLIVHG 6XE IORruv DUHDV ZHUH LQVSHFWHG RQO\ WR WKH DFFHVVLEOH DQG XQIL[HG KDWFK E\ ZD\ RI DQ LQ LQVSHFWLRQ DW WKH DFFHVV SRLQW 3K\VLFDQ DFFHVV WR WKH VXE IORruv DUHD PD\ E LV LV VDIH DQG UHVRQDEOH WR GR VR DQG VX P EHWZH HQ WKH XQGHUVLGH RI IORruv mrlvwv D IURP WKH DFFHVV KDWFK
,QWHUQDO MRLQ ILWWLQJV	QWHUQDO MRLQV ILWWLQJV XQWHG NLWFKHQ ILWWLQJV DU ,QWHUQDO MRLQHUI\ LV LQ VRIWZRRG DQG KDUGZ %XLOW LQ FXSERDUGV ZHUH ORRNHG LQWR EXW C .LWFKHQ XQLWV ZHUH YLVXDOO\ LQVSHFWHG H[FO
&KLPQH\ EUHDVW ILUHSODFHV	YUDQDO FKLPH\ EUHDVWV DUH DVVXPHG WR KD DQG YHQWLODWHG 9LVXDOO\ LQVSHFWHG 1R WHVWLQJ RI WKH IOXH
,QWHUQDO GHFR ILUHSODFHV	YUDQDO FKLPH\ EUHDVWV DUH DVVXPHG WR KD DQG YHQWLODWHG 9LVXDOO\ LQVSHFWHG
&HOODUV	1RW DSSOLFDEOH

(OHFWULFLW\	7KH SURSHUW\ KDV D PDLQV VXSSO\ ZLWK 39& FR XQLW DPS SRZHU VRFNHWV DUH VLWXDWHG ZLWKLQ D KDOOZD\ \$FFHVVLEOH SDUWV RI WKH ZLULQJ ZHUH YLVXDO ILWWLQJV 1R WHVWV ZKDWRHYHU ZHUH FDUULH 9LVXDO LQVSHFWLRQ GRHV QRW DVVHV DQ\ VHU SURSHUOLBDQCMIO\ DQG PHHW PRGHUQ VWDQGDUG WXUQHGRH 6XUYH\RU ZLOO VWDWH WKDW LQ WKH RQ
*DV	7KHUH LV D PDLQV JDV VXSSO\ WR WKH SURSHUW \$FFHVVLEOH SDUWV RI WKH V\WHP ZHUH YLVXDO ILWWLQJV 1R WHVWV ZKDWRHYHU ZHUH FDUULH 9LVXDO LQVSHFWLRQ GRHV QRW DVVHV DQ\ VHU SURSHUOLBDQCMIO\ DQG PHHW PRGHUQ VWDQGDUG WXUQHGRH 6XUYH\RU ZLOO VWDWH WKDW LQ WKH RQ
: DWH\SOXPQLQJ DQG EDWKURRP ILWWLQJV	7KHUH SLHFH VDQLWDU\ ILWWLQJV DUH SURYLGHG :KHUH YLVLEOH SOXPQLQJ LQVWDOODWLRQV FRP PDWHULDOV 9LVXDO LQVSHFWLRQ RI WKH DFFHVVLEOH SLSHZF ILWWLQJV ZLWKRXW UHPYLQJ DQ\ LQVXODWLRQ 1R WHVWV ZKDWRHYHU ZHUH FDUULHG RXW WR V
+HDWLQJ DQG KRWDWHU	7KHUH FHQWUDO KHDWLQJ V\WHPKHV SURYL %D[L %HUPXGD EDFN ERLOHU LV VLWXDWHG ZLWK XQGHUVWRRG WR VHUYH WKH GRPSO\PHQ RMGZEV LPPHUVLRQ KHDWHU +RW ZDWHU SDQHO UDGLDWRUV DUH VLWXDWHG Z KDOOZD\ \$FFHVVLEOH SDUWV RI WKH V\WHP ZHUH YLVXDO FRPPXQDO V\WHPV ZKLFK ZHUH QRW LQVSHFWH 1R WHVWV ZKDWRHYHU ZHUH FDUULHG RXW WR V
'UDLQDJH	'UDLQDJH LV FRQQHF\$XWK RULWKMHZHO 'UDLQDJH FRYHUV HWF ZHUH QRW OLIVHG

)LUH VPRNH DQG DODUPV	6PRNH DQW HFWRU V DUH SURYLGHG ZLWKLQ WKH 9LVXDOO\ LQVSHFWHG 1R WHVW ZKDWVRHYHU ZHUH FDUULHG RXW WR D 7KHUH LV QRZ D UHTXLUHPHQW LQ SODFH IRU FR DQG KHDW GHWHFWRU V LQ KH QHZHQW DOP SURSHQ DODUP VWDQGDUG FDPH LQWR IRUFH LQ 6FRWODQ VPRNH DODUP WR EH LQVWDOOHG LQ WKH URRP P SXUSRVHV DQG LQ HYHU\ FLUFX \$W D WQD VSDUHQ UHTXLUHV WR EH LQVWDOOHG LQ PHDQHGL WRKEHQ PRXQWHG DQG LQWHUOLQNHG :KHUH WKHUH LV D DV D ERRSHQ ILUH RU ZRRG EXUQHU HWF D FDUH DOVR UHTXLUHG 7KH VXUYH\RU ZLOO RQO\ FRPPHQW RQ WKH SUHV EXW ZLOO QRW WHVW WKHP DVFHUUHQW ULOLQH DQG RU IXOO\ FRPSOLDQW ZLWK WKH ILUH DQG LQWURGXFHG LQ : H KDYH IRU WKH SXUSRVHV RI WKH UHSRUW DV FRPSOLDQW LI QRW WKHQ WKH DSSURSULDWH FR LQVWDOOHG SKULRUWRXUWHK VKRXOG EH FRQILUP DGYLVRU
\$Q\ DGGLWLRQDO LQVSHFWLRQ	1GLPHVVWR VXE IORRU DUHDV 1R DFFHVV WR URRI YRLG DUHDV)LWWHG IORRU FRYHULQJV LQ DUHDV WKURXJKRX 2QO\ WKH VXEMHFW IODW DQG LQWHUQDO FRPPXQ ZHUH LQVSHFWHG ,I WKH URRI VSDFH RU XQGHU EXLOGLQJ EDVHPH DQG VDIH DFFHVV LV QRW DOZD\V SRVVLEOH ,I Q ZLOO EH VWDWHG ,I QR LQVSHFWLRQ ZDV SRVVLEOH WKH 6XUYH\RU GHIHFWV WKDW ZLOO OHDYRQDWPHWDOO\ DWHUQ 7KH EXLOGLQJ FRQWDLQLQJ WKH IODW LQFOXGLQ ZDV YLVXDOO\ LQVSHFWHG RQO\ WR WKH H[WHQW DQ RSLQLRQ RQ WKH JHQHUDO FRQGLWLRQ DQG V \$Q LQVSHFWLRQ IRU -DSDQHVH .QRWZHVG ZDV QR 7KLV LV D SODQW ZKLFK LV VXEMHFW WR FRQWUR LQYDVLV DQG RQH ZKLFK FDQ UHQGHU D SURSHU PRUWJDJH OHQGHU ,W LV WKHUH RUH DVVXPHG .QRWZHVG ZLWKLQ WKH ERXQGDULHV RI WKH SUR SURSHUW\ ,GHQWLILFDWLRQ RI -DSDQHVH .QRWZHVG LV EHV FRQWUDFWRU\ LVWV UHPRYDO PXVW EH XQGHUW E\ VSHFLDOLVW FRQWUDFWRU WR EH H[SHQVLYH

Sectional Diagram showing elements of a typical house



Reference may be made in this report to some or all of the above component parts of the property. This diagram may assist you in locating and understanding these items.

7KLV VHFWRQ LGHQWLILHV SUREOHPV DQG WHOOV \RX DERXW
DERYH FDWHJRULHV

&DWHJRUI\	&DWHJRUI\	&DWHJRUI\
8UJHQW UHSDLUV RU UHSODFHPSHQWVDBHQHSDQIRGHPHQWLDWH)DLOXUH WR GHDO ZLWK WKHPHFDXLEDOYHXSURLOHFWWQHQWLRQ WR RWKHU SDUVV RI WKH SURSHUHWWRUFDXVHQHGHGHWDO KDJDUG (VWLPDWHV IRU UHSODGVLVRIUHSODFHPHQW DUH QHHGHG QRZ		

6WUXFWXUDO PRYHPHQW	
5HSDLU FDWHJRUI\	1
1RWHV	7KHUH LV HYLGHQFH RI D VHWWOHPHQW KDYLQJ EXW WKLV LV QRW LQFRQVLVWHQW ZLWK SURSHU VLQJOH VXSHUILFLDO H[DPLQDWLRQ UHYHDOHG Q PRYHPHQW LV RI D SURJUHVVLYH QDWXUH

'DPSQHVV URW DQG LQIHVWDWLQ	
5HSDLU FDWHJRUI\	1
1RWHV	8VLQJ D KDQG KHOG SURWLPHWHU ZH WRRN VSRU PHGLXP UHGGLQJV ZHUH HYLGHQW WR WKH YHVV DFFHSWDEOHKHUHQHSHUW\ LV LQ JHQHUDO RI DQ D UHGGLQJV FDQ GHYHORS DQG LW LV LPSRUWDQV KHDWHG DQG YHQWLODWHG WRKDHFRQVWHLBQYH ZDOOV VKRXOG EH PRQLWRUHGH UHJXODUO\

&KLPQH\ VWDFNV	
5HSDLU FDWHJRUI\	1
1RWHV	2ULJLQDO FKLPQH\ VWDFNV DSSHU WR KDYH EH FRQVLVWHQWZLWKZLWKDQJHVVXPHG WR KDYH EHHQ DQG YHQWLODWHG

&DWHJRUI\	&DWHJRUI\	&DWHJRUI\
8UJHQW UHSDLUV RU UHSODFHPHQW DWH QHSDIRGHQRIQGLDWH)DLOXUH WR GHDO ZLWK WKHPHFDXLFHQVHXSWRUDHWHWQH QWLRQS WR RWKHU SDUWV RI WKH SURSWUHWWRUFDXVHQDHHGHWLO KDJDUG (VWLPDWHV IRU UHSODGVVVRUG UHSODFHPHQW DUH QHHGHG QRZ		

5RRILQJ LQFOXGLQJ URRI VSDFH	
5HSDLU FDWIRUI	2
1RWHV	5RRI FRYHULQJV ZLOO UHTXLUH RQJRLQXPDGQWH HPSKDVLVH WKDW ZH ZHUHFLOQDQVDFWRVJMWQRDXQ DUHDV DV D UHVXOW RKHDFRNVKIRXDFHFKHFN UHJXODU RQJRLQJ EDVLV E\ D UHSXWDEOH 5RRIL H[SHQGGLWXUH DQWLFLSDWHG

5DLQZDWHU ILWWLQJV	
5HSDLU FDWIRUI	2
1RWHV	*XWWHUW GRZQSLSHV ZHUH IRXQG WR EH LQ D FF JHQHUDO PDLQWHQDQFH ZLOLEHVKIRXQGUEHFWDRU DV SDUW DQG SDFHO RI DQ\ IXWXUH FRPPRQ PD

0DLQ ZDOOV	
5HSDLU FDWIRUI	2
1RWHV	*HQHUDO SRLQWLQJ DQG SDWFKLQJ LV UHTXLUHG EXLOGGLQJ LQFOXGLQJILWVRKVRXQGVHLOQWWHVGW SDFHO RI DQ\ IXWXUH RQJRLQJ PDLQWHQDQFH S

:LQGRZV H[WHUQDO GRRUV DQG MRLQHU\	
5HSDLU FDWIRUI	2
1RWHV	'RXEOH JODJHG XQLWV DUH RI DQ DJH ZKHUHE\ JI FDQ EH DQWLFLSDWHG 6RPH PLVWHG ZLQGRZV Z IXOO RYHUKDXO RU UHSODFHPHQW RI ZLQGRZV Z 7KHVH IDFWRUV KDYH EHHQ UHIOHFWHG ZLWKLQ

([WHUQDO GHFRUDWLRQV	
5HSDLU FDWIRUI	2
1RWHV	5HGHFRUDWLRQ ZRUN LV UHTXLUHG WR H[WHUQD VHFWLRQV DQG WLPEHUZRUN

&DWHJRUI\	&DWHJRUI\	&DWHJRUI\
8UJHQW UHSDLUV RU UHSODFHPHQW DWH QHSDIRGHQPRHQ DWH)DLOXUH WR GHDO ZLWK WKHPHFDXLE DQVHXSWRUDH DWH QHSDIRGHQPRHQ DWH WR RWKHU SDUVV RI WKH SURSWUHWWRU FDH VHQ DWH QHSDIRGHQPRHQ DWH KDJDUG (VWLPDWHV IRU UHSODFHPHQW UHSDIRGHQPRHQ DWH QHSDIRGHQPRHQ DWH DUH QHHGHG QRZ		

&RQVHUYDWRULHV SRUFKHV	
5HSDLU FDWHJRUI\	
1RWHV	1RW DSSOLFDEOH

&RPPXQDO DUHDV	
5HSDLU FDWHJRUI\	1
1RWHV	&RPPRQ DUHDV ZHUH DGHTXDWHO\ NHSW

*DUDJHV DQG SHUPDQHQW RXWEXLOGLQJV	
5HSDLU FDWHJRUI\	
1RWHV	1RW DSSOLFDEOH

2XWVLGH DUHDV DQG ERXQGDULHV	
5HSDLU FDWHJRUI\	2
1RWHV	*HQHUDO PDLQWHQDQFH ZRUN LV UHTXLUHG WR I ZDOOV HWF

&HLOLQJV	
5HSDLU FDWHJRUI\	1
1RWHV	&HLOLQJV ZHUH IRXQG WR EH LQ D FRQGLWLRQ F JHQHUDO PDLQWHQDQFH ZLOO EH UHTXLUHG GXU PDLQWHQDQFH UHGHFRUDWLRQ SURJUDPPH

,QWHUQDO ZDOOV	
5HSDLU FDWHJRUI\	1
1RWHV	: DOOV ZHUH IRXQG WR EH LQ D FRQGLWLRQ FRQ PDLQWHQDQFH ZLOO EH UHTXLUHG GXULQJ DQ\ IX

&DWHJRUI\	&DWHJRUI\	&DWHJRUI\
8UJHQW UHSDLUV RU UHSODFHPHQWVDEHQHSGIRGHPHQWLDWH)DLOXUH WR GHDO ZLWK WKHPHFDXLEFDQVHXSWURLOHDEWQHQWLRQ WR RWKHU SDUWV RI WKH SURSWUHWWRUFDQVHQDHHGHWLO KDJDUG (VWLPDWHV IRU UHSODGVVVRUG UHSODFHPHQW DUH QHHGHG QRZ		

)ORRUV LQFOXGLQJ VXE IORRUV	
5HSDLU FDWIRUI	1
1RWHV	)ORRUV ZHUH IRXQG WR EH LQ D FRQGLWLRQ FRQ IORRULQJ ZDV HYLGHQWFRWLQGDDEHVVQXDOG EH I)XUWKHUPRUH XSJUDGH RI IORRU FRYHULQJV ZR

,QWHUQDO MRLQHU\ DQG NLWFKHQ ILWWLQJV	
5HSDLU FDWIRUI	1
1RWHV	.LWFKHQ ILWWLQJV DSSHUHG IXQFWLRQDO DOE EH RI EHQHILWMMHYDQWIRUV KDYH EHQ UHIOHFV YDOXDWLRQ ILJXUH *HQHUDO PDLQWHQDQFH ZRUN LV UHTXLUHG WR I

&KLPQH\ EUHDVWV DQG ILUHSODFHV	
5HSDLU FDWIRUI	
1RWHV	1RW DSSOLFDEOH

,QWHUQDO GHFRUDWLRQV	
5HSDLU FDWIRUI	1
1RWHV	7KH SURSHU\ ZRXOG EHQHILW IURP LQWHUQDO 3XUFKDVHU LV OLNHO\ WR UHGHFRUDWH WR WKH

&HOODUV	
5HSDLU FDWIRUI	
1RWHV	1RW DSSOLFDEOH

&DWHJRUI\	&DWHJRUI\	&DWHJRUI\
8UJHQW UHSDLUV RU UHSODFHPHQW DWH QHSDIRGHQPRQGLDWH)DLOXUH WR GHDO ZLWK WKHPHFDXLEDOYHXSURLOHEDWQHQWLRQSD WR RWKHU SDUVV RI WKH SURSWUHWWRUFDXVHQDHHGHVDO KDJDUG (VWLPDWHV IRU UHSDDGUVVRUG UHSODFHHPHQW DUH QHHGHG QRZ		

(OHFWULFLW\	
5HSDLU FDW\RU\	2
1RWHV	7KH HOHFWULFDO V\ VWHP DSSH DUHG IXQFWLRQDO WKDW WKLV ZDV QRW FKHFNHG RU WHVWHG REWDLQHG

*DV	
5HSDLU FDW\RU\	1
1RWHV	1R PDMRU GHIHFWV ZHUH DSSDUHQW &XUHQW V REWDLQHG

: DWHSDXPELQJ DQG EDWKURRP ILWWLQJV	
5HSDLU FDW\RU\	1
1RWHV	6DQLWDU\ ILWWLQJV DSSH DUHG IXQFWLRQDO DO ZRXOG EH RI EHQRKHUWFRYDOWHRQ KDV EHQ IX WKH YDOXDWLRQ ILJXUH : H GLG QRW GHWHFW DQ\ HYLGHQFH RI GHIHFW V WLPH RI RXU LQVSHFWLHQV ZHUH KRZHYHU IXOO\

+HDWLQJ DQG KRW ZDWHU	
5HSDLU FDW\RU\	2
1RWHV	7KH FHQWUDO KHDWLQJ V\ VWHP DW WKH WLPH RI IXQFWLRQDO DQG WKH LQGLFDWLRQ ZDV WKDW V 7KH LQVWDOODWLRQ RI D PRUH PRGHUQ FHQWUD EHQHILW WR YDOXH DQG DGylfH VKRXOG EH VRX

'UDLQDJH	
5HSDLU FDW\RU\	1
1RWHV	1R VXUIDFH HYLGHQFH RI GHIHFW ZDV DSSDUHQW

6HW RXW EHORZ LV D VXPPDU\ RI WKH FRQGLWLRQ RI WKH SUR
<RX VKRXOG UHIHU WR WKH FRPPHQWV DERYH IRU GHWDLOHG

6WUXFWXUDO PRYHPHQW	
'DPSQHVV URW DQG LQIHVWDWLRQ	
&KLPQH\ VWDFNV	
5RRILQJ LQFOXGLQJ URRI VSDFH	
5DLQZDWHU ILWWLQJV	
0DLQ ZDOOV	
: LQGRZV H[WHUQDO GRRUV DQG MRLQHU\	
([WHUQDO GHFRUDWLRQV	
&RQVHUYPDWRULHV SRUFKHV	
&RPPXQDO DUHDV	
*DUDJHV DQG SHUPDQHQW RXWEXLOGLQJV	
2XWVLGH DUHDV DQG ERXQGDULHV	
&HLOLQJV	
,QWHUQDO ZDOOV	
)ORRUV LQFOXGLQJ VXE IORruv	
,QWHUQDO MRLQHU\ DQG NLWFKHQ ILWWLQJV	
&KLPQH\ EUHDVWV DQG ILUHSODFHV	
,QWHUQDO GHFRUDWLRQV	
&HOODUV	
(OHFWULFLW\	
*DV	
: DWHSDUOXPELQJ DQG EDWKURRP ILWWLQJV	
+HDWLQJ DQG KRW ZDWHU	
'UDLQDJH	

5HPHPEHU

7KH FRVW RI UHSDLUV PD\ LQIOXHQFH WKH DPRXQW VHPHQH
UHFRPPHQG WKDW UHOHYDQW HVWLPDWHV DQG UHSRUWV DUH

: DUQLQJ

,I OHIW XQDWWHQGHG HYHQ IRU D UHODWLYHO\ VKRUW SHULR
PRUH VHULRXV &DWHURU[LW\SRQHVR\ &DWHJRU\ RU &DWHJRU
DGYHUVH\WIRQ PDUNEDQW WKH VDOH SULFH XOWLWDO\WHO\
LV SDUWLFXODUO\ WUXH GXULQJ VOIRZWDQJWHFRQVWLGHQDE

_____,Q IODWWHG GHYHORSP
PDLQ HQWUDQFH ZRXOG EH WKH RWDWKH RZVH LQWUDQRRUGWR
7KH WKUHH VWHSV RU IHZHU DUH FRXQWHG IURP H[W:HKHQDIO
D OLIW LV SUHVHQW WKH FRXQW LV EDVHG RQ WKH QXPEHU R

_____)RU WKLX SXUSRVH 8QUHVWULFWHG
DYDLODEOH E\ PHDQV RI D SDUNLQJ SHUPLW 5HVWULFWHG SD
SDUNLQJ UHVWULFWLRQV DV LQGLFDWHGGERUWKLSUHHQHQM R
WKH URDG RU E\ D SDUNLQJ FRQWURO VLJQ SDUNLQJ PHWHUV

:KLFK IORRU V LV WKH OLYLQJ DFFRPPRGDWLRQ RXXQG	
\$UH WKHUH WKUHH VWHSV RU IHZHU WR D P SURSHUW\"	DLO HQWUDQFH >[@ < (6 > @ 12
,V WKHUH D OLIW WR WKH PDLQ HQWUDQFH	GRRU<R6 WKLX @ 12
\$UH DOO GRRU RSHQLQJV JUHDWHU WKDQ	P@ "> @ < (6 > [@ 12
,V WKHUH D WRLOHW RQ WKH VDPH OHYHO	DV>WKH (6 > Y @ Q 2 U
,V WKHUH D WRLOHW RQ WKH VDPH OHYHO	DV>P@ < (6 > R @ P 2
\$UH DOO URRPV RQ WKH VDPH OHYHO ZLWK	QR>L@ < (6 > Q @ 02V
,V WKHUH XQUHVWULFWHG SDUNLQJ ZLWKL WKH EXLOGLQJ"	Q > [@ < (6 > @ 12 PHWHUV RI D

7KL V VHFWRQ KLJKOLJKWV LQIRUPDWLRQ WKDW VKRXOG EH F
,W DOVR JLYHV DQ RSLQLRQ RI PDUNHW YDOXH DQG DQ HVWLP
SXUSRVHV

0DWWHUV IRU D VROLFLWRU RU OLFHQVHG FRQYH\DQFHU	
\$EVROXWH 2ZQHUVKLS DVVXPHG	
: H DUH XQDZDUH RI DQ\ DGYHUVHF3WDQJWQH SURSRUDV DI %RXQGDULHV 5LJKWV :EH FKHFNHG LQ WKH QRUPDO PDQQH :KHUH LWHPV RI PDLQWHQDQFH RU UHSDLU KDYH EHHQ LGHQV WKHPVHOYHV DV WR WKH FRVWV DQG LPSOLFDEHQWRRRI WKHV 3XUFKDVH	
(VWLPDWHG UH LQVWDWHPHQW FRVW ... IRU LQVXUDQFH SXU	
7ZR +XQGURVVDQG 3RXQGV	
9DOXDWLRQ ... DQG PDUNHW FRPPHQWV	
2QH +XQGUHG7KQV)DQ 3RXQGV	
5HSRUW DXWKRU	3HWHU %HQQHW 05,&6
&RPSDQ\ QDPH	'XQIHUPDQHG 6XUYH\RUV 6FRWODQG /WG
\$GGUHV	D 'LFNVRQ 6WUHHW 'XQIHUPOLQH . < 6/
6LJQH	(OHFWURQLFDOO\ 6LJQH D H D GE
'DWH RI UHSRUW	

P A R T 2 .

MORTGAGE VALUATION REPORT

Includes a market valuation of the property.





Mortgage Valuation Report

Property:	27 Fod Street Halbeath, Dunfermline KY11 8EJ	Client: Mr. Steven Farish Tenure: Outright Ownership
Date of Inspection:	20/11/2025	Reference: DD3000

This report has been prepared as part of the seller's instructions to carry out a Single Survey on the property referred to above. The purpose of this report is to summarise the Single Survey for the purpose of advising a potential lender on the suitability of the property for mortgage purposes. The decision as to whether mortgage finance will be provided is entirely a matter for the lender. You should not rely on this report in making your decision to purchase but consider all the documents provided in the Home Report. Your attention is drawn to the additional comments elsewhere within the report which set out the extent and limitations of the service provided. This report should be read in conjunction with the Single Survey Terms and Conditions (with MVR). In accordance with RICS Valuation – Global Standards 2017 this report is for the use of the party to whom it is addressed or their named client or their nominated lender. No responsibility is accepted to any third party for the whole or any part of the reports contents. Neither the whole or any part of this report may be included in any document, circular or statement without prior approval in writing from the surveyor.

1.0 LOCATION

The subjects are situated within the village of Halbeath which is on the fringes of the city of Dunfermline. All normal local amenities and facilities can be found within an easy reach. In addition, the M90 motorway is a short distance away providing good access to Edinburgh and the north.

2.0 DESCRIPTION 2.1 Age: 95 years approx.

The subjects comprise a self contained flat on the ground floor of a two storey purpose built detached block of four .

3.0 CONSTRUCTION

Brick cavity construction, roughcast externally under a pitched roof slate clad externally.

4.0 ACCOMMODATION

GROUND FLOOR

Entrance Vestibule/Hall, Living Room, Breakfasting Kitchen, Three Bedrooms and Bathroom.

5.0 SERVICES (No tests have been applied to any of the services)

Water:	Mains	Electricity:	Mains	Gas:	Mains	Drainage:	Mains
---------------	-------	---------------------	-------	-------------	-------	------------------	-------

Central Heating: Full gas fired central heating system installed.

6.0 OUTBUILDINGS

Garage: None.

Others: None.

7.0 GENERAL CONDITION - A building survey has not been carried out, nor has any inspection been made of any woodwork, services or other parts of the property which were covered, unexposed or inaccessible. The report cannot therefore confirm that such parts of the property are free from defect. Failure to rectify defects, particularly involving water penetration may result in further and more serious defects arising. Where defects exist and where remedial work is necessary, prospective purchasers are advised to seek accurate estimates and costings from appropriate Contractors or Specialists before proceeding with the purchase. Generally we will not test or report on boundary walls, fences, outbuildings, radon gas or site contamination.

The subjects have been maintained in a condition consistent with age. General/ongoing maintenance work can be anticipated, and we would emphasise that these factors have been fully reflected within our valuation figure.

8.0	ESSENTIAL REPAIR WORK <i>(as a condition of any mortgage or, to preserve the condition of the property)</i>
------------	--

None.

8.1 Retention recommended:	--
-----------------------------------	----

9.0	ROADS & FOOTPATHS
------------	------------------------------

Made.

10.0	BUILDINGS INSURANCE (£):	200,000	GROSS EXTERNAL FLOOR AREA	103 m2	Square metres
-------------	---------------------------------	---------	----------------------------------	--------	----------------------

This figure is an opinion of an appropriate sum for which the property and substantial outbuildings should be insured against total destruction on a re-instatement basis assuming reconstruction of the property in its existing design and materials. Furnishings and fittings have not been included. No allowance has been included for inflation during the insurance period or during re-construction and no allowance has been made for VAT, other than on professional fees. Further discussions with your insurers is advised.

11.0	GENERAL REMARKS
-------------	------------------------

Absolute Ownership assumed.

We are unaware of any adverse Planning Proposals affecting the property.

Boundaries/Rights of Way should be checked in the normal manner.

Where items of maintenance or repair have been identified, the Purchaser should satisfy themselves as to the costs and implications of these issues prior to making an Offer to Purchase.

12.0	VALUATION <i>On the assumption of vacant possession and that the property is unaffected by any adverse planning proposals, onerous burdens, title restrictions or servitude rights. It is assumed that all necessary Local Authority consents, which may have been required, have been sought and obtained. No investigation of any contamination on, under or within the property has been made as we consider such matters to be outwith the scope of this report. All property built prior to the year 2000 may contain asbestos in one or more of its components or fittings. It is impossible to identify without a test. It is beyond the scope of this inspection to test for asbestos and future occupants should be advised that if they have any concerns then they should ask for a specialist to undertake appropriate tests.</i>
-------------	--

12.1	Market Value in present condition (£):	105,000	One Hundred and Five Thousand Pounds
-------------	---	----------------	--------------------------------------

12.2	Market Value on completion of essential works (£):		
-------------	---	--	--

12.3	Suitable security for normal mortgage purposes?	Yes
-------------	--	-----

12.4	Date of Valuation:	20/11/2025
-------------	---------------------------	------------

Signature:	Electronically Signed: 302294-4a0e2a31-80db		
-------------------	---	--	--

Surveyor:	Peter Bennet	MRICS	Date:	24/11/2025
------------------	--------------	-------	--------------	------------

Dunfermline - Allied Surveyors Scotland Ltd

Office:	18a Dickson Street Dunfermline KY12 7SL	Tel: 01383 728 833 Fax: email: dunfermline@alliedsurveyorsscotland.com
----------------	---	--

P A R T 3 .

ENERGY REPORT

A report on the energy efficiency of the property.



energy report

energy report on:

Property address	27 Fod Street Halbeath, Dunfermline KY11 8EJ
-------------------------	--

Customer	Mr. Steven Farish
-----------------	-------------------

Customer address	27 Fod Street Halbeath, Dunfermline KY11 8EJ
-------------------------	--

Prepared by	Peter Bennet, MRICS Dunfermline - Allied Surveyors Scotland Ltd
--------------------	--

Energy Performance Certificate (EPC)

Dwellings

Scotland

27 FOD STREET, HALBEATH, DUNFERMLINE, KY11 8EJ

Dwelling type: Ground-floor flat
Date of assessment: 20 November 2025
Date of certificate: 20 November 2025
Total floor area: 83 m²
Primary Energy Indicator: 242 kWh/m²/year

Reference number: 9120-2420-4190-2625-8045
Type of assessment: RdSAP, existing dwelling
Approved Organisation: Elmhurst
Main heating and fuel: Boiler and radiators, mains gas


You can use this document to:

- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO₂ emissions by improving your home

Estimated energy costs for your home for 3 years*	£5,469	See your recommendations report for more information
Over 3 years you could save*	£2,757	

* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions

Very energy efficient - lower running costs



Not energy efficient - higher running costs

Current	Potential
58	77


Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band D (58)**. The average rating for EPCs in Scotland is **band D (61)**.

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Very environmentally friendly - lower CO₂ emissions



Not environmentally friendly - higher CO₂ emissions

Current	Potential
68	78

Environmental Impact (CO₂) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO₂) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band D (68)**

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Cavity wall insulation	£900 - £1,500	£639.00
2 Floor insulation (suspended floor)	£5,000 - £10,000	£441.00
3 Add additional 80 mm jacket to hot water cylinder	£20 - £40	£165.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

THIS PAGE IS THE ENERGY PERFORMANCE CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE

Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, as built, no insulation (assumed)	★★☆☆☆	★★☆☆☆
Roof	(another dwelling above)	—	—
Floor	Suspended, no insulation (assumed)	—	—
Windows	Fully double glazed	★★☆☆☆	★★☆☆☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★★☆	★★★★☆
Secondary heating	None	—	—
Hot water	Electric immersion, standard tariff	★☆☆☆☆	★★★★★
Lighting	Good lighting efficiency	★★★★☆	★★★★☆

The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO₂ emissions, running costs and the savings possible from making improvements.

The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 40 kg CO₂/m²/yr.

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 3.3 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 1.0 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

Estimated energy costs for this home

	Current energy costs	Potential energy costs	Potential future savings
Heating	£3,171 over 3 years	£1,893 over 3 years	
Hot water	£2,115 over 3 years	£636 over 3 years	
Lighting	£183 over 3 years	£183 over 3 years	
Totals	£5,469	£2,712	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

Recommendations for improvement

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

Recommended measures	Indicative cost	Typical saving per year	Rating after improvement	
			Energy	Environment
1 Cavity wall insulation	£900 - £1,500	£213		
2 Floor insulation (suspended floor)	£5,000 - £10,000	£147		
3 Add additional 80 mm jacket to hot water cylinder	£20 - £40	£55		
4 Replace boiler with new condensing boiler	£2,200 - £3,500	£504		

Alternative measures

There are alternative improvement measures which you could also consider for your home. It would be advisable to seek further advice and illustration of the benefits and costs of such measures.

- External insulation with cavity wall insulation
- Micro CHP

Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.

About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

1 Cavity wall insulation

Cavity wall insulation, to fill the gap between the inner and outer layers of external walls with an insulating material, reduces heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. The insulation material is pumped into the gap through small holes that are drilled into the outer walls, and the holes are made good afterwards. As specialist machinery is used to fill the cavity, a professional installation company should carry out this work, and they should carry out a thorough survey before commencing work to ensure that this type of insulation is suitable for this home and its exposure. They should also provide a guarantee for the work and handle any building standards issues. Further information about cavity wall insulation and details of local installers can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

2 Floor insulation (suspended floor)

Insulation of a floor will significantly reduce heat loss; this will improve levels of comfort, reduce energy use and lower fuel bills. Suspended floors can often be insulated from below but must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about floor insulation is available from many sources including www.energysavingtrust.org.uk/scotland/Insulation/Floor-insulation. Building regulations generally apply to this work so it is best to check with your local authority building standards department.

3 Hot water cylinder insulation

Increasing the thickness of existing insulation by adding an 80 mm cylinder jacket around the hot water cylinder will help maintain the water at the required temperature; this will reduce the amount of energy used and lower fuel bills. The jacket should be fitted over the top of the existing foam insulation and over any thermostat clamped to the cylinder. Hot water pipes from the hot water cylinder should also be insulated, using pre-formed pipe insulation of up to 50 mm thickness, or to suit the space available, for as far as they can be accessed to reduce losses in summer. All these materials can be purchased from DIY stores and installed by a competent DIY enthusiast.

4 Condensing boiler

A condensing boiler is capable of much higher efficiencies than other types of boiler, meaning it will burn less fuel to heat this property. This improvement is most appropriate when the existing central heating boiler needs repair or replacement, however there may be exceptional circumstances making this impractical. Condensing boilers need a drain for the condensate which limits their location; remember this when considering remodelling the room containing the existing boiler even if the latter is to be retained for the time being (for example a kitchen makeover). Building regulations generally apply to this work and a building warrant may be required, so it is best to check with your local authority building standards department and seek advice from a qualified heating engineer.

Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit <https://energysavingtrust.org.uk/energy-at-home> for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	11,015.02	N/A	N/A	N/A
Water heating (kWh per year)	2,479.6			

Addendum

About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. Peter Bennet
Assessor membership number:	EES/014875
Company name/trading name:	Allied Surveyors Scotland Ltd
Address:	18a Dickson Street Dunfermline KY12 7SL
Phone number:	01383 738 585
Email address:	dunfermline@alliedsurveyorsscotland.com
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit [greener-scotland.org](https://www.greener-scotland.org) or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.

HOMEENERGYSCOTLAND.ORG
0808 808 2282
FUNDED BY THE SCOTTISH GOVERNMENT



P A R T 4 .

PROPERTY QUESTIONNAIRE

The owner of the property is required to complete this document which asks for information on the property such as 'Which council tax band?' etc.



Property Questionnaire

Property Address

27 Fod Street

Halbeath, Dunfermline

KY11 8EJ

Seller(s)

S F property company limited

Completion date of property questionnaire

21/11/2025

Note for sellers

1.	Length of ownership
	How long have you owned the property? 16 years
2.	Council tax
	Which Council Tax band is your property in? (Please circle) []A [x]B []C []D []E []F []G []H
3.	Parking
	What are the arrangements for parking at your property? (Please tick all that apply) Garage [] Allocated parking space [] Driveway [x] Shared parking [] On street [x] Resident permit [] Metered parking [] Other (please specify):

4.	Conservation area	
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?	☐ YES ☒ NO ☐ Don't know
5.	Listed buildings	
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?	☐ YES ☒ NO
6.	Alterations/additions/extensions	
a	(i) During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?	☐ YES ☒ NO
	If you have answered yes, please describe below the changes which you have made:	
	(ii) Did you obtain planning permission, building warrant, completion certificate and other consents for this work?	☐ YES ☐ NO
	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking.	
	If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:	
b	Have you had replacement windows, doors, patio doors or double glazing installed in your property	☐ YES ☒ NO
	If you have answered yes, please answer the three questions below:	
	(i) Were the replacements the same shape and type as the ones you replaced?	☐ YES ☐ NO
	(ii) Did this work involve any changes to the window or door openings?	☐ YES ☐ NO
	(iii) Please describe the changes made to the windows doors, or patio doors (with approximate dates when the work was completed): Please give any guarantees which you received for this work to your solicitor or estate agent.	
7.	Central heating	
a	Is there a central heating system in your property? (Note: a partial central heating system is one which does not heat all the main rooms of the property - the main living room, the bedroom(s), the hall and the bathroom).	☐ YES ☒ NO ☐ Partial

property questionnaire

	If you have answered yes or partial - what kind of central heating is there? (Examples: gas-fired, solid fuel, electric storage heating, gas warm air).																									
	If you have answered yes, please answer the three questions below:																									
	(i) When was your central heating system or partial central heating system installed?																									
	(ii) Do you have a maintenance contract for the central heating system?	☐ YES ☐ NO																								
	If you have answered yes, please give details of the company with which you have a maintenance contract																									
	(iii) When was your maintenance agreement last renewed? (Please provide the month and year).																									
8.	Energy Performance Certificate																									
	Does your property have an Energy Performance Certificate which is less than 10 years old?	☒ YES ☐ NO																								
9.	Issues that may have affected your property																									
a	Has there been any storm, flood, fire or other structural damage to your property while you have owned it?	☐ YES ☒ NO																								
	If you have answered yes, is the damage the subject of any outstanding insurance claim?	☐ YES ☐ NO																								
b	Are you aware of the existence of asbestos in your property?	☐ YES ☒ NO ☐ Don't know																								
	If you have answered yes, please give details:																									
10.	Services																									
a	Please tick which services are connected to your property and give details of the supplier:																									
	<table border="1"> <thead> <tr> <th>Services</th><th>Connected</th><th>Supplier</th></tr> </thead> <tbody> <tr> <td>Gas or liquid petroleum gas</td><td>Y</td><td></td></tr> <tr> <td>Water mains or private water supply</td><td>Y</td><td>Scottish water</td></tr> <tr> <td>Electricity</td><td>Y</td><td>Scottish power</td></tr> <tr> <td>Mains drainage</td><td>Y</td><td></td></tr> <tr> <td>Telephone</td><td>N</td><td></td></tr> <tr> <td>Cable TV or satellite</td><td>N</td><td></td></tr> <tr> <td>Broadband</td><td>N</td><td></td></tr> </tbody> </table>	Services	Connected	Supplier	Gas or liquid petroleum gas	Y		Water mains or private water supply	Y	Scottish water	Electricity	Y	Scottish power	Mains drainage	Y		Telephone	N		Cable TV or satellite	N		Broadband	N		
Services	Connected	Supplier																								
Gas or liquid petroleum gas	Y																									
Water mains or private water supply	Y	Scottish water																								
Electricity	Y	Scottish power																								
Mains drainage	Y																									
Telephone	N																									
Cable TV or satellite	N																									
Broadband	N																									
b	Is there a septic tank system at your property?	☐ YES ☒ NO																								

	If you have answered yes, please answer the two questions below:	
	(i) Do you have appropriate consents for the discharge from your septic tank?	[] YES [] NO [] Don't know
	(ii) Do you have a maintenance contract for your septic tank?	[] YES [] NO
	If you have answered yes, please give details of the company with which you have a maintenance contract:	
11.	Responsibilities for shared or common areas	
a	Are you aware of any responsibility to contribute to the cost of anything used jointly, such as the repair of a shared drive, private road, boundary, or garden area? If you have answered yes, please give details:	[] YES [x] NO [] Don't know
b	Is there a responsibility to contribute to repair and maintenance of the roof, common stairwell or other common areas? If you have answered yes, please give details:	[] YES [x] NO [] N/A
c	Has there been any major repair or replacement of any part of the roof during the time you have owned the property?	[] YES [x] NO
d	Do you have the right to walk over any of your neighbours' property- for example to put out your rubbish bin or to maintain your boundaries? If you have answered yes, please give details: <i>Access the rear</i>	[x] YES [] NO
e	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin or to maintain their boundaries? If you have answered yes, please give details:	[] YES [x] NO
f	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.) If you have answered yes, please give details:	[] YES [x] NO
12.	Charges associated with your property	
a	Is there a factor or property manager for your property? If you have answered yes, please provide the name and address, and give details of any deposit held and approximate charges:	[] YES [x] NO
b	Is there a common buildings insurance policy?	[] YES [x] NO [] Don't know
	If you have answered yes, is the cost of the insurance included in your monthly/annual factors charges?	

c	Please give details of any other charges you have to pay on a regular basis for the upkeep of common areas or repair works, for example to a residents' association, or maintenance or stair fund.	
13.	Specialist works	
a	As far as you are aware, has treatment of dry rot, wet rot, damp or any other specialist work ever been carried out to your property?	[]YES [x]NO
	If you have answered yes, please say what the repairs were for, whether you carried out the repairs (and when) or if they were done before you bought the property.	
b	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	[]YES [x]NO
	If you have answered yes, please give details:	
c	If you have answered yes to 13(a) or (b), do you have any guarantees relating to this work?	[]YES []NO
	If you have answered yes, these guarantees will be needed by the purchaser and should be given to your solicitor as soon as possible for checking. If you do not have them yourself please write below who has these documents and your solicitor or estate agent will arrange for them to be obtained. You will also need to provide a description of the work carried out. This may be shown in the original estimate. Guarantees are held by:	

14.	Guarantees	
a	Are there any guarantees or warranties for any of the following:	
(i)	Electrical work	☒ NO ☐ YES ☐ Don't know ☐ With title deeds ☐ Lost
(ii)	Roofing	☒ NO ☐ YES ☐ Don't know ☐ With title deeds ☐ Lost
(iii)	Central heating	☒ NO ☐ YES ☐ Don't know ☐ With title deeds ☐ Lost
(iv)	National House Building Council(NHBC)	☒ NO ☐ YES ☐ Don't know ☐ With title deeds ☐ Lost
(v)	Damp course	☒ NO ☐ YES ☐ Don't know ☐ With title deeds ☐ Lost
(vi)	Any other work or installations? (for example, cavity wall insulation, underpinning, indemnity policy)	☒ NO ☐ YES ☐ Don't know ☐ With title deeds ☐ Lost
b	If you have answered 'yes' or 'with title deeds', please give details of the work or installations to which the guarantee(s) relate(s):	
c	Are there any outstanding claims under any of the guarantees listed above?	☐ YES ☒ NO
	If you have answered yes, please give details:	

15.	Boundaries	
	So far as you are aware, has any boundary of your property been moved in the last 10 years?	☐ YES ☒ NO ☐ Don't know
	If you have answered yes, please give details:	
16.	Notices that affect your property	
In the past three years have you ever received a notice:		
a	advising that the owner of a neighbouring property has made a planning application?	☐ YES ☒ NO
b	that affects your property in some other way?	☐ YES ☒ NO
c	that requires you to do any maintenance, repairs or improvements to your property?	☐ YES ☒ NO
	If you have answered yes to any of a-c above, please give the notices to your solicitor or estate agent, including any notices which arrive at any time before the date of entry of the purchaser of your property.	

Declaration by the seller(s)/or other authorised body or person(s) I/We confirm that the information in this form is true and correct to the best of my/our knowledge and belief.

Signature(s): Steven farish

Capacity:

☒Owner

☐Legally Appointed Agent for Owner

Date:

21/11/2025