# **Energy performance certificate (EPC) recommendation** report

15b Wintersells Road Byfleet WEST BYFLEET KT14 7LF Report number **0218-0201-0404-2019-3814** 

Valid until **22 September 2034** 

### **Energy rating and EPC**

This property's energy rating is D.

For more information on the property's energy performance, see the EPC for this property.

### Recommendations

Changes that may pay for themselves within 3 years	
Recommendation	Potential impact on carbon emissions
Add time control to heating system.	Medium
In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to windows.	Medium
Consider replacing T8 lamps with retrofit T5 conversion kit.	High
Add optimum start/stop to the heating system.	Medium
The default heat generator efficiency is chosen. It is recommended that the heat generator system be investigated to gain an understanding of its efficiency and possible improvements.	Low
Changes that may pay for themselves within 3 to 7 years	
Changes that may pay for themselves within 3 to 7 years Recommendation	Potential impact on carbon emissions
3. 3	
Recommendation  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of	carbon emissions
Recommendation  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.	carbon emissions Low
Recommendation  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.  Some windows have high U-values - consider installing secondary glazing.	Low  Medium
Recommendation  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.  Some windows have high U-values - consider installing secondary glazing.  Add local temperature control to the heating system.	Carbon emissions  Low  Medium  Medium
Recommendation  Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of fittings required.  Some windows have high U-values - consider installing secondary glazing.  Add local temperature control to the heating system.	Carbon emissions  Low  Medium  Medium

## Changes that may pay for themselves in over 7 years

Carry out a pressure test, identify and treat identified air leakage. Enter result in

Consider switching from gas to biomass.

EPC calculation.

Recommendation	Potential impact on carbon emissions
Some glazing is poorly insulated. Replace/improve glazing and/or frames.	Medium
Consider installing an air source heat pump.	High
Consider installing a ground source heat pump.	High

High

Medium

Recommendation	Potential impact on carbon emissions
The default chiller efficiency is chosen. It is recommended that the chiller system be investigated to gain an understanding of its efficiency and possible improvements.	Low
Consider installing solar water heating.	Low

## Property and report details

Report issued on	23 September 2024
Total useful floor area	162 square metres
Building environment	Heating and Natural Ventilation
Calculation tool	G-ISBEM Ltd, G-ISBEM, v25.3, SBEM, v6.1.e.0

## Assessor's details

Assessor's name	Usman Hussain
Telephone	07939302868
Email	usman@energyexpertise.co.uk
Employer's name	ENERGY EXPERTISE LTD
Employer's address	07939302868
Assessor ID	QUID201051
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Quidos Limited