# **Energy performance certificate (EPC)**

2b Pilot Close
Coventry
CV3 4RS

Energy rating
Valid until: 9 June 2026

Certificate number: 9287-3076-0666-0000-9901

Property type B1 Offices and Workshop businesses


Total floor area 271 square metres

### Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.

### **Energy rating and score**

This property's energy rating is B.



Properties get a rating from A+ (best) to G (worst) and a score.

The better the rating and score, the lower your property's carbon emissions are likely to be.

## How this property compares to others

Properties similar to this one could have ratings:

If newly built	25 A
If typical of the existing stock	73 C

# Breakdown of this property's energy performance

Main heating fuel	Natural Gas
Building environment	Heating and Natural Ventilation
Assessment level	4
Building emission rate (kgCO2/m2 per year)	20.55

## **Recommendation report**

Guidance on improving the energy performance of this property can be found in the <u>recommendation</u> <u>report (/energy-certificate/0920-0046-8669-7706-9002)</u>.

### Who to contact about this certificate

### **Contacting the assessor**

If you're unhappy about your property's energy assessment or certificate, you can complain to the assessor who created it.

Assessor's name	Andrew Knapp
Telephone	01745 854170
Email	andrew.knapp@colesknapp.co.uk

### **Contacting the accreditation scheme**

If you're still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation scheme	Elmhurst Energy Systems Ltd
Assessor's ID	EES/005009
Telephone	01455 883 250
Email	enquiries@elmhurstenergy.co.uk
About this assessment	
	<b>a</b>
Employer	Coles Knapp
Employer address	Coles Knapp  8 Tai Tywyn Business Centre Prestatyn LL19 7SF
	• • • • • • • • • • • • • • • • • • • •
Employer address	8 Tai Tywyn Business Centre Prestatyn LL19 7SF
Employer address	8 Tai Tywyn Business Centre Prestatyn LL19 7SF The assessor is not related to the owner of the