


Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.

Energy rating and score

This property's current energy rating is D.



Properties get a rating from A+ (best) to G (worst) and a score.

The better the rating and score, the lower your property's carbon emissions are likely to be.

1 of 3 24/08/2023, 13:21

How this property compares to others

Properties similar to this one could have ratings:

| If newly built | 12 A |
|----------------------------------|------|
| If typical of the existing stock | 48 B |

Breakdown of this property's energy performance

| Main heating fuel | Grid Supplied Electricity |
|--|---------------------------------|
| Building environment | Heating and Natural Ventilation |
| Assessment level | 3 |
| Building emission rate (kgCO2/m2 per year) | 16.28 |
| Primary energy use (kWh/m2 per year) | 170 |

Recommendation report

Guidance on improving the energy performance of this property can be found in the <u>recommendation</u> <u>report (/energy-certificate/9675-6453-9522-7168-0325)</u>.

2 of 3 24/08/2023, 13:21

Who to contact about this certificate

Contacting the assessor

If you're unhappy about your property's energy assessment or certificate, you can complain to the assessor who created it.

Assessor's name Dean Mortimer

Contacting the accreditation scheme

If you're still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

| Accreditation scheme | Stroma Certification Ltd |
|----------------------|--------------------------|
| Assessor's ID | STRO001680 |
| Telephone | 0330 124 9660 |
| Email | certification@stroma.com |

About this assessment

| DEM Associates |
|---|
| Botelers, basildon, Essex SS165SE |
| The assessor is not related to the owner of the property. |
| 31 January 2023 |
| 31 January 2023 |
| |

3 of 3 24/08/2023, 13:21