## **Energy performance certificate (EPC)**

4 Dunholme Road Scothern LINCOLN LN2 2UD Energy rating

Valid until: 2 August 2032

Certificate number: 0370-3018-6208-0882-9204

Property type

Detached house

Total floor area

137 square metres

### Rules on letting this property


Properties can be rented if they have an energy rating from A to E.

If the property is rated F or G, it cannot be let, unless an exemption has been registered. You can read <u>guidance for landlords on the regulations and exemptions (https://www.gov.uk/guidance/domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance)</u>.

## Energy efficiency rating for this property

This property's current energy rating is D. It has the potential to be B.

See how to improve this property's energy performance.



The graph shows this property's current and potential energy efficiency.

Properties are given a rating from A (most efficient) to G (least efficient).

Properties are also given a score. The higher the number the lower your fuel bills are likely to be.

For properties in England and Wales:

the average energy rating is D the average energy score is 60

### Breakdown of property's energy performance

This section shows the energy performance for features of this property. The assessment does not consider the condition of a feature and how well it is working.

Each feature is assessed as one of the following:

- · very good (most efficient)
- good
- average
- poor
- very poor (least efficient)

When the description says "assumed", it means that the feature could not be inspected and an assumption has been made based on the property's age and type.

Feature	Description	Rating
Wall	Cavity wall, filled cavity	Average
Roof	Pitched, 150 mm loft insulation	Good
Roof	Flat, limited insulation (assumed)	Very poor
Window	Fully double glazed	Average
Main heating	Boiler and radiators, mains gas	Good
Main heating control	Programmer, room thermostat and TRVs	Good
Hot water	From main system, no cylinder thermostat	Poor
Lighting	Low energy lighting in 68% of fixed outlets	Good
Floor	Solid, no insulation (assumed)	N/A
Secondary heating	Room heaters, wood logs	N/A

#### Low and zero carbon energy sources

Low and zero carbon energy sources release very little or no CO2. Installing these sources may help reduce energy bills as well as cutting carbon emissions. The following low or zero carbon energy sources are installed in this property:

- · Biomass secondary heating
- Solar photovoltaics

#### Primary energy use

The primary energy use for this property per year is 259 kilowatt hours per square metre (kWh/m2).

# **Environmental impact of this property**

This property's current environmental impact rating is D. It has the potential to be B.

Properties are rated in a scale from A to G based on how much carbon dioxide (CO2) they produce.

Properties with an A rating produce less CO2 than G rated properties.

An average household produces

6 tonnes of CO2

This property produces	5.5 tonnes of CO2	
This property's potential production	2.3 tonnes of CO2	

By making the <u>recommended changes</u>, you could reduce this property's CO2 emissions by 3.2 tonnes per year. This will help to protect the environment.

Environmental impact ratings are based on assumptions about average occupancy and energy use. They may not reflect how energy is consumed by the people living at the property.

### Improve this property's energy performance

By following our step by step recommendations you could reduce this property's energy use and potentially save money.

Carrying out these changes in order will improve the property's energy rating and score from D (64) to B (82).

Step	Typical installation cost	Typical yearly saving
1. Flat roof or sloping ceiling insulation	£850 - £1,500	£78
2. Floor insulation (solid floor)	£4,000 - £6,000	£111
3. Low energy lighting	£30	£25
4. Hot water cylinder thermostat	£200 - £400	£92
5. Condensing boiler	£2,200 - £3,000	£234
6. Solar water heating	£4,000 - £6,000	£35

#### Paying for energy improvements

Find energy grants and ways to save energy in your home. (https://www.gov.uk/improve-energy-efficiency)

# Estimated energy use and potential savings

Estimated yearly energy cost for this property	£1644
Potential saving	£575

The estimated cost shows how much the average household would spend in this property for heating, lighting and hot water. It is not based on how energy is used by the people living at the property.

The potential saving shows how much money you could save if you <u>complete each</u> recommended step in order.

For advice on how to reduce your energy bills visit <u>Simple Energy Advice</u> (<a href="https://www.simpleenergyadvice.org.uk/">https://www.simpleenergyadvice.org.uk/</a>).

#### Heating use in this property

Heating a property usually makes up the majority of energy costs.

# Estimated energy used to heat this property

Type of heating	Estimated energy used	
Space heating	16922 kWh per year	
Water heating	3471 kWh per year	
Potential energy savings by installing insulation		

Amount of energy saved

**Loft insulation** 429 kWh per year

Type of insulation

### Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

#### Assessor contact details

Assessor's name David Handley Telephone 07801 845934

Email <u>handleyenergyassessors@sky.com</u>

#### Accreditation scheme contact details

Accreditation scheme Elmhurst Energy Systems Ltd

Assessor ID EES/005310
Telephone 01455 883 250

Email <u>enquiries@elmhurstenergy.co.uk</u>

#### **Assessment details**

Assessor's declaration

Date of assessment

Date of certificate

Type of assessment

No related party
3 August 2022
3 August 2022

RdSAP