


Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.

Energy rating and score

This property's energy rating is E.



Properties get a rating from A+ (best) to G (worst) and a score.

The better the rating and score, the lower your property's carbon emissions are likely to be.

How this property compares to others

Properties similar to this one could have ratings:



Breakdown of this property's energy performance

Main heating fuel	Grid Supplied Electricity
Building environment	Heating and Natural Ventilation
Assessment level	3
Building emission rate (kgCO2/m2 per year)	81.22

Recommendation report

Guidance on improving the energy performance of this property can be found in the <u>recommendation report</u> (/energy-certificate/0598-9430-5940-8700-3603).

Who to contact about this certificate

Contacting the assessor

If you're unhappy about your property's energy assessment or certificate, you can complain to the assessor who created it.

CS IRRV(Ho	71101
JU 1	1 11 1 2 (1 10

Contacting the accreditation scheme

If you're still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation scheme	Stroma Certification Ltd
Assessor's ID	STRO001058
Telephone	0330 124 9660
Email	certification@stroma.com

About this assessment

Employer	DWA Surveyors Limited
Employer address	23 Stamford Park Road Hale Cheshire WA15 9EL
Assessor's declaration	The assessor is not related to the owner of the property.
Date of assessment	18 July 2016
Date of certificate	25 July 2016