Air conditioning inspection certificate

Yorkshire Water Services
Livingstone House, Chadwick Street
LEEDS
LS10 1LJ

Certificate number **2560-6097-0506-0300-4805**

Valid until
4 March 2025

Assessment details

Inspection date	4 March 2020
Inspection level	Level 4
Assessment software	Quidos, AIRS, v2.0
Assessor's declaration	Not related to the owner/occupier or person who has technical control of the system or subcontractor.
F-Gas compliant date	Not Provided
Total effective rated output	741 kW
System sampling	Yes
Treated floor area	3,867 square metres
Subsystems metered	No
Total estimated refrigerant charge	89 kg

Inspection report

For the assessor's recommendations, see the inspection report (/energy-certificate/0070-5258-0560-6490-3004).

Subsystems inspected

Subsystem ID	Description	Refrigerant type	Age of main components
VOL001/SY S001	Single split heat pump inverter system serving the maintenance office	R410A	2010
VOL001/SY S002	Air cooled chiller provides a cooling coil to two air handling units which utilise heat recovery through the use of a thermal wheel, boilers provide a heating coil. AHU 1 serves the north side of the building, whilst AHU 2 serves the south side of the building. Chiller additionally provides a cooling coil to FCU's throughout the building	HFC 134a	2008

Assessor's details

Assessor's name	Karl Sharpe
Email	karl@greenzonesurveys.com
Assessor ID	QUID201500
Employer/Trading name	Green Zone Surveys (UK) Ltd
Employer/Trading address	Second Floor Cobalt Business Exchange Cobalt Park Way Newcastle Upon Tyne NE28 9NZ
Accreditation scheme	Quidos Limited
Accreditation scheme telephone	01225 667 570
Accreditation scheme email	info@quidos.co.uk