# 158 Tonbridge Road

# Material information

158 Tonbridge Road Hildenborough, Tonbridge, TN11 9HP Kotini has gathered this property information and the sellers have confirmed it to be accurate as of: **08/08/2024 10:59** 



# Introduction

Estate agents are required to provide consumers with 'material information' in property listings to ensure they can make an informed decision when buying a property. Material information is information that the average person needs to make an informed transactional decision#basically, whether a buyer decides to enquire further, view, or buy a property.

The estate agent you're buying from is dedicated to helping people find the right property for them and, as such, has put together this comprehensive summary of the property you've requested to view to help inform your purchasing decision.

If you have any questions about the information contained in this report, please contact your estate agent.

|   |   | • |
|---|---|---|
|   |   | - |
| U |   | _ |
|   | ш |   |

# Contents

Additional information Alterations & changes Boundaries Completion & moving Connectivity Council tax **Delay factors** Displutes & complaints Electricity **Electrical works Energy efficiency Environmental issues** Guarantees, warranties, and indemnity insurances Heating Insurance Listing & conservation Notices Other issues Ownership Parking **Rights and informal arrangements** Sellers capacity Services crossing the property **Specialist issues** Type of construction Water & drainage



# **Additional information**

#### Non-compliant with restrictions on use and alterations

No

#### Other material issues

No

#### Other charges not mentioned elsewhere

No



# Alterations & changes

# Planning permission breaches

No

Unfinished works at the property No

**Unresolved planning issues** No

### Structural alterations

**Structural alterations made to the property** No

### $\checkmark$ Change of use

**Property subject to a change of use** No

### ↓ Windows, roof windows, roof lights or glazed doors installations

**Details of the windows, roof windows, roof lights or glazed doors installation** Replace all windows and doors with 'Double Glazing' units

**Planning permission obtained for the windows, roof windows, roof lights or glazed doors** Not required

Windows, roof windows, roof lights or glazed doors installed since 1st April 2002 Yes

# Year the installation was completed 2020

Details why planning permission approval wasn't obtained

Only windows were replaced

Details why deed restriction consent wasn"t obtained Not mentioned in deeds

Deed restriction consent obtained for the windows, roof windows, roof lights or glazed doors No

**Details why listed building consent wasn"t obtained** Not Listed

Building regulation approval obtained for the windows, roof windows, roof lights or glazed doors Yes

Listed building consent obtained for the windows, roof windows, roof lights or glazed doors Not required

### ↓ Conservatories

Conservatory added to the property No



| Boundaries   |
|--|
| <b>Boundaries are uniform</b><br>Yes   |
| Property boundaries differ from the title plan<br>No   |
| Boundaries have been moved<br>No   |
| Proposal to alter the boundaries<br>No   |
| Part of the property are outside the legal ownership of the seller<br>No   |
| P <b>art of the property on separate deed</b><br>Yes   |
| <b>Details of the parts of the property on a separate deed</b><br>Right of Way to the property using the roadway to the rear of the property |
| Adjacent land included in the sale<br>No   |
| Fl <b>ying freehold at the property</b><br>No  |

# $\checkmark$ Boundary ownership

#### Left boundary

Neighbour

#### Rear boundary

Not known

#### **Right boundary**

Not known

#### Front boundary

Not known



# **Completion & moving**

| Seller will remove any rubbish<br>true       |  |
|--|--|
|  |  |
| Seller will replace any light fittings       |  |
| true   |  |
| Seller will take reasonable care             |  |
| true   |  |
| Seller will leave all keys                   |  |
| true   |  |
| Property in a chain                          |  |
| No   |  |
| Any dates the seller can't move on           |  |
| No   |  |
| Sale price sufficient to settle the mortgage |  |
| No mortgage                                  |  |

# Connectivity

↓ Telephone

**Telephone line connected to the property** Yes

Telephone supplier

Sky

## ↓ Cable & TV

Cable or satellite TV supplier Sky

Cable or satellite TV connected to the property Yes

### ↓ Broadband

**Broadband connection at the property** Cable

### ↓ Mobile coverage

Mobile signal issues at the property No





Council Tax band

Е

Alterations affecting Council Tax band

No

Annual Council Tax

2727.0



# **Delay factors**

Potential delays to the transaction

No



# **Disputes & complaints**

Past disputes and complaints

No

Potential disputes and complaints No

110



# Electricity

↓ Mains electricity

**Electricity meter location** Under the stairs

Mains electricity supplier British Gas

**Property connected to mains electricity** Yes

### $\checkmark$ Solar or photovoltaic panels

Solar or photovoltaic panels installed at the property No

### $\checkmark$ Other electricity sources

Other sources of electricity connected to the property No



| <b>Electrical works</b>                                       |  |
|---|--|
| <b>Electrics tested by a qualified electrician</b><br>Yes     |  |
| Year the electrics were tested<br>2023                        |  |
| <b>Year the electrical work was carried out</b><br>2023       |  |
| <b>Details of the electrical work</b><br>New Consumer Box     |  |
| <b>Any electrical works at the property since 2005</b><br>Yes |  |



# **Energy efficiency**

#### **Current EPC rating**

С

### Green deal loan in place

No



# **Environmental issues**

### $\checkmark$ Flooding

#### Property flooded before

No

#### Property at risk of flooding

No

### ↓ Radon

#### Radon test carried out No

Radon remedial measures on construction

Not known

## $\downarrow$ Coal mining

### Coal mining risk

No

# $\checkmark$ Other mining

# Other mining risk

No

### $\downarrow$ Coastal erosion

#### Coastal erosion risk No

### ↓ Other

#### Other environmental risks

No



# Guarantees, warranties, and indemnity insurances

| <b>Guarantees or warranties available for the property</b><br>Yes          |
|--|
| <b>New home warranty</b><br>No   |
| <b>Guarantes or warranties for roofing work</b><br>No                      |
| <b>Guarantes or warranties for damp proofing treatment</b><br>No           |
| Guarantes or warranties for central heating and/or plumbing<br>Yes         |
| <b>Guarantes or warranties for double glazing</b><br>No                    |
| <b>Guarantes or warranties for electrical repair or installation</b><br>No |
| <b>Guarantes or warranties for subsidence work</b><br>No                   |

#### Guarantes or warranties for solar panels

No

#### Outstanding claims or applications against the guarantees or warranties

No

#### Title defect insurance in place

No

#### Any other guarantees or warranties

No

#### Guarantes or warranties for timber rot infestation treatment

No



# Heating

**Type of heating system** Central heating

**Central heating fuel** Mains gas

**Mains gas, Oil or LPG supplier** British Gas

Date of the last service or maintenance 24/04/2024

Was a gas boiler installed after 1st April 2005, or a solid fuel or oil boiler installed after 1st October 2010?

Yes

Location of the gas meter Outside Wall

**Is the heating system in good working order** Yes

**Other heating features at the property** Double glazing



# Insurance

**Property insured** 

Yes

### $\checkmark$ Insurance concerns

**Details of insurance claims** Replacement of front door and window arising from attempted burglary

Insurance previously refused
No
Insurance subject to high excesses
No
Insurance subject to unusual conditions
No
Past insurance claims
Yes

Abnormal rise in insurance premiums

No



# Listing & conservation

### $\downarrow$ Listing status

#### Listed building in England or Wales

No

# $\checkmark$ Conservation

Located in a designated conservation area No

## ↓ Tree Preservation

**Tree preservation order in place** No

| • |  |
|---|--|
| * |  |
|   |  |

**Notices** 

# Planning application notice(s)

**Required maintenance notice(s)** No

Neighbour development notice(s)

Listed building application notice(s) No

**Infrastructure project notice(s)** No

Party wall act notice(s)

Yes

#### Details of party wall act notice(s)

October 2015 - Adjacent Property 158A knocked down their internal wall between dining and sitting room.

#### Other notices

No



| Other issues   |  |
|--|--|
| <b>Excessive noise issues</b><br>No  |  |
| <b>Crime issues</b><br>Yes   |  |
| <b>Details of issues with crime</b><br>Attempted burglary in or about 2022 |  |
| <b>Occupied by someone under caution or conviction</b><br>No               |  |
| <b>Failed transactions in last 12 months</b><br>No                         |  |



# **Ownership - Freehold**

#### Title number

K582974

#### **Tenure of the property** Freehold

#### Whole freehold being sold

Yes





#### **Type of parking available** Driveway

**Disabled parking available** Not known

#### Controlled parking in place

No

Electrical vehicle charging point at the property

No



# **Rights and informal arrangements**

| hared contributions<br>o                          |
|---|
| eighbouring land rights<br>o                      |
| <b>ublic right of way</b><br>o                    |
| ights of light<br>o                               |
| ights of support<br>o                             |
| ights created through custom<br>o                 |
| <b>ights to take from land</b><br>o               |
| <b>lines and minerals under the property</b><br>o |
| o   |

### Other rights

No

#### Attempts to restrict access

No

# **Sellers capacity**

**Capacity** Legal Owner



# Services crossing the property

**Pipes, wires, cables, drains coming to property** No

**Pipes, wires, cables, drains from property** No

Formal or informal agreements for services crossing the property No



| Specialist issues   |  |
|---|--|
| <b>Property treated for dry rot, wet rot or damp</b><br>Yes   |  |
| <b>Details of treatment for dry rot, wet rot or damp</b><br>Previous owners had preventative treatment. |  |
| <b>Japanese knotweed at the property or neighbouring land</b><br>Not known                              |  |
| Subsidence or structural faults<br>No   |  |
| <b>Ongoing health or safety issues at the property</b><br>No  |  |
| <b>Asbestos at the property</b><br>No   |  |



# Type of construction

Property is built with standard forms of construction

Yes

**Details of the sprayfoam installation** July 2011 Cavity Wall Installation installed

**Spray foam installed at the property** Yes

**Details of any accessibility adaptations at the property** No accessibility adaptations

## ↓ Building safety

**Building safety issues at the property** No

### ↓ Loft

**Property has access to a loft** Yes

How the loft is accessed Pull-Down Ladder

Loft boarded

Yes

### Loft insulated

Yes

# Water & drainage

| Y TYMIGI | $\mathbf{V}$ |  | N | a | t | e | r |
|----------|--------------|--|---|---|---|---|---|
|----------|--------------|--|---|---|---|---|---|

Location of the water meter

Outside Front Gate

Mains water connected to the property Yes

Mains water supplier South East Water

Mains water supply metered Yes

**Location of the stopcock** Outside Front Gate and in Kitchen

### ↓ Drainage

Mains foul drainage connected to the property Yes

Mains foul drainage supplier South East Water

Surface water drainage connected to the property Yes British Gas Service

### Maintenance agreements in place for the drainage system

Yes