English | Cymraeg

Energy performance certificate (EPC)




Rules on letting this property

Properties can be let if they have an energy rating from A+ to E.

You can read guidance for landlords on the regulations and exemptions (https://www.gov.uk/government/publications/non-domestic-private-rented-property-minimum-energy-efficiency-standard-landlord-guidance).

Energy rating and score

This property's energy rating is E.



Properties get a rating from A+ (best) to G (worst) and a score.

The better the rating and score, the lower your property's carbon emissions are likely to be.

How this property compares to others

Properties similar to this one could have ratings:



Breakdown of this property's energy performance

Main heating fuel	Grid Supplied Electricity		
Building environment	Heating and Natural Ventilation		

Assessment level	3
Building emission rate (kgCO2/m2 per year)	70.36
Primary energy use (kWh/m2 per year)	416

About primary energy use

Recommendation report

Guidance on improving the energy performance of this property can be found in the recommendation report (/energy-certificate/4428-8673-4684-4001-0873).

Who to contact about this certificate

Contacting the assessor

If you're unhappy about your property's energy assessment or certificate, you can complain to the assessor who created it.

Δ	66	ess	or	'e	na	m	Δ
м	22	E22	UI	3	Пa	ш	E

Ieuan Stevens

Contacting the accreditation scheme

If you're still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation scheme	Stroma Certification Ltd	a Certification Ltd	
Assessor's ID	STRO002630		
Telephone	0330 124 9660		
Email	certification@stroma.com		

About this assessment

Employe	r
----------------	---

Dragon Energy

Employer address	31 Cae Crwn, Machynlleth, SY20 8HG		
Assessor's declaration	The assessor is not related to the owner of the property.		
Date of assessment	5 April 2022		
Date of certificate	27 April 2022		

Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at mhclg.digital-services@communities.gov.uk or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related certificates for this property.



Help (/help) Accessibility (/accessibility-statement) Cookies (/cookies)

Give feedback (https://forms.office.com/e/KX25htGMX5)

Service performance (/service-performance)

OGL

All content is available under the <u>Open Government</u> <u>Licence v3.0 (https://www.nationalarchives.gov.uk/doc/opengovernment-licence/version/3/)</u>, except where otherwise stated



© Crown copyright (https://www.nationalarchives.gov.uk/information-management/reusing-public-sector-information/uk-government-licensing-framework/crown-copyright/)

English | Cymraeg

Energy performance certificate (EPC) recommendation report

2 Church Street
CHIRK
LL14 5HA

Report number
4428-8673-4684-40010873

Valid until
26 April 2032

Energy rating and EPC

This property's energy rating is E.

fittings required.

For more information on the property's energy performance, see the EPC for this property (/energy-certificate/2831-8439-6249-2778-5832).

Recommendations

Changes that may pay for themselves within 3 years

Recommendation	Potential impact on carbon emissions
Replace tungsten GLS lamps with CFLs: Payback period dependent on hours of use.	Low
Consider replacing T8 lamps with retrofit T5 conversion kit.	Medium
In some spaces, the solar gain limit defined in the NCM is exceeded, which might cause overheating. Consider solar control measures such as the application of reflective coating or shading devices to windows.	Medium
Introduce HF (high frequency) ballasts for fluorescent tubes: Reduced number of	Low

Changes that may pay for themselves within 3 to 7 years

Recommendation	Potential impact on carbon emissions
Add time control to heating system.	Medium
Add optimum start/stop to the heating system.	Medium
Changes that may pay for themselves in over 7 years	
Recommendation	Potential impact on carbon emissions
Some walls have uninsulated cavities - introduce cavity wall insulation.	Medium
Improve insulation on HWS storage.	Low
Some windows have high U-values - consider installing secondary glazing.	Medium
Add weather compensation controls to heating system.	Medium

Medium

Property and report details

Some loft spaces are poorly insulated - install/improve insulation.

27 April 2022	
335 square metres	
Heating and Natural Ventilation	
CLG, iSBEM, v5.6.b, SBEM, v5.6.b.0	

Assessor's details

Assessor's name	leuan Stevens
Employer's name	Dragon Energy
Employer's address	31 Cae Crwn, Machynlleth, SY20 8HG
Assessor ID	STRO002630
Assessor's declaration	The assessor is not related to the owner of the property.
Accreditation scheme	Stroma Certification Ltd

Other reports for this property

If you are aware of previous reports for this property and they are not listed here, please contact us at mhclg.digital-services@communities.gov.uk or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related reports for this property.



Help (/help) Accessibility (/accessibility-statement) Cookies (/cookies)

Give feedback (https://forms.office.com/e/KX25htGMX5)

Service performance (/service-performance)

OGL

All content is available under the <u>Open Government</u>
<u>Licence v3.0 (https://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/)</u>, except where otherwise stated



© Crown copyright (https://www.nationalarchives.gov.uk/information-management/re-using-public-sector-information/uk-government-licensing-framework/crown-copyright/)