### 51 Grasmere Road

#### **Material information**

51 Grasmere Road Gatley, Cheadle, SK8 4RS Kotini has gathered this property information and the sellers have confirmed it to be accurate as of:

01/08/2024 08:15





### Introduction

Estate agents are required to provide consumers with 'material information' in property listings to ensure they can make an informed decision when buying a property. Material information is information that the average person needs to make an informed transactional decision#basically, whether a buyer decides to enquire further, view, or buy a property.

The estate agent you're buying from is dedicated to helping people find the right property for them and, as such, has put together this comprehensive summary of the property you've requested to view to help inform your purchasing decision.

If you have any questions about the information contained in this report, please contact your estate agent.



### **Contents**

- %	_
- 7	v

Additional information

Alterations & changes

**Boundaries** 

Completion & moving

Connectivity

Council tax

**Delay factors** 

Displutes & complaints

**Electricity** 

**Electrical works** 

**Energy efficiency** 

**Environmental issues** 

Guarantees, warranties, and indemnity insurances

**Heating** 

Insurance

Listing & conservation

**Notices** 

Other issues

Ownership

**Parking** 

Rights and informal arrangements

Sellers capacity

Services crossing the property

Specialist issues

Type of construction

Water & drainage



### **Additional information**

No

Other material issues

No

Other charges not mentioned elsewhere

No



### Alterations & changes

Planning permission breaches No Unfinished works at the property No Unresolved planning issues No ↓ Structural alterations Structural alterations made to the property No ↓ Change of use Property subject to a change of use No

→ Windows, roof windows, roof lights or glazed doors installations

**Details of the windows, roof windows, roof lights or glazed doors installation**Double glazing lounge and back door

Details why building regulation approval wasn"t obtained

Exempt

Planning permission obtained for the windows, roof windows, roof lights or glazed doors Not required

Windows, roof windows, roof lights or glazed doors installed since 1st April 2002 Yes			
Year the installation was completed 2014			
Details why planning permission approval wasn't obtained Permitted Development			
Details why deed restriction consent wasn"t obtained Not needed			
Deed restriction consent obtained for the windows, roof windows, roof lights or glazed doors Not required			
Details why listed building consent wasn"t obtained Not listed			
Building regulation approval obtained for the windows, roof windows, roof lights or glazed doors  Not required			
Listed building consent obtained for the windows, roof windows, roof lights or glazed doors  Not required			
↓ Conservatories			
Conservatory added to the property No			
End of section			



### **Boundaries**

Boundaries
Boundaries are uniform Yes
Property boundaries differ from the title plan Yes
Boundaries have been moved No
Proposal to alter the boundaries No
Details of the differences vs the title plan  Part of the lawn to next door belongs to 51 Grasmere Road. This may need checking on site plan as the front is open and it may not be obvious.
Part of the property are outside the legal ownership of the seller No
Part of the property on separate deed No
Adjacent land included in the sale No
Flying freehold at the property No

### ↓ Boundary ownership

#### Left boundary

Not known

#### Rear boundary

Not known

#### Right boundary

Not known

#### Front boundary

Not known



# **Completion & moving**

Seller will remove any rubbish	
Seller will replace any light fittings	
Seller will take reasonable care	
Seller will leave all keys	
Property in a chain No	
Any dates the seller can't move on No	
Sale price sufficient to settle the mortgage No mortgage	
End of section	



### Connectivity

#### 

Telephone line connected to the property

No

#### ↓ Cable & TV

Cable or satellite TV connected to the property

No

#### ↓ Broadband

Broadband connection at the property

None

#### 

Mobile signal issues at the property

No



### **Council tax**

Council Tax band

F

Alterations affecting Council Tax band

No



# **Delay factors**

Potential delays to the transaction

Yes

Details of the delays

Waiting for Grant of Probate



Past disputes and complaints

No

Potential disputes and complaints

No



### **Electricity**

#### 

**Electricity meter location** 

Garage

Mains electricity supplier

Scottish Power

Property connected to mains electricity

Yes

↓ Solar or photovoltaic panels

Solar or photovoltaic panels installed at the property

No

**↓** Other electricity sources

Other sources of electricity connected to the property

No



### **Electrical works**

Electrics tested by a qualified electrician

No

Any electrical works at the property since 2005

No



# **Energy efficiency**

#### **Current EPC rating**

No Certificate

#### Green deal loan in place

No



### **Environmental issues**

#### ↓ Flooding

Property flooded before

No

Property at risk of flooding

No



Radon test carried out

No

Radon remedial measures on construction

No

↓ Coal mining

Coal mining risk

No

◆ Other mining

Other mining risk

No

↓ Coastal erosion

Coastal erosion risk

No

#### **↓** Other

#### Other environmental risks

No



# Guarantees, warranties, and indemnity insurances

Guarantees or warranties available for the property No
New home warranty
No
Guarantes or warranties for roofing work No
Guarantes or warranties for damp proofing treatment No
Guarantes or warranties for central heating and/or plumbing No
Guarantes or warranties for double glazing No
Guarantes or warranties for electrical repair or installation No
Guarantes or warranties for subsidence work No

Guarantes or warranties for solar panels No	
Outstanding claims or applications against the guarantees or warranties No	
Title defect insurance in place No	
Any other guarantees or warranties No	
Guarantes or warranties for timber rot infestation treatment No	
End of section	



# **Heating**

Type of heating system Central heating
Central heating fuel Mains gas
Mains gas, Oil or LPG supplier Scottish Power
Date of installation 29/07/2014
Was a gas boiler installed after 1st April 2005, or a solid fuel or oil boiler installed after 1st October 2010? Yes
Location of the gas meter Garage
Is the heating system in good working order Yes
Other heating features at the property  Double glazing
End of section



# **Insurance**

Property insured Yes		
↓ Insurance concerns		
Details of unusual conditions		
Empty property		
Insurance previously refused		
Insurance subject to high excesses No		
Insurance subject to unusual conditions Yes		
Past insurance claims		
No		
Abnormal rise in insurance premiums No		
End of section		



### **Listing & conservation**

#### ↓ Listing status

Listed building in England or Wales

No

**↓** Conservation

Located in a designated conservation area

No

**↓** Tree Preservation

Tree preservation order in place

No



## **Notices**

Planning application notice(s) No	
Required maintenance notice(s) No	
Neighbour development notice(s)	
Listed building application notice(s) No	
Infrastructure project notice(s) No	
Party wall act notice(s) No	
Other notices No	
End of section	



### Other issues

Excessive noise issues		
No		
Crimo issues		

Crime issues

No

Occupied by someone under caution or conviction

No

Failed transactions in last 12 months

No



# **Ownership - Freehold**

Title number

CH44694

Tenure of the property

Freehold



# **Parking**

Type of	parking	avai	lable
Garage	, Drivew	ay, F	Private

Disabled parking available

No

Controlled parking in place

No

Electrical vehicle charging point at the property

No



Shared contributions No
Neighbouring land rights No
<b>Public right of way</b> No
Rights of light No
Rights of support No
Rights created through custom No
Rights to take from land No
Mines and minerals under the property No
Church chancel liability No

#### Other rights

No

#### Attempts to restrict access

No



# **Sellers capacity**

#### Capacity

Personal Representative for a Deceased Owner

#### Sellers capacity details

Executor+sister is executor



# Services crossing the property

Pipes, wires, cables, drains coming to property	
No	

Pipes, wires, cables, drains from property

No

Formal or informal agreements for services crossing the property

No



# **Specialist issues**

Property treated for dry rot, wet rot or damp No
Details of asbestos Front door and possibly ceilings don't believe a management plan is in place
Japanese knotweed at the property or neighbouring land No
Subsidence or structural faults No
Ongoing health or safety issues at the property No
Asbestos at the property Yes
End of section



### Type of construction

Property is built with standard forms of construction

Yes

Spray foam installed at the property

No

Details of any accessibility adaptations at the property

No accessibility adaptations, Ramped access

→ Building safety

Building safety issues at the property

No



### Water & drainage



Mains water connected to the property

Yes

Mains water supplier

Northwest Water

Mains water supply metered

No

Location of the stopcock

Under the sink kitchen

#### ↓ Drainage

Details of the off mains foul drainage system

Not my property probate sale

Mains foul drainage connected to the property

No

Surface water drainage connected to the property

Yes

Type of off mains foul drainage system

Not known

#### $\label{eq:maintenance} \textbf{Maintenance} \ \textbf{agreements} \ \textbf{in} \ \textbf{place} \ \textbf{for} \ \textbf{the} \ \textbf{drainage} \ \textbf{system}$

No