2 Cartmel Close

Material information

2 Cartmel Close Gatley, Cheadle, SK8 4QP Kotini has gathered this property information and the sellers have confirmed it to be accurate as of:

23/08/2024 15:56





Introduction

Estate agents are required to provide consumers with 'material information' in property listings to ensure they can make an informed decision when buying a property. Material information is information that the average person needs to make an informed transactional decision#basically, whether a buyer decides to enquire further, view, or buy a property.

The estate agent you're buying from is dedicated to helping people find the right property for them and, as such, has put together this comprehensive summary of the property you've requested to view to help inform your purchasing decision.

If you have any questions about the information contained in this report, please contact your estate agent.



Contents

- %	_
- 7	~

Additional information

Alterations & changes

Boundaries

Completion & moving

Connectivity

Council tax

Delay factors

Displutes & complaints

Electricity

Electrical works

Energy efficiency

Environmental issues

Guarantees, warranties, and indemnity insurances

Heating

Insurance

Listing & conservation

Notices

Other issues

Ownership

Parking

Rights and informal arrangements

Sellers capacity

Services crossing the property

Specialist issues

Type of construction

Water & drainage



Additional information

No

Other material issues

No

Other charges not mentioned elsewhere

No



Alterations & changes

Planning permission breaches No
Unfinished works at the property No
Unresolved planning issues No
↓ Structural alterations
Details of the structural alterations
Ground floor side extension 1997 1st floor side extension 2001 Rear ground floor extension 2005 Kitchen into rear extension 2020
Building regulation approval obtained for the structural changes Yes
Planning permission approved for the strucutral changes Yes
Listed building consent obtained for the structural changes Not required
Structural alterations made to the property Yes

Not required
Details why deed restriction consent wasn"t obtained Permission not required

Details why listed building consent wasn"t obtained

Not a listed building

↓ Change of use

Property subject to a change of use

No

→ Windows, roof windows, roof lights or glazed doors installations

Windows, roof windows, roof lights or glazed doors installed since 1st April 2002

No

↓ Conservatories

Conservatory added to the property

No



Left boundary Not known

Boundaries

boundaries
Boundaries are uniform Yes
Property boundaries differ from the title plan No
Boundaries have been moved No
Proposal to alter the boundaries No
Part of the property are outside the legal ownership of the seller No
Part of the property on separate deed No
Adjacent land included in the sale No
Flying freehold at the property No
↓ Boundary ownership

Not known			
Right boundary Not known			
Front boundary Not known			

End of section

Rear boundary



Completion & moving

Completion & moving
Seller will remove any rubbish true
Seller will replace any light fittings true
Seller will take reasonable care true
Seller will leave all keys true
Property in a chain Yes
Type of transaction this sale is dependant on Sale
Address of the dependant property {'line1': '2 Cartmel Close', 'line2': 'Gatley', 'postcode': 'SK8 4QP', 'town': 'Cheadle'}
Any dates the seller can't move on Yes
Details of those dates

Sale price sufficient to settle the mortgageNo mortgage



Connectivity

Telephone line connected to the property

Yes

Telephone supplier

Virgin media



Cable or satellite TV supplier

Virgin

Cable or satellite TV connected to the property

Yes

Broadband connection at the property

FTTP (Fibre to the Premises)

Mobile signal issues at the property

No



Council tax

Council Tax band

C

Alterations affecting Council Tax band

No

Annual Council Tax

2085.0



Delay factors

Potential delays to the transaction

No



Past disputes and complaints

No

Potential disputes and complaints

No



Electricity

Electricity meter location

In a cupboard in the hall

Mains electricity supplier

Utility warehouse

Property connected to mains electricity

Yes

↓ Solar or photovoltaic panels

Solar or photovoltaic panels installed at the property

No

↓ Other electricity sources

Other sources of electricity connected to the property

No



Electrical works

Electrics tested by a qualified electrician

Yes

Year the electrics were tested

2020

Year the electrical work was carried out

2020

Details of the electrical work

Renew main circuit board and wired for new kitched

Any electrical works at the property since 2005

Yes



Energy efficiency

Current EPC rating

F

Green deal loan in place

No



Environmental issues

↓ Flooding

Property flooded before

No

Property at risk of flooding

No



Radon test carried out

No

Radon remedial measures on construction

Not known

↓ Coal mining

Coal mining risk

No

↓ Other mining

Other mining risk

No

↓ Coastal erosion

Coastal erosion risk

No

↓ Other

Other environmental risks

No



Guarantees, warranties, and indemnity insurances

Guarantees or warranties available for the property No
New home warranty
No
Guarantes or warranties for roofing work No
Guarantes or warranties for damp proofing treatment No
Guarantes or warranties for central heating and/or plumbing No
Guarantes or warranties for double glazing No
Guarantes or warranties for electrical repair or installation No
Guarantes or warranties for subsidence work No

Guarantes or warranties for solar panels No	
Outstanding claims or applications against the guarantees or warranties No	
Title defect insurance in place No	
Any other guarantees or warranties No	
Guarantes or warranties for timber rot infestation treatment No	
End of section	



Heating
Type of heating system Central heating
Central heating fuel Mains gas
Mains gas, Oil or LPG supplier Utility warehouse
Was a gas boiler installed after 1st April 2005, or a solid fuel or oil boiler installed after 1st October 2010? Yes
Location of the gas meter Outside
Is the heating system in good working order Yes
Other heating features at the property Double glazing
End of section



End of section

Insurance

Property insured Yes	
↓ Insurance concerns	
Insurance previously refused	
No	
Insurance subject to high excesses No	
Insurance subject to unusual conditions	
No	
Past insurance claims	
No	
Abnormal rise in insurance premiums	
No	



Listing & conservation

↓ Listing status

Listed building in England or Wales

No

↓ Conservation

Located in a designated conservation area

No

↓ Tree Preservation

Tree preservation order in place

No



Notices

Planning application notice(s) No	
Required maintenance notice(s) No	
Neighbour development notice(s)	
Listed building application notice(s) No	
Infrastructure project notice(s) No	
Party wall act notice(s) No	
Other notices No	
End of section	



Other issues

xcessive noise issues	
No	
Crime issues	
No	

Occupied by someone under caution or conviction

No

Failed transactions in last 12 months

No



Ownership - Freehold

Title number

GM716124

Tenure of the property

Freehold

Whole freehold being sold

Yes



Parking

Type of parking available

Driveway, Gated, Garage, Off Street, On Street

Disabled parking available

Yes

Controlled parking in place

No

Electrical vehicle charging point at the property

No



Shared contributions No
Neighbouring land rights No
Public right of way No
Rights of light No
Rights of support No
Rights created through custom No
Rights to take from land No
Mines and minerals under the property No
Church chancel liability No

Other rights

No

Attempts to restrict access

No



Sellers capacity

Capacity Legal Owner



Services crossing the property

Pipes, wires, cables, drains coming to property	

Pipes, wires, cables, drains from property

Yes

Not known

Details of pipes, wires, cables, drains from property

Sewerage drain

Formal or informal agreements for services crossing the property

Not known



Specialist issues

Property treated for dry rot, wet rot or damp No	
Japanese knotweed at the property or neighbouring land No	
Subsidence or structural faults No	
Ongoing health or safety issues at the property No	
Asbestos at the property No	
End of section	



Loft boarded

Yes

Type of construction

Property is built with standard forms of construction No
Details of the non-standard construction Standard construction
Spray foam installed at the property No
Details of any accessibility adaptations at the property Wide doorways, Level access shower, Level access
↓ Building safety
Building safety issues at the property No
↓ Loft
Property has access to a loft Yes
How the loft is accessed Left space over hadroom for storage Left batch on landing to access main Left space

Loft insulated

Yes



Water & drainage

↓ Water

Mains water connected to the property
Yes

Mains water supplier

United utilities

Mains water supply metered

No

Location of the stopcock

Under kitchen sink

↓ Drainage

Mains foul drainage connected to the property

Yes

Mains foul drainage supplier

United utilities

Surface water drainage connected to the property

Yes

Maintenance agreements in place for the drainage system

Nο