8 Lime Grove

Property Information Questionnaire

8 Lime Grove Cheadle, SK8 1PF

Kotini has gathered this property information, and the sellers have confirmed it to be accurate as of:

24/12/2024 20:52

Introduction

Estate agents are required to provide consumers with 'material information' in property listings to ensure they can make an informed decision when buying a property. Material information is information that the average person needs to make an informed transactional decision#basically, whether a buyer decides to enquire further, view, or buy a property.

The estate agent you're buying from is dedicated to helping people find the right property for them and, as such, has put together this comprehensive report of the property you're looking to buy, helping you to make an informed purchasing decision.

If you have any questions about the information contained in this report, please contact your estate agent.



Contents

- %	_
- 7	~

Additional information

Alterations & changes

Boundaries

Completion & moving

Connectivity

Council tax

Delay factors

Displutes & complaints

Electricity

Electrical works

Energy efficiency

Environmental issues

Guarantees, warranties, and indemnity insurances

Heating

Insurance

Listing & conservation

Notices

Other issues

Ownership

Parking

Rights and informal arrangements

Sellers capacity

Services crossing the property

Specialist issues

Type of construction

Water & drainage



Additional information

No

Other material issues

No

Other charges not mentioned elsewhere

No



Alterations & changes

Unfinished works at the property No	
Unresolved planning issues No	
Planning permission breaches No	
↓ Structural alterations	
Listed building consent obtained for the structural changes Not required	
Planning permission approved for the strucutral changes Not required	
Building regulation approval obtained for the structural changes Yes	
Structural alterations made to the property Yes	
Details why planning permission wasn't obtained No change to aperture size. Like for like	

ח	etail	s of the	structural	alterations

Two new rear windows and a new bi-fold rear door in 2024. Approved by Stockport Council Building Control.

Details why listed building consent wasn"t obtained

Not required

Deed restriction consent obtained for the structural changes

Not required

Details why deed restriction consent wasn"t obtained

Not required

↓ Change of use

Property subject to a change of use

No

→ Windows, roof windows, roof lights or glazed doors installations

Year the installation was completed

2024

Details why planning permission approval wasn't obtained

Not required

Windows, roof windows, roof lights or glazed doors installed since 1st April 2002

Yes

Details of the windows, roof windows, roof lights or glazed doors installation

Like for like size. New rear windows x2 and a new bi-fold rear door to the garden

Details why deed restriction consent wasn"t obtained

N/a

Deed restriction consent obtained for the windows, roof windows, roof lights or glazed doors Not required		
Details wh N/a	ny listed building consent wasn"t obtained	
Listed bui l Not requir	ding consent obtained for the windows, roof windows, roof lights or glazed doors	
Building re	egulation approval obtained for the windows, roof windows, roof lights or glazed doors	
Planning p Not requir	permission obtained for the windows, roof windows, roof lights or glazed doors	
↓ Cor	nservatories	
Conserva No	tory added to the property	
End of sec	ction	



Seller

Boundaries

boolidaries
Boundaries are uniform Yes
Boundaries have been moved No
Property boundaries differ from the title plan No
Proposal to alter the boundaries No
Part of the property are outside the legal ownership of the seller No
Part of the property on separate deed No
Adjacent land included in the sale No
Flying freehold at the property No
↓ Boundary ownership
Front boundary

Right boundary Seller			
Rear boundary Seller			
Left boundary Shared			



Completion & moving

Callan will manage and multiple	
Seller will remove any rubbish true	
Seller will replace any light fittings true	
Seller will take reasonable care true	
Seller will leave all keys true	
Property in a chain No	
Sale price sufficient to settle the mortgage No mortgage	
Any dates the seller can't move on No	
End of section	



Connectivity

Telephone line connected to the property

Yes

Telephone supplier

Vodaphone

↓ Cable & TV

Cable or satellite TV connected to the property

No

Broadband connection at the property

ADSL copper wire

Mobile signal issues at the property

No



Council tax

Council Tax band

C

Alterations affecting Council Tax band

No

Annual Council Tax

1450.0



Delay factors

Potential delays to the transaction

No



Past disputes and complaints

No

Potential disputes and complaints

No



Electricity

Mains electricity supplier

Octopus

Electricity meter location

By the front door

Property connected to mains electricity

Yes

↓ Solar or photovoltaic panels

Solar or photovoltaic panels installed at the property

No

↓ Other electricity sources

Other sources of electricity connected to the property

No



Electrical works

Electrics tested by a qualified electrician

No

Any electrical works at the property since 2005

No



Energy efficiency

Current EPC rating

D

Green deal loan in place

No



Environmental issues

↓ Flooding

Property flooded before

No

Property at risk of flooding

No



Radon test carried out

No

Radon remedial measures on construction

Not known

↓ Coal mining

Coal mining risk

No

↓ Other mining

Other mining risk

No

↓ Coastal erosion

Coastal erosion risk

No

↓ Other

Other environmental risks

No



Guarantees, warranties, and indemnity insurances

Guarantees or warranties available for the property No
New home warranty
No
Guarantes or warranties for roofing work No
Guarantes or warranties for damp proofing treatment No
Guarantes or warranties for central heating and/or plumbing No
Guarantes or warranties for double glazing No
Guarantes or warranties for electrical repair or installation No
Guarantes or warranties for subsidence work No

Guarantes or warranties for solar panels No	
Guarantes or warranties for timber rot infestation treatment No	
Any other guarantees or warranties No	
Outstanding claims or applications against the guarantees or warranties No	
Title defect insurance in place No	
End of section	



Heating
Type of heating system
Central heating
Central heating fuel
Mains gas
Mains gas, Oil or LPG supplier
Octopus
Was a gas boiler installed after 1st April 2005, or a solid fuel or oil boiler installed after 1st October 2010?
Yes
Location of the gas meter
Cellar
Is the heating system in good working order
Yes
Other heating features at the property
Double glazing
End of section



End of section

Insurance

Property insured Yes	
↓ Insurance concerns	
Insurance subject to high excesses	
No	
Insurance subject to unusual conditions No	
Insurance previously refused	
No	
Past insurance claims	
No	
Abnormal rise in insurance premiums	
No	



Listing & conservation

↓ Listing status

Listed building in England or Wales

No

↓ Conservation

Details of conservation area

Cheadle Village

Located in a designated conservation area

Yes

↓ Tree Preservation

Tree preservation order in place

No



Notices

Planning application notice(s) No		
Required maintenance notice(s) No		
Neighbour development notice(s) No		
Listed building application notice(s) No		
Infrastructure project notice(s) No		
Party wall act notice(s) No		
Other notices No		
End of section		



Other issues

xcessive noise issues	
No	
Crime issues	
No	

Occupied by someone under caution or conviction

No

Failed transactions in last 12 months

No



Ownership - Freehold

Title number

GM661400

Tenure of the property

Freehold

Whole freehold being sold

Yes



Parking

Type of parl	king	avail	ab	le
--------------	------	-------	----	----

Allocated

Disabled parking available

Not known

Controlled parking in place

Yes

Electrical vehicle charging point at the property

No



Shared contributions No	
Neighbouring land rights No	
Public right of way No	
Rights of light No	
Rights of support No	
Rights created through custom No	
Rights to take from land No	
Mines and minerals under the property No	
Church chancel liability No	

Other rights

No

Attempts to restrict access

No



Sellers capacity

Capacity Legal Owner



Services crossing the property

Pipes, wires, cables, drains coming to property	
No	

Pipes, wires, cables, drains from property

No

Formal or informal agreements for services crossing the property

No



Specialist issues

Property treated for dry rot, wet rot or damp No	
Japanese knotweed at the property or neighbouring land No	
Subsidence or structural faults No	
Ongoing health or safety issues at the property No	
Asbestos at the property No	
End of section	



End of section

Type of construction

Property is built with standard forms of construction Yes
Spray foam installed at the property No
Details of any accessibility adaptations at the property No accessibility adaptations
→ Building safety
Building safety issues at the property No
↓ Loft
Property has access to a loft
Yes
How the loft is accessed
First floor landing hatch
Loft boarded No
Loft insulated Yes



Water & drainage



Mains water connected to the property Yes Mains water supplier United Utilities Mains water supply metered No Location of the stopcock Cellar ↓ Drainage Surface water drainage connected to the property Yes Mains foul drainage connected to the property Yes Mains foul drainage supplier Not known Maintenance agreements in place for the drainage system

End of section

Nο