



5 Melrose Avenue

Property Information Questionnaire

5 Melrose Avenue Stockport, SK3 0QX

Kotini has gathered this property information, and the sellers have confirmed it to be accurate as of:

27/02/2025 18:20

Introduction

Estate agents are required to provide consumers with 'material information' in property listings to ensure they can make an informed decision when buying a property. Material information is information that the average person needs to make an informed transactional decision#basically, whether a buyer decides to enquire further, view, or buy a property.


The estate agent you're buying from is dedicated to helping people find the right property for them and, as such, has put together this comprehensive report of the property you're looking to buy, helping you to make an informed purchasing decision.

If you have any questions about the information contained in this report, please contact your estate agent.



Contents

- ↓ Additional information
- Alterations & changes
- Boundaries
- Completion & moving
- Connectivity
- Council Tax
- Delay factors
- Disputes & complaints
- Electricity
- Electrical works
- Energy efficiency
- Environmental issues
- Guarantees, warranties, and indemnity insurances
- Heating
- Insurance
- Listing & conservation
- Notices
- Other issues
- Ownership
- Parking
- Rights and informal arrangements
- Sellers capacity
- Services crossing the property
- Specialist issues
- Type of construction
- Water & drainage



Additional information

Other material issues

No

Other charges not mentioned elsewhere

No

Non-compliant with restrictions on use and alterations

No

End of section



Alterations & changes

↓ Structural alterations

Structural alterations made to the property

No

↓ Change of use

Property subject to a change of use

No

↓ Windows, roof windows, roof lights or glazed doors installations

Windows, roof windows, roof lights or glazed doors installed since 1st April 2002

No

↓ Conservatories

Conservatory added to the property

Yes

Year the conservatory was completed

2000

Details of the conservatory

Done before we purchased. Unsure

Planning permission obtained for the conservatory

Yes

Building regulation approval obtained for the conservatory

Yes

Listed building consent obtained for the conservatory

Not required

Details why listed building consent wasn't obtained

Not listed

Deed restriction consent obtained for the conservatory

Not required

Details why deed restriction consent wasn't obtained

Not required

Unfinished works at the property

No


Unresolved planning issues

No

Planning permission breaches

No

End of section



Boundaries

↓ Boundary ownership

Front boundary

Seller

Left boundary

Not known

Rear boundary

Seller

Right boundary

Not known

Boundaries are uniform

Yes

Boundaries have been moved

No

Property boundaries differ from the title plan

No

Proposal to alter the boundaries

No

Adjacent land included in the sale

No

Part of the property on separate deed

No

Part of the property are outside the legal ownership of the seller

No

Flying freehold at the property

No

End of section



Completion & moving

Any dates the seller can't move on

No

Property in a chain

No

Sale price sufficient to settle the mortgage

Yes

Seller will leave all keys

true

Seller will remove any rubbish

true

Seller will replace any light fittings

true

Seller will take reasonable care

true

End of section



Connectivity

↓ Telephone

Telephone line connected to the property

Yes

Telephone supplier

Virgin

↓ Cable & TV

Cable or satellite TV connected to the property

Yes

Cable or satellite TV supplier

Virgin

↓ Broadband

Broadband connection at the property

FTTP (Fibre to the Premises)

↓ Mobile coverage

Mobile signal issues at the property

No

End of section



Council Tax

Local Authority
Stockport

Council Tax band
C

Annual Council Tax
2085.9

Alterations affecting Council Tax band
No

End of section




Delay factors

Potential delays to the transaction

No

End of section



Disputes & complaints


Past disputes and complaints

No

Potential disputes and complaints

No

End of section



Electricity

↓ Mains electricity

Property connected to mains electricity

Yes

Mains electricity supplier

Octopus

Electricity meter location

Porch

↓ Solar or photovoltaic panels

Solar or photovoltaic panels installed at the property

No

↓ Other electricity sources

Other sources of electricity connected to the property

No

End of section



Electrical works


Electrics tested by a qualified electrician

No

Any electrical works at the property since 2005

No

End of section



Energy efficiency

Date of inspection

2014-01-21

Certificate date (valid for 10yrs)

2014-01-21

Certificate number

0016-2889-7290-9324-3205

Current Energy Performance rating

E

Current energy efficiency

47

Potential Energy Performance rating

B


Potential energy efficiency

83

Green deal loan in place

No

End of section



Environmental issues

↓ Flooding

Property flooded before

No

Property at risk of flooding

No

↓ Radon

Radon remedial measures on construction

No

Radon test carried out

No

↓ Coal mining

Coal mining risk

No

↓ Other mining

Other mining risk

No

↓ Coastal erosion

Coastal erosion risk

No

↓ Other

Other environmental risks

No

End of section



Guarantees, warranties, and indemnity insurances

Guarantees or warranties available for the property

No

Guarantes or warranties for central heating and/or plumbing

No

Guarantes or warranties for damp proofing treatment

No

Guarantes or warranties for double glazing

No

Guarantes or warranties for electrical repair or installation

No

Guarantes or warranties for roofing work

No

Guarantes or warranties for solar panels

No

Guarantes or warranties for subsidence work

No

Guarantes or warranties for timber rot infestation treatment

No

New home warranty

No

Any other guarantees or warranties

No

Outstanding claims or applications against the guarantees or warranties

No

Title defect insurance in place

No

End of section



Heating

Type of heating system

Central heating

Central heating fuel

Mains gas

Mains gas, Oil or LPG supplier

Octopus

Location of the gas meter

Porch

Was a gas boiler installed after 1st April 2005, or a solid fuel or oil boiler installed after 1st October 2010?

Yes

Date of the last service or maintenance

01/08/2024

Is the heating system in good working order

Yes

Other heating features at the property

Double glazing

End of section



Insurance

Property insured

Yes

↓ Insurance concerns

Abnormal rise in insurance premiums

No

Insurance subject to high excesses

No

Insurance subject to unusual conditions

No

Insurance previously refused

No

Past insurance claims

No

End of section



Listing & conservation

↓ Listing status

Listed building in England or Wales

No

↓ Conservation

Located in a designated conservation area

No

↓ Tree Preservation

Tree preservation order in place

No

End of section



Notices

Infrastructure project notice(s)

No

Neighbour development notice(s)

No

Listed building application notice(s)

No

Party wall act notice(s)

No

Planning application notice(s)

No

Required maintenance notice(s)

No

Other notices

No

End of section



Other issues

Excessive noise issues

No

Crime issues

No

Occupied by someone under caution or conviction

No

Failed transactions in last 12 months

No

End of section



Ownership - GM279777

Tenure of the property

Freehold

Title number

GM279777

Whole freehold being sold

Yes

End of section



Parking

Type of parking available

Driveway

Controlled parking in place

No

Disabled parking available

No

Electrical vehicle charging point at the property

No

End of section



Rights and informal arrangements

Shared contributions

No

Neighbouring land rights

No

Attempts to restrict access

No

Public right of way

No

Rights of light

No

Rights of support

No

Rights created through custom

No

Rights to take from land

No

Mines and minerals under the property

No

Church chancel liability

No

Other rights

No

End of section



Services crossing the property

Pipes, wires, cables, drains from property

No

Pipes, wires, cables, drains coming to property

No

Formal or informal agreements for services crossing the property

No

End of section



Specialist issues

Subsidence or structural faults

No

Property treated for dry rot, wet rot or damp

No

Ongoing health or safety issues at the property

No

Japanese knotweed at the property or neighbouring land

No

Asbestos at the property

No

End of section



Type of construction

Property is built with standard forms of construction

Yes

Spray foam installed at the property

Yes

Details of the sprayfoam installation

Don't know done before we came

Details of any accessibility adaptations at the property

No accessibility adaptations

↓ Building safety

Building safety issues at the property

No

↓ Loft

Property has access to a loft

Yes

How the loft is accessed

Ladder

Loft boarded

Yes

Loft insulated

Yes

End of section



Water & drainage

↓ Water

Mains water connected to the property

Yes

Mains water supplier

United utilities

Location of the stopcock

Cupboard under stairs

Mains water supply metered

Yes

Location of the water meter

Cupboard under stairs

↓ Drainage

Surface water drainage connected to the property

Yes

Mains foul drainage connected to the property

Yes

Mains foul drainage supplier

United utilities

Maintenance agreements in place for the drainage system

No

End of section