

Rede House
Corporation Road
Middlesbrough
TS1 1LY

Removal of Artex from concrete understairs ground floor entrance cupboard,
first stage clear down removal of top coat. Due to concrete left overnight
with remover second stage wet strip to concrete level.

Fire proof ruber sealing solution applied after strip (White) to ensure area
completely sealed following Artex strip.

(Job description)

TASC Environmental Services Ltd

by: _____ (Name of contractor)

PO Box 592

Whitley Bay
Tyne & Wear

NE250DG _____ (Contractor's address)

All areas have had the Asbestos materials removed double bagged and
transported from site taken to a Environment Agency Approved site
consignment.

The rooms had then been cleaned using type H cleaner followed by surfaces
being wiped down and finally sealing of areas.

I can confirm all areas have been cleaned and are free from Asbestos
contamination all Asbestos materials identified for removal have been cleared
from site. And sealed sealed ready for reinstatement _____ (Areas inspected)

I am satisfied that the area can be returned to normal use.

Signed:  _____

Name: Ray Doyle _____ (capitals)

Date: 19-2-14 _____